

ASS. REC. BY:

REF:

es/FCI18009308/4fd3

n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Hung Yin Min

of

FCI

Date/Time: 22/5/18 @ 2:56pm

Estimated Cost:

Bill to:

OD / ① / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCV 8210G

Insured:

SHC 7806K

at Workshop m/s

ABWIN SERVICE

Tel:

6713 9400

of No. 8 Kaki Bukit Ave 4 # 07-48

Policy No:

Claim No:

D1800 4066MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/05/2018

CA / REV / REP. / REV 24 HRS

Cwp

H.O.D. Endorsement:

Date/Time: 3:01pm @ 22/5/18

Person Contacted:

Linda

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SCV 8210G-X
	SHC 7806K-CC3/LCR17008506/H129392
25/5 @ 3:49pm	revert via email preli advise

DOA: 24/4/17

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SCV8240Gat Workshop m/s Abw.1

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

D.A.C. Accident Report: 2 Consistent? : Yes or NoD.A. / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction 21/4/18 5949023/5/18 confirmed L/S \$2200 with 1.20. (red: 8444.26: 79%)

RECEIVED 25 MAY 2018

Data/Time, File Pass to?

1) 25/5 Typist

Data/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I. (\$) 2200f☐

Prel. Report

☒

Final Report

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

130
50
30
250

Veh No: SCV8240G Yr Regn: 616

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/Make: Toyota harrier o.c. 1986Colour: silver A/C: Insured / Std / NI / NASp. Reading: 29020 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 254600077503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225/65-17

R: _____

☒ BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 3 mm R/Bal. 3 mmL/Bal. 3 mm L/Bal. 3 mmD.O.A. 21/5/18 D.O.A. 23/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s.

The U/C / Chassis frame / Body Structure affected due to collision:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009308/Utd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7806K	Veh. Inspected	SCV 8210G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004066MFSH	Excess (\$)	0.00	
Assign From	CWS (AUNG YIN MIN)	Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/05/2018	Inspection Date		
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004066MFSH

Date: 25/5/2018

Our Ref: CS/FCI18009308/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SCV 8210G.

Please be informed that we had conducted the inspection of the abovementioned vehicle
23/05/2018 at the premises of M/s Abwin service and have the following to report: -

Workshop Estimate Amount	: S\$ <u>10,644.26</u>
Revised Estimate Amount	: S\$ <u>2,200.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-05-2018	Our Ref No. D18004066MFSH
Accident Date	21-05-2018	Claim Type. Third Party
Insured Vehicle	SHC7806K	Third Party Vehicle. SCV8210G
Survey Location	NO 8 KAKI BUKIT AVE 4 #07-48 PREMIER @ KAKI BUKIT GATE 2	
Contact Person.	LINDA LIAO	
Contact No.	67139400/ 0	Fax No. 67139415
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ABWIN SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240611)



PRI Documents



Close



PRI Header Details

Claim No	D18004066MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & ABWIN SE
Workshop Name	ABWIN SERVICE PTE LTD (Contact Person : LINDA LIAO)	Survey Location & Contact Details	NO 8 KAKI BUKIT AVE 4 #07-48 PREMIER @ KAKI BUKI Mobile: 0 , Phone: 67139400 , Fax: 67139415 EmailId: LINDALIAO@ABWIN.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7806K	TP Vehicle No	SCV8210G
PRI Recieved Date	22-05-2018 03:13:09 PM	Surveyor Appointed Date	22-05-2018 02:54:51 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-05-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 25 May 2018 3:49 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004066MFSH/1
Attachments: PRELI ADVISED SCV 8210G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SCV 8210G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 22 May 2018 3:04 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004066MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 22 May 2018 2:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004066MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4498J
Vehicle Details	
Vehicle No.:	SCV8210G
Vehicle to be Exported:	No
Intended De-registration Date:	23 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	3ZRB777642
Chassis No.:	ZSU600077503
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$28,431.00
Original Registration Date:	07 Jun 2016
First Registration Date:	07 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$26,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2026
PARF Rebate Amount:	\$20,103.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$39,387.00
Total Rebate Amount:	\$59,490.00

The information contained herein is correct as at 23 May 2018

OK

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 21/05/2018
TP Vehicle No. : SHC-7806-K
To : **FIRST CAPITAL INSURANCE LTD**
Attn : **Motor Claim Department**

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : CHUNG THIAN LI (CHEN TIANLI)
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5080601079-01
Vehicle No. : SCV-8210-G
Make & Model : TOYOTA HARRIER ELEGANCE 2.0 A

Accident Date: 21/05/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR BUMPER	\$1,492.70	✓
1	REAR BUMPR BRACKET RH	\$71.60	X
1	REAR BUMPER BRACKET LH	\$71.60	X
1	REAR BUMPER RETAINER RH	\$98.60	X
1	REAR BUMPER RETAINER LH	\$98.60	✓
10	REAR BUMPER CLIPS	\$50.00	✓
1	REAR BUMER LOWER GARNISH	\$396.91	✓
1	REAR BUMPER REFLECTOR LH	\$57.80	X
1	REAR BUMPER REFLECTOR RH	\$57.80	X
1	TAILGATE	\$1,492.70	X
1	TAILGATE EMBLEM" HARRIER"	\$68.90	✓
1	TAILGATE LOGO	\$136.80	X
1	TAILGATE WEATHER	\$401.20	X
1	TAILGATE GLASS MOULDING	\$256.90	X
1	TAILGATE ABSORBER LH	\$289.60	X
1	TAILGATE ABSORBER RH	\$289.60	X
1	REAR END PANEL	\$791.60	X
1	REAR END PANEL TOP GARNISH	\$367.10	X
10	REAR END PANEL TOP GARNISH CLIPS	\$50.00	X
1	TAILLAMP RH	\$552.60	X
1	TAILLAMP LH	\$552.60	X
1	REAR REFLECTOR (RH)	\$486.90	X
1	REAR REFLECTOR LH	\$486.90	X
	Sub Total	\$8,619.01	
	Discount 25% on Parts	(\$2,154.75)	
		\$6,464.26	

Special Nett

1	REAR BUMPR REVERSE SENSOR	\$450.00	X
1	TAILGATE GLASS SEALANT	\$65.00	X

Date : 21/05/2018
 TP Vehicle No. : SHC-7806-K
 To : **FIRST CAPITAL INSURANCE LTD**
 Attn : **Motor Claim Department**

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Owner : CHUNG THIAN LI (CHEN TIANLI)
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5080601079-01
 Vehicle No. : SCV-8210-G
 Make & Model : TOYOTA HARRIER ELEGANCE 2.0 A

Accident Date: 21/05/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	REAR NUMBER PLATE & CASEING 11	\$65.00	X
	Sub Total	\$580.00	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00	500
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	600
TO TRANSFER ALL REAR TAILGATE, FITTING TO NEW 11	\$150.00	X
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	\$150.00	50
TO CHECK ALL NECESSARY WIRINGS	\$150.00	20
TO APPLY TUFF KOTE. 11	\$150.00	X
Sub Total	\$3,600.00	

Sub Total \$10,644.26
GST 7% \$745.10
Total \$11,389.36

2750.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009308/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7806K	Veh. Inspected	SCV 8210G	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004066MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600077503	Colour	SILVER	
Odometer	29020	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	BRIDGESTONE	7 mm	
L/H Front Tyre	225/65 R17	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/65 R17	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/65 R17	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/05/2018	Inspection Date	23/05/2018	
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCV 8210G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	1,492.70	1,492.70
1	REAR BUMPER BRACKET RH	NOT NECESSARY	71.60	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	71.60	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	98.60	-
1	REAR BUMPER RETAINER LH	BENT	98.60	98.60
10	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER GARNISH	DISTORTED	396.91	396.91
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	57.80	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	57.80	-
1	TAILGATE	TO REPAIR SEE LABOUR	1,492.70	-
1	TAILGATE EMBLEM "HARRIER"	NECESSARY	68.90	68.90
1	TAILGATE LOGO	NOT NECESSARY	136.80	-
1	TAILGATE WEATHER	NOT NECESSARY	401.20	-
1	TAILGATE GLASS MOULDING	NOT NECESSARY	256.90	-
1	TAILGATE ABSORBER LH	NOT NECESSARY	289.60	-
1	TAILGATE ABSORBER RH	NOT NECESSARY	289.60	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	791.60	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	367.10	-
10	REAR END PANEL TOP GARNISH CLIPS	NOT NECESSARY	50.00	-
1	TAILLAMP RH	NOT NECESSARY	552.60	-
1	TAILLAMP LH	NOT NECESSARY	552.60	-
1	REAR REFLECTOR (RH)	NOT NECESSARY	486.90	-
1	REAR REFLECTOR LH	NOT NECESSARY	486.90	-
	LESS 25% DISCOUNT		-2,154.75	-526.78
			6,464.26	1,580.33
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	450.00	-
1	TAILGATE GLASS SEALANT (SN)	NOT NECESSARY	65.00	-

Report Ref No. CS/FCI18009308/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE & CASING (SN)	NOT NECESSARY	65.00	-
			580.00	-
	LABOUR			
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL.		1,500.00	500.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,500.00	600.00
	TO TRANSFER ALL REAR TAILGATE, FITTING TO NEW.	NOT NECESSARY	150.00	-
	TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY.		150.00	50.00
	TO CHECK ALL NECESSARY WIRINGS.		150.00	20.00
	TO APPLY TUFF KOTE.	NOT NECESSARY	150.00	-
			3,600.00	1,170.00
GRAND TOTAL			10,644.26	2,750.33
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/FCI18009308/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.