

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18007343/T1QBS2-1
Date: 08/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: P27075458DMV
Claimant Vehicle No : SJM9626Z **Insured Vehicle No :** SGU9167A
Date of Loss: 17/04/2018 Nature of Claim: TP Claim No: 556082

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM9626Z**
Make & Model: SUBARU IMPREZA, 2.5 WRX 5D (M) Engine No: EJ25D373490
Reg. Date: 22/01/2009 (Man. Year: 2008) Chassis No: JF1GHEKD38G016142
Colour: Black Odometer: 138330 km
Engine Capacity: 2457 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50R17 Rear Tyre Size: 205/50R17
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,678.17	2,433.40	2,244.77	47.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,190.00	660.00	35.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,528.17	3,623.40	2,904.77	44.50
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	6,528.17	2,900.00	3,628.17	55.58
+ GST 7.00/7.00% (S\$)	456.97	203.00	253.97	55.58
Nett Amount (S\$)	6,985.14	3,103.00	3,882.14	55.58

INSPECTION

Date of Assignment: 20/04/2018
Date Inspected: 23/04/2018 Inspected At: Hoe Heng Private Limited- Gul Crescent (HQ)
50 Gul Crescent
Singapore 629543
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 Jun 2018)**Parts:** 143 SUBARU IMPREZA 2.5 WRX 5D (M) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SJM9626Z)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Repair	1,012.90 FL	*- FL
2	1		*TAIL GATE BADGE	Necessary	64.60 FL	*64.60 FL
3	1		*TAIL GATE IMPREZA EMBLEM	Necessary	61.50 FL	*61.50 FL
4	1		*TAIL GATE WRX EMBLEM	Necessary	68.50 FL	*68.50 FL
5	1		*TAIL GATE UPPER LOCK	Repair	200.30 FL	*- FL
6	1		*TAIL GATE WEATHERSTRIP	Damaged	168.30 FL	*168.30 FL
7	1		*TAIL GATE N/S REFLECTOR	Serviceable	265.30 FL	*- FL
8	1		*N/S TAIL LAMP	Chafed / Damaged	421.80 FL	*421.80 FL
9	2		*N/S TAIL LAMP CLIPS	Necessary	11.40 FL	*11.40 FL
10	1		*N/S TAIL LAMP TROUGH PANEL	Repair	138.20 FL	*- FL
11	1		*REAR END PANEL	Repair	491.60 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Warped	184.30 FL	*184.30 FL
13	1		*SET REAR END PANEL GARNISH CLIPS	Necessary	20.00 FL	*20.00 FL
14	1		*REAR BUMPER	Chafed / Deformed	758.60 FL	*758.60 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Badly Dented / Bent	232.30 FL	*232.30 FL
17	1		*REAR BUMPER TOW COVER	Damaged	68.50 FL	*68.50 FL
18	2		*REAR BUMPER SIDE BRACKETS	Damaged	131.20 FL	*131.20 FL
19	2		*REAR BUMPER SIDE RETAINERS	Damaged	137.00 FL	*137.00 FL
20	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
21	1		*REAR BUMPER LOWER DIFFUSER	Chafed / Distorted	500.00 FS	*450.00 FS
22	1		*EXHAUST TAIL PIPE	Dented	85.00 FS	*85.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,126.30	2,908.00
- List Item Discount on L Items 10.00/20.00% (S\$)	448.13	474.60
Total Parts (S\$)	4,678.17	2,433.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / RE-INSTALL REAR WINDSCREEN TO FACILITATE REPAIRS.	New	120.00	0.00
2	TO REMOVE / RE-INSTALL LUGGAGE COMPARTMENT GARNISH & TRIMS TO FACILITATE REPAIRS.	New	80.00	40.00
3	LABOUR CHARGES TO REPAIR, PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND REPLACE THE ABOVE-MENTIONED PARTS.	New	780.00	600.00
4	TO CHECK WIRING FUNCTIONS.	New	30.00	20.00
5	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.	New	780.00	500.00
6	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.	New	60.00	30.00
			Gross Labour Cost (\$\$)	1,850.00
				1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >