

ASS. REC. BY:

REF: CS/EGI18009424/ Urd3

n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

24/5/18 @ 9:09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGR 7787P

Insured:

XD1410M

at Workshop m/s:

Autolution Industrial

Tel:

9645 0079

of

19 ubi Road 4

Policy No:

Claim No:

DSM CV1800929/RA/p1

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lap

H.O.D. Endorsement:

Date/Time:

9:46am @ 24/5/18

Person Contacted:

Himzah

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

SGR 7787P - CG 1A1G13009788 / M16193Y

D.O.A. 23/5/2013

XD1410M - CG 1A1A14065665 / M16193C3

D.O.A. 25/05/14

19/6/18

Revert him email

REF: EGI

ASSIGNMENT

From:

Date: 31/05/2018

Veh No: SGR 7787P

Yr Regn: 207

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or (A)

To Inspect Vehicle No:

SGR 7787P
Autoplution (ubi)

Make:

Nissan Sunny

C.C. 1597

at Workshop m/s

Colour:

3/400

A/C: Insured / Std / NI / NA

of

Sp. Reading:

177256

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JN1CFAN1620106770

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

9am

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

185-65R15

R:

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

50k.

IDAC Accident Rpt:

Consistent? : Yes or No

BIA / PR Seen:

2

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

sup

14/2/2017

Vehicle: IN / OUT

Date:

Person Contacted:

(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

15/5/18

D.O.I.

3-15/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rd.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 43884 net 6116

Syr 9-11.

7/8/18 conf. with P. ref by 4930.68 with home L.
Ref: 42042.36, 297.

Date/Time: File Pass to?

1)

typist

Date/Time: File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

250

Report Format:

TP

Lump Sum / I.B.I. (\$)

4930.68

Add Fee:

☐ : Site Insp (\$

) Interview (\$

☐ : Tech. Invs (\$

) Weekend (\$

☐ : Weekend (\$

) Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18009424/Urd3		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 24-05-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 1410M	Veh. Inspected	SGR 7787P	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1800929/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	24/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/05/2018	Inspection Date		
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMCV1800929/RH/PL

Our Ref: CS/EG118009424/Urd3

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SGR 7787P

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31/05/2018 at the premises of M/s AUTOLUTION INDUSTRIAL PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 4,920.68
Revised Estimate Amount	: S\$ 1,037.24
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages
at the front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

MARCUS
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 24 May 2018 9:09 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XD1410M / TP : SGR7787P/LKK / DOA : 15/05/2018 (DSMCV1800929)
Attachments: XD1410M - SAS.pdf; SGR7787P - SAS.pdf; SGR7787P - ESTIMATE.pdf; SGR7787P - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **AUTOLUTION INDUSTRIAL PTE LTD**,

ADDRESS : 19 UBI ROAD 4
SINGAPORE 408623

PERSON TO CONTACT : HAMZAH SA'AD @ 6703 8690 / 9645 0079

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 23.05.2018
Our Reference: DSMCV1800929/RH/pl
Your Reference: SGR 7787P

Sent via Fax

or

Email: hamzah_saad@tanchong.com

To: AUTOLUTION INDUSTRIAL PTE. LTD.

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SGR 7787P
Insured's Vehicle: XD 1410M
Date Of Accident: 15.05.2018

We acknowledge receipt of your request for PRS on: 22.05.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto Consultants
Pte. Ltd.

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us today.
☒	Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE ROHAINI

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

*Sharing
&
Serving***COME VOLUNTEER WITH US!**

If you are 40 years old and above and are able to spend half a day every month to contribute your talents and skills in many meaningful ways, we want you

Nissan Sunny

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼

Home » Used Cars » ABWIN (1994) Pte Ltd » Nissan Sunny 1.6A EX (COE till 05/2026)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Nissan Sunny 1.6A EX (COE till 05/2026)

Overview

Financial

Accessories

Similar

Research

Photos

Map

ABWIN 諭輝

YOUR FIRST CHOICE AUTOMOTIVE SERVICE

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$44,800	
Depreciation	\$5,640 /yr	?
Reg Date	08-May-2006 (7yrs 11mths 6days COE left)	
Manufactured	2006	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,597 cc	
Road Tax	\$890 /yr	?
Power	81.0 kW (108 bhp) View specs of the Nissan Sunny (2005-2010)	
Curb Weight	1,110 kg	?
Features	1.6L DOHC CVTC Engine 4 Speed Auto Transmission, SRS, Airbags.	
Accessories	Factory Fitted Interior.	
Description	\$0 Down Payment! 100% In House Loan Available! Low Depreciation! Nice Paint. Hurry Call For Viewing!	
COE	\$45,578	?
OMV	\$12,089	?
ARF	\$13,298	?



Seller Infor

Company

Car Tyres

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9315H
Vehicle Details	
Vehicle No.:	SGR7787P
Vehicle to be Exported:	No
Intended De-registration Date:	31 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	SUNNY 1.6EXA
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	QG16421376
Chassis No.:	JN1CFAN16Z0106770
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,037.00
Original Registration Date:	15 Feb 2007
First Registration Date:	15 Feb 2007
Transfer Count:	0
Actual ARF Paid:	\$12,141.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Feb 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$50,394.00
COE Rebate Amount:	\$43,884.00
Total Rebate Amount:	\$43,884.00

The information contained herein is correct as at 31 May 2018

OK

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0305/18
DATE : 15-MAY-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038995)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : ONG SOON LEONG
ADDRESS : BLK 212 SERANGDON AVE 4
#02-56
S(550212)
TELEPHONE NO : 91788021/62865411

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SGR7787P
MODEL CODE : CDGARSAN16EPA2-L--
MODEL/YEAR : SUNNY 1.6EX A/T S0407
ENGINE NO : OG16421376
CHASSIS NO : JN1CFAN16Z0106770
MILEAGE : 176410 KM
DATE IN : 15/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 15/05/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorized
2nd Mercus
31/5/18
S. Luy.
When photo before repair.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGR7707P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
		390		
1	ZZ/001	LABOUR CHARGES TO REPAIR RADIATOR SUPPORT, BOTH FRONT FENDER, RENEW BONNET AND FRONT BUMPER.	900.00	800
		250		
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1200.00	1000
3	ZZ/003	RENEW DAMAGED HEADLAMP AND FOCUS.	48.00	✓
4	ZZ/004	RENEW A/C COND. CONDENSER, FAN MOTOR, VACUUM AND REFILL FREON GAS.	120.00	✓
5	ZZ/005	SUPPLY FRONT LICENCE PLATE		
		TOTAL LABOUR CHARGES	2268.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGR7787P

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN		me	50.00	10
2	FRT LICENCE PLATE	FLP		34	60.00	—
3	A/C COND CONDENSER	92110-8N000		me	517.90	—
4	RADIATOR FAN MOTOR	21481-5M006		me	615.50	2
5	RADIATOR ASSY	21460-4M17		me	687.40	X
6	HEADLAMP LH	26060-6N625	820	—	486.80	—
7	HEADLAMP RH	26010-6N625	me	—	486.80	—
8	BONNET LOCK	65601-8M100	7m	—	62.20	—
9	BONNET	F5100-4M5MM	me	X	893.90	—
10	CLIP RAD GRILLE @ \$3.20 EACH	11296-AG000		me	19.20	—
11	EMBLEM RAD GRILLE	62890-8N700	me	—	50.70	—
12	GRILLE-RADIATOR	62310-8N700	me	—	223.00	—
13	FRT BUMPER STAY LH	62211-6N600	4	—	86.60	—
14	FRT BUMPER STAY RH	62210-6N600	11	X	86.60	—
15	FRT BUMPER RETAINER	62290-6N600	4	—	162.70	—
16	FRT BUMPER REINFORCEMENT	62032-6N000	me	X	288.20	—
17	FRONT BUMPER MOULDING	62072-6N600	me	—	175.20	—
18	FRT BUMPER SIDE BRKT LH	62223-6N600	4	—	23.00	—
19	FRT BUMPER SIDE BRKT RH	62222-6N600	4	—	23.00	—
20	CLIP FRONT BUMPER @ \$1.20 EACH	01553-10501	me	—	7.20	—
21	FRONT BUMPER FASCIA	62022-6N625	me	—	387.90	—

SUB TOTAL	3443.80	0.00	1950.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)	688.76	0.00	0.00
GRAND TOTAL	2755.04	0.00	1950.00
OVERALL TOTAL	4705.04		

AUTOLUTION INDUSTRIAL PTE. LTD.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGR7787P

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
------------------------	--------------	------	------	----------------

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGR7787P

TOTAL LABOUR CHARGES	2268.00
TOTAL SPARE PARTS CHARGES	4705.04

GRAND TOTAL	6973.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Marcus

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0305/18
DATE : 15-MAY-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : ONG SOON LEONG
ADDRESS : BLK 212 SERANGOON AVE 4
#02-56
S(550212)
TELEPHONE NO : 91788021/62865411

5 days

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SGR7787P
MODEL CODE : CDGARSAN16EPA2-L--
MODEL/YEAR : SUNNY 1.6EX A/T S0407
ENGINE NO : QG16A21376
CHASSIS NO : JN1CFAN16Z0106770
MILEAGE : 178249 KM
DATE IN : 15/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 15/05/2018

- 96450079

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGR7787P

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR RADIATOR SUPPORT, BOTH FRONT FENDER, BONNET AND RENEW FRONT BUMPER.	900.00	800.00
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1200.00	1000.00
3 ZZ/003	RENEW DAMAGED HEADLAMP AND FOCUS.	48.00	48.00
4 ZZ/004	RENEW A/COND CONDENSER, FAN MOTOR, VACUUM AND REFILL FREON GAS.	120.00	120.00
5 ZZ/005	SUPPLY FRONT LICENCE PLATE.		
	TOTAL LABOUR CHARGES	2268.00	1968.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGR7787P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	FRT BUMPER STAY RH	62210-6N600	86.60		X
2	BONNET	F5100-4M5MM	893.90		X
3	A/COND CONDENSER	92110-8N000			517.90 OK
4	RADIATOR FAN MOTOR	21481-5M006			615.50 OK
5	RADIATOR ASSY	21460-4M417			687.40 X
6	HEADLAMP LH	26060-6N625	486.80		OK
7	HEADLAMP RH	26010-6N625	486.80		OK
8	BONNET LOCK	65601-8M100	62.20		OK
9	CLIP RAD GRILLE @ \$3.20 EACH	11296-AG000			19.20 OK
10	EMBLEM RAD GRILLE	62890-8N700	50.70		OK
11	GRILLE-RADIATOR	62310-8N700	223.00		OK
12	FRT BUMPER STAY LH	62211-6N600	86.60		OK
13	FRT BUMPER REINFORCEMENT	62032-6N000	288.20		X
14	FRONT BUMPER MOULDING	62072-6N600	175.20		OK
15	FRT BUMPER SIDE BRKT LH	62223-6N600	23.00		OK
16	FRT BUMPER SIDE BRKT RH	62222-6N600	23.00		OK
17	CLIP FRONT BUMPER @ \$1.20 EACH	01553-10501	7.20		OK
18	FRONT BUMPER FASCIA	62022-6N625	387.90		OK
19	SUNDRIES	NPN			10.00 OK
20	FRT LICENCE PLATE	FLP			60.00 OK
21	FRT BUMPER RETAINER	62290-6N600	162.70		OK
SUB TOTAL			2175.10	0.00	1222.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			435.02	0.00	0.00
GRAND TOTAL			1740.08	0.00	1222.60
OVERALL TOTAL			2962.68		

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGR7787P

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS

LEGEND: REMARKS(OK) = APPROVED. REMARKS(X) = NOT APPROVED



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18009424/Urd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 14-08-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 1410M	Veh. Inspected	SGR 7787P	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1800929/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	24/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SUNNY (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JN1CFAN16Z0106770	Colour	BLACK	
Odometer	177256	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/05/2018	Inspection Date	31/05/2018	
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 7787P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP LH (N)	BROKEN	486.80	486.80
1	HEADLAMP RH (N)	CRACKED	486.80	486.80
1	BONNET LOCK (N)	TWISTED	62.20	62.20
1	BONNET (N)	TO REPAIR SEE LABOUR	893.90	-
1	EMBLEM RAD GRILLE (N)	NECESSARY	50.70	50.70
1	GRILLE-RADIATOR (N)	CRACKED	223.00	223.00
1	FRT BUMPER STAY LH (N)	BENT	86.60	86.60
1	FRT BUMPER STAY RH (N)	NOT NECESSARY	86.60	-
1	FRT BUMPER RETAINER (N)	BENT	162.70	162.70
1	FRT BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	288.20	-
1	FRONT BUMPER MOULDING (N)	NECESSARY	175.20	175.20
1	FRT BUMPER SIDE BRKT LH (N)	BENT	23.00	23.00
1	FRT BUMPER SIDE BRKT RH (N)	BENT	23.00	23.00
6	CLIP FRONT BUMPER @\$1.20 (N)	NECESSARY	7.20	7.20
1	FRONT BUMPER FASCIA (N)	TORN	387.90	387.90
	LESS 20% DISCOUNT		-688.76	-435.02
			2,755.04	1,740.08
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	10.00
1	FRT LICENCE PLATE (SN)	BENT	60.00	60.00
1	A/COND CONDENSER (SN)	PUNCTURE	517.90	517.90
1	RADIATOR FAN MOTOR (SN)	CRACKED	615.50	615.50
1	RADIATOR ASSY (SN)	SERVICEABLE	687.40	-
6	CLIP RAD GRILLE @\$3.20 (SN)	NECESSARY	19.20	19.20
			1,950.00	1,222.60
<u>LABOUR</u>				
	LABOUR CHARGES TO REPAIR RADIATOR SUPPORT,BOTH FRONT FENDER.RENEW BONNET AND FRONT BUMPER.INCLUSIVE OF THE REPAIR OF BONNET AND FRT BUMPER REINFORCEMENT.		900.00	800.00

Report Ref No. CS/EGI18009424/Urd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHARGES TO SPRAY PAINTING SAME.		1,200.00	1,000.00
	RENEW DAMAGED HEADLAMP AND FOCUS.		48.00	48.00
	RENEW A/COND CONDENSER,FAN MOTOR,VACUUM AND REFILL FREON GAS.		120.00	120.00
			2,268.00	1,968.00
	GRAND TOTAL		6,973.04	4,930.68
RECOMMENDED COST OF REPAIRS				4,930.68

Report Ref No. CS/EGI18009424/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.