Khek Joo Motor Workshop

Blk 9004 Tampines St 93, #01-94, Singapore 528838 Tel/Fax: 67854258 Mobile: 96766658

Date: 22 May 2018

The Motor Claims Department India International Insurance Pte Ltd 64 Cecil Street #04/#05 IOB Building Singapore 049711

Tel: 63476100

Fax: 62244174/62257743

REPAIR QUOTATION FOR SKB1343M MAZDA 3

	Qty	(\$) Disc	ount	(\$)	
Rear bumper	1	974.80	20%	779.84	dert
Rear bumper reflector LH	1	54.90	20%	43.92	X NO
Rear bumper side retainer	2	68.60	20%	54.88	?
Rear bumper retaining clip	10	45.00	20%	36.00	?
		Total Cost of parts		878.64	
LABOUR					
To check wiring.				30.00	× nn
To reinstall reverse sensors and check sensing distance.			120.00	×	
Laboour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas.			400:00	200	
Spray painting charges to putty and spray all affected parts/areas.			300.00	200	
		Total Cost of la	bour	850.00	
Yours faithfully		Total Repair Co	st _	1,728.64	
· · · · · · · · · · · · · · · · · · ·	NAZ LKK				
Wee Kiang	2 days				
		2 days 98804220			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: