

Khek Joo Motor Workshop

Blk 9004 Tampines St 93, #01-94, Singapore 528838

Tel/Fax: 67854258 Mobile: 96766658

Date: 22 May 2018

The Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Tel: 63476100 Fax: 62244174/62257743

REPAIR QUOTATION FOR SKB1343M MAZDA 3

	Qty	(\$)	Discount	(\$)
Rear bumper	1	974.80	20%	779.84 <i>dent</i>
Rear bumper reflector LH	1	54.90	20%	43.92 <i>x nn</i>
Rear bumper side retainer	2	68.60	20%	54.88 <i>?</i>
Rear bumper retaining clip	10	45.00	20%	36.00 <i>?</i>
Total Cost of parts				878.64

LABOUR

To check wiring.	30.00 <i>x nn</i>
To reinstall reverse sensors and check sensing distance.	120.00 <i>x</i>
Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas.	400.00 <i>200</i>
Spray painting charges to putty and spray all affected parts/areas.	300.00 <i>200</i>

Total Cost of labour 850.00

Total Repair Cost 1,728.64

Yours faithfully

Wee Kiang

NA2 LKK

2 days

98804220

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: