

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III18009476/KPS3N2**Date:** 19/08/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015		
Claimant				
Vehicle No : SHC5087G	Insured Vehicle No :	SHA3711L		
Date of Loss: 22/05/2018	Nature of Claim: TP	Claim No:	MCT18050592	

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5087G			
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Engine No:	M9R8839C000648	
Reg. Date:	27/12/2013 (Man. Year: 2013)	Chassis No:	VF1ABL15AUC275903	
Colour:	Metallic White/Red	Odometer:	541919 km	
Engine Capacity:	1995 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Primewell 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Primewell 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	37,376.45	28,636.20	8,740.25	23.38	
Miscellaneous Items	0.00	0.00	0.00		
Labour	12,920.00	4,450.00	8,470.00	65.56	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	50,296.45	33,086.20	17,210.25	34.22	
Approved Total (Overridden) (S\$)		19,600.00			
	(S\$)	50,296.45	19,600.00	30,696.45	61.03
+ GST 7.00/7.00% (S\$)	3,520.75	1,372.00	2,148.75	61.03	
Nett Amount (S\$)	53,817.20	20,972.00	32,845.20	61.03	
+ Loss of Use (20.0 x S\$40.00/day) (S\$)		800.00			
+ Car Rental (20.0 x S\$99.32/day) (S\$)		1,986.40			
	Nett Liability (S\$)	23,758.40			
	Global Sum Settlement (S\$)	22,000.00			

INSPECTION

Date of Assignment:	23/05/2018	
Date Inspected:	23/05/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	18.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Book Value: \$57,200.00(est) less LTA Rebate: \$37,559.00(est) = Nett Value :\$19,641.00(est)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2019)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5087G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Cracked	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Distorted	135.97 FL	*135.97 FL
5	1		*BUMPER RETAINER RH REAR	Distorted	44.99 FL	*44.99 FL
6	1		*BUMPER REFLECTOR RH	Broken	43.61 FL	*43.61 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Distorted	135.97 FL	*135.97 FL
8	1		*BUMPER RETAINER LH REAR	Distorted	44.99 FL	*44.99 FL
9	1		*BUMPER REFLECTOR LH	Cracked	43.61 FL	*43.61 FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	225.95 FL	*225.95 FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Cut	323.05 FL	*323.05 FL
16	1		*BOOT REFLECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
17	1		*BOOT REFLECTOR LAMP RH	Cracked	493.35 FL	*493.35 FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Dented	202.67 FL	*202.67 FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
31	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
32	1		*FENDER PANEL REAR LH	Buckled	3,299.13 FL	*3,299.13 FL
33	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1		*FENDER PANEL INNER TRIM REAR RH	Deformed	671.45 FL	*671.45 FL
35	1		*FENDER PANEL REAR RH	Buckled	3,299.13 FL	*3,299.13 FL
36	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
37	1		*TAILLAMP RH	Cracked	552.55 FL	*552.55 FL
38	1		*TAILLAMP PANEL RH	Bent	986.70 FL	*986.70 FL
39	1		*TAILLAMP LH	Cracked	552.55 FL	*552.55 FL
40	1		*TAILLAMP PANEL LH	Bent	986.70 FL	*986.70 FL
41	1		*OUTER PANEL REAR (EMD PANEL)	Bent	1,471.77 FL	*1,471.77 FL
42	1		*OUTER PANEL REAR (EMD PANEL)TRIM	Cracked	404.56 FL	*404.56 FL
43	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Bent / Buckled	2,189.88 FL	*2,189.88 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
45	1		*EXHAUST REAR	Bent	7,489.05 FL	*7,489.05 FL
46	1		*EXHAUST CAP REAR	Missing	230.49 FL	*230.49 FL
47	1		*FUEL FLAP L70Y	Serviceable	343.57 FL	*- FL
48	1		*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
49	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
50	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
51	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
52	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
53	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
54	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
55	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
56	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
57	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
58	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
59	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
60	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
61	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
62	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
63	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
64	1		*FENDER INNER TRIM CLIP LH	Necessary	28.00 FS	*28.00 FS
65	1		*FENDER INNER TRIM CLIP LH	Necessary	28.00 FS	*28.00 FS
66	1		*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
67	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
68	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
69	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
70	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
71	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
72	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	41,282.17	31,700.11
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,905.72	3,063.91
Total Parts (\$\$)	37,376.45	28,636.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	1,540.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,200.00	2,200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	150.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE }	New	170.00	80.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE }	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	100.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	80.00
11	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	120.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
14	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
			Gross Labour Cost (\$)	4,450.00
			12,920.00	12,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >