

Surveyor

REF: CS1/SPF18009485/K1dbs2

Special Instruction: US: # 2000.00

From (Person): Abdul Rahman of SPF Date/Time: 24052018

ASSIGNMENT (Object)

Third Parties: Claimant: Km Auto Surveyor: Premier Workshop: Premier

OD/TP Re-inspection / (Evaluation) To Inspect Vehicle No: SHB 8592A Insured: TP 11216 at Workshop m/s Premier Tel: 6544 6671 of 23 Changi South Ave 2 # 03-02 Policy No: Claim No: AEMD / 1105 / 009 / 2018 / 042B (PD) Sum Insured: Excess: Make of Veh: (Client's Record) D.O.A. 10-03-2018

Do Not Finalize H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 3 days) Date/Time: 25/5/18 Submit Final Fig 1600, 3 days (Red \$ 400, 1.20%; Original 3 days)

Table with 2 columns: Date/Time, Action/Instruction. Entry: SHB 8592A - CS/EGL16013201/Highsol TP 11216 - X. Date: 12072018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 28 MAY 2018

Para(3) : Nett Value

Table with 4 columns: Market Value, Salvage Value, Nett Value, Inspected/Evaluated by, Fee Charged (Basic & Add, Transport, Photos, Others, Total), Date.

- 1) Date/Time 28/5/18 File Pass to [Signature] 2) Date/Time File Return to 3) Date/Time File Pass to 4) Date/Time File Return to 5) Date/Time File Pass to 6) Date/Time File Return to



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SHB8592A

Our Ref : AEMD/105/009/2018/042B(PD)

Date : 24 May 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax Only: 62564315

Dear Sir/Madam,

ACCIDENT ON 10 MARCH 2018 INVOLVING GOVT VEH TP1121G AND OTHER VEH SHB8592A

We refer to the above matter.

- 2 Please arrange for a Paper Survey of vehicle no. SHB8592A at M/s Premier Taxis Pte Ltd of 23 Changi South Ave 2 #03-02, Singapore 486443.
- 3 For appointment kindly contact Tel: 64488208.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

cc : M/s Vision Law LLC (Ref: AM1-yiv-Ins-P36-105525-18-er
Via fax: 65356802 only

A FORCE FOR THE NATION



**AUTOMOBILE
INSPECTION REPORT**

NO. 8/3/TP006/1
ACC DATE 10-Mar-18

To: PREMIER AUTOMOTIVE SERVICES PTE LTD
23 CHANGI SOUTH AVE 2 #01-02 S'PORE 486443

General Condition: Poor/Fair/Good/Excellent

Reg. No.	SHB 8592 A	Make/Model	KIA OPTIMA 1.7 TAXI AUTO	Year	2013
Engine No.	D4FDDH308143	Chassis No.	KNAGM414ME5447103	Colour	Metallic Silver
Condition of Tyres			Speedometer Reading - Km		
Front N/S	MAXXIS 205/65R16	worn	10 %	Front O/S	MAXXIS 205/65R16
Rear N/S	ACHILLES 205/65R16	worn	10 %	Rear O/S	ACHILLES 205/65R16
Requested By		YOURSELF		On 12-Mar-18	
The Above Vehicle					

Was Inspected At (12-Mar-18) PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVE 2 #01-02 S'PORE 486443
And The Undermentioned Damage Was Noted:-

Rear bumper o/s portion grazed, cut, dented and bent, o/s rear door lower portion grazed, dented and bent, inner sill bent, o/s body sill panel dented, garnish grazed, sliced, dented and deformed.

Photographs:-	30 Copies	were taken at time of inspection and are attached.
The Repairers estimate was for a total amount of	\$	3,071.00
After adjustment the estimate was revised and agreed at	\$	2,493.60

SPECIAL REMARKS

The Repairers were **NOT AUTHORISED** to proceed with the repairs.
Survey was carried out without prejudice.
The above were due to impact to the o/s portion of the taxi.

Alternatively, we recommend that repairs be carried out on a Lump Sum basis instead, @\$2,000/- Nett.

MICHAEL EE Dip. A. Eng. AMIRTE, AMSAE, AMSCE, AMIM, MSAAA

Date 15-Mar-18



KM AUTO ASSESSORS PTE. LTD.
Insurance Loss Assessors / Adjusters

47 Jalan Pemimpin
#02-07 Halcyon 2
Singapore 577200

T 6448 8208
F 6442 9690
E kmautoassessors@gmail.com
Regn. No. 2009073402

APPENDIX 'A'
TO REPORT NO: 8/3/TP006/I
REGN. NO: SHB 8592 A

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
1 pce rear bumper fascia	696.00	grazed, cut, dented, deformed	696.00
1 pce o/s body sill panel garnish	278.00	grazed, sliced, dented, deformed	278.00
		less 10%	974.00 97.40
	974.00		876.60
S.NETT			
1 set rear bumper clips	35.00	necessary	35.00
1 set o/s body sill panel garnish clips	42.00	necessary	42.00
1 set o/s doors' "SILVERCAB" stickers	100.00	necessary	100.00
Remove necessary o/s rear door's fittings to enable to repair door, check and refit same. Remove necessary interior upholsterys and fittings to enable necessary repairs, check and refit same.	120.00		80.00 50
Remove damaged parts, jack out, straighten up damaged body panels, repair body parts and fittings, whichever possible and necessary, replace necessary damaged parts, refit and align whichever parts necessary.	600.00		400.00 ✓
Paint replacement parts and repaint damaged sections in and outside.	1,100.00		900.00 540
Rustproof damaged section.	100.00		60.00 X
TOTAL	3,071.00		2,493.60
<i>1/5 \$1600/3/2</i>			
Total Amount Revised		\$	2,493.60
Lump Sum Repairs Amount		\$	2,000.00
It is estimated that the repairs will take		THREE	days to complete.



Your Ref: AEMD/105/009/2018/042B(PD)

Date: 01st June 2018

Our Ref: CS1/SPF18009485/K1qbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SHB 8592A INSURED VEHICLE: TP 1121G ACCIDENT DATE: 10/03/2018**

We thank you for your instruction on 24/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHB 8592A from M/s KM Auto Assessors Pte. Ltd.
- b) Colour damaged vehicle photographs of SHB 8592A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHB 8592A
Make & Model	: Kia Optima 1.7 Taxi Auto
Year of Registration	: 2013
Chassis Number	: KNAGM414ME5447103

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8592A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER FASCIA	GRAZED / CUT / DENTED / DEFORMED	696.00	696.00
1	O/S BODY SILL PANEL GARNISH	GRAZED / SLICED / DENTED / DEFORMED	278.00	278.00
	LESS 10% DISCOUNT		-	-97.40
			974.00	876.60
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
1	SET O/S BODY SILL PANEL GARNISH CLIPS (SN)	NECESSARY	42.00	42.00
1	SET O/S DOORS' "SILVERCAB" STICKERS (SN)	NECESSARY	100.00	100.00
			177.00	177.00
<u>LABOUR</u>				
	REMOVE NECESSARY O/S REAR DOOR'S FITTINGS TO ENABLE TO REPAIR DOOR, CHECK AND REFIT SAME. REMOVE NECESSARY INTERIOR UPHOLSTERY AND FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME.		120.00	50.00
	REMOVE DAMAGED PARTS, JACK OUT, STRAIGHTEN UP DAMAGED BODY PANELS, REPAIR BODY PARTS AND FITTINGS, WHICHEVER POSSIBLE AND NECESSARY, REPLACE NECESSARY DAMAGED PARTS, REFIT AND ALIGN WHICHEVER PARTS NECESSARY.		600.00	400.00
	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS IN AND OUTSIDE.		1,100.00	540.00
	RUSTPROOF DAMAGED SECTION.	NOT NECESSARY	100.00	-
			-	-
			-	-
			1,920.00	990.00
GRAND TOTAL			3,071.00	2,043.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS1/SPF18009485/K1qbs2



Report Ref No. CS1/SPF18009485/K1qbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'K.K. LAU'.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.