

21627901

ASS. REC. BY:

REF: CS3/AIG 18002898/Sqb-47

Special Instructions:

Surveyor

Substation

ASSIGNMENT (Office)

From (Person):

Norsiah

of

AIG

Date/Time:

24/5/2018

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBC 5146R

Insured:

SLS 7104X

at Workshop m/s

Brothers Motor

Tel:

9643 2546

of Bk 1016, Yishun Ind. Prk A #01-218

Policy No:

Claim No:

08554670755G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/01/2018

CA / REV / REP. / REV 24 HRS

wp

14/02/2018

H.O.D. Endorsement:

Date/Time:

1:06pm 13/2/18

Person Contacted:

Mr. Teh

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FBC 5146R - CS/INC/30205-20/Hlgm 3k3
	SLS 7104X - X
	After repair: 12/3/2018
	US \$4350, 4 days (Net \$850, 16%)

URGENT

RECEIVED 20 JUN 2018

150.00

AIG

## ASSIGNMENT

From \_\_\_\_\_ Date 14/02/18

Estimated Cost \_\_\_\_\_

OD ☒ WS ☐ TP RES ☐ GO RES ☐ EVA ☐ INV ☐ MVTo inspect Vehicle No FBC 5146Rat Workshop No Brothers Motorat B1K1016, Yishun Ind. Prk A #01-218

Insured \_\_\_\_\_

Policy No \_\_\_\_\_

Claims No \_\_\_\_\_

Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_


(Client's Record)

Make of Veh \_\_\_\_\_

Mr. Tat @ 96432540

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA PR Seen \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS Wp

Date \_\_\_\_\_ Person Contacted \_\_\_\_\_

Vehicle IN / OUT

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

at No FBC 5146RPage 16/4/2008Type Motor Car Bus Van Lorry Taxi Prime Mover

Truck Trailer

Make Yamaha X-1KCC 135Colour Red / White

AC Insured Std N: NA

Sp Reading 405537

T-Part Insured Std N: NA

Eng No \_\_\_\_\_

Ch No 453201593Gen Cond Good (2) Poor BurntSteering In (2) Jammed / Leaked / Burnt orBrake In (2) Jammed / Leaked / Burnt orMod NO S/Rim / STD A/Rim orTyre Size = 70/90-17

R. \_\_\_\_\_

BS / DUN / EXNOVA / BY / FS / LIZA / MID / OHTSU / PIR / SUMI

TOYO / YOKO or

Dunlop

Front

Rear

R.Ba. 6 --- R.Ba. 6 ---L.Ba. 6 --- L.Ba. 6 ---D.O.A. 27/1/15D.O. 14/2/18Surveyed at Brothers MotorDes. of Damages Fr Rear OS CS UIC / Roofed or

The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 18 APR 2018

Date/Time File Pass to:



: Prel. Report

Days Of Repair 4

Date/Time File Return to:



: Final Report

Resurvey No. of Trip \_\_\_\_\_

Survey Fee

180

Report Format:

DAR

Lum Sum: LB 11/3

Add Fee:



Site Fee: \$



Travel Fee: \$



Tool Fee: \$



App Fee: \$

Transport Fee

Lump Sum

Total Fee

20

200

**Catherine Chong (LKK Auto)**

---

**From:** Md Noor, Norsiah <Norsiah.MdNoor@aig.com>  
**Sent:** Thursday, 24 May, 2018 3:14 PM  
**To:** assignments  
**Subject:** Our Claim No: 0855467075SG-Paper Resurvey  
**Attachments:** 0855467075SG\_Survey report.pdf  
  
**Importance:** High

Hi Team,

Please assist to conduct paper resurvey urgently.

Thank you

Norsiah Md Noor  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419-1606 | Fax +(65) 6835-7417  
[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**  
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**  
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# FOR MOTORCYCLE

## Motorcycle

Table No. **FBC 5146 R**

NAC	INC	Item	CUR	AC	Qty	NAC	INC	Item	CUR	AC	Qty
1001	991826	Front Fender Plate				1001	991874	Radiator	DM	✓	
1002	991865	Front Tire				1002	992238	Radiator Covering			
1003	995095	Front Rim				1003	994146	Seat Assy			
1004	994072	Front Tire Pump/Spoke				1004	990815	Engine Chain Bar			
1005	991771	Front Fender Wheel Guard	CUT	✓		1005	990028	Engine Guard	CUT	✓	
1006	991283	Front Brake Drum				1006	990219	Battery			
1007	991285	Front Brake Caliper				1007	990224	Battery Cover			
1008	991287	Front Fork Inner Tube				1008	990223	Battery Bracket			
1009	991289	Front Fork Outer Tube				1009	991144	Foot Brake	BR	✓	
1010	991167	Front Fork Bracket				1010	991154	Front Foot Rest	DM	✓	
1011	991162	Front Fork Oil Seal				1011	991779	Front Foot Rest Bracket	DD	✓	
1012	991174	Front Fork Garnish				1012	994269	Side Stand	DD	✓	
1013	992336	Front Headlamp Rim				1013	992549	Mud Stand			
1014	992338	Front Headlamp	DM	✓		1014	990615	Clutch Engine Cover			
1015	992337	Front Headlamp Bracket	SR	✓		1015	992478	Kick Starter Rubber	CUT	✓	
1016	992345	Front Headlamp Fanning				1016	992477	Kick Starter Lever			
1017	992130	Front Windshield	SCR	✓		1017	991145	Foot Gear Shifter			
1018	992134	Front Wing Mirror	BR	✓		1018	993500	Rear Foot Rest	DM	✓	
1019	995245	Front LH Signal Lamp	SCR	✓		1019	993501	Rear Foot Rest Bracket			
1020	995246	Front RH Signal Lamp				1020	992581	Exhaust Muffler Heat Shield	CUT	✓	
1021	992536	Meter Clamp	BR	✓		1021	991058	Exhaust Muffler Assy			
1022	992553	Meter Assy				1022	993719	Rear LH Shock Absorber			
1023	991019	RRP Bracket	DD	✓		1023	993720	Rear RH Shock Absorber			
1024	991020	RRP Unit	CUT	✓		1024	995065	Rear Tyre			
1025	992446	Ignition Switch				1025	991200	Rear Rim			
1026	992442	Ignition Key Assy				1026	994872	Rear Tyre Rim Spoke			
1027	990706	Cowling Stay				1027	993474	Rear Fender Wheel Guard			
1028	994470	Steering Stem				1028	993443	Rear Fender Mudflap			
1029	994427	Steering Cone				1029	992940	Rear Brake Disc			
1030	992299	Handle Bar				1030	992936	Rear Brake Caliper			
1031	992312	Handle Bar Switch				1031	995236	Rear Spocket			
1032	992310	Handle Bar Grip	CUT	✓		1032	990585	Chain			
1033	995384	Handle Bar Balancer LH	MS	✓		1033	990580	Chain Guard			
1034	992300	Handle Bar Balancer RH	MS	✓		1034	991530	Swing Arm			
1035	992179	Fuel Tank				1035	993819	Rear Sub frame			
1036	990838	Brake Reservoir				1036	995245	Rear LH Signal Lamp			
1037	990621	Clutch Lever	CUT	✓		1037	995246	Rear RH Signal Lamp			
1038	992293	Hand Brake Lever	CUT	✓		1038	995251	Rear Taillamp			
1039	991119	Side Fanning	CUT	✓		1039	991626	Rear Number Plate			
1040	994220	Side Fanning Top Garnish				1040	994192	Side Box			
1041	994219	Side Fanning Inner Garnish				1041	992927	<del>Rear Box</del> Front Box	BR	✓	
1042	991118	Fanning Shield	BR	✓		1042	992928	<del>Rear Box</del> Front Box	DD	✓	
1043	992047	Front Top Fanning Inner Garnish				1043	991328	Emblem			
1044	994173	Fanning Top Garnish				1044	990247	Sticker			
1045	990538	Center Fanning	BR	✓							
1046	991328	Rear Fanning	CUT	✓							
1047	991121	Fanning Ropper									
1048	991112	Fanning <del>to</del> Rear Guard	DM	✓							

\* 4 days

File of Items:

Accessories

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3884Z

## Vehicle Details

Vehicle No.: FBC5146R

Vehicle to be Exported: No

Intended De-registration Date: 19 Feb 2018

Vehicle Make: YAMAHA

Vehicle Model: X-1R

Primary Colour: Red

Manufacturing Year: 2007

Engine No.: 4S3201593

Chassis No.: 4S3201593

Maximum Power Output: -

Open Market Value: \$1,952.00

Original Registration Date: 16 Apr 2008

First Registration Date: 16 Apr 2008

Transfer Count: 4

Actual ARF Paid: \$293.00

## Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

## Intended COE Rebate Details

COE Expiry Date:	31 Jan 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$5,910.00
COE Rebate Amount:	\$5,879.00
<b>Total Rebate Amount:</b>	<b>\$5,879.00</b>

The information contained herein is correct as at 19 Feb 2018

OK

MSI11802067# / STA INSPECTION PTE LTD - Sin Ming  
 ENTRY DATE & TIME: 10/02/2018 15:59  
 SUBMITTED BY: Wang Lip Yong

Your NCD will be affected due to late reporting  
 Actual e-Filing Submission Date & Time: 10/02/2018 16:07

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	10/02/2018 15:59
Date Of Accident	29/01/2018 16:15
Exact Location Of Accident	ALONG WOODLANDS RING ROAD JUNCTION TO DR 42
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Name Of Registered Owner	MR MUHAMMAD NUR ARIFF BIN ZAILAN
NRIC No	S9523884Z
Email Address	ARIFFZAILAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90912844
Alternative Phone No	OTHERS-90912844
Vehicle Particulars	
Manufacturer	YAMAHA
Model	X-1R-135CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/VMT/17-372528-CA
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD NUR ARIFF BIN ZAILAN
NRIC No	S9523884Z
Date Of Birth	07/07/1995
Occupation	OUTDOOR
Date Of Driving Pass	27/06/2018
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90912844
Fax Number	
Contact Number	OTHERS-90912844
E-Mail Address	ARIFFZAILAN@GMAIL.COM

Address BLK 664 WOODLANDS RING ROAD #08-196  
SINGAPORE  
Postcode 730664  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident COLLISION - MAJOR/MINOR RD  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? YES  
Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station

Police Station Name

Police Station Address

Police Station Contact

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SLS7104X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage



## Accident Sketch Plan Pg. 1

**SINGAPORE  
POLICE FORCE**

T/20180206/2189

2 of 3

Police Station Of Origin:  
Woodlands West N.P.C.  
9 Marsiling Lane SINGAPORE 739146  
Tel No: 1800-363 9999

Report No. T/20180206/2189

## CONTINUATION OF REPORT

Brief Details.

On 04/02/2018 at about 1719hrs, my son namely, Muhammad Nur Ariff Bin Zailan, S9523884Z, already lodged police report online vide report F/20180204/7019 with in-charge case TP IO Wong Sieu Lui, Tel: 65476151. However, after report was confirmed. My son realized that he would like to make amendments as followed:

The said car did not give way or signal to indicate that he was going to turn into the junction.






































I wish to state that my son was conveyed to KTPH conscious and was admitted from 29/01/2018 to 02/02/2018. He was then given 28 days of MC from 29/01/2018 to 23/02/2018. I am lodging this report on behalf of my son as he was still injured and unable to proceed to Police Station to make the above mentioned amendment.















































## Claim Documents





















\*FBC5146R (0855467075SG)  
[SLS7104X]

TP

MUHAMMAD NUR ARIF  
Jan 29 2018 12:00AM  
[GOH PEI SHAN (WU PEISHAN)]  
Brother Motors

Upload Documents   Upload Photos   Compose New Letter   Upload Video   Upload Audio			View <input type="button" value="View in Browser"/>	
Photos/Images			3 per page <input type="button" value="3 per page"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
2	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
3	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
4	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
5	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
6	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
7	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
8	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
9	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
10	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
11	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
12	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
13	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
14	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
15	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
16	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
17	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
18	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
19	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
20	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
21	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
22	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
23	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
24	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
25	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
26	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
27	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
28	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
29	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
30	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
31	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
32	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
33	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
34	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
68	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	18/04/18 18:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
85	18/04/18 18:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
86	18/04/18 18:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
87	18/04/18 18:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/04/18 12:34	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18002898/SD3E2

Date: 20/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle  
No : FBC5146R

Insured Vehicle No : SLS7104X

Date of Loss: 29/01/2018

Nature of Claim: TP

Claim No: 0855467075SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBC5146R

Make &amp; Model: YAMAHA X-1R, 135cc (M)

Engine No: 4S3201593

Reg. Date: 16/04/2008 (Man. Year: 2007)

Chassis No: 4S3201593

Colour: Red/White

Odometer: 405537 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size: 70/90-17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 13/02/2018

Date Inspected: 14/02/2018 Inspected At:

Brother Motors (HQ)  
BLK 1016 YISHUN INDUSTRIAL PARK A,  
#01-218  
Singapore 768758

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\\_...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_...) 20/4/2018

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*-F
2	1		*FRONT HEADLAMP	Damaged	0.00 F	*-F
3	1		*FRONT HEADLAMP BRACKET	Broken	0.00 F	*-F
4	1		*FRONT WINDSHIELD	Scratched	0.00 F	*-F
5	1		*FRONT WING MIRROR	Broken	0.00 F	*-F
6	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*-F
7	1		*METER CASING	Broken	0.00 F	*-F
8	1		*ERP BRACKET	Dented	0.00 F	*-F
9	1		*ERP UNIT	Cut	0.00 F	*-F
10	1		*HANDLE BAR GRIP	Cut	0.00 F	*-F
11	1		*HANDLE BAR BALANCER LH	Missing	0.00 F	*-F
12	1		*HANDLE BAR BALANCER RH	Missing	0.00 F	*-F
13	1		*CLUTCH LEVER	Cut	0.00 F	*-F
14	1		*HAND BRAKE LEVER	Cut	0.00 F	*-F
15	1		*SIDE FAIRING	Cut	0.00 F	*-F
16	1		*FAIRING SHIELD	Broken	0.00 F	*-F
17	1		*CENTER FAIRING	Broken	0.00 F	*-F
18	1		*REAR FAIRING	Cut	0.00 F	*-F
19	1		*FAIRING REAR GUARD	Damaged	0.00 F	*-F
20	1		*RADIATOR	Damaged	0.00 F	*-F
21	1		*ENGINE GUARD	Cut	0.00 F	*-F
22	1		*FOOT BRAKE	Broken	0.00 F	*-F
23	1		*FRONT FOOT REST	Damaged	0.00 F	*-F
24	1		*FRONT FOOT REST BRACKET	Dented	0.00 F	*-F
25	1		*SIDE STAND	Dented	0.00 F	*-F
26	1		*KICK STARTER RUBBER	Cut	0.00 F	*-F
27	1		*REAR FOOT REST	Damaged	0.00 F	*-F
28	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*-F
29	1		*FRONT BOX	Broken	0.00 F	*-F
30	1		*FRONT BOX BRACKET	Dented	0.00 F	*-F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

# PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L

Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref : PS/007/02/18

Date : 06th March 2018

Mr Muhammad Nur Ariff Bin Zailan  
c/o Blk 1016 Yishun Industrial Park A  
#01-218  
Singapore 768758

Dear Sir,

## Re : **THIRD PARTY CLAIM**

We refer to your instruction to appraise the vehicle **FBC 5146 R** on 13th February 2018.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Brother Motors** for **S\$8,370.00** as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of **S\$5,200.00 lump sum** corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **FIVE (5) days**. Photographs of the damaged vehicle taken by us during our inspection are enclosed.


We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

**PRESTIGE APPRAISER SERVICES**

  
**FRANCIS A NG CAE AMIMI**  
**Dip. MTM. Automotive Engineer**  
**Licensed Appraiser**

Encl.



# PRESTIGE APPRAISER SERVICES

## VEHICLE INSPECTION REPORT

To: Mr Muhammad Nur Ariff Bin Zailan	Date	: 06th March 2018
c/o Blk 1016 Yishun Industrial Park A	Our Ref	: PS/007/02/18
#01-218	Policy No	:
Singapore 768758	Sum Insured	:
	Excess	: T/P Claim

Assigned By	: Mr Muhammad Nur Ariff Bin Zailan
Assignment Date	: 13th February 2018
Accident Date	: 29th January 2018
Inspection Date	: 13th February 2018
Workshop Name	: Brother Motors
Survey Conducted At	: Blk 1016 Yishun Industrial Park A
	#01-218
	Singapore 768758

### PARTICULARS OF VEHICLE

Registration No	: FBC 5146 R	Mileage	: 40553km
Make/Model	: Yamaha X-1R	Engine No	: 4S3201593
Type Of Body	: Motorcycle	Chassis No	: 4S3201593
Year Of Manu./Regn.	: 2007/2008	Passenger Cap.	: 1 Passenger
Colour	: Red	Others	: -

### CONDITION OF TYRES

Front Tyre	: 5mm 80/90-17 Dunlop
Rear Tyre	: 5mm 80/90-17 Dunlop

*The above represent the estimated remaining life of the tyre treads.*

### PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

### POINT OF IMPACT

The vehicle sustained an impact on the front, R/H & L/H portion.

### GENERAL DESCRIPTION OF DAMAGES

The main body frame, handle bar, forks, wheel rim, exhaust muffler were dented/bent.

For details of damages please refer to schedule attached.

### REMARKS:

This survey was conducted strictly without prejudice.

# PRESTIGE APPRAISER SERVICES

Vehicle No : FBC 5146 R

Our Ref :

PS/007/02/18

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
	<u>LIST ITEMS</u>			
1	steering cone w/bearing ✓ <i>NEC</i>	necessary	\$ 85.00	\$ 85.00 ✓
1	R/H fairing ✓ <i>BR</i>	broken	218.00	218.00 ✓
1	R/H fairing inner garnish ✓ <i>BR</i>	broken	85.00	85.00 ✓
1	R/H lower fairing ✓ <i>BR</i>	broken	98.00	98.00 ✓
2	front fork ✓ <i>BT</i>	warped	650.00	650.00 ✓
1	under bracket ✓ <i>DT</i>	dented	95.00	95.00 ✓
1	basket ✓ <i>BR</i>	cracked	52.00	52.00 ✓
1	brake container ✓ <i>MS</i>	sliced	78.00	78.00 ✓
1	front wheel rim X <i>SVC</i>	warped	368.00	368.00
1	front brake disc X <i>NN</i>	warped	170.00	170.00
2	handle bar ✓ <i>BT</i>	bent	148.00	148.00
2	handle bar grip ✓ <i>CUT</i>	sliced	60.00	60.00
1	brake lever ✓ <i>CUT</i>	sliced	52.00	<i>NN</i> 52.00 X <i>DT</i>
2	mirror ✓ <i>BR</i>	broken	98.00	98.00
1	clutch lever ✓ <i>CUT</i>	sliced	52.00	52.00
1	front mudguard ✓ <i>CUT</i>	sliced	168.00	168.00 ✓
1	L/H magnet cover ✓ <i>CUT</i>	sliced	198.00	198.00 ✓
1	L/H magnet cover gasket ✓ <i>NEC</i>	necessary	22.00	22.00 ✓
1	gear lever ✓ <i>BT</i>	bent	58.00	58.00
1	L/H front foot rest ✓ <i>DMG</i>	sliced	45.00	45.00
1	R/H rear foot rest ✓ <i>CUT</i>	sliced	45.00	45.00
1	L/H rear foot rest ✓ <i>CUT</i>	sliced	45.00	45.00
1	radiator ✓ <i>DMG</i>	dented	485.00	485.00
1	rear mudguard X <i>NM</i>	dented/cut	138.00	138.00
1	swing arm R	dented - repair	480.00	-
1	rear wheel rim X <i>SVC</i>	serviceable	390.00	-
1	taillamp ✓ <i>SCR</i>	scratched	168.00	168.00
2	rear side garnish ✓ <i>CUT</i>	sliced	186.00	186.00
1	headlamp ✓ <i>DMG</i>	broken	192.00	192.00 ✓
1	headlamp cowling ✓ <i>BR</i>	cracked	88.00	88.00
1	speedometer ✓ <i>BR</i>	damaged	328.00	328.00 ✓
1	speedometer cover ✓ <i>BR</i>	damaged	65.00	65.00
1	exhaust muffler ✓ <i>CUT</i>	dented/sliced	660.00	660.00
1	taillamp cover ✓ <i>CRK</i>	cracked	55.00	55.00
1	pillion handle ✓ <i>CUT</i>	sliced	48.00	48.00
1	R/H front signal lamp ✓ <i>BR</i>	broken	52.00	52.00
1	L/H front signal lamp ✓ <i>SCR</i>	scratched	52.00	52.00
1	L/H fairing ✓ <i>CUT</i>	sliced	218.00	218.00
1	L/H fairing inner garnish ✓ <i>DT</i>	dented	85.00	85.00
1	front cover ✓ <i>SCR</i>	broken	105.00	105.00
1	front cover bracket ✓ <i>DT</i>	dented	35.00	35.00
			6,720.00	5,850.00
		Less 10%	-	585.00
			\$ 6,720.00	\$ 5,265.00
	<u>S/NETT ITEM</u>			
1	IU unit ✓ <i>CUT</i>	sliced	200.00	156.00
		Balance c/f	\$ 6,920.00	\$ 5,421.00

# PRESTIGE APPRAISER SERVICES

Vehicle No : FBC 5146 R

Our Ref : PS/007/02/18

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
		Balance b/d	\$ 6,920.00	\$ 5,421.00
	<u>Labour Charges &amp; Misc</u>			
	To dismantle & replace damaged parts, panel beat where necessary.		600.00	450.00 <del>400</del> 300
	To putty, apply primer & spray-paint on the affected portion.		500.00	350.00 200
	To align main body frame.		300.00	250.00 <del>200</del> 150
	Transportation charges. *receipt		50.00	40.00 ✓ 30
			<u>\$ 8,370.00</u>	<u>\$ 6,511.00</u>

4 days

**Note:** The repairer has agreed to undertake the repairs at our adjusted amount of **\$5,200.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FIVE ( 5 )** days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES

FRANCIS S A NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18002898/Sqbe2-1

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 21-06-2018



ATTN : NORSIAH

Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 7104X	Veh. Inspected	FBC 5146R
Policy No.		Coverage (\$)	0.00
Claim No.	0855467075SG	Excess (\$)	0.00
Assign From	NORSIAH	Assign Date	24/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	YAMAHA X-1R	c.c	135
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	4S3201593	Colour	RED / WHITE
Odometer	405537	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90-17	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	70/90-17	DUNLOP	6 mm
L/H Rear Tyre			mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	29/01/2018	Inspection Date	14/02/2018
Survey held at	BROTHER MOTORS BLK 1016 YISHUN INDUSTRIAL PARK A #01-218 SINGAPORE 768758		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 5146R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	STEERING CONE W/BEARING	NECESSARY	85.00	85.00
1	R/H FAIRING	BROKEN	218.00	218.00
1	R/H FAIRING INNER GARNISH	BROKEN	85.00	85.00
1	R/H LOWER FAIRING	BROKEN	98.00	98.00
2	FRONT FORK	BENT	650.00	650.00
1	UNDER BRACKET	DENTED	95.00	95.00
1	BASKET	BROKEN	52.00	52.00
1	BRAKE CONTAINER	MISSING	78.00	78.00
1	FRONT WHEEL RIM	SERVICEABLE	368.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	170.00	-
2	HANDLE BAR	BENT	148.00	148.00
2	HANDLE BAR GRIP	CUT	60.00	60.00
1	BRAKE LVER	NOT NECESSARY	52.00	-
2	MIRROR	BROKEN	98.00	98.00
1	CLUTCH LEVER	CUT	52.00	52.00
1	FRONT MUDGUARD	CUT	168.00	168.00
1	L/H MAGNET COVER	CUT	198.00	198.00
1	L/H MAGNET COVER GASKET	NECESSARY	22.00	22.00
1	GEAR LEVER	BENT	58.00	58.00
1	L/H FRONT FOOT REST	DAMAGED	45.00	45.00
1	R/H REAR FOOT REST	CUT	45.00	45.00
1	L/H REAR FOOT REST	CUT	45.00	45.00
1	RADIATOR	DAMAGED	485.00	485.00
1	REAR MUDGUARD	NOT NECESSARY	138.00	-
1	SWING ARM	TO REPAIR SEE LABOUR	480.00	-
1	REAR WHEEL RIM	SERVICEABLE	390.00	-
1	TAILLAMP	SCRATCHED	168.00	168.00
2	REAR SIDE GARNISH	CUT	186.00	186.00
1	HEADLAMP	DAMAGED	192.00	192.00
1	HEADLAMP COWLING	BROKEN	88.00	88.00

Report Ref No. CS3/AIG18002898/Sqbe2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPEEDMETER	BROKEN	328.00	328.00
1	SPEEDMETER COVER	BROKEN	65.00	65.00
1	EXHAUST MUFFLER	CUT	660.00	660.00
1	TAILLAMP COVER	CRACKED	55.00	55.00
1	PILLION HANDLE	CUT	48.00	48.00
1	R/H FRONT SIGNAL LAMP	BROKEN	52.00	52.00
1	L/H FRONT SIGNAL LAMP	SCRATCHED	52.00	52.00
1	L/H FAIRING	CUT	218.00	218.00
1	L/H FAIRING INNER GARNISH	DENTED	85.00	85.00
1	FRONT COVER	SCRATCHED	105.00	105.00
1	FRONT COVER BRACKET	DENTED	35.00	35.00
	LESS 10% DISCOUNT		-	-512.20
			6,720.00	4,609.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	IU UNIT (SN)	CUT	200.00	156.00
			200.00	156.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF SWING ARM.		600.00	300.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		500.00	200.00
	TO ALIGN MAIN BODY FRAME.		300.00	150.00
	TRANSPORTATION CHARGES.		50.00	30.00
			1,450.00	680.00
	<b>GRAND TOTAL</b>		<b>8,370.00</b>	<b>5,445.80</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,350.00</b>

Report Ref No. CS3/AIG18002898/Sqbe2-1

YEANG WAI KEEN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.