

SWIFT

Menmen

ASSIGNMENT (Office)

Private (Owner)

Kwok Woun

M81G

Date/Time

25/5/18 @ 9:27am

Estimated Cost

Bill for

① TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJM7774S

Insured

at Workshop no

Jack Cars

Tel

67488824

of

81k 3007 Ubi Rd 1 # 01-450

Policy No

A29010337 QMX

Claim No

559323

Sum Insured

Excess

\$700.00

Make of Veh

(Client's Record)

D.O.A

22/05/2018

CA / REV

/ REP. / REV 24 HRS

Date/Time

11am @ 25/5/18

Person Contacted

Thana

H.O.D. Endorsement

Vehicle

IN

OUT

Date/Time

Action/Instruction

(✓) Estimate Pending Insd NRIC & DL

28/5/18

Sent Prel. thn menmen

30/5/18

Auto dex not yet assign; Daniel (M81G) on MC; Speak to Siew Wei

(12:40pm)

She will go to check and get back to us.

31/5/18

Report with auto dex adjustment

4/6/18

Authorise repair; Inform Thana to proceed repair.

REF: MSIG

ASSIGNMENT

From:

Date:

25/5/2018

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

SYM 7774S

at Workshop m/s

Jack Cars

of Blk 3007, Ubi Rd 1 # 01-450

Insured.

Policy No.

Claims No.

Sum Insured

Excess: \$700.00


(Client's Record)

Pending Insd NRIC & DL

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$125K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SYM 7774S

Yr Regd

24 Aug 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hilux Premium cc 1986

Colour

white

A/C

Insured / Std / NI / NA

Sp. Reading

1286.6 km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZSY 600110172

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/55/18

R: 235/55/18

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

22/5/2018

D.O.I.

25/5/2018

Survey held at

Jack Cars

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/5 Continued final Sig @ 4,155.90 with Thana. (Red 2770.10, 39%)

RECEIVED 11 JUN 2019

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation

1 S + RS 51

Photos

Others

TOTAL

Report Format: OD

Lump Sum / I.E. \$ 4,155.90

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

150

11

161



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18009526/Grd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 25-05-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SJM 7774S	
Policy No.	A29010337QMX	Coverage (\$)	0.00	
Claim No.	559323	Excess (\$)	0.00	
Assign From	MERIMEN (KWOK WOON)	Assign Date	25/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/05/2018	Inspection Date		
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Est Submitted	Ins Auth'd	Status
Main	24 May 2018 Sendback Est	24 May 2018 12:58 S\$6,926.00	25 May 2018 09:27 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	CHOO PENG LEONG PHILLIP, ID: S1694707E, Tel: +6597681222, Email: PHILLIPCHOO@YMAIL.COM	
Vehicle Reg. No.:	SJM7774S	Date of Loss: 22/05/2018 08:00 - :59 [8 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 559323	Policy/Cover Note No.: A29010337QMX (Comprehensive) Coverage: 24/08/2017 - 23/08/2018
		Excess: S\$700.00
Repairer:	Jack Cars Enterprise Pte Ltd (HQ) 61 Ubi Avenue 2, #01-20 Automobile Megamart, 408898 Ubi - Tel: 67441900	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/05/2018]	
Driver/Custodian:	CHOO PENG LEONG PHILLIP (52 / Male), NRIC: S1694707E, Tel: +6597681222	
Adj Asg. Remarks:	Survey TODAY and REVERT. Car at Blk 3007 Ubi Rd 1 #01-450 S408701 PENDING FOR INSD NRIC & DL	

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completion	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 31 May 2018

Preliminary Advice

Vehicle No	: SJM7774S	Accident Date	: 22/05/2018
Make	: TOYOTA HARRIER	Policy No.	: A29010337QMX
Assignment Date	: 25/05/2018	Excess	: S\$700.00
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 6.00
Inspection At	: JACK CARS ENTERPRISE PTE LTD (HQ) 61 UBI AVENUE 2, #01-20 AUTOMOBILE MEGAMART SINGAPORE 408898		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,926.00
Revised Amount	:S\$	4,155.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,155.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	74,315.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,685.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

View Received Message

This mail is associated with :

SJM7774S (559323)

OD

May 22 2018 8:00AM

[CHOO PENG LEONG PHILLIP]
Jack Cars Enterprise Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 04/06/2018 11:14 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4155.90) - SJM7774S - Claim Handler: Kwok Woon Choo

Approved:4155.90:a lf c

DOCUMENTS SUMMARY

There are no documents.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, June 04, 2018 11:56 AM
To: 'Thanaletchumi Santerashigaram'
Cc: SUR
Subject: RE: SJM7774S
Attachments: SJM 7774S JC007774_1.AudatexMS.pdf

Dear Thana,

As instructed by our client, please proceed to repair the insured vehicle **SJM 7774S (excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler


LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



97681222
phillipchoo@ymail.com



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4707E
Vehicle Details	
Vehicle No.:	SJM7774S
Vehicle to be Exported:	No
Intended De-registration Date:	28 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	3ZRC024756
Chassis No.:	ZSU600110172
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$33,659.00
Original Registration Date:	24 Aug 2017
First Registration Date:	24 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$34,123.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2027
PARF Rebate Amount:	\$25,592.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$52,751.00
COE Rebate Amount:	\$48,723.00
Total Rebate Amount:	\$74,315.00

The information contained herein is correct as at 28 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/05/2018 16:13
Date Of Accident	22/05/2018 08:00
Exact Location Of Accident	VANDA ROAD EXITING INTO ENG NEO AVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJM7774S
Insured/Policyholder	
Name Of Registered Owner	CHOO PENG LEONG PHILLIP
NRIC No	S1694707E
Email Address	PHILLIPCHOO@YMAIL.COM
Mobile Phone No	(LOCAL) +65-97681222
Alternative Phone No	OFFICE-97681222
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARRIER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29010337QMX
Cover Note Number	
Driver	
Name of Driver	CHOO PENG LEONG PHILLIP
NRIC No	S1694707E
Date Of Birth	18/11/1965
Occupation	INDOOR
Date Of Driving Pass	07/08/1985
Driving Experience	32 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97681222
Fax Number	
Contact Number	OFFICE-97681222
Email Address	PHILLIPCHOO@YMAIL.COM

Address	1E SHELFORD ROAD
	#05-36
Postcode	286890
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

----- REFER TO ATTACHMENT -----

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	RECORDING WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1492X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers to the SIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time

JACK CARS ENTERPRISE PTE LTD
 BLK 3007 UBI ROAD 1
 #01-448 / 450 / 452
 SINGAPORE 408701
 TEL: 6748 5824 FAX: 6748 8824
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN

REFER TO ANNEX A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/05/2018 at about 0800hrs, I was travelling along Vanda Road exiting into Eng Neo Ave.

As the traffic was at a stop, I exited into Eng Neo Ave and waited in the yellow box for the traffic to move.

Once the traffic was moving, a lorry bearing registration number XE 1492X hit the rear of my car. My car registration number 8jm 7774S.

DECLARATION

I/we declare the foregoing particulars are true in every respect.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

JACK CARS ENTERPRISE PTE LTD
BLK 3007 UBI ROAD 1
#01-448 / 450 / 452
SINGAPORE 408701
TEL: 6748 8824 FAX: 6748 8834
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Google Maps Singapore



Google, Inc.

Street View - Apr 2015

A - sgm 77748
B - XE 1492X

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	A29010337QMX	Date of Loss:	22/05/2018
Vehicle Reg. No.:	SJM7774S	Driveable?	
Driver Age/Info:	52 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOO PENG LEONG PHILLIP	Contact No:	+6597681222
Driver:	CHOO PENG LEONG PHILLIP		

Make/Model:	TOYOTA HARRIER, 2.0 (A)	Vehicle Reg. Date:	24/08/2017
Vehicle Colour:	Pearl White		
Engine No:	3ZRC024756	Chassis No:	ZSU600110172
Odometer:	0 KM		

Paint Type:	Pearl Effect
Total Loss?	NO
Est. Duration of Repair (day)	12

Description of Accident/Loss ----- REFER TO ATTACHMENT -----

Present Location: JACK CARS ENTERPRISE PTE LTD (HQ)

COST OF CLAIMS		Amount
Parts		2,706.00
Miscellaneous Items		200.00
Labour		2,520.00
Paintwork Labour		1,500.00
Towing		0.00
Calculated Gross Total (S\$)		6,926.00
- Excess (S\$)		700.00
(S\$)		6,226.00
+ GST 7.00% (S\$)		435.82
Nett Amount (S\$)		6,661.82

This claim is handled by: **THANALETCHUMI SANTERASHIGARM**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 May 2018)
Parts: M1-SUV TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Jack Cars Enterprise Pte Ltd/SJM7774S/24/05/2018 12:58
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR RIGHT DOOR	0.00	0.00	*750.00 F	BUC
2	1		*REAR RIGHT BUMPER <i>Bumper</i>	0.00	0.00	*650.00 F	BUC
3	1		*REAR BUMPER	0.00	0.00	*700.00 F	WUT
4	1		*REAR RIGHT TAILGATE LIGHT	0.00	0.00	*300.00 F	WRA
5	1		*REAR RIGHT BUMPER BRACKET	0.00	0.00	*60.00 F	WDS
						Sub Total (S\$)	2,460.00
						+ Margin on L,N Items 10.00% (S\$)	246.00
						Total Parts (S\$)	2,706.00

F=Franchise part.

Jack Cars Enterprise Pte Ltd/SJM7774S/24/05/2018 12:58. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

DOI 25/5/18
 1700 hr

Service by Simon & TG Lim LK

Not authorised w/s

Excess \$700/2 6 days to repair

P&P

Excess TBA

Reservey before paint


 6/6/18

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	CLIPS	80.00 <i>30 nu</i>
2	1	SILICON SEALANT	120.00 <i>60 nu</i>
Sub Total (\$\$)			200.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	<i>800</i> 1,500.00 ✓
<u>Labour Items</u>			
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	<i>800</i> 1,900.00
3	TO CHECK WIRING & REWIRE & WATER TEST	New	<i>50</i> 120.00
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	<i>60</i> 150.00
5	TO REMOVE AND REINSTALL REAR RIGHT DOOR WINDOW	New	<i>80</i> 200.00
6	TO REMOVE & REINSTALL REVERSE SENSOR	New	<i>60</i> 150.00
Gross Labour Cost (\$\$)			4,020.00

Jack Cars Enterprise Pte Ltd/SJM7774S/24/05/2018 12:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey del. when spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**JackCars Enterprise Pte
Ltd**

**Blk 3007 Ubi Rd 1
#01-448/450/452
Singapore 408701**

**Claim Reference: JC / 2018 / SJM7774S
Assessment Number: JC007774
Version: JACKCARS/3
Date Calculated: 31/05/2018 04:14**

**Full Report - V1
Registration: SJM7774S
Printed: 31/05/2018 11:36**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	22/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	JC / 2018 / SJM7774S	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Harrier
Sub Model:	BASE MODEL
Model Sheet Number:	YMH 01
Registration:	SJM7774S
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 06.2011	2.4 LTR 120 KW
TWO COAT METALLIC	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	24/05/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,195.00
Total Paint/Material	\$184.90
Total Parts	\$3,058.00
Repair Cost Exc GST:	\$4,437.90
Overall Discount (0.0%):	- \$0.00
Excess:	-\$700.00
After Deduction -	
Grand Total Exc GST:	\$3,737.90
7 % GST:	\$261.65
Grand Total Inc GST:	\$3,999.55

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	RENEW R/R DOOR	27.0	135.00
	INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, ADJUST DOOR		
NO NUMBER	RENEW R/R SIDE PANEL	80.0	400.00
	INCLUDES: R + R TAILLAMP, BOOT CARPET AND ALL TRIMS IN THE REPAIR SECTION DOES NOT INCLUDE: R + R SEAT CUSHION, R/R SIDE WINDOW AND REAR BUMPER		
NO NUMBER	R + R TAILGATE TRIM	2.0	10.00
NO NUMBER	R + R REAR BUMPER	5.0	25.00
	INCLUDES: R + R BOOT TRIMS		
NO NUMBER	RENEW REAR BUMPER (REMOVED)	2.0	10.00
NO NUMBER	R + R TAILGATE FRAME SEAL	2.0	10.00
NO NUMBER	R + R R/C-PILLAR TRIM	5.0	25.00
NO NUMBER	R + R RIGHT REAR SIDE WINDOW GLASS	11.0	55.00
NO NUMBER	R + R LEFT REAR SEAT	2.0	10.00
NO NUMBER	R + R RIGHT REAR SEAT	2.0	10.00
NO NUMBER	R + R REAR SEAT CUSHIONS (ADD/WORK)	1.0	5.00
NO NUMBER	R + R TAILGATE WIRING HARNESS	12.0	60.00

LABOUR COST

Total Work Units	151.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	15.1HRS	\$755.00
Paint Labour	8.8HRS	\$440.00
Total Labour	23.9HRS	\$1,195.00

JackCars Enterprise Pte Ltd

Claim Reference: JC / 2018 / SJM7774S
 Assessment Number: JC007774
 Version: JACKCARS/3
 Date Calculated: 31/05/2018 04:14

Full Report - V1
 Registration: SJM7774S
 Printed: 31/05/2018 11:36

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
1782	R/R DOOR NEW PART PAINTING	15.0	
3482	R/R SIDE PANEL NEW PART PAINTING	34.0	
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
LABOUR COST - PAINT			
	TIME(PAINT)	62.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	88.0	
	Total Paintwork Labour	8.8HRS	\$440.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$92.36
	New Part Painting - Plastic K1R		\$65.44
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$184.90
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$184.90

PARTS

Guide No. Qty		Description	Part Number	Supplier	Bet.	Price (\$)	
1782	1	R/R DOOR	67003 48080		0%	750.00*	/ Bul
2583	1	REAR BUMPER	52159 48903		0%	700.00*	/ Int
2622	1	R/R BUMPER BRACKET	52155 48011		0%	60.00*	/ Dis
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS	(chps) SN	0%	80.00*	/ Mcl
3292	1	R/R OUTER LAMP	81551 48061		0%	300.00*	/ LRA
3482	1	R/R SIDE PANEL	61611 48051		0%	650.00*	/ Bul
3806	1	R/R SIDE WINDOW	62710 48160		0%	0.00	
3862	1*	R/S WINDOW BOND KIT	PZ49I 00C1131	(Silicon Sealant) SN	0%	120.00*	/ Mcl
9615	1	REAR LAMPS WIRING	82184 48090	(Inbowr)	0%	120.00*	
f: OEM Parts			Sub Total			\$2,780.00	
g: Original			Mark Up From Cost	(10 %)		\$278.00	
h: Secondhand			Total Parts			\$3,058.00	
p: Parallel							
x: Exchange							

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER
Total Extras **\$0.00**

Final Calculation

Total Parts		\$3,058.00
Labour		
Total Panel/Mechanical	735	\$755.00
Total Paintwork		\$440.00
Total Labour		\$1,195.00
Total Paint/Material Costs		\$184.90
Repair Costs Excludes GST		\$4,437.90

JackCars Enterprise Pte Ltd

Claim Reference: JC / 2018 / SJM7774S
Assessment Number: JC007774
Version: JACKCARS/3
Date Calculated: 31/05/2018 04:14

Full Report - V1
Registration: SJM7774S
Printed: 31/05/2018 11:36

Deductions

Deduction for Excess (Fixed)	- \$700.00	
Total Deductions		- \$700.00
Grand Total Excludes GST (After Deduction)		\$3,737.90
GST @ 7 %		\$261.65
Grand Total Includes GST (After Deduction)		\$3,999.55

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: JC / 2018 / SJM7774S
Assessment Number: JC007774
Version: LKKAUTOC/2
Date Calculated: 31/05/2018 05:44

Full Report - V1
Registration: SJM7774S
Printed: 31/05/2018 12:47

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	22/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	JC / 2018 / SJM7774S	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Harrier
Sub Model:	BASE MODEL
Model Sheet Number:	YMH 01
Registration:	SJM7774S
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 06.2011	2.4 LTR 120 KW
TWO COAT METALLIC	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	24/05/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,130.00
Total Paint/Material	\$184.90
Total Parts	\$2,805.00
Repair Cost Exc GST:	\$4,119.90
Overall Discount (0.0%):	- \$0.00
Excess:	-\$700.00
After Deduction -	
Grand Total Exc GST:	\$3,419.90
7 % GST:	\$239.39
Grand Total Inc GST:	\$3,659.29

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	RENEW R/R DOOR	27.0	135.00
	INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, ADJUST DOOR		
NO NUMBER	RENEW R/R SIDE PANEL	80.0	400.00
	INCLUDES: R + R TAILLAMP, BOOT CARPET AND ALL TRIMS IN THE REPAIR SECTION DOES NOT INCLUDE: R + R SEAT CUSHION, R/R SIDE WINDOW AND REAR BUMPER		
NO NUMBER	R + R REAR BUMPER	5.0	25.00
	INCLUDES: R + R BOOT TRIMS		
NO NUMBER	RENEW REAR BUMPER (REMOVED)	2.0	10.00
NO NUMBER	R + R TAILGATE FRAME SEAL	2.0	10.00
NO NUMBER	R + R R/C-PILLAR TRIM	5.0	25.00
NO NUMBER	R + R RIGHT REAR SIDE WINDOW GLASS	11.0	55.00
NO NUMBER	R + R LEFT REAR SEAT	2.0	10.00
NO NUMBER	R + R RIGHT REAR SEAT	2.0	10.00
NO NUMBER	R + R REAR SEAT CUSHIONS (ADD/WORK)	1.0	5.00
9615	REPAIR REAR LAMPS WIRING	1.0*	5.00

LABOUR COST**Total Work Units**

138.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Sub Total

13.8HRS

\$690.00

Paint Labour

8.8HRS

\$440.00

Total Labour

22.6HRS

\$1,130.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
1782	R/R DOOR NEW PART PAINTING	15.0	
3482	R/R SIDE PANEL NEW PART PAINTING	34.0	
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
LABOUR COST - PAINT			
	TIME(PAINT)	62.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	88.0	
	Total Paintwork Labour	8.8HRS	\$440.00
MATERIAL COST - PAINT			
	New Part Painting		\$92.36
	New Part Painting - Plastic K1R		\$65.44
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$184.90
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$184.90

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1782	1	R/R DOOR	67003 48080		0% 750.00*
2583	1	REAR BUMPER	52159 48903		0% 700.00*
2622	1	R/R BUMPER BRACKET	52155 48011		0% 60.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0% 30.00*
3292	1	R/R OUTER LAMP	81551 48061		0% 300.00*
3482	1	R/R SIDE PANEL	61611 48051		0% 650.00*
3806	1	R/R SIDE WINDOW	62710 48160		0% 0.00
3862	1	R/S WINDOW BOND KIT	PZ491 00C1131		0% 60.00F
f: OEM Parts		Sub Total			\$2,550.00
g: Original		Mark Up From Cost (10 %)			\$255.00
h: Secondhand		Total Parts			\$2,805.00
p: Parallel					
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts	\$2,805.00
Labour	
Total Panel/Mechanical	\$690.00
Total Paintwork	\$440.00
Total Labour	\$1,130.00
Total Paint/Material Costs	\$184.90
Repair Costs Excludes GST	\$4,119.90
Deductions	
Deduction for Excess (Fixed)	-\$700.00

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: JC / 2018 / SJM7774S

Full Report - V1

Assessment Number: JC007774

Registration: SJM7774S

Version: LKKAUTOC/2

Printed: 31/05/2018 12:47

Date Calculated: 31/05/2018 05:44

Total Deductions	- \$700.00
Grand Total Excludes GST (After Deduction)	<u>\$3,419.90</u>
GST @ 7 %	\$239.39
Grand Total Includes GST (After Deduction)	<u>\$3,659.29</u>

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Full Report - V1
Registration: SJM7774S
Printed: 31/05/2018 18:03

Claim Reference: JC / 2018 / SJM7774S
Assessment Number: JC007774
Version: LKKAUTOC/2
Date Calculated: 31/05/2018 11:02

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	22/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	JC / 2018 / SJM7774S	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Harrier
Sub Model:	BASE MODEL
Model Sheet Number:	YMH 01
Registration:	SJM7774S
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 06.2011	2.4 LTR 120 KW
TWO COAT METALLIC	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	24/05/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,175.00
Total Paint/Material	\$184.90
Total Parts	\$2,706.00
Total of Additional Costs	\$90.00
Repair Cost Exc GST:	\$4,155.90
Overall Discount (0.0%):	- \$0.00
Excess:	-\$700.00
After Deduction -	
Grand Total Exc GST:	\$3,455.90
7 % GST:	\$241.91
Grand Total Inc GST:	\$3,697.81

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	RENEW R/R DOOR	27.0	135.00
	INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, ADJUST DOOR		
NO NUMBER	RENEW R/R SIDE PANEL	80.0	400.00
	INCLUDES: R + R TAILLAMP, BOOT CARPET AND ALL TRIMS IN THE REPAIR SECTION DOES NOT INCLUDE: R + R SEAT CUSHION, R/R SIDE WINDOW AND REAR BUMPER		
NO NUMBER	R + R REAR BUMPER	5.0	25.00
	INCLUDES: R + R BOOT TRIMS		
NO NUMBER	RENEW REAR BUMPER (REMOVED)	2.0	10.00
NO NUMBER	R + R TAILGATE FRAME SEAL	2.0	10.00
NO NUMBER	R + R R/C-PILLAR TRIM	5.0	25.00
NO NUMBER	R + R RIGHT REAR SIDE WINDOW GLASS	11.0	55.00
NO NUMBER	R + R LEFT REAR SEAT	2.0	10.00
NO NUMBER	R + R RIGHT REAR SEAT	2.0	10.00
NO NUMBER	R + R REAR SEAT CUSHIONS (ADD/WORK)	1.0	5.00
9615	REPAIR REAR LAMPS WIRING	10.0*	50.00

LABOUR COST

Total Work Units	147.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	14.7HRS	\$735.00
Paint Labour	8.8HRS	\$440.00
Total Labour	23.5HRS	\$1,175.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
1782	R/R DOOR NEW PART PAINTING	15.0	
3482	R/R SIDE PANEL NEW PART PAINTING	34.0	
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
LABOUR COST - PAINT			
	TIME(PAINT)	62.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	88.0	
	Total Paintwork Labour	8.8HRS	\$440.00
MATERIAL COST - PAINT			
	Cost Price		
	New Part Painting		\$92.36
	New Part Painting - Plastic K1R		\$65.44
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$184.90
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$184.90

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
1782	1	R/R DOOR	67003 48080		0% 750.00*
2583	1	REAR BUMPER	52159 48903		0% 700.00*
2622	1	R/R BUMPER BRACKET	52155 48011		0% 60.00*
3292	1	R/R OUTER LAMP	81551 48061		0% 300.00*
3482	1	R/R SIDE PANEL	61611 48051		0% 650.00*
3806	1	R/R SIDE WINDOW	62710 48160		0% 0.00
3862	1	R/S WINDOW BOND KIT	PZ49I 00C1131		0% 0.00F
f: OEM Parts		Saving			\$38.18
g: Original		Sub Total			\$2,460.00
h: Secondhand		Mark Up From Cost (10 %)			\$246.00
p: Parallel		Total Parts			\$2,706.00
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
CLIPS SPECIALIST	0%	\$30.00
SILICON SEALANT SPECIALIST		\$60.00
Total Extras		\$90.00

Final Calculation

Total Parts		\$2,706.00
Labour		
Total Panel/Mechanical	\$735.00	
Total Paintwork	\$440.00	
Total Labour		\$1,175.00

Additional Costs

Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$90.00	\$90.00
Total of Additional Costs		\$90.00
Total Paint/Material Costs		\$184.90
Repair Costs Excludes GST		\$4,155.90
Deductions		
Deduction for Excess (Fixed)	-\$700.00	
Total Deductions		-\$700.00
Grand Total Excludes GST (After Deduction)		\$3,455.90
GST @ 7 %		\$241.91
Grand Total Includes GST (After Deduction)		\$3,697.81

Assessment Notes



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: JACK CARS ENTERPRISE PTE LTD

BLK 3007 UBI ROAD 1
#01-450/452
SINGAPORE 408701
SJM7774S

NO: DL19217995
PAGE: 1
DATE: 22/05/2018
A/C CODE: LDJC001
TERMS: CR
P/O NO: sjm7774s

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	T67003-48170	DOOR RR RH	1	750.00	750.00
2	T61601-48030	RR FENDER RH	1	650.00	650.00
3	T81551-48332	RR LAMP UNIT RH	1	300.00	300.00
4	T52159-48220-A0	RR BUMPER	1	700.00	700.00
5	T52115-48110	RR BUMPER BRACKET RH	1	60.00	60.00
6	T52161-16010	CLIP, RR BUMPER	20	1.50	30.00

TOTAL QUANTITY: 25 TOTAL SIN 2,490.00
ADD GST @ 7% 174.30
GRAND TOTAL SIN 2,664.30



Print / KMK / 24/05/2019 9:10:35

SALESMAN: CHAI

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E. GOODS RECEIVED BY



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2018 Sendback Est	24 May 2018 12:58 \$56,926.00	25 May 2018 09:27 Edit Adj Rpt	\$44,155.90 Edit Estimates	\$44,155.90 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

Insured:

CHOO PENG LEONG PHILLIP, ID: S1694707E, Tel: +6597681222, Email: PHILLIPCHOO@YMAIL.COM

Vehicle Reg. No.:

SJM7774S

Date of Loss:

22/05/2018 08:00 - :59
[8 Months and 28 Days From LTA Reg Date (Man Yr)]

Claim Type:

OD / 559323

Policy/Cover Note No.:

A29010337QMX (Comprehensive)
Coverage: 24/08/2017 - 23/08/2018

Excess:

\$4700.00

Repairer:

Jack Cars Enterprise Pte Ltd (HQ) 61 Ubi Avenue 2, #01-20 Automobile Megamart, 408898 Ubi - Tel: 67441900

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/06/2018]

Driver/Custodian:

CHOO PENG LEONG PHILLIP (S2 / Male) , NRIC: S1694707E, Tel: +6597681222 Email: PHILLIPCHOO@YMAIL.COM

Adj Asg. Remarks:

Survey TODAY and REVERT. Car at Blk 3007 Ubi Rd 1 #01-450 5408701 PENDING FOR INSD NRIC & DL

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

• MSIG_SG (04/06/2018): Alert - Adj Mandate Approved (\$4155.90) - SJM7774S - Claim Handler: Kwok Woon C...

• MSIG_SG (31/05/2018): Alert - Adj Mandate Approved (\$0.00) - SJM7774S - Claim Handler: Kwok Woon Choo

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On






























Created On
































Done?

No results.








Claim Documents












SJM7774S (559323)
OD
May 22 2018 8:00AM
[CHOO PENG LEONG PHILLIP]
Jack Cars Enterprise Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View			View in Browser		
Assessment Reports										1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)						Thumbnail	Print			
1	22/05/18 17:26	Accident Statement						 Load HTM				
2	24/05/18 12:40	Addendum Sheet						 Load JPG	<input checked="" type="checkbox"/>			
3	24/05/18 12:41	Accident Statement Addm. #1						 Load HTM				
4	24/05/18 12:58	Repairer Estimates						 Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	28/05/18 17:00	Adjuster Immediate Advice						 Load HTM				
2	31/05/18 14:26	Adjuster Immediate Advice						 Load HTM				
3	31/05/18 18:18	Adjuster Immediate Advice						 Load HTM				
Photos/Images										3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)						Thumbnail	Print			
1	22/05/18 17:25	Accident Photo 1 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
2	22/05/18 17:25	Accident Photo 2 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
3	22/05/18 17:25	Accident Photo 3 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
4	22/05/18 17:25	Accident Photo 4 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
5	22/05/18 17:25	Accident Photo 5 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
6	22/05/18 17:25	Accident Photo 6 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
7	22/05/18 17:25	Accident Photo 7 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
8	22/05/18 17:25	Accident Photo 8 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
9	22/05/18 17:25	Accident Photo 9 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
10	22/05/18 17:25	Accident Photo 9 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
11	22/05/18 17:25	Accident Photo 10 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
12	22/05/18 17:25	Accident Photo 11 [Linked Accident Report Documents]						 Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
2	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
3	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
4	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
5	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
6	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
7	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
8	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
9	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
10	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
11	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			
12	31/05/18 14:38	General View						 Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
13	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
23	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
24	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
25	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
26	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
27	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
28	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
29	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
30	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
31	31/05/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/06/19 17:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	11/06/19 17:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	11/06/19 17:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 16:57	Sketch Plan [Linked Accident Report Documents]	 Load TIFF	
2	22/05/18 16:57	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIFF	
3	22/05/18 16:57	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIFF	
4	24/05/18 17:01	AUDATEX ESTIMATE	 Load PDF	
5	24/05/18 18:37	Copy of Claimant's Identity Card	 Load JPG	<input checked="" type="checkbox"/>
6	31/05/18 15:33	AUDATEX AMENDED ESTIMATE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/18 17:07	SJM 7774S ESTIMATE	 Load PDF	
2	31/05/18 18:19	SJM 7774S JC007774_1.AudatexMS	 Load PDF	
3	25/06/19 10:43	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 17:26	Accident Statement	 Load HTM	
2	24/05/18 12:40	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	24/05/18 12:41	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 17:25	Accident Photo 1	 Load JPG	<input checked="" type="checkbox"/>
2	22/05/18 17:25	Accident Photo 2	 Load JPG	<input checked="" type="checkbox"/>
3	22/05/18 17:25	Accident Photo 3	 Load JPG	<input checked="" type="checkbox"/>
4	22/05/18 17:25	Accident Photo 4	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)		Thumbnail	Print
5	22/05/18 17:25	Accident Photo 5		Load JPG	<input checked="" type="checkbox"/>
6	22/05/18 17:25	Accident Photo 6		Load JPG	<input checked="" type="checkbox"/>
7	22/05/18 17:25	Accident Photo 7		Load JPG	<input checked="" type="checkbox"/>
8	22/05/18 17:25	Accident Photo 8		Load JPG	<input checked="" type="checkbox"/>
9	22/05/18 17:25	Accident Photo 9		Load JPG	<input checked="" type="checkbox"/>
10	22/05/18 17:25	Accident Photo 9		Load JPG	<input checked="" type="checkbox"/>
11	22/05/18 17:25	Accident Photo 10		Load JPG	<input checked="" type="checkbox"/>
12	22/05/18 17:25	Accident Photo 11		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)		Thumbnail	Print
1	22/05/18 16:57	Sketch Plan		Load TIFF	
2	22/05/18 16:57	Sketch Plan #2		Load TIFF	
3	22/05/18 16:57	Sketch Plan #3		Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18009526/GCD3E2

Date: 25/06/2019

REFERENCE

Insured/Claimant: CHOO PENG LEONG PHILLIP

Policy No: A29010337QMX

Date of Loss: 22/05/2018

Nature of Claim: OD

Claim No: 559323

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM7774S**

Make & Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 3ZRC024756

Reg. Date: 24/08/2017 (Man. Year: 2017)

Chassis No: ZSU600110172

Colour: White

Odometer: 12866 km

Engine Capacity: 1986 cc

Market Value/New Car Price: S\$125,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,706.00	2,706.00	0.00	0.00
Miscellaneous Items	200.00	90.00	110.00	55.00
Labour	2,520.00	1,359.90	1,160.10	46.04
Paintwork Labour	1,500.00	0.00	1,500.00	100.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,926.00	4,155.90	2,770.10	40.00
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	6,226.00	3,455.90	2,770.10	44.49
+ GST 7.00/7.00% (S\$)	435.82	241.91	193.91	44.49
Nett Amount (S\$)	6,661.82	3,697.81	2,964.01	44.49

INSPECTION

Date of Assignment: 25/05/2018 Present Location: Jack Cars Enterprise Pte Ltd (HQ)

Date Inspected: 25/05/2018 Inspected At: Jack Cars Enterprise Pte Ltd (HQ)

BLK 3007 UBI ROAD 1 #01-450

SINGAPORE 408700

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM7774S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIGHT DOOR (WCP)	Buckled	750.00 F	*750.00 F
2	1		*REAR RIGHT BUMPER REAR RIGHT FENDER INSTEAD OF REAR RIGHT BUMPER (WCP)	Buckled	650.00 F	*650.00 F
3	1		*REAR BUMPER (WCP)	Cut	700.00 F	*700.00 F
4	1		*REAR RIGHT TAILGATE LIGHT (WCP)	Cracked	300.00 F	*300.00 F
5	1		*REAR RIGHT BUMPER BRACKET (WCP)	Distorted	60.00 F	*60.00 F
					Sub Total (S\$)	2,460.00 2,460.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	246.00 246.00
					Total Parts (S\$)	2,706.00 2,706.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	CLIPS (NECESSARY)	80.00	30.00
2	1	SILICON SEALANT (NECESSARY)	120.00	60.00
Sub Total (S\$)			200.00	90.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,500.00	0.00
<u>Labour Items</u>				
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,900.00	0.00
3	TO CHECK WIRING & REWIRE & WATER TEST	New	120.00	0.00
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	150.00	0.00
5	TO REMOVE AND REINSTALL REAR RIGHT DOOR WINDOW	New	200.00	0.00
6	TO REMOVE & REINSTALL REVERSE SENSOR	New	150.00	0.00
7	PANEL / MECHANICAL	New	-	735.00
8	PAINTWORK	New	-	440.00
9	PAINT / MATERIAL COSTS	New	-	184.90
Gross Labour Cost (S\$)			4,020.00	1,359.90

Report was unsubmitted during this print-out.

< END OF ESTIMATES >