

Repair Estimates

## **ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

| Parts                    | (a) Cost / List Price Items   | \$           | 2,098.00                |                 | 1           | of Nothanz |
|--------------------------|---|--------------|-------------------------|-----------------|-------------|------------|
|                          | Plus/Less10%  | \$           | 209.80                  |                 |             |            |
|                          | Total of Cost / List  | \$           | 1,888.20                |                 |             |            |
|                          | (b) Nett Price Items  |              |                         |                 |             |            |
|                          | Less  |              |                         |                 |             |            |
|                          | Total of Nett Item  |              |                         |                 |             |            |
|                          | (c) Special Nett Items  |              |                         |                 |             |            |
| otal Pa                  | arts Cost   | \$           | 1,888.20                |                 |             |            |
|                          |   | •            | 900.00                  |                 |             |            |
| .abour                   |   | \$           |                         |                 |             |            |
| Labour  Total  The abo   | ove total will be subjected to  | \$           | 2,788.20                |                 |             |            |
| otal<br>The abo          |   | \$           | 2,788.20                | Kenn            | uri la .    |            |
| otal The abo             | ove total will be subjected to  | \$           |                         | Kenn            | ille<br>Cle |            |
| The abo                  | ove total will be subjected to<br>ne of Surveyor  | \$           |                         | Kenn<br>(,      | Clc at      |            |
| Nam Com                  | ove total will be subjected to<br>ne of Surveyor  | \$           |                         | Kenn<br>(,      |             |            |
| Nam Com Surv             | nve total will be subjected to<br>ne of Surveyor<br>npany<br>vey conducted on   | \$ 7% G.S.T. | is not authorized until | 16118           |             |            |
| Nam Com Surv Rem (a)     | ne of Surveyor npany vey conducted on   | \$ 7% G.S.T. | 4                       | further notice. |             |            |
| Nam Com Surv Rem (a)     | ne of Surveyor npany vey conducted on narks By Surveyor The repair of this vehicle is                                 | \$ 7% G.S.T. | is not authorized until | further notice. | at          |            |
| Nam Com Surv Rem (a) (b) | ne of Surveyor npany vey conducted on narks By Surveyor The repair of this vehicle is Recommended Days of Re Resurvey | \$ 7% G.S.T. | is not authorized until | further notice. | at          | 8/6/18     |

SDY 2222 J



## **ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

| S | pai | re | P | aı | ts |
|---|-----|----|---|----|----|
|---|-----|----|---|----|----|

| Vehicle No. : | SDY 2222 J        | Submit By        | : | Carmen Lim |
|---------------|-------------------|------------------|---|------------|
| Make & Model: | BMW 320 i         | Year Manufacture | : | 2010       |
| Chassis No :  | WBAPG56040NM25624 | Engine No.       | : |            |
| _             |                   | Coot / Lint      |   |            |

| S/No. | Part Description              |    | Qty | Unit<br>Price                             | Price   | Disposition by<br>Surveyor        |
|-------|-------------------------------|----|-----|---|---|-----------------------------------|
| 1     | Front bumper                  | R  | 1   | \$1,420.00                                |   |                                   |
| 2     | Front bumper clip             | Nn | 10  | \$65.00                                   |   |                                   |
| 3     | Front bumper reinforcement    | N  | 1   | \$285.00                                  |   | X                                 |
| 4     | Front bumper side retainer LH | Sa | 1   | \$30.00                                   |   | /                                 |
| 5     | Front bumper side retainer RH | Sm | 1   | \$30.00                                   |   |                                   |
| 6     | Fog lamp RH                   | J. | 1   | \$193.00                                  |   |                                   |
| 7     | Fog lamp garnish RH           | Sh | 1   | \$75.00                                   | J   |                                   |
| 8     |                               |    |     |   |   |                                   |
| 9     |                               |    |     |   |   |                                   |
| 10    |                               |    |     |   |   |                                   |
| 11    |                               |    | *   |   |   |                                   |
| 12    |                               |    |     | LKK Auto O                                |   |                                   |
| 13    |                               |    |     | the Repairer of t                         | Itants hence notify   |                                   |
| 14    |                               |    |     | To display damage                         | arter spray painting  |                                   |
| . 15  |                               |    |     | Third party suprey :                      | pject to confirmation   | 1                                 |
| 16    |                               |    |     | No illegal modificati     Supplement      | pject to confirmation<br>on a "Without Prejudio<br>on(s) is allowed   | e" basis                          |
| 17    |                               |    |     | is subject to final ap                    | on(s) is allowed<br>(s) must be resurveyed<br>proval from Insurance ( | and                               |
| 18    |                               |    |     | Acknowledged by Rep                       | Birer   | Simpany                           |
| 19    |                               |    |     | Signature:<br>Date:                       |   |                                   |
| 20    |                               |    |     |   |   |                                   |
| 21    |                               |    | 1   | 14 10 10 10 10 10 10 10 10 10 10 10 10 10 |   |                                   |
| 22    |                               |    |     | - Canada pag                              | THE PART CALLSON AND  | To the first with making the same |
| 23    |                               |    |     |   |   |                                   |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## **ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Labour

| Vehicl | e No. :                                  | SDY 2222 J          | Submit By       | : Ca              | rmen Lim          |  |
|--------|--|---------------------|-----------------|-------------------|-------------------|--|
|        | ke & Model : BMW 320 i Year of Manufactu |                     |                 | e:2010            |                   |  |
| S/No   |  | Labour Descript     | ion             | Esimated<br>Price | Adjusted<br>Price |  |
| 1      | TO RENEW DA                              | AMAGED PARTS & KNO  | CK OUT ACCIDENT |                   |                   |  |
|        | REPAIR AREA                              | . (FRONT BUMPER)    |                 | \$400.00          | 1001              |  |
| 2      | TO PUTTY, RE                             | SPRAY PAINT FOR AFF | ECTED ACCIDENT  |                   |                   |  |
|        | REPAIR AREA                              | . (FRONT BUMPER)    |                 | \$400.00          | 2501              |  |
| 3      | To check wiring                          | ]                   | 10              | \$50.00           | ×                 |  |
| 4      | To tuff coat                             |                     | w               | \$50.00           | X                 |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |
|        |  |                     |                 |                   |                   |  |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.