

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG18009540/NZ4D3S2**Date:** 07/06/2018REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800058715
Claimant Vehicle No :	SJY6051M	Insured Vehicle No :	SJT7642C
Date of Loss:	21/05/2018	Nature of Claim:	TP
		Claim No:	5087424937SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY6051M		
Make & Model:	MITSUBISHI COLT, 1.5 RALLIART VERSION-R (M)	Engine No:	4G15HS7306
Reg. Date:	02/03/2007 (Man. Year: 2006)	Chassis No:	Z27A0400389
Colour:	White	Odometer:	278085 km
Engine Capacity:	1468 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/45R16	Rear Tyre Size:	205/45R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	RePAIRer's	ADJuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/05/2018		
Date Inspected:	30/05/2018	Inspected At:	Avis Management 8 Kaki Bukit Ave 4 #05-01/02
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Missing	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Missing	0.00 F	*- F
3	1		*REAR BUMPER	Damaged	0.00 F	*- F
4	1		*REAR BUMPER LOWER	Broken	0.00 F	*- F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*REAR BUMPER BRACKET	Dented	0.00 F	*- F
7	1		*REAR BUMPER PROTECTOR	Cut	0.00 F	*- F
8	1		*REAR BUMPER MOULDING	Broken	0.00 F	*- F
9	1		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
10	1		*REAR END PANEL	Dented	0.00 F	*- F
11	1		*BOOTLID	Dented	0.00 F	*- F
12	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID HANDLE	Scratched	0.00 F	*- F
14	1		*REAR EXHAUST PIPE	Cut	0.00 F	*- F
15	1		*REAR RH FENDER PROTECTOR	Scratched	0.00 F	*- F
16	1		*FRT NUMBER PLATE	Broken	0.00 F	*- F
17	1		*FRT NUMBER PLATE BASE	Broken	0.00 F	*- F
18	1		*FRT BUMPER	Cut	0.00 F	*- F
19	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
20	1		*FRT BUMPER LOWER SPOILER	Broken	0.00 F	*- F
21	1		*FRT GRILLE EMBLEM	Cut	0.00 F	*- F
22	1		*FRT SUPPORT PANEL	Dented	0.00 F	*- F
23	1		*BONNET	Repair	0.00 F	*- F
24	1		*FRT LH FENDER	Repair	0.00 F	*- F
25	1		*FRT LH FENDER PROTECTOR	Cracked	0.00 F	*- F
26	1		*FRONT BUMPER AIR INTAKE	Deformed	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >