

Supervisor:

ASSIGNMENT (Office)

CWS

From (Person):

Serene Ler

of

FCI

Date/Time:

25/5/18 @ 2:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 9282P

Insured:

SHD 4939A

at Workshop m/s

SME Motor

Tel:

6747 6106

of

1 Kaki Bukit Ave 6 Blk D # 02-15

Policy No:

Claim No:

D18004183MFSTH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A

23/05/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

4:09pm @ 25/5/18

Person Contacted:

Sebastian

Vehicle IN / OUT

(OUT)

Date/Time	Action/Instruction (✓) Estimate
	SJU 9282P - NA / III13009829/r3 DOA: 1/06/13
	SHD 4939A - CC3/AIG/6014074/H/ph3g2 DOA: 26/07/16
05/6/18 @ 2:21pm	Informed Serene, we are pending estimate from repairer.
21/6/18 @ 4:24pm	Vehicle visited to Serene by email.
21/6/18 @ 9:16am	Quotation confirmed with Yung US \$3300, 7 days. by email. (Ltd \$1495.40, 31%)

REF: FCI

9734A

ASSIGNMENT

From: _____ Date: 4/6/18

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 9282 P
at Workshop m/s: SME Motor
of: 1 kaki Bukit Ave 6 #02-15

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: 7 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJU 9282 P Yr Regn: 2010 / Jun 04

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Honda Fit 136A c.c. 1339

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 70421 T/Radio: Insured / Std / NI / NA

Eng/No: _____

Cr/No: 6E61197403

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15
R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	04/06/18

Survey held at: SME

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 2 JUN 2018

Date/Time: File Pass to? : Preli. Report1) 2/6 trans : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ - RE \$

) Photo

) Other

TOTAL

Report Format: TP

Lump Sum / I.B.A. 3300

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

135

50

50

39

274



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004183MFSH

Date: 21 June 2018

Our Ref: CS/FCI18009557/Aqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJU 9282P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/06/2018 at the premises of M/s SME MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,607.40</u>
Revised Estimate Amount	: S\$ <u>3,300.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	24-05-2018	Our Ref No. D18004183MFSH
Accident Date	23-05-2018	Claim Type. Third Party
Insured Vehicle	SHD4939A	Third Party Vehicle. SJU9282P
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY @ KAKI BUKIT	
Contact Person.	PEIYING	
Contact No.	67476106/ 0	Fax No. 67442368
Survey Type	DIRECT SETTLEMENT: EST. COR - \$4,929.92	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240753)



PRI Documents



Close



PRI Header Details

Claim No	D18004183MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & SME MOTI
Workshop Name	SME MOTOR PTE LTD (Contact Person : PEIYING)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY (Mobile: 0 , Phone: 67476106 , Fax: 67442368 EmailId: PEIYING@SMEMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR - \$4,929.92		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4939A	TP Vehicle No	SJU9282P
PRI Recieved Date	24-05-2018 08:13:29 PM	Surveyor Appointed Date	25-05-2018 02:42:52 PM	Surveyor Accept Date	25-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	25-05-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

Shiau Chan (LKKAuto)

From: Ying <ying@smemotor.com.sg>
Sent: Thursday, 21 June 2018 9:16 AM
To: Shiau Chan (LKKAuto); Adrian Ling (LKKAuto)
Cc: SUR
Subject: Re: SJU9282P pending for finalise

Hi Shiau Chan,

Amount confirmed.

Thanks & Regards

Ying
SME MOTOR PTE LTD
1 Kaki Bukit Ave 6,
Blk D, #02-15/16/17/18
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6747 6106 (6 Lines)
Fax: 6744 2368

From: Shiau Chan (LKKAuto)
Sent: Wednesday, June 20, 2018 5:43 PM
To: Ying ; Adrian Ling (LKKAuto)
Cc: SUR
Subject: RE: SJU9282P pending for finalise

Dear Ying,

Offer Lump Sum \$3,300.00 before GST and 7 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ying [mailto:ying@smemotor.com.sg]
Sent: Wednesday, 20 June 2018 5:03 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: SJU9282P pending for finalise

hi Adrian,

Please refer to the attached, kindly check and confirm.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 21 June 2018 4:24 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004183MFSH/1
Attachments: CSFCI18009557Aqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SJU 9282P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 5 June 2018 2:21 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004183MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SJU 9282P on 04/06/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 25 May 2018 3:52 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004183MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 5 June 2018 2:21 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004183MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SJU 9282P on 04/06/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 25 May 2018 3:52 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004183MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 25 May 2018 2:43 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004183MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD #16-01
 CITY HOUSE
 Singapore 068877
TEL: 65073848 **FAX:** 65073849
ATTN: Motor Claim Department
Your Ref No: 18/FC/TP-105 (05)
Claim Type: Third Party
Accident Date: 23/05/2018
TP Veh Reg No: SHD4939A

Estimate No: EST0004138
Date: 24 May 2018
Policy No: 8-V0012171-MVA-R002
Veh Reg No: SJU9282P
Make/Model: HONDA FIT
Chasis No: GE61197403
Engine No:
Reg. Date:

Estimate Repair Cost to Vehicle No :SJU9282P

Description	Quantity	List Price SS	Amount SS
List Price			
1 REAR WINDSCREEN MOULDING <i>n</i>	2 PC	90.00 ✓	
2 REAR GATE <i>Dented</i>	1 PC	767.00 ✓	
3 REAR GATE LOGO <i>new</i>	1 PC	34.00 +	
4 REAR GATE EMBLEM 'FIT' <i>new</i>	1 PC	35.00 ✓	
5 REAR GATE LOCK <i>Right</i>	1 PC	185.00 ✓	
6 REAR GATE INNER RUBBER <i>cut</i>	1 PC	95.00 ✓	
7 REAR BUMPER <i>Dislodged</i>	1 PC	475.00 ✓	
8 REAR BUMPER RETAINER <i>n</i>	2 PC	40.00 ✓	
9 REAR BUMPER CLIP <i>n</i>	10 PC	55.00 ✓	
10 REAR END PANEL <i>Dented</i>	1 PC	289.00 ✓	
11 REAR END PANEL TOP GARNISH <i>replaced</i>	1 PC	65.00 ✓	
12 REAR END PANEL TOP GARNISH CLIP <i>n</i>	8 PC	44.00 ✓	
13 REAR BUMPER TOW COVER <i>missing</i>	1 PC	19.00 ✓	
14 TAIL LAMP LH <i>new</i>	1 PC	210.00 +	
15 Tool Box (Sponge) <i>form</i>		2,403.00	
	Less 20%	480.60	1,922.40
Special Net			
15 REAR WINDSCREEN GUM <i>new</i>	1 PC	40.00 ✓	
16 REAR NUMBER PLATE <i>new</i>	1 PC	40.00 30	
17 REAR REVERSE SENSOR <i>new</i>	1 PC	250.00 200	
		330.00	330.00
Labour			
18 WIRE CHECKING	1 UNIT	20.00 ✓	
19 REMOVE & REFIX REAR WINDSCREEN	1 UNIT	120.00 100	
20 TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	1 UNIT	100.00 80	
21 REMOVE & REFIX REAR GATE UPHOLSTERY TO FACILITATE REPAIR	1 UNIT	100.00 60	
22 CAVITY PROTECTION ON ALL AFFECTED AREA	1 UNIT	100.00 50	
23 LTA CHARGE	1 UNIT	65.00 ✓	
24 LABOUR CHARGE	1 UNIT	1,000.00 800	
25 SPRAY PAINTING	1 UNIT	850.00 800	
		2,355.00	2,355.00

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO.201119451E

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 18/FC/TP-105 (05)

Claim Type: Third Party

Accident Date: 23/05/2018

TP Veh Reg No: SHD4939A

Estimate No: EST0004138

Date: 24 May 2018

Policy No: 8-V0012171-MVA-R002

Veh Reg No: SJU9282P

Make/Model: HONDA FIT

Chasis No: GE61197403

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :SJU9282P

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
		Total	SS 4,607.40
		Add GST @ 7%	322.52
		Total Amount Payable	SS 4,929.92

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND NINE HUNDRED TWENTY NINE AND CENTS NINETY TWO ONLY

For SME Motor Pte Ltd

Adrian Lij
1/5 DA/06/18
079yr.

AUTHORISED SIGNATURE

total: 4160.20
4/c: 3.3K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4795.60

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : GOH YEOW SENG

Singapore

ATTN:

Your Ref No: 18/FC/TP-105 (05)

Claim Type: Third Party

Accident Date: 23/05/2018

TP Veh Reg No: SHD4939A

Estimate No: EST0004138

Date: 20 Jun 2018

Policy No: 8-V0012171-MVA-R002

Veh Reg No: SJU9282P

Make/Model: HONDA FIT

Chasis No: GE61197403

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :SJU9282P

Description	Quantity	List Price	Amount
		SS	SS
Supplementary Parts to Repair			
List Price			
1 REAR TOOLS SPONGE BOX	1 PC	235.00	235.00
			Turn
	Less 20%	47.00	188.00
Total			SS 188.00
GST Amount			SS 13.16
Total Amount Payable			SS 201.16

List 23914
 - 20% 1915.20
 SN 270
 LC 1975

 4160.20

US 3350
 =

20/06/2018

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD #16-01
 CITY HOUSE
 Singapore 068877
 TEL: 65073848 FAX: 65073849
 ATTN: Motor Claim Department
 Your Ref No: 18/FC/TP-105 (05)
 Claim Type: Third Party
 Accident Date: 23/05/2018
 TP Veh Reg No: SHD4939A

Estimate No: EST0004138
 Date: 24 May 2018
 Policy No: 8-V0012171-MVA-R002
 Veh Reg No: SJU9282P
 Make/Model: HONDA FIT
 Chasis No: GE61197403
 Engine No:
 Reg. Date:

Estimate Repair Cost to Vehicle No :SJU9282P

Description	Quantity	List Price S\$	Amount S\$
List Price			
1 REAR WINDSCREEN MOULDING <i>~</i>	2 PC	90.00 ✓	
2 REAR GATE <i>Painted</i>	1 PC	767.00 ✓	
3 REAR GATE LOGO <i>Painted</i>	1 PC	31.00 ✓	
4 REAR GATE EMBLEM 'FIT' <i>~</i>	1 PC	35.00 ✓	
5 REAR GATE LOCK <i>Painted</i>	1 PC	185.00 ✓	
6 REAR GATE INNER RUBBER <i>cut</i>	1 PC	95.00 ✓	
7 REAR BUMPER <i>Disassembled</i>	1 PC	475.00 ✓	
8 REAR BUMPER RETAINER <i>~</i>	2 PC	40.00 ✓	
9 REAR BUMPER CLIP <i>~</i>	10 PC	55.00 ✓	
10 REAR END PANEL <i>Painted</i>	1 PC	289.00 ✓	
11 REAR END PANEL TOP GARNISH <i>Painted</i>	1 PC	65.00 ✓	
12 REAR END PANEL TOP GARNISH CLIP <i>~</i>	8 PC	44.00 ✓	
13 REAR BUMPER TOW COVER <i>Missing</i>	1 PC	19.00 ✓	
14 TAIL LAMP LH <i>~</i>	1 PC	210.00 ✓	
<i>Rev tail sponge box \$235. ±</i>			
		2,403.00	
	Less 20%	480.60	1,922.40
Special Net			
15 REAR WINDSCREEN GUM <i>~</i>	1 PC	40.00 ✓	
16 REAR NUMBER PLATE <i>~</i>	1 PC	40.00 <i>30</i>	
17 REAR REVERSE SENSOR <i>Painted</i>	1 PC	250.00 <i>200</i>	
		<i>290</i> 330.00	330.00
Labour			
18 WIRE CHECKING	1 UNIT	20.00 ✓	
19 REMOVE & REFIX REAR WINDSCREEN	1 UNIT	420.00 <i>100</i>	
20 TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	1 UNIT	100.00 <i>30</i>	
21 REMOVE & REFIX REAR GATE UPHOLSTERY TO FACILITATE REPAIR	1 UNIT	100.00 <i>60</i>	
22 CAVITY PROTECTION ON ALL AFFECTED AREA	1 UNIT	100.00 <i>50</i>	
23 LTA CHARGE	1 UNIT	65.00 ✓	
24 LABOUR CHARGE	1 UNIT	1,000.00 <i>80</i>	
25 SPRAY PAINTING	1 UNIT	850.00 <i>800</i>	
		2,355.00	2,355.00

1925

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 18/FC/TP-105 (05)

Claim Type: Third Party

Accident Date: 23/05/2018

TP Veh Reg No: SHD4939A

Estimate No: EST0004138

Date: 24 May 2018

Policy No: 8-V0012171-MVA-R002

Veh Reg No: SJU9282P

Make/Model: HONDA FIT

Chasis No: GE61197403

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :SJU9282P

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
		Total	S\$ 4,607.40
		Add GST @ 7%	322.52
		Total Amount Payable	S\$ 4,929.92

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND NINE HUNDRED TWENTY NINE AND CENTS NINETY TWO ONLY

For SME Motor Pte Ltd

Adrian Lij
M/S 0A/06/18
079yr.

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009557/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4939A	Veh. Inspected	SJU 9282P
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004183MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	25/05/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT 1.3G A	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	GE61197403	Colour	BLUE
Odometer	70421	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	MICHELIN	6 mm
L/H Front Tyre	185/60 R15	MICHELIN	6 mm
R/H Rear Tyre	185/60 R15	MICHELIN	6 mm
L/H Rear Tyre	185/60 R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/05/2018	Inspection Date	04/06/2018
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 9282P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	REAR WINDSCREEN MOULDING	NECESSARY	90.00	90.00
1	REAR GATE	DENTED	767.00	767.00
1	REAR GATE LOGO	NOT NECESSARY	34.00	-
1	REAR GATE EMBLEM "FIT"	NECESSARY	35.00	35.00
1	REAR GATE LOCK	DAMAGED	185.00	185.00
1	REAR GATE INNER RUBBER	CUT	95.00	95.00
1	REAR BUMPER	DISTORTED	475.00	475.00
2	REAR BUMPER RETAINER	NECESSARY	40.00	40.00
10	REAR BUMPER CLIP	NECESSARY	55.00	55.00
1	REAR END PANEL	DENTED	289.00	289.00
1	REAR END PANEL TOP GARNISH	DEFORMED	65.00	65.00
8	REAR END PANEL TOP GARNISH CLIP	NECESSARY	44.00	44.00
1	REAR BUMPER TOW COVER	MISSING	19.00	19.00
1	TAIL LAMP LH	NOT NECESSARY	210.00	-
1	REAR TOOLS SPONGE BOX (ADDITIONAL)	TORN	235.00	235.00
	LESS 20% DISCOUNT		-527.60	-478.80
			2,110.40	1,915.20
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN GUM (SN)	NECESSARY	40.00	40.00
1	REAR NUMBER PLATE (SN)	NECESSARY	40.00	30.00
1	REAR REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
			330.00	270.00
LABOUR				
	WIRE CHECKING.		20.00	20.00
	REMOVE & REFIX REAR WINDSCREEN.		120.00	100.00
	TRANSFER REAR GATE COMPONENT FROM OLD TO NEW.		100.00	80.00
	REMOVE & REFIX REAR GATE UPHOLSTERY TO FACILITATE REPAIR.		100.00	60.00
	CAVITY PROTECTION ON ALL AFFECTED AREA.		100.00	50.00
	LTA CHARGE.		65.00	65.00

Report Ref No. CS/FC118009557/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGE.		1,000.00	800.00
	SPRAY PAINTING.		850.00	800.00
			2,355.00	1,975.00
	GRAND TOTAL		4,795.40	4,160.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00

Report Ref No. CS/FCI18009557/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.