

CHUNNI MOTOR WORK PTE LTD

To Survey by LKK

REPAIR ESTIMATE*

VEHICLE NO : SHA 3039U

DATE : 25.05.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper Cvt			\$ 603.60 ✓
	Rear Bumper Clip 10 pcs N/C			\$ 22.00 ✓
	Rear Bumper Bracket, RH S/C			\$ 49.00 X
	Tail Lamp (RH) new mounting crack			\$ 565.60 X ✓
	Rear Fender With Housing (RH) N/C			\$ 4,736.80 ✓
	Rear Fender Inner Lining (RH) deformed			\$ 164.40 ✓
	Rear Fender Air-Duct N/C			\$ 51.60 X
	Rear Windscreen Moulding N/C			\$ 60.00 ✓
	Rear Tyre Rim (RH) distorted			\$ 351.90 2 ✓
	Rear Wheel Hub-Cap (RH) crack			\$ 150.70 ✓
	Rear Wheelbearing IN & Hub Distorted			\$ 401.40 2 ✓
	Rear Trailing Arm (RH) distorted			\$ 120.00 2 ✓
	Rear Assist (RH) distorted			\$ 120.00 2 ✓
	Rear Shock Absorber (RH) distorted			\$ 342.20 2 ✓
	Rear Shock Absorber Mounting (RH) N/C			\$ 57.70 X
	Rear Crossmember distorted			\$ 1,190.00 2 ✓
	Stabilizer Bar distorted			\$ 204.60 2 ✓
	Stabilizer Link distorted			\$ 68.15 2 ✓
	Rear Upper Arm (RH) distorted			\$ 335.75 2 ✓
	Rear Lower Arm (RH) distorted			\$ 204.35 2 ✓
	Rear Knuckle Arm (RH) distorted			\$ 574.80 2 ✓
	SUB TOTAL			\$ 10,374.55
	LESS 20%			\$ 2,074.91
	DISCOUNTED TOTAL			\$ 8,299.64
	Rear Bumper Rubber Mat N/C			\$ 50.00 Nett ✓
	Rear Windscreen Sealant N/C			\$ 46.00 Nett ✓
	Rear Tyre (RH) S/C			\$ 216.00 Nett X
				\$ 312.00
	Labour Charge			
	Panel Beating			\$ 1,200.00 600 700/r
	Spray Painting Charge			\$ 750.00 500 500/r
	Wiring Charge			\$ 50.00 N/C
	Tuff Kote			\$ 50.00 30/r
	Towing Charge			\$ 50.00 N/C
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/r
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/r
	Remove/Refix Reverse Sensor			\$ 120.00 40/r
	Remove/Refix Undercarriage (RR)			\$ 400.00 180/r
	Rear Wheel Alignment			\$ 120.00 60/r
	TOTAL LABOUR			\$ 3,010.00
	ESTIMATE TOTAL			\$ 11,621.64