



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CRANE (548234)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	GLASS	CRACKED	3,950.00	3,950.00
1	TRIM	NECESSARY	340.00	340.00
1	WEDGE	NECESSARY	106.00	106.00
			4,396.00	4,396.00
	<u>LABOUR</u>			
	BEING SUPPLY OF MANPOWER TO REPAIR THE CRANE CABIN.		2,000.00	900.00
	TOWING CHARGES FROM TUAS SOUTH LINK 1 TO 18 KRANJI ROAD.	* CHECK	500.00	-
	BEING LOST OF USAGE (ESTIMATED (02) MONTHS RENTAL STARTING FROM 10/05/2018)	* CHECK	12,000.00	-
	**SUBJECT TO CHANGE BASE ON RENTAL PERIOD.			
			14,500.00	900.00
	GRAND TOTAL		18,896.00	5,296.00

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$12,500.00 NETT)			5,296.00
LESS EXCESS			-5,000.00
NETT LIABILITY			296.00

Report Ref No. CS/MSG18009634/R1cf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CRANE (548234)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF REAR PARTS</u>			
1	GLASS	CRACKED	3,840.00	3,840.00
1	TRIM	NECESSARY	437.00	437.00
1	WEDGE	NECESSARY	85.00	85.00
			4,362.00	4,362.00
	<u>LABOUR</u>			
	BEING SUPPLY OF MANPOWER TO REPAIR THE CRANE CABIN.		2,000.00	900.00
	TOWING CHARGES FROM TUAS SOUTH LINK 1 TO 18 KRANJI ROAD.	* CHECK	500.00	-
	BEING LOST OF USAGE (ESTIMATED (02) MONTHS RENTAL STARTING FROM 10/05/2018)	* CHECK	12,000.00	-
	**SUBJECT TO CHANGE BASE ON RENTAL PERIOD.			
			14,500.00	900.00
	GRAND TOTAL		18,862.00	5,262.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$12,500.00 NETT)			5,262.00
	LESS EXCESS			-5,000.00
	NETT LIABILITY			262.00

Report Ref No. CS/MSG18009634/R1cf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.