



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009634/R1cf3e2

4 SHENTON WAY #21-01,SGX
CENTRESINGAPORE 068807

Date : 24-07-2020



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	CRANE (548234)
Policy No.	29070262MAR	Coverage (\$)	0.00
Claim No.	558096	Excess (\$)	5,000.00
Assign From	NG KEET WAI	Assign Date	28/05/2018

2. Vehicle Particulars & Condition

Make & Model	CRANE	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	548234	Colour	MULTI COLOUR
Odometer	847	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	29.5-25	YOKOHAMA	8 mm
L/H Front Tyre	29.5-25	YOKOHAMA	8 mm
R/H Rear Tyre	29.5-25	YOKOHAMA	8 mm
L/H Rear Tyre	29.5-25	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE ROOFTOP PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/05/2018	Inspection Date	30/05/2018
Survey held at	20 TUAS SOUTH AVE 14 SINGAPORE 637312		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR :	4 Working Days
ESTIMATED NORMAL PERIOD FOR REPAIR :	4 Working Days