Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC3/III18009639/KBA3Q2 Our File No:

Date: 09/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd M492470 Policy No: Claimant

SHD9604H Insured Vehicle No: **GBC1904X** Vehicle No:

Date of Loss: 07/05/2018 Nature of Claim: TP Claim No: MC20182386

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD9604H Reg No:

Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: Z20S1456231K Chassis No: Reg. Date: 27/07/2012 (Man. Year: 2011) KL1LA69RJBB100125

Colour: Red/White Odometer: 244563 km

Engine Capacity: 1991 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Giti 8 mm Rear Left Side: Giti 8 mm Front Right Side: Rear Right Side: Giti 8 mm Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,473.89	2,561.16	7,912.73	75.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,460.00	810.00	9,650.00	92.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,933.89	3,371.16	17,562.73	83.90
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	20,933.89	2,700.00	18,233.89	87.10
+ GST 7.00/7.00% (S\$)	1,465.37	189.00	1,276.37	87.10
Nett Amount (S\$)	22,399.26	2,889.00	19,510.26	87.10
+ Loss of Use (5.0 x S\$	40.00/day) (S\$)	200.00		
+ Car Rental (5.0 x S\$	+ Car Rental (5.0 x S\$75.25/day) (S\$)			
+ Doc/Search Fee (S\$)		7.49		
Ne	tt Liability (S\$)	3,472.74		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment: 10/05/2018

Date Inspected: 10/05/2018 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Adjuster Report Page 2 of 5

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference					
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2020)			
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	(Unsubmitted, no print-code for SHD9604H)				
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.					

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	837.60 FL	*-FL
2	1		*FRONT FENDER LINER LH	Serviceable	47.00 FL	*-FL
3	1		*FENDER INSULATION LH	Serviceable	39.00 FL	*- FL
4	1		*FRONT FENDER INNER WHEEL HOUSE PANEL LH	Repair	1,437.00 FL	*-FL
5	1		*FRONT DOOR LH	Bent	1,133.00 FL	*1,133.00 FL
6	1		*FRONT DOOR GLASS GUIDE RH CHROME MOULDING	Serviceable	60.00 FL	*-FL
7	1		*FRONT DOOR OUTER MOULDING	Dented	220.00 FL	*220.00 FL
8	1		*FRONT DOOR OUTER HANDLE	Broken	125.00 FL	*125.00 FL
9	1		*FRONT DOOR HANDLE SUPPORT	Missing	3.00 FL	*3.00 FL
10	1		*FRONT DOOR OUTER HANDLE INNER SEAL	Necessary	89.15 FL	*89.15 FL
11	1		*FRONT DOOR OUTER KEY LOCK	Serviceable	25.00 FL	*-FL
12	1		*FRONT DOOR HINGE UPPER	Repair	65.00 FL	*-FL
13	1		*FRONT DOOR HINGE LOWER	Repair	65.00 FL	*-FL
14	1		*FRONT DOOR INNER LOCK	Repair	586.00 FL	*-FL
15	1		*FRONT DOOR INNER LOCK LATCH LH	Repair	206.00 FL	*-FL
16	1		*FRONT DOOR CHECK /ARRESTOR	Serviceable	67.50 FL	*-FL
17	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	138.79 FL	*-FL
18	1		*FRONT DOOR GLASS CHANNEL WEATHERSTRIP	Serviceable	160.00 FL	*-FL
19	1		*FRONT DOOR INNER TRIM BOARD	Serviceable	455.69 FL	*-FL
20	1		*FRONT DOOR WINDOW GLASS	Serviceable	456.12 FL	*-FL
21	1		*FRONT DOOR POWER WINDOW MOTOR (MASTER) LH		284.97 FL	*- FL
22	1		*FRONT DOOR POWER WINDOW MOTOR SWITCH	Serviceable	145.00 FL	*-FL
23	1		*FRONT DOOR WINDOW REGULATOR GEAR LH	Bent	84.58 FL	*84.58 FL
24	1		*FRONT DOOR OUTER PILLAR PANEL LH	Repair	715.00 FL	*-FL
25	1		*FRONT DOOR PILLAR INNER PANEL LH	Repair	850.00 FL	*-FL
26	1		*FRONT DOOR CENTER PILLAR PANEL LH	Repair	698.15 FL	*-FL
27	1		*FRONT SIDE VIEW MIRROR ASSY LH	Broken		*1,191.00 FL
28	1		*REAR DOOR RH (PANEL A-RR DR LH)	Repair	1,133.00 FL	*-FL
29	1		*SET FRONT BUMPER FASTENER CLIP	Not Necessary	24.00 FS	*-FS
30	1		*SET FRONT LICENCE PLATE WITH HOLDER	Not Necessary	192.00 FS	*-FS
31	1		*SET RADIATOR GRILLE CLIP	Not Necessary	35.00 FS	*-FS
32	1		*SET FRONT FENDER LINER CLIP	Not Necessary	30.00 FS	*-FS
33 F=Fra	1 anchise	part. S=S	*FRONT FENDER RR BRACKET RH SpcNett. L=ListItemDisc.	Repair	7.10 FS	*-FS
			•	Sub Total (S\$)	11,605.65	2,845.73
			- List Item Discount on L Items 1	• •	•	284.57
_				Total Parts (S\$)	10,473.89	2,561.16
			Report was unsubmitted during this pr	int-out.		

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars		Condition	Repairer's	Amount
						,	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	4,500.00	250.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,000.00	400.00
4	TOWING FEES	New	120.00	50.00
5	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
12	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labou	r Cost (S\$)	10,460.00	810.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >