

ASS. REC. BY:

REF:

CS3/EG118009640/Kp4dB<sup>52</sup>

Special Instruction:

Surveyor:

Guo Zhong

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

28/5/2018 @ 9:46am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 8930M

Insured:

YK 118X

at Workshop m/s

Michelin Engineering

Tel:

8181 0737

of

56 Loyang way #06-07

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp

06062018

H.O.D. Endorsement:

Date/Time:

10:37am @ 28/5/18

Person Contacted:

Nizam

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

GBE 8930M-X

YK 118X-X

18/6/18

After Repair

PRS

REF: EGS

C1635R

## ASSIGNMENT

From:

Date:

6/6/18

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GIB E 8930M

at Workshop m/s:

Michelin Engineering

of

56 lajeng way #06-07

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

1 up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GIB E 8930M Yr Regn: 18 Apr 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

CC

2982

Colour:

silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

103209

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDH 2010182 802

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ N/S / Rim / STD A/Rim or

Tyre Size:

F:

155 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GST

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

06-06-18

Survey held at

w/s

12:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt N/S

The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

Estimated repair range \$3,000 - \$4,000

  
 20/6/2018

Date/Time File Pass to?

☐  
☐

Preli. Report

Final Report

1)

Date/Time File Return to?

2)

Report Format :

Lump Sum / L.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐  
☐  
☐  
☐

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

Y S + RS S

Photos

Others

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS3/EGI18009640/Gz4d3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 28-05-2018



Code : EGI

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YK 118X	Veh. Inspected	GBE 8930M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	28/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

## 5. General Information

Accident Date	23/05/2018	Inspection Date
Survey held at	MICHELIN ENGINEERING PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775	

## 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Monday, 28 May 2018 9:46 AM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : YK118X / TP : GBE8930M/LKK / DOA : 23/05/2018  
**Attachments:** YK18X - SAS.pdf; GBE8930M - SAS.pdf; RE: ERGO Insured YK18X [EAL.2018.5683.MK.ya - GBE8930M] (14.6 KB)

Dear Catherine,

We have rejected to their PRS list, please assist to conduct this survey **EAST ASIA LAW CORPORATION**,

ADDRESS : MICHELIN ENGINEERING PTE LTD  
56 LOYANG WAY  
#06-07 LOYANG ENTERPRISE BUILDING  
SINGAPORE 508775

PERSON TO CONTACT : MALCOLM @ 8181 0737

ERGO OFFICER-IN-CHARGE : STEVE LIM

*Note: To survey on without prejudice basis. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.*

Please update the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18009640/Gz4d3s2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 22-06-2018		
FIVESINGAPORE 038985		Code: EGI		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	YK 18X	Veh. Inspected	GBE 8930M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CDMCG18000098	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	28/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDH2010182802	Colour	SILVER	
Odometer	103209 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15	GST	5 mm	
L/H Front Tyre	195 R15	GST	5 mm	
R/H Rear Tyre	195 R15	GST	5 mm	
L/H Rear Tyre	195 R15	GST	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
<b>5. General Information</b>				
Accident Date	23/05/2018	Inspect Date / Time	06/06/2018 ( 12:30 PM )	
Survey held at	MICHELIN ENGINEERING PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000- \$4,000				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	

Report Ref No. CS3/EGI18009640/Gz4d3s2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.