

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG18009647/GZ4D3S2**Date:** 11/07/2018REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100505524
Claimant Vehicle No :	SDH6699F	Insured Vehicle No :	SJR3637E
Date of Loss:	26/05/2018	Nature of Claim:	TP
		Claim No:	7546359516SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH6699F	Engine No:	HIDDEN
Make & Model:	VOLKSWAGEN GOLF A7, 1.4 (A)	Chassis No:	WVWZZZ1KZAW367197
Reg. Date:	01/01/1990 (Man. Year: 1990)	Odometer:	136814 km
Colour:	Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/05/2018	Inspected At:	No.25 Kaki Bukit Rd4 #03-39 Synergy Repairer: Verve Motor Clinic 10 Kaki Bukit Rd 2 Singapore 417868
Date Inspected:	28/05/2018		
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR NUMBER PLATE	Broken	0.00 F	*- F	
2	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*- F	
3	1		*REAR BUMPER	Deformed	0.00 F	*- F	
4	1		*REAR BUMPER LOWER	Deformed	0.00 F	*- F	
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
6	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F	
7	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F	
8	1		*REVERSE SENSOR	Damaged	0.00 F	*- F	
9	1		*REAR END PANEL	Dented	0.00 F	*- F	
10	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F	
11	1		*REAR RH TAILLAMP	Cut	0.00 F	*- F	
12	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F	
13	1		*REAR BUMPER BRACKET	Deformed	0.00 F	*- F	
14	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F	
15	1		*TAILGATE	Bent	0.00 F	*- F	
16	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F	
17	2		*TAILGATE LAMP	Cracked	0.00 F	*- F	
18	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F	
19	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F	
20	1		*TAILGATE LOCK	Dented	0.00 F	*- F	
21	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F	
22	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*- F	
23	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F	
24	1		*REAR LH FENDER INNER TRIM	Deformed	0.00 F	*- F	
25	1		*REAR RH FENDER INNER TRIM	Deformed	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >