

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 1022K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR NUMBER PLATE LAMP ASSY (CONSISTENT)	SERVICEABLE	61.56	-
2	TAILLAMP ASSY (LH&RH) @\$180.00 (CONSISTENT)	N/S CRACKED	360.00	180.00
1	TAILGATE (CONSISTENT)	BENT	1,750.00	1,750.00
2	TAILGATE SAFETY LOCK (LH&RH) @\$380.00 (CONSISTENT)	N/S BENT	760.00	380.00
2	TAILGATE RUBBER STOPPER @\$30.00 (CONSISTENT)	N/S MISSING	60.00	30.00
1	TAILGATE "MITSUBISHI" STICKER (CONSISTENT)	NECESSARY	150.00	150.00
1	N/S SIDE GATE (CONSISTENT)	BENT	2,440.00	2,440.00
	LESS 25% DISCOUNT		-1,395.39	-1,232.50
			4,186.17	3,697.50
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)(CONSISTENT)	SERVICEABLE	40.00	-
1	REAR REINFORCEMENT BEAM (SN)(CONSISTENT)	BENT	600.00	600.00
1	REAR STEP PANEL (SN)(CONSISTENT)	BENT	100.00	100.00
1	TAILGATE "60KM/H" STICKER (SN)(CONSISTENT)	NECESSARY	25.00	15.00
1	TAILGATE "21 PAX" STICKER (SN)(CONSISTENT)	NECESSARY	25.00	15.00
1	TAILGATE INNER TRIM WOODEN (SN)(CONSISTENT)	CRACKED	200.00	200.00
1	N/S SIDE GATE COMPANY ADVERTISEMENT STICKER (SN)(CONSISTENT)	NECESSARY	300.00	200.00
			1,290.00	1,130.00
	<u>LABOUR</u>			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.		700.00	540.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		800.00	600.00
	TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	20.00
			1,550.00	1,160.00
	GRAND TOTAL		7,026.17	5,987.50

RECOMMENDED COST OF LUMP SUM REPAIRS		4,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/AXA14008437/Kea3s2-1





Report Ref No. CC6/AXA14008437/Kea3s2-1

KONG SENG CHEONG

Licensed Appraiser