

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120**Our File No:** CC3/AIG18009702/ASD3E2**Date:** 15/07/2019REFERENCE

Insured/Claimant:	ONG SWEE SENG, RAYMOND	Policy No:	1700065210
Date of Loss:	25/05/2018	Nature of Claim:	OD Claim No: 2742446143SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1093C		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	CVK047034
Reg. Date:	17/10/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF58JA034474
Colour:	Black	Odometer:	17357 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	78,514.52	30,884.20	47,630.32	60.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,772.00	11,372.00	8,400.00	42.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	98,286.52	42,256.20	56,030.32	57.01
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	96,686.52	40,656.20	56,030.32	57.95
+ GST 7.00/7.00% (\$\$)	6,768.06	2,845.93	3,922.13	57.95
Nett Amount (\$\$)	103,454.58	43,502.13	59,952.45	57.95

INSPECTION

Date of Assignment:	30/05/2018	
Date Inspected:	28/05/2018	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	28.0 days	

Adjuster: ADRIAN LING**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,970.00 FS	*1,576.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Distorted	349.00 FS	*279.20 FS
3	1		*FRONT BUMPER GRILLE	Distorted	171.00 FS	*136.80 FS
4	1		*RADIATOR GRILLE	Distorted	2,022.00 FS	*1,617.60 FS
5	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Missing	100.00 FS	*79.68 FS
6	1		*RADIATOR GRILLE COVER	Distorted	165.00 FS	*132.00 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Distorted	195.00 FS	*156.00 FS
8	1		*FRONT BUMPER SPOILER	Deformed	465.00 FS	*372.00 FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Distorted	828.00 FS	*662.40 FS
10	2		*FRONT PARKING AID SENSOR	Missing	421.00 FS	*336.80 FS
11	4		*FRONT PARKING AID SENSOR SEAL	Missing	14.00 FS	*10.88 FS
12	1		*FRONT BUMPER WIRING	Damaged	456.00 FS	*364.80 FS
13	1		*FOAM FILLER PIECE	Cracked	107.00 FS	*85.20 FS
14	1		*FRONT BUMPER CARRIER	Bent	702.00 FS	*561.60 FS
15	2		*FRONT BUMPER SUPPORT - LH / RH	Damaged	48.00 FS	*38.24 FS
16	2		*FRONT BUMPER BRACKET - LH / RH	Damaged	368.00 FS	*294.40 FS
17	1		*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
18	1		*FRONT BUMPER COVER	Deformed	109.00 FS	*87.20 FS
19	1		*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
20	1		*BOWDEN CABLE - CENTER	Not Necessary	50.00 FS	*- FS
21	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
22	1		*AIR CONDITIONER STICKER	Necessary	7.00 FS	*4.88 FS
23	2		*FRONT FENDER - LH / RH	Buckled	1,840.00 FS	*1,471.20 FS
24	2		*FENDER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
25	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	130.00 FS	*- FS
26	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	62.00 FS	*- FS
27	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	206.00 FS	*- FS
28	2		*FRONT FENDER COVER - LH / RH	Necessary	28.00 FS	*20.96 FS
29	2		*COVER - LH / RH	Necessary	60.00 FS	*48.00 FS
30	2		*STONE CHIP GUARD - LH / RH	Necessary	88.00 FS	*69.12 FS
31	2		*FRONT WHEEL SPOILER - LH / RH	Deformed	126.00 FS	*100.32 FS
32	2		*LED HEADLIGHT - LH / RH	Cracked	14,038.00 FS	*11,230.40 FS
33	1		*LED HEADLIGHT POWER MODULE	Not Necessary	665.00 FS	*- FS
34	1		*LED HEADLIGHT CONTROL UNIT	Not Necessary	657.00 FS	*- FS
35	2		*LED WITH HEAT SINK - LH / RH	Not Necessary	1,980.00 FS	*- FS
36	2		*HOSE	Not Necessary	60.00 FS	*- FS
37	4		*COMPENSATING PIECE	Not Necessary	145.00 FS	*- FS
38	2		*RETAINER PLATE SPACER	Not Necessary	70.00 FS	*- FS
39	1		*LED HEADLIGHT LIFT CYLINDER - LH / RH	N/S Damaged	348.00 FS	*147.20 FS
40	2		*LED HEADLIGHT LIFT CYLINDER BRAKET - LH / RH	Not Necessary	26.00 FS	*- FS
41	1		*CORRUGATED PIPE	Bent	73.00 FS	*58.00 FS
42	1		*BONNET	Distorted	2,499.00 FS	*1,999.20 FS
43	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
44	2		*BONNET LID HINGE - LH / RH	Not Necessary	734.00 FS	*- FS
45	1		*IMPACT PROTECTION - CENTER	Necessary	24.00 FS	*18.88 FS
46	2		*IMPACT PROTECTION - RH / LH	Necessary	48.00 FS	*37.76 FS
47	1		*BONNET SOUND ABS	Crumpled	296.00 FS	*236.80 FS
48	2		*BONNET GAS FILLED STRUT	Not Necessary	209.00 FS	*- FS
49	2		*BONNET STRIKER - LH / RH	Not Necessary	88.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*BONNET BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
51	2		*BONNET LID LOCK	Not Necessary	376.00 FS	*- FS
52	1		*LOCK CARRIER WITH MOUNTING	Cracked	891.00 FS	*712.80 FS
53	2		*AIR GUIDE - LH / RH	Distorted	52.00 FS	*40.88 FS
54	2		*INNER AIR DUCT - LH / RH	Distorted	28.00 FS	*21.12 FS
55	1		*UPPER AIR GUIDE	Deformed	14.00 FS	*10.56 FS
56	1		*AIR COOLER CHARGE	Distorted	514.00 FS	*411.20 FS
57	1		*AIR COOLER SEAL RING	Not Necessary	79.00 FS	*- FS
58	2		*HOSE CLAMP	Not Necessary	37.00 FS	*- FS
59	1		*A/C CONDENSER	Distorted	550.00 FS	*440.00 FS
60	1		*PRESSURE SENSOR	Not Necessary	170.00 FS	*- FS
61	1		*PRESSURE VALVE	Not Necessary	46.00 FS	*- FS
62	1		*RADIATOR	Distorted	630.00 FS	*503.60 FS
63	2		*SLEEVE	Not Necessary	15.00 FS	*- FS
64	4		*RUBBER BUSH	Necessary	38.00 FS	*30.40 FS
65	4		*COOLANT CONCENTRATE	Necessary	133.00 FS	*65.28 FS
66	1		*BREATHER LINE	Not Necessary	29.00 FS	*- FS
67	1		*FAN RING	Cracked	230.00 FS	*184.00 FS
68	1		*RADIATOR FAN WITH CONTROL UNIT	Distorted	2,055.00 FS	*1,644.00 FS
69	2		*FRONT WINDOW SLOT SEAL - LH / RH	Not Necessary	690.00 FS	*- FS
70	2		*FRONT FENDER TRIM - LH / RH	Necessary	276.00 FS	*220.80 FS
71	2		*FRONT DOOR TRIM - LH / RH	Not Necessary	276.00 FS	*- FS
72	2		*THREE POINT AUTOMATIC SEAT BELT - LH / RH	Not Necessary	1,912.00 FS	*- FS
73	2		*SEAT BELT HEIGHT ADJUSTER	Not Necessary	306.00 FS	*- FS
74	1		*AIR BAG CONTROL UNIT	Not Necessary	1,870.00 FS	*- FS
75	4		*AIRBAG CRASH SENSOR	Not Necessary	545.00 FS	*- FS
76	1		*CENTRAL PROTECTION	Not Necessary	470.00 FS	*- FS
77	1		*INTAKE AIR DUCT - RH	Distorted	18.00 FS	*14.16 FS
78	1		*AIR INTAKE HOSE	Distorted	31.00 FS	*24.80 FS
79	1		*FRONT NO. PLATE	Missing	25.00 FS	*25.00 FS
80	1		*SUNDRIES	Necessary	600.00 FS	*257.60 FS
81	1		*WIRE CONNECTOR	Cracked	11.36 FS	*11.36 FS
82	1		*A/C PIPE	Bent	115.60 FS	*115.60 FS
83	1		*WIRE CONNECTOR	Cracked	5.12 FS	*5.12 FS
84	1		*FLAT CONNECTOR HOUSING	Cracked	12.32 FS	*12.32 FS
85	2		*HEADLIGHT WASHER JET BRACKET - LH / RH	Cracked	19.84 FS	*19.84 FS
86	2		*WASHER JAT SPRING CLIP	Necessary	34.08 FS	*34.08 FS
87	1		*BASE ENGINE	Not Necessary	27,809.00 FS	*- FS
88	1		*OIL SUMP-LOWER PART	Cracked	236.80 FS	*236.80 FS
89	1		*SET OIL SUMP BOLT	Necessary	13.60 FS	*13.60 FS
90	1		*OIL LEVEL SENSOR	Damaged	194.80 FS	*194.80 FS
91	1		*ENGINE OIL	Necessary	210.80 FS	*210.80 FS
92	1		*A/C COMPRESSOR	Cracked	1,861.60 FS	*1,861.60 FS
93	1		*VABRATION DAMPER	Bent	302.80 FS	*302.80 FS
94	1		*TIMING CASE	Scratched	202.00 FS	*202.00 FS
95	1		*SILICON SEALANT	Necessary	27.52 FS	*27.52 FS
96	1		*POLY-V-BELT	Cut	35.68 FS	*35.68 FS
97	1		*BELT TENSIONER DAMPER	Damaged	102.40 FS	*102.40 FS
98	1		*CHASSIC SHOCK ABSORBER MOUNTING - RH	Bent	43.20 FS	*43.20 FS
99	1		*ENGINE SUMP GUARD	Damaged	396.00 FS	*396.00 FS
100	1		*SUN VISOR - DRIVER SIDE	Not Necessary	394.00 FS	*- FS
101	2		*FRONT BUMPER AIR GUIDE - LH / RH	Distorted	146.00 FS	*115.68 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	78,514.52	30,884.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	480.00	480.00
2	TO REMOVE AND RENEW, AIRCON CONDENSER, TURBO COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,100.00	1,100.00
3	TO REMOVE AND REINSTALL CENTER CONSOLE. RENEW BOTH FRONT SEAT BELTS, AIR BAG CONTROL UNIT AND BATTERY CENTRAL PROTECTION	New	1,800.00	0.00
4	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	4,000.00
5	TO REMOVE BOTH FRONT DOOR PANEL TRIMS, DISMANTLE WING MIRROR ASSY AND RENEW BOTH DOORS CHROME MOLDINGS	New	600.00	600.00
6	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, LHS A-PILLAR. AND BOTH FRONT DOORS	New	5,300.00	3,300.00
7	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
8	TO CUT OUT AND WELD RHS FRONT CHASSIS FRAME STRIKER PLATE. ALIGN TO POSITION	New	900.00	500.00
9	TO RESPRAY RHS FRONT CHASSIS FRAME	New	500.00	300.00
10	TO REMOVE AND RENEW ENGINE ASSY AND DAMAGED ATTACHMENT	New	3,200.00	900.00
11	TO CARRY OUT LTA INSPECTION FOR ENGINE STAMPING	New	300.00	0.00
Gross Labour Cost (S\$)			19,772.00	11,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >