

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG18009715/GRA3Q2
Date: 29/06/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700088478
Claimant Vehicle No :	FBA7368P	Insured Vehicle No :	SLU7729H
Date of Loss:	22/05/2018	Nature of Claim:	TP
		Claim No:	7613704010SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBA7368P	Engine No:	HIDDEN
Make & Model:	YAMAHA SPARK, 135cc	Chassis No:	0
Reg. Date:	(Man. Year: 1900)	Odometer:	89550 km
Colour:	Blue		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/29/2021

Adjuster Report

Date of Assignment: 30/05/2018

Date Inspected: 30/05/2018

Estimated Period of Repair: 3.0 days

Inspected At:

Evolution Motors leasing & Services (HQ)
25 KAKI BUKIT ROAD 4 #01-63
Singapore 417800

Adjuster: XING GUO QIANG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F	
2	1		*FRONT FORK ASSY	Bent	0.00 F	*- F	
3	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F	
4	1		*FRONT FORK OIL	Necessary	0.00 F	*- F	
5	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F	
6	2		*FRONT WING MIRROR	Scratched	0.00 F	*- F	
7	1		*STEERING STEM	Bent	0.00 F	*- F	
8	1		*STEERING CONE AND BEARING	Necessary	0.00 F	*- F	
9	1		*HANDLE BAR	Bent	0.00 F	*- F	
10	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F	
11	1		*SIDE FAIRING	Deformed	0.00 F	*- F	
12	1		*CENTER FAIRING REAR	Deformed	0.00 F	*- F	
13	2		*REAR FAIRING	Cut	0.00 F	*- F	
14	1		*FRONT FOOT REST	Cut	0.00 F	*- F	
15	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F	
16	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F	
17	1		*STICKER	Necessary	0.00 F	*- F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >