

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 3833H

DATE 28/5/2018 9:23

MAKE :

MODEL : HYUNDAI i40

9 LKK/Kalvin 4Sum
Like AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	License Lamp Cover			\$ 100.00	
	Rear Bumper <i>x Reps</i>			\$ 603.60	
	Rear Bumper Reinforcement			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips <i>x</i>			\$ 22.00	
	Rear Bumper Sponge			\$ 143.40	
	Rear Bumper Under Cover <i>x</i>			\$ 225.00	
	SUB TOTAL			\$ 2,007.35	
	LESS 20%			\$ 401.47	
	DISCOUNTED TOTAL			\$ 1,605.88	
	 Rear Bumper Reverse Sensor <i>x</i>			\$ 135.70	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
	Rear No. Plate			\$ 25.00	Nett
				\$ 460.70	
	Labour Charge				
	Panel Beating			\$ 280.00	
	Spray Painting Charge			\$ 250.00	
	Wiring Charge			\$ 50.00	
	R/Refix Reverse Sensor			\$ 120.00	
	TOTAL LABOUR			\$ 700.00	
	ESTIMATE TOTAL			\$ 2,766.58	

Kalvin 16/6/14
M 28/5/18 15 45h
2 Reps
45
Athir Reps pth

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature
 Date