



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2006264  
INV Date 11/09/2020  
Reference CC4/EQI18009734/Ups3q2  
Code EQI



#### PROFESSIONAL SERVICE FEE

Vehicle No. GZ 7477S  
Insured Veh. GBD 4860M  
Claim No.  
Policy No. DMCPHQ17-006560  
Accident Date 18/05/2018  
Inspection Date 30/05/2018

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18009734/Ups3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 11-09-2020		
		Code : EQI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	GBD 4860M	<b>Veh. Inspected</b>	GZ 7477S
	<b>Policy No.</b>	DMCPHQ17-006560	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>		<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	FRANCIS	<b>Assign Date</b>	30/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	MITSUBISHI L300 (M)	<b>c.c</b>	2477
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2006
	<b>Chassis No.</b>	JMAJNP15V6A001518	<b>Colour</b>	WHITE
	<b>Odometer</b>	403484	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	185 R14	LING LONG	7 mm
	<b>L/H Front Tyre</b>	185 R14	LING LONG	7 mm
	<b>R/H Rear Tyre</b>	185 R14	LING LONG	7 mm
	<b>L/H Rear Tyre</b>	185 R14	LING LONG	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	18/05/2018	<b>Inspection Date</b>	30/05/2018
	<b>Survey held at</b>	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 7477S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DISTORTED	945.00	765.00
1	FRONT BUMPER REINFORCEMENT	DISTORTED	452.00	266.00
1	FRONT O/S BUMPER PROTECTOR	TORN	198.00	115.00
1	FRONT O/S BUMPER SIDE RETAINER	BENT	65.00	65.00
1	FRONT PANEL	BADLY DENTED	746.00	746.00
1	FRONT PANEL GARNISH	BENT	73.00	73.00
1	FRONT WINDSCREEN GLASS MOULDING	NECESSARY	260.00	166.00
1	FRONT WIPER ARM	NOT NECESSARY	172.00	-
1	FRONT WIPER LINK	NOT NECESSARY	492.00	-
1	FRONT CORNER PANLE O/S	BADLY DENTED	239.00	239.00
1	FRONT HEAD LAMP O/S	NOT NECESSARY	180.00	-
1	FRONT HEAD LAMP PANEL O/S	BENT	266.00	266.00
1	FRONT HEAD LAMP RIM O/S	CRACKED	315.00	315.00
1	FRONT SIGNAL LAMP O/S	BROKEN	146.00	146.00
1	FRONT OIL COOLER	BENT / PUNCTURE	1,090.00	1,090.00
1	FRONT LOWER INNER PANEL	TO REPAIR SEE LABOUR	980.00	-
1	FRONT DOOR O/S	DENTED / BENT	1,105.00	951.00
1	FRONT DOOR LOCK O/S	JAMMED	105.00	105.00
1	FRONT DOOR RUBBER O/S	TORN	116.00	116.00
1	FRONT DOOR BOARD O/S	NOT NECESSARY	420.00	-
1	FRONT DOOR PILLAR O/S	BADLY DENTED / TWISTED	1,184.00	899.00
2	FRONT DOOR HINGES O/S @\$95.00	TWISTED	190.00	190.00
1	FRONT AIRCON BLOWER	NOT NECESSARY	1,164.00	-
1	FRONT BRAKE PANEL	NOT NECESSARY	970.00	-
1	FRONT SLIDING DOOR O/S	NOT NECESSARY	1,170.00	-
	LESS 10% DISCOUNT		-	-651.30
			13,043.00	5,861.70
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	45.00	30.00

Report Ref No. CC4/EQ118009734/Ups3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
22	FRONT WINDSCREEN GLASS GARNISH CLIPS @\$4.80 (SN)	NOT NECESSARY	105.60	-
1	FRONT WINDSCREEN GLASS MOULDING (SN)	REPEATED	171.00	-
1	FRONT NUMBER PLATE 'METAL' (SN)	BENT	28.00	14.00
1	FRONT DOOR 'CORPORATE ROC DETAIL' STICKER (SN)	NECESSARY	48.00	30.00
			397.60	74.00
	<b>LABOUR</b>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		400.00	30.00
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER .		120.00	60.00
	REMOVE & REINSTALL DASHBOARD ,METER INSTRUMENTS ,DISCONNECT WIRING & ETCS.		400.00	200.00
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		100.00	100.00
	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF FRONT LOWER INNER PANEL .		2,500.00	1,300.00
	TO PUTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.		1,400.00	900.00
			4,920.00	2,590.00
<b>GRAND TOTAL</b>			<b>18,360.60</b>	<b>8,525.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,800.00</b>

Report Ref No. CC4/EQ118009734/Ups3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GZ 7477S

INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GZ 7477S

RE-INSPECTION

