

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping-CP/P) TS

VEHICLE NO : SHA 2222M

DATE 28/5/2018

MAKE :

LKK - Kalvin

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Return</i>			459.40
	Rear Bumper Reinforcement <i>Return</i>			294.80
	Rear Bumper Clip <i>Return</i>			22.00
	Rear Bumper Sponge <i>Return</i>			X
	Rear Bumper Under Cover <i>Return</i>			270.10
	Rear Bumper Protector (LH/RH) <i>Return</i>			X
	<i>Rear RH Fender X Repair</i>			
	SUB TOTAL			\$1046.40
	LESS 20%			\$209.28
	DISCOUNTED TOTAL			\$837.12
	Rear Bumper Reverse Sensor <i>X Return</i>			\$ 135.70
	Rear Bumper Rubber Mat <i>Return</i>			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 280.00
	Spray Painting Charge			\$ 500.00 400
	Wiring Charge			\$ 50.00 X 17
	Remove/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$1722.82
	<i>Kalvin 10064</i>			
	<i>28/5/18 1145hrs</i>			
	<i>2 Days</i>			
	<i>PIP</i>			
	<i>Before Paint photo</i>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.