

22/03/2002

SS. REC. BY:

REF: C83/ AIG 18009777/12403 Special Instruction: ✓

Survivor: Adrian ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIGDate/Time: 30/5/18 @ 4.02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 7797H

Insured:

EB 11332

at Workshop m/s

Twincar Automotive

Tel:

6842 0051

of

2 Kaki Bukit Ave 2 # 01-17 118

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/05/201828/05/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

4.35pm @ 30/5/18

Person Contacted:

MelodyVehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	<u>GBF 7797H - NA / AIG 18009777 / r3</u>	<u>DUA: 28/5/18</u>
	<u>EB 11332 - NA / AIG 18009777 / r3</u>	<u>DUA: 28/5/18</u>
<u>1/6/18</u>	<u>Dismantled</u>	

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBF797HYr Regn: 2016/ Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota HiaceC.C. 2982Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 41538

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P200207386

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 135R15CR: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 31/05/18Survey held at Twincar.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG PRS1/6/18Submit DAR Report.

RECEIVED 01 JUN 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009747/Az4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 30-05-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	EB 1133Z	Veh. Inspected	GBF 7797H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	30/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/05/2018	Inspection Date
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE EB1133Z AND GBF7797H ON 28/05/2018

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 30/5/2018 4:02:54 PM

Attachments:  30052018154917.pdf  30052018112158-0001.pdf  30052018144807.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Wednesday, May 30, 2018 3:51 PM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE EB1133Z AND GBF7797H ON 28/05/2018

Dear Sir/Madam,

Vehicle already at our workshop, please arrange your surveyor to PRI.

Please see attached.

Thank you

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: GBF 7797 H
Your ref: EB 1133 Z

30 May 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY EMAIL yokeshi.chan@aig.com ONLY

NO: 78 SHENTON WAY

#07-16 CHARTIS BUILDING

SINGAPORE 079120

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : NEW PLUMBING SERVICES PTE LTD

VEHICLE NUMBER : GBF 7797 H

YOUR INSURED VEHICLE NUMBER : EB 1133 Z

**ACCIDENT ON 28 May 2018 ALONG CTE TOWARDS AYE BEFORE PIE CHANGI EXIT
AT ABOUT 19:00 HOURS**

We refer to your email/fax dated **30 May 2018** wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2018 15:42
Date Of Accident	28/05/2018 19:00
Exact Location Of Accident	CTE TWDS AYE B4 PIE CHANGI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF7797H
Insured/Policyholder	
Name Of Registered Owner	NEW PLUMBING SERVICES PTE LTD
Co Reg No	201200003D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98537797

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100486923-01
Cover Note Number	

Driver

Name of Driver	ANKUSAMY BALUSAMY
Passport No/FIN	G8237351P
Date Of Birth	15/03/1988
Occupation	OUTDOOR
Date Of Driving Pass	21/08/2017
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90454760
Fax Number	
Contact Number	
Email Address	NOEMAIL

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

 30/05/18
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

VAN / LORRY (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	993958	Rear Bumper	DT	✓	
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper new Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor	SC	✓	
1159	993327	Rear End Panel	DT	✓	
1163	993851	Rear LH Taillamp	SCR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	DT	✓	
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock	DT	✓	
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	995165	Rear RH Chassis Member			

Vehicle No: **GBF 7797 H**

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hood			
2068	994965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992860	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker	NEC	✓	
		Rear Camera	SCR	✓	

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018 Edit Reg		30 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SOONG ANGELO PETER, ID: S1585123F		
Main Claimant:	NEW PLUMBING SERVICES, Co. Reg. No.: 201200003D		
Vehicle Reg. No.:	GBF7797H	Date of Loss:	28/05/2018 19:00 - :59 [19 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3636111274SG	Policy/Cover Note No.:	2100465527 (Comprehensive)
Vehicle Reg. No. (Insured):	EB1133Z	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (05/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Claim Documents

***GBF7797H (3636111274SG)**

[EB1133Z]

TP

NEW PLUMBING SERVICES

May 28 2018 7:00PM

[SOONG ANGELO PETER]

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	01/06/18 14:49	General View										Load JPG		
2	01/06/18 14:49	General View										Load JPG		
3	01/06/18 14:49	General View										Load JPG		
4	01/06/18 14:49	General View										Load JPG		
5	01/06/18 14:49	General View										Load JPG		
6	01/06/18 14:49	General View										Load JPG		
7	01/06/18 14:49	General View										Load JPG		
8	01/06/18 14:49	General View										Load JPG		
9	01/06/18 14:49	General View										Load JPG		
10	01/06/18 14:49	General View										Load JPG		
11	01/06/18 14:49	General View										Load JPG		
12	01/06/18 14:49	General View										Load JPG		
13	01/06/18 14:49	General View										Load JPG		
14	01/06/18 14:49	General View										Load JPG		
15	01/06/18 14:49	General View										Load JPG		
16	01/06/18 14:49	General View										Load JPG		
17	01/06/18 14:49	General View										Load JPG		
18	01/06/18 14:49	General View										Load JPG		
19	01/06/18 14:49	General View										Load JPG		
20	01/06/18 14:49	General View										Load JPG		
21	01/06/18 14:49	General View										Load JPG		
22	01/06/18 14:49	General View										Load JPG		
23	01/06/18 14:49	General View										Load JPG		
24	01/06/18 14:49	General View										Load JPG		
25	01/06/18 14:49	General View										Load JPG		
26	01/06/18 14:49	General View										Load JPG		
27	01/06/18 14:49	General View										Load JPG		
28	01/06/18 14:49	General View										Load JPG		
29	01/06/18 14:49	General View										Load JPG		
30	01/06/18 14:49	General View										Load JPG		
31	01/06/18 14:49	General View										Load JPG		
32	01/06/18 14:49	General View										Load JPG		
33	01/06/18 14:50	Dismantled Parts										Load JPG		
34	01/06/18 14:50	Dismantled Parts										Load JPG		
35	01/06/18 14:50	Dismantled Parts										Load JPG		
36	01/06/18 14:50	Dismantled Parts										Load JPG		

Photos/Images					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	01/06/18 14:50	Dismantled Parts		Load JPG	
38	01/06/18 14:50	Dismantled Parts		Load JPG	
39	01/06/18 14:50	Dismantled Parts		Load JPG	
40	01/06/18 14:50	Dismantled Parts		Load JPG	
41	01/06/18 14:50	Dismantled Parts		Load JPG	
42	01/06/18 14:50	Dismantled Parts		Load JPG	
43	01/06/18 14:50	Dismantled Parts		Load JPG	
44	01/06/18 14:50	Dismantled Parts		Load JPG	
45	01/06/18 14:50	Dismantled Parts		Load JPG	
46	01/06/18 14:50	Dismantled Parts		Load JPG	
47	01/06/18 14:50	Dismantled Parts		Load JPG	
48	01/06/18 14:50	Dismantled Parts		Load JPG	
49	01/06/18 14:50	Dismantled Parts		Load JPG	
50	01/06/18 14:50	Dismantled Parts		Load JPG	
51	01/06/18 14:50	Dismantled Parts		Load JPG	
52	01/06/18 14:50	Dismantled Parts		Load JPG	
53	01/06/18 14:50	Dismantled Parts		Load JPG	
54	01/06/18 14:50	Dismantled Parts		Load JPG	
55	01/06/18 14:50	Dismantled Parts		Load JPG	
56	01/06/18 14:50	Dismantled Parts		Load JPG	
57	01/06/18 14:50	Dismantled Parts		Load JPG	
58	01/06/18 14:50	Dismantled Parts		Load JPG	
59	01/06/18 14:50	Dismantled Parts		Load JPG	
60	01/06/18 14:50	Dismantled Parts		Load JPG	
61	01/06/18 14:50	Dismantled Parts		Load JPG	
62	01/06/18 14:50	Dismantled Parts		Load JPG	
63	01/06/18 14:50	Dismantled Parts		Load JPG	
64	01/06/18 14:50	Dismantled Parts		Load JPG	
65	01/06/18 14:50	Dismantled Parts		Load JPG	
66	01/06/18 14:50	Dismantled Parts		Load JPG	
67	01/06/18 14:50	Dismantled Parts		Load JPG	
68	01/06/18 14:50	Dismantled Parts		Load JPG	
69	01/06/18 14:50	Dismantled Parts		Load JPG	
70	01/06/18 14:50	Dismantled Parts		Load JPG	
71	01/06/18 14:50	Dismantled Parts		Load JPG	
72	01/06/18 14:50	Dismantled Parts		Load JPG	
73	01/06/18 14:50	Dismantled Parts		Load JPG	
74	01/06/18 14:50	Dismantled Parts		Load JPG	
75	01/06/18 14:50	Dismantled Parts		Load JPG	
76	01/06/18 14:50	Dismantled Parts		Load JPG	
77	01/06/18 14:50	Dismantled Parts		Load JPG	
78	01/06/18 14:50	Dismantled Parts		Load JPG	
Documentation					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/06/18 13:00	OI GIA REPORT		Load PDF	
2	08/06/18 10:17	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009747/AZ4D3S2
Date: 02/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. **Policy No:** 2100465527
Claimant Vehicle No : GBF7797H **Insured Vehicle No :** EB1133Z
Date of Loss: 28/05/2018 **Nature of Claim:** TP **Claim No:** 3636111274SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF7797H
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) **Engine No:** 1KD2655010
Reg. Date: 20/10/2016 (Man. Year: 2016) **Chassis No:** JTFHT02P200207386
Colour: Silver **Odometer:** 41538 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195 R15C **Rear Tyre Size:** 195 R15C
Front Left Side: Bridgestone 6 mm **Rear Left Side:** Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm **Rear Right Side:** Bridgestone 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/05/2018
Date Inspected: 31/05/2018 **Inspected At:** TWINCAR AUTOMOTIVE PTE LTD
 2 KAKI BUKIT AVE 2
 #01-17/18 KAKI BUKIT AUTOHUB
 SINGAPORE 417921
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
4	1		*REAR END PANEL	Dented	0.00 F	*- F
5	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
6	1		*TAILGATE	Dented	0.00 F	*- F
7	1		*TAILGATE LOCK	Dented	0.00 F	*- F
8	1		*STICKER	Necessary	0.00 F	*- F
9	1		*REAR CAMERA	Scratched	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >