



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 29/6/2019

Survey Details:

Date of loss	14.05.2018
Date of appointment	30.05.2018
Date of survey	05.06.2018
Location of survey	TAN CHONG MOTOR SALES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLU748Z
Make and Model	Nissan Qashqai 1197cc
Date of registration	22.11.2017
Parf Rebate	
Market Value	\$ 96,000.00
Parf Rebate	\$ 55,556.00
Nett Loss	\$ 40,444.00

Repair details:

Initial Estimate	10,731.28
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 4,341.50
Check items (estimate)	NIL
Labour	\$ 2,365.50
Total	\$ 6,707.00
Lump Sum(if applicable)	

Number of days for repair	6.0
---------------------------	-----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Pending OI LOA

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	7,176.49
Loss of use		NIL
Loss of rental (w/GST)	\$	749.00 (7days x\$100.00)
Loss of income		NIL
LTA search fees	\$	2.00
Others		NIL
Proposed Total	\$	7,927.49



Re:RE: <TP - Mandate IA> - S8M00H71 [ACCIDENT INVOLVING YN 3306D(OI) & SLU 748Z(TP) ON 14/05/2018]

Type

 Question

Message

Hi, pls proceed as per mandate. TY.

Reply

Letter Of Claim For Uninsured Loss

Insurance Company: AAA / LKK Date: _____
Address : _____

Attention : Claims Department – Motor Claims Manager

Dear Sir/Madam,

Subject: Accident involving vehicle number SLU748Z & YN3306D
at Gambas Ave to Woodlands Ave 12 on 14/05/2018.

I am the owner of Vehicle Number SLU748Z which was involved with the accident as mentioned above.

As the accident was solely caused by your insured vehicle, bearing registration number YN3306D, I hereby submit my claim against your company for the uninsured loss which are as follows:

Excess payment for OD claim	\$ _____
Loss of usage (S\$/day) for _____ days	\$ _____
Car rental as per invoice attached	\$ <u>749.00</u>
Search fee	\$ <u>2.00</u>
Others <u>Cost of Repair</u>	\$ <u>7176.49</u>
Total claim amount	\$ <u>7927.49</u>

Enclosed please find copies of GIA report, invoices and certificate of insurance for your necessary review.

Kindly reply me within 14 days from the date hereof, or alternatively let me have the full and final settlement for all uninsured loss which amounted to \$ 7927.49, failing which I will have to recover all losses via legal action. Please also note your prompt action will help to reduce the claim cost.

Yours sincerely

* Wing

(Owner of motor vehicle)

Name : Ng Chiu Li
Address : 804 B Kent Hong Close
#14-34
Telephone : 96252886

S(682804)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18009763/T1pb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: RICHARD ANG		Date : 09-09-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 3306D	Veh. Inspected	SLU 748Z
Policy No.	VCA/P1954247	Coverage (\$)	0.00
Claim No.	S8M00H71	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	30/05/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI 1.2	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SJNFEAJ11U2064575	Colour	SILVER
Odometer	11886	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/05/2018	Inspection Date	05/06/2018
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911, BUKIT TIMAH RD, SINGAPORE 589623.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 748Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	GROMMET C/LAMP @ \$4.40 (N) (CONSISTENT)	NOT NECESSARY	8.80	-
1	GROMMET C/LAMP (N) (CONSISTENT)	NOT NECESSARY	1.90	-
2	CLIP C/LAMP @ \$4.80 (N) (CONSISTENT)	NOT NECESSARY	9.60	-
1	LAMP COMB RR, LH TAILGATE (DISC 5%) (N) (CONSISTENT)	CUT	215.90	205.11
1	LAMP COMB RR, LH (N) (CONSISTENT)	NOT NECESSARY	323.70	-
1	EMBLEM (DISC 5%) (N) (CONSISTENT)	NECESSARY	87.00	82.65
1	EMBLEM - REAR (DISC 5%) (N) (CONSISTENT)	NECESSARY	59.70	56.72
1	STRIKER - TAIL GA (N) (CONSISTENT)	NOT NECESSARY	31.70	-
1	A LOCK LIFT (N) (CONSISTENT)	NOT NECESSARY	116.70	-
1	A FIN BACK DOOR NO PLATE (N) (CONSISTENT)	NOT NECESSARY	336.00	-
1	DOOR BACK (DISC 5%) (N) (CONSISTENT)	BENT	2,936.80	2,789.96
1	RUBBER - DUM (DISC 5%) (N) (CONSISTENT)	NECESSARY	60.20	57.19
1	GLASS - TAIL GATE (DISC 5%) (N) (CONSISTENT)	NECESSARY	930.00	883.50
1	STAY ASSY - REAR RH (N) (CONSISTENT)	NOT NECESSARY	126.00	-
1	STAY ASSY - REAR LH (N) (CONSISTENT)	NOT NECESSARY	126.00	-
1	REINF-BUMPER RR (N) (CONSISTENT)	NOT NECESSARY	619.20	-
1	ENERGY ABSORBER (DISC 5%) (N) (CONSISTENT)	CRACKED	126.40	120.08
2	CANOE BUMPER @ \$6.50 (DISC 5%) (N) (CONSISTENT)	NECESSARY	13.00	12.35
3	CLIP BUMPER @ \$7.40 (DISC 5%) (N) (CONSISTENT)	NECESSARY	22.20	21.09
1	BRACKET - BUMPER RH (N) (CONSISTENT)	NOT NECESSARY	35.90	-
1	RETAINER - BUMPER RH (N) (CONSISTENT)	NOT NECESSARY	23.80	-
1	BRACKET - BUMPER LH (DISC 5%) (N) (CONSISTENT)	NECESSARY	35.90	34.11
1	RETAINER - BUMPER LH (DISC 5%) (N) (CONSISTENT)	NECESSARY	23.80	22.61
1	FINISHER - REAR BUMPER TOW (N) (CONSISTENT)	NOT NECESSARY	16.80	-
1	FASCIA - RR BUMP (DISC 5%) (N) (CONSISTENT)	DEFORMED	717.00	681.15
2	CLIP FENDER @ \$1.20 (DISC 5%) (N) (CONSISTENT)	NECESSARY	2.40	2.28
4	CLIP FENDER @ \$1.20 (DISC 5%) (N) (CONSISTENT)	NECESSARY	4.80	4.56
1	PLATE - LUGGAGE (DISC 5%) (N) (CONSISTENT)	GRAZED	63.50	60.33
5	CLIP FENDER @ \$1.20 (DISC 5%) (N) (CONSISTENT)	NECESSARY	6.00	5.70
1	GROMMET FENDER (N) (CONSISTENT)	NOT NECESSARY	1.50	-

Report Ref No. CC4/ASM18009763/T1pb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PROTECTOR - REAR LH FENDER (N) (CONSISTENT)	NOT NECESSARY	186.40	-
1	FENDER LH REAR ARC (N) (CONSISTENT)	NOT NECESSARY	483.00	-
	LESS 20% DISCOUNT		-1,550.32	-1,007.89
			6,201.28	4,031.50
	SPECIAL NETT ITEMS			
1	REAR W/SCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	20.00
1	REVERSE SENSOR (J11 & T32) (SN) (CONSISTENT)	CUT	210.00	210.00
1	REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
			450.00	310.00
	LABOUR			
	REMOVE / INSTALL& TEST REAR REVERSE CAMERA.		120.00	120.00
	PERFORM RUST PROOFING & TREATMNT FOR AFFECTED PANEL.		360.00	120.00
	SUPPLY & INSTALL REVERSE SENSOR.		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		300.00	100.00
	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN.		150.00	150.00
	RENEW REAR WINDSHIELD GLASS ASSY.		240.00	240.00
	REPAIR BOTH REAR FENDER AND RENEW END PANEL, TAILGATE, REAR BUMPER.		1,200.00	750.00
	S/PAINT REAR PORTION AND BUMPER (2 TONES).		1,400.00	700.00
	TRANSFER TAILGATE MECHANICAL PARTS.		80.00	80.00
	R/I DVR TO ASSIST REPAIR.		120.00	120.00
1	SUPPLY AND RENEW REAR NO. PLATE (SMART PLATE WITH CASING) BLACK CASING (LONG). (NPA)	NOT NECESSARY	-	-
			-	-
			-	-
			-	-
	LESS 5% DISCOUNT		-	-124.50
			4,080.00	2,365.50
	GRAND TOTAL		10,731.28	6,707.00

Report Ref No. CC4/ASM18009763/T1pb3s2



RECOMMENDED COST OF REPAIRS			6,707.00
-----------------------------	--	--	----------

Report Ref No. CC4/ASM18009763/T1pb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.