

ASS/REC BY:

REF: CS/FCI18009765/D4D3ⁿ² Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Serever

of

FEI

Date/Time: 28/5/18 @ 6.12pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 1251A

Insured:

SHA 7839B

at Workshop m/s

Pegasus Engineering

Tel:

68581846

of

51 Deft Lane 40

Policy No:

Claim No:

D18001211 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/05/2018

CA / REV / REP. / REV 24 HRS

hup)

H.O.D. Endorsement:

Date/Time:

3.09pm @ 30/5/18

Person Contacted:

william

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 1251A - x
	SHA 7839B - cc3/LCR 17020551/k126392 DOA: 25/10/17
06/6/18 @ 10.00am	OK'd revised to Serever by email.

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: 3 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Sub No: **SLM 1251A** Yr/Reg: **2017 March**
 Type: **MC** / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Mazda 3** 1496
 Colour: **Red** A/C: Insured / Std / NI / NA
 Sp Reading: **101106** T/Ratio: Insured / Std / NI / NA
 Engine: **P520430799**
 C/No: **JM6BN22A8H0143358**
 Gen. Cond: **G** / Fair / Poor / Burnt
 Steering: **G** / Jammed / Leaked / Burnt or
 Brake: **G** / Jammed / Leaked / Burnt or
 Modi: **G** / STD A/Rim or
 Tyre Size: F: **205/60 R16**
 R: **-11-**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Wastake**
 Front: _____ Rear: _____
 R/Bal: **S** mm R/Bal: **S** mm
 L/Bal: **S** mm L/Bal: **S** mm
 D.O.A: **24/05/2018** D.O.I: **05/06/2018**
 Survey held at: **Tan Lim Motor Repair Lane**
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear N/S
 The UIC / Chassis frame / Body Structure affected due to collision



Date / Time: _____ Action / Instruction

19/04/18 First Capital **SHA 7839B**
 Jpnagr 1/s 27001- with 3 dy. & r ✓
 (Red: 3430; 55%)

RECEIVED 20 JUN 2018

Date/Time: File Pass 107

20/6 Typist

Date/Time: File Return 107



Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp: (\$)
☐ Interview: (\$)
☐ Tech. Supp: (\$)
☐ Workshop: (\$)

Survey Fee:

Transport:

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

11. 12. 13. 14. 15. 16. 17. 18. 19. 20.

21. 22. 23. 24. 25. 26. 27. 28. 29. 30.

31. 32. 33. 34. 35. 36. 37. 38. 39. 40.

41. 42. 43. 44. 45. 46. 47. 48. 49. 50.

51. 52. 53. 54. 55. 56. 57. 58. 59. 60.

Report Format:

Lump Sum / LB: (\$). 2700

145

50

50

39

284



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004211MFSH
Our Ref: CS/FCI18009765/Dtd3

Date: 06 June 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 1251A

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/06/2018 at the premises of M/s PEGASUS ENGINEERING, and have the following to report:-

Workshop Estimate Amount	: S\$ 6,130.00
Revised Estimate Amount	: S\$ 3,399.60
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages
at the rear n/s portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	25-05-2018	Our Ref No. D18004211MFSH
Accident Date	24-05-2018	Claim Type. Third Party
Insured Vehicle	SHA7839B	Third Party Vehicle. SLM1251A
Survey Location	51 DEFU LANE 10	
Contact Person.	ALVIN LOW	
Contact No.	68581846/ 0	Fax No. 64876070
Survey Type	DIRECT SETTLEMENT: EST. COR - \$6,559.10	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240787)



PRI Documents



Close



PRI Header Details

Claim No	D18004211MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD [M/S NG EVAN]
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR - \$6,559.10		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7839B	TP Vehicle No	SLM1251A
PRI Recieved Date	28-05-2018 02:28:39 PM	Surveyor Appointed Date	28-05-2018 06:11:28 PM	Surveyor Accept Date	30-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-05-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name	Action
-----------	--------

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 6 June 2018 10:04 AM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004211MFSH/1
Attachments: CSFCI18009765Dtd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLM 1251A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 30 May 2018 4:00 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004211MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 28 May 2018 6:11 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004211MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	7200G

Vehicle Details

Vehicle No.:	SLM1251A
Vehicle to be Exported:	Yes
Intended De-registration Date:	24 May 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	P520430799
Chassis No.:	JM6BN22A8H0143358
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,096.00
Original Registration Date:	22 Mar 2017
First Registration Date:	22 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$11,096.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2027
PARF Rebate Amount:	\$8,322.00

Intended COE Rebate Details

COE Expiry Date:	21 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$39,544.00
Total Rebate Amount:	\$47,866.00

The information contained herein is correct as at 24 May 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/05-1286	Quotation Date : 28/05/2018	Terms : 30 DAYS
Vehicle No : SLM1251A	Chassis No : JM6BN22A8H0143358	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEHICLE NO: SHA7839B, DATE OF ACCIDENT: 24.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>Dented</i>	1	1,075.0000	1,075.00 ✓
2	N/S REAR BUMPER REFLECTOR <i>mounting crack</i>	1	51.0000	51.00 ✓
3	N/S REAR BUMPER SIDE RETAINER <i>svc</i>	1	92.0000	92.00 ✗
4	N/S REAR BUMPER SIDE HOLDER <i>svc</i>	1	74.0000	74.00 ✗
5	REAR BUMPER SIDE HOLDER RIVETS <i>new</i>	4	6.0000	24.00 ✓
6	REAR BUMPER CLIPS <i>new</i>	6	5.0000	30.00 ✓
7	N/S REAR BUMPER TOW COVER <i>svc</i>	1	17.0000	17.00 ✗
8	REAR BUMPER CENTRE BRACKET <i>svc</i>	1	12.5000	12.50 ✗
9	N/S REAR BUMPER END SPLASHIELD COVER <i>new</i>	1	80.0000	80.00 ✗
10	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	538.0000	538.00 ✓
11	REAR END PANEL <i>rep</i>	1	556.0000	556.00 ✗
12	REAR END PANEL INNER TRIM <i>new</i>	1	96.0000	96.00 ✗
13	N/S REAR FENDER LOWER EXTENSION PANEL <i>new</i>	1	102.0000	102.00 ✗
14	N/S REAR LAMP <i>crack mounting</i>	1	519.0000	519.00 ✓
15	REAR LAMP CLIP HOLDER <i>svc</i>	2	10.0000	20.00 ✗
16	BOOTLID <i>rep</i>	1	958.0000	958.00 ✗
17	BOOTLID MAZDA 3 BADGE <i>svc</i>	1	54.0000	54.00 ✗
18	BOOTLID CENTRE LOGO BADGE <i>svc</i>	1	75.0000	75.00 ✗
19	BOOTLID SKYACTIV BADGE <i>svc</i>	1	64.0000	64.00 ✗
20	LESS 20% ITEM (1-19)	1	-887.5000	-887.50
21	REAR BUMPER PARKING SENSOR <i>shorted</i>	1	450.0000	220/- 450.00 ✓
22	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00 40/-
23	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00 30/-

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/05-1286	Quotation Date : 28/05/2018	Terms : 30 DAYS
Vehicle No : SLM1251A	Chassis No : JM6BN22A8H0143358	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEHICLE NO: SHA7839B, DATE OF ACCIDENT: 24.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	150.00 80/-
25	TO RUST PROOFING OF THE AFFECTED AREAS	1	120.0000	120.00 40/-
26	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	880.0000	880.00 600/-
27	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	800.0000	800.00 600/-

05/06/2018 @ 1245hrs

Not Authored

L/sum

3 days.

LKK Auto

Photo after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	6,130.00
GST(7.00%)	429.10
Total (SGD)	6,559.10

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009765/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7839B	Veh. Inspected	SLM 1251A	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004211MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	28/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0143358	Colour	RED	
Odometer	101106	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2018	Inspection Date	05/06/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 1251A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	1,075.00	1,075.00
1	N/S REAR BUMPER REFLECTOR	MOUNTING CRACKED	51.00	51.00
1	N/S REAR BUMPER SIDE RETAINER	SERVICEABLE	92.00	-
1	N/S REAR BUMPER SIDE HOLDER	SERVICEABLE	74.00	-
4	REAR BUMPER SIDE HOLDER RIVETS @\$6.00	NECESSARY	24.00	24.00
6	REAR BUMPER CLIPS @\$5.00	NECESSARY	30.00	30.00
1	N/S REAR BUMPER TOW COVER	SERVICEABLE	17.00	-
1	REAR BUMPER CENTRE BRACKET	SERVICEABLE	12.50	-
1	N/S REAR BUMPER END SPLASHIELD COVER	NOT NECESSARY	80.00	-
1	REAR BUMPER REINFORCEMENT	DENTED	538.00	538.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	556.00	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	96.00	-
1	N/S REAR FENDER LOWER EXTENSION PANEL	NOT NECESSARY	102.00	-
1	N/S REAR LAMP	MOUNTING CRACKED	519.00	519.00
2	REAR LAMP CLIP HOLDER @\$10.00	SERVICEABLE	20.00	-
1	BOOTLID	TO REPAIR SEE LABOUR	958.00	-
1	BOOTLID MAZDA 3 BADGE	SERVICEABLE	54.00	-
1	BOOTLID CENTRE LOGO BADGE	SERVICEABLE	75.00	-
1	BOOTLID SKYACTIV BADGE	SERVICEABLE	64.00	-
	LESS 20% DISCOUNT		-887.50	-447.40
			3,550.00	1,789.60
SPECIAL NETT ITEMS				
1	REAR BUMPER PARKING SENSOR (SN)	SHORTED	450.00	220.00
			450.00	220.00
LABOUR				
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	40.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	30.00

Report Ref No. CS/FCI18009765/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		150.00	80.00
	TO RUST PROOFING OF THE AFFECTED AREAS.		120.00	40.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND BOOTLID.		880.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		800.00	600.00
			2,130.00	1,390.00
GRAND TOTAL			6,130.00	3,399.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/FCI18009765/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.