### 51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore 408933

Claim Reference: SF28

Assessment Number: SF000136

**Version: LKKAUTOC/3** 

Date Calculated: 20/06/2018 07:10

**Full Report - V1** 

Registration: SKU3889S Printed: 20/06/2018 14:10

**Summary Information** 

Claim

Location: Singapore (SG) LKK AUTO Printed by: **Authorisation Status:** Interim

Work Provider:

MSIG Insurance (Singapore) Pte

SF28

Not Known

%

Claim Reference:

Policy Number: Other Reference: Third Party: Insured Amount: Under Warranty: Warranty Expired:

SGD Currency: Date of Incident: 07/05/2018

Able to Authorise Repairs: TBA Repairs Authorised: **TBA** 

Estimated Repair Time: Quote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

**Vehicle Details** 

Vehicle

**HONDA** Manufacturer: Model: Mobilio Sub Model: RS(0) Model Sheet Number: HM2 14 SKU3889S Registration:

Registration Month: Registration Year:

VIN Number:

Odometer:

Colour:

**Engine Number:** 

Fuel Level:

**Model Specs** 

FROM MODEL 2016 **ELECT DOOR MIRRORS** SEATBELT TENSIONER XENON HEADLAMPS SIDE FLASHER

REAR WIPER PAINTED DOOR HANDLES MOULDINGS PAINTED

1.5 LTR 88KW

**ELECT POWER STEERING** 

**AIRBAG** 

S-WHEEL RADIO CONT

**ROOF SPOILER** 

SILL TRIMS

TWO COAT PEARL/MICA

AUTO AIR CON REARVIEW CAMERA **TOUCHSCREEN** 

FOG LAMPS

AUTO HEADLAMP LEVEL CTR BUMP CTR CVR CVT AUTO GEARBOX

ABS SYSTEM

TYRES 185/65 VR 15 LWR GRILLE PAINTED FRONT/REAR MUDFLAPS PAINTING OFF VEHICLE

**Vehicle Condition** 

**Vehicle Status** 

Pre-Accident Condition: Steering:

Severity of Impact: Vehicle Status on Inspection:

Brakes Pedal Travel: Date of Inspection: 15/05/2018 Place of Inspection:

Tyres Condition:

Pre-Accident Damage:

Tread Depth LHF: Tread Depth RHF: Tread Depth RHR: Tread Depth LHR: Direction of Impact: Damage Areas:


# 51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore


Claim Reference: SF28

**Assessment Number: SF000136** 

Version: LKKAUTOC/3

Date Calculated: 20/06/2018 07:10





**Full Report - V1** 

Registration: SKU3889S Printed: 20/06/2018 14:10

### **Addresses**

<b>Cost Summary</b>	/
---------------------	---

Total Labour	\$565.00
Total Paint/Material	\$105.36
Total Parts	\$272.80
Total of Additional Costs	\$30.00
Excess:	TBA
Grand Total Exc GST:	\$973.16
7 % GST:	\$68.12
Grand Total Inc GST:	\$1,041.28

# **Repair Information**

LABOUR

#### Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR Price/Dent = \$50.00/HR

Repair /

WU	Cost Price (\$)
4.0	20.00
20.0*	100.00
30.0*	150.00
54.0	
0.0HRS	0.00
0.0HRS	0.00
5.4HRS	\$270.00
5.9HRS	\$295.00
11.3HRS	\$565.00
	4.0 20.0* 30.0* 54.0 0.0HRS 0.0HRS 5.4HRS 5.9HRS

PAINT W	ORK T	Time Basis 10 WU = 1 HR. Price = \$50.00/HR			
Guide Nu	ımber Description	W	U	Cost Price (\$)	
	- PAINTING OFF VEHICLE - TWO COAT PEARL/MICA				
2583	REAR BUMPER NEW PART PAINT K1R	10.	0		
2711	REAR PANEL REPAIR PAINTING <50%	9.	0		
3481	L/R SIDE PANEL REPAIR PAINTING <5	)% <b>14.</b>	0		
	LABOUR COST - PAINT				
	TIME(PAINT)	33.	0		
	Preparation Main Work Metal	21.	0		
	Preparation Comp. Work Plastic	5.	0		
	Preparation Work Multi Layer Paint	: <b>0.</b>	0		
	Total Work Units (10WU/HR)	59.	0		
	Total Paintwork Labour		9HRS	\$295.00	

# 51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SF28 Full Report - V1
Assessment Number: SF000136 Registration: SKU3889S

Version: LKKAUTOC/3 Printed: 20/06/2018 14:10

Date Calculated: 20/06/2018 07:10

	MATERIAL COST - PAINT  New Part Painting - Plastic K1R  Repair Painting  Material-Const Main Work Metal  Material-Const Comp. Work Plastic  Total Excluding Pearlescent Uplift  Pearlescent Uplift @ 0.0%  Total Paint Material Cost					Cost Price \$48.22 \$30.04 \$18.10 \$9.00 \$105.36 \$0.00 \$105.36
PARTS					Drice \/	alid: 01/06/2015
<b>Guide No. 0</b> 2619 1	Qty	<b>Description</b> L/R BUMPER BRACKET	Part Number 71598TE7K01	Supplier	Bet 0%	alid: 01/06/2015 . Price (\$) 24.00*
2583 1	1	REAR BUMPER	71501TE7K00ZZ		0%	200.00*
	I s and	RR BUMPER CLAMP KIT	USE SINGLE PAR Sub Total Mark Up Fr Sundry Par Total Part	rom Cost rts	0% (10 %) (Fixed)	24.00* \$248.00 \$24.80 \$0.00 \$272.80
x. Excilainge	_	NB - COLOUR CODED	ITEMS/TRIM - PART	NUMBERS M	IAY DIFFER	
Extras			, <u>-</u>			
		<b>Description</b> RR SENSORS	0%	terment al Extras		<b>Price</b> \$30.00 <b>\$30.00</b>
Final Cal	cula	ation				·
Total Parts Labour	5					\$272.80
		Panel/Mechanical Paintwork			\$270.00 \$295.00	
Total Labo Additional	Cos					\$565.00
C	Corr	Prot Materials External Prot Materials Internal of Specialist			\$0.00 \$0.00 \$30.00	
Total of Ad		•			·	\$30.00
	-	aterial Costs ccludes GST				\$105.36 \$973.16
		@ 7 % cludes GST		_		\$68.12 \$1,041.28

#### **Assessment Notes**