

ASS. REC. BY:

REF: CS/MSG/18009793/ T1vd3k

Special Instruction:

SMV/VNT  
Merimen

Taufik

ASSIGNMENT (Office)

From (Person):

Eliza Ho

of

MSG

Date/Time:

28/5/18 @ 4:03pm

Estimated Cost:

Bill to:

① /TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 3889S

Insured:

at Workshop in/s:

Shu Fatt Auto

Tel:

62730119

of

Blk 1009 Bkt meruh lane 3 #01-90

Policy No:

P4022801DMV

Claim No:

557752

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

05/05/2018

CA / RV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:05pm @ 30/5/18

Person Contacted:

Julia

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 3889S - C03/MSG/1800887/Srb

D.O.A: 5/5/18

31/5/18

Perce approved from ming shao by merimen

31/5/18

Informed Pat c/A ex \$500 by email

31/5/18

Revert by merimen (Audatex)

8/6/18

@ 350pm Pat said vehicle has not send in for repair

Signature

Tang

REF:

MSIG

ASSIGNMENT

o/c

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: **9500**  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **\$70K**  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / **REV** REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SK43889S** Yr Regn: **2015 July**

Type: **MC** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Handy disabilities** cc: **1497**

Colour: **white** A/C: Insured / Std / NI / NA

Sp. Reading: **29718** T/Radio: Insured / Std / NI / NA

EngiNo: \_\_\_\_\_

C/No: **MR4004870FP000188**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **185/65R15**

R: \_\_\_\_\_

BS / **DUN** / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R/Bal: **6** mm R/Bal: **6** mm

L/Bal: **6** mm L/Bal: **6** mm

D.O.A: \_\_\_\_\_ D.O.I: **30/5/18 2130pm**

Survey held at: **Shin Fatt 6m**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

**N/S Rear**

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

**20/6/18 Final fig \$ 973.16 confirmed by email (Red 892.74, 481)**

RECEIVED 21 JUN 2018

Draw/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Draw/Time, File Return to?

2) **21/6 - typist**

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee

Transportation

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format: **merimen**

Lump Sum / I.B.I: (\$ **973.16**)

TOTAL

**150**

**10**

**160**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009793/T1vd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-05-2018



Code : MSG

1.

## Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKU 3889S
Policy No. P4022801DMV	Coverage (\$)	0.00
Claim No. 557752	Excess (\$)	500.00
Assign From MERIMEN (ELIZA HO)	Assign Date	30/05/2018

2.

## Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer	Steering	
Brakes	Modification	
General		

3.

## Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

## Description of Damages

--

5.

## General Information

Accident Date 05/05/2018	Inspection Date 30/05/2018
Survey held at SHU FATT AUTO WORKS	
BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723	

5a.

## Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Ret	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018 <a href="#">Sendback Est</a>	15 May 2018 13:56 <b>S\$1,865.90</b>	28 May 2018 16:03 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS	
Insured:	ONG GEOK TIN, SHEILA, ID: S7824553J, Tel: +6593675373
Vehicle Reg. No.:	SKU3889S
Claim Type:	OD / 557752
Date of Loss:	05/05/2018 14:00 - :59 [33 Months and 12 Days From LTA Reg Date (Man Yr)]
Policy/Cover Note No.:	P4022801DMV (Comprehensive) Coverage: 23/07/2017 - 22/07/2018
Excess:	S\$500.00
Repairer:	Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90, 159723 Bukit Merah - Tel: 62730119
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/05/2018]
Driver/Custodian:	TAN EE CHONG (38 / Male), NRIC: S7923842B, Tel: +6593675373
Adj Asg. Remarks:	Survey on 30/05/18(Wed), car in 10am. Survey & revert. Please contact us ASAP if you cannot attend this assignment.

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

in

## View Received Message

This mail is associated with :

**SKU3889S (557752)**

OD

May 5 2018 2:00PM

[ONG GEOK TIN, SHEILA]

Shu Fatt Auto Works

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 21/06/2018 11:25 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (\$973.16) - SKU3889S - Claim Handler: Eliza Ho Teng Boon

Approved:973.16.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 20 Jun 2018

**Preliminary Advice**

Vehicle No	: SKU3889S	Accident Date	: 05/05/2018
Make	: HONDA MOBILIO SV	Policy No.	: P4022801DMV
Assignment Date	: 28/05/2018	Excess	: S\$500.00
Date of Inspection	: 30/05/2018	Est. Duration of Repair	: 3.00
Inspection At	: SHU FATT AUTO WORKS (HQ) BLOCK 1009 BUKIT MERAH LANE 3, #01-90 SINGAPORE 159723		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages .n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,865.90
Revised Amount	:S\$	973.16
Check Items (Estimated)	:S\$	
Total	:S\$	973.16

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	44,008.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,992.00

**Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

## View Received Message

This mail is associated with :

**SKU3889S (557752)**

OD

May 5 2018 2:00PM

[ONG GEOK TIN, SHEILA]

Shu Fatt Auto Works

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 01/06/2018 10:51 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$1503.60) - SKU3889S - Claim Handler: Eliza Ho Teng Boon

Approved:1503.60:check items to be verified and confirmed.

### DOCUMENTS SUMMARY

There are no documents.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 31 May 2018 9:34 AM  
**To:** 'Pat-Shu Fatt Auto Works'  
**Cc:** SUR  
**Subject:** SKU 3889S-DOA: 5/5/2018 (MSIG OD)

Dear Pat,

As instructed by our client, please proceed to repair the insured vehicle **SKU 3889S (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## View Received Message

This mail is associated with :

**SKU3889S (557752)**

OD

May 5 2018 2:00PM

[ONG GEOK TIN, SHEILA]

Shu Fatt Auto Works

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 31/05/2018 09:14 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$1616,20) - SKU3889S - Claim Handler: Eliza Ho Teng Boon

Approved:1616,20:check items to be verified and confirmed.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Eliza Ho Teng Boon	Date: 31 May 2018
<b><u>Preliminary Advice</u></b>	

Vehicle No	: SKU3889S	Accident Date	: 05/05/2018
Make	: HONDA MOBILIO SV	Policy No.	: P4022801DMV
Assignment Date	: 28/05/2018	Excess	: S\$500.00
Date of Inspection	: 30/05/2018	Est. Duration of Repair	: 3.00
Inspection At	: SHU FATT AUTO WORKS (HQ) BLOCK 1009 BUKIT MERAH LANE 3, #01-90 SINGAPORE 159723		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,865.90
Revised Amount	:S\$	1,356.20
Check Items (Estimated)	:S\$	147.40
Total	:S\$	1,503.60
Lump Sum Repair	:S\$	
<b>Total Loss Consideration</b>		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	44,008.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,992.00

**Remarks**

<input checked="" type="checkbox"/> ( X )	The vehicle is economical for repair.
<input type="checkbox"/> ( )	The above survey was conducted on a 'without prejudice' basis.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 30 May 2018

## Preliminary Advice

Vehicle No	: SKU3889S	Accident Date	: 05/05/2018
Make	: HONDA MOBILIO SV	Policy No.	: P4022801DMV
Assignment Date	: 28/05/2018	Excess	: S\$500.00
Date of Inspection	: 30/05/2018	Est. Duration of Repair	: 3.00
Inspection At	: SHU FATT AUTO WORKS (HQ) BLOCK 1009 BUKIT MERAH LANE 3, #01-90 SINGAPORE 159723		

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,865.90
Revised Amount	:S\$	1,616.20
Check Items (Estimated)	:S\$	147.40
Total	:S\$	1,763.60

Lump Sum Repair	:S\$	
-----------------	------	--

## Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	44,008.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,992.00

## Remarks

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4553J
<b>Vehicle Details</b>	
Vehicle No.:	SKU3889S
Vehicle to be Exported:	No
Intended De-registration Date:	28 May 2018
Vehicle Make:	HONDA
Vehicle Model:	MOBILIO SV 1.5 CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15Z12100740
Chassis No.:	MRHDD4870FP000188
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,935.00
Original Registration Date:	23 Jul 2015
First Registration Date:	23 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$18,935.00
<b>OPC Cash Rebate Details</b>	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2025
PARF Rebate Amount:	\$14,201.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,700.00
COE Rebate Amount:	\$29,807.00
<b>Total Rebate Amount:</b>	<b>\$44,008.00</b>

The information contained herein is correct as at 28 May 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/05/2018 14:17
Date Of Accident	05/05/2018 14:40
Exact Location Of Accident	JUNCTION OF BRAS BASAH RD & VICTORIA STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU3889S
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	ONG GEOK TIN, SHEILA - 92982606
NRIC No	S7824553J
Email Address	ALIEHSGNO@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-93675373
Alternative Phone No	OFFICE-93675373

#### Vehicle Particulars

Manufacturer	HONDA
Model	MOBILO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

#### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P4022801DMV
Cover Note Number	

#### Driver

Name of Driver	TAN EE CHONG
NRIC No	S7923842B
Date Of Birth	23/08/1979
Occupation	INDOOR
Date Of Driving Pass	18/09/1999
Driving Experience	18 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93675373
Fax Number	
Contact Number	
Email Address	ALIEHSGNO@HOTMAIL.COM


**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time: 7/5/18 12:40pm

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 7/5/18 12:40pm

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

**Shu Fatt Auto Works**  
**Bukit Merah Lane 3**  
**Blk 1009 #01-90**  
**Singapore 568047**

**Claim Reference:**  
**Assessment Number: SF000136**  
**Version: SHU FATT/1**  
**Date Calculated: 15/05/2018 06:23**

**Full Report - V1**  
**Registration: SKU3889S**  
**Printed: 15/05/2018 13:23**

**Summary Information**

**Claim**

Location: Singapore (SG)  
 Printed by: Shu Fatt  
 Authorisation Status: Interim  
 Work Provider: MSIG Insurance (Singapore) Pte

Currency: SGD  
 Date of Incident: 07/05/2018  
 Able to Authorise Repairs: TBA  
 Repairs Authorised: TBA

Claim Reference:  
 Policy Number:  
 Other Reference:  
 Third Party:  
 Insured Amount:  
 Under Warranty:  
 Warranty Expired:

Estimated Repair Time:  
 Quote Due Date:  
 Actual Repair Days:  
 Parts Ordered Date:  
 Hire Car Start:  
 Hire Car End:  
 Vehicle Collected:

*Tanpin 97495749*  
*Ex \$500*  
*30/5/18 @ 150pm*  
*Not authorise*  
*\*Resurvey before paint*  
*03 days*

**Vehicle Details**

**Vehicle**

Manufacturer: HONDA  
 Model: Mobilio  
 Sub Model: RS(O)  
 Model Sheet Number: HM2 14  
 Registration: SKU3889S  
 Registration Month:  
 Registration Year:  
 VIN Number:  
 Odometer: Not Known  
 Colour:  
 Engine Number:  
 Fuel Level: %

**Model Specs**

FROM MODEL 2016  
 ELECT DOOR MIRRORS  
 SEATBELT TENSIONER  
 XENON HEADLAMPS  
 SIDE FLASHER  
 REAR WIPER  
 PAINTED DOOR HANDLES  
 1.5 LTR 88KW  
 ELECT POWER STEERING  
 AIRBAG  
 S-WHEEL RADIO CONT  
 ROOF SPOILER  
 SILL TRIMS  
 TWO COAT PEARL/MICA

*sup @ the auto.com*  
 AUTO AIR CON  
 REARVIEW CAMERA  
 TOUCHSCREEN  
 FOG LAMPS  
 AUTO HEADLAMP LEVEL  
 CTR BUMP CTR CVR  
 MOULDINGS PAINTED  
 CVT AUTO GEARBOX  
 ABS SYSTEM  
 TYRES 185/65 VR 15  
 LWR GRILLE PAINTED  
 FRONT/REAR MUDFLAPS  
 PAINTING OFF VEHICLE

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:  
 Steering:

Brakes Pedal Travel:  
 Place of Inspection:  
 Pre-Accident Damage:

Tyres Condition:  
 Tread Depth LHF:  
 Tread Depth LHR:  
 Damage Areas:

Severity of Impact:  
 Vehicle Status on  
 Inspection:  
 Date of Inspection: 15/05/2018

Tread Depth RHF:  
 Tread Depth RHR:  
 Direction of Impact:

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# Shu Fatt Auto Works

Claim Reference:

Assessment Number: SF000136



Version: SHU FATT/1

Date Calculated: 15/05/2018 06:23

Full Report - V1

Registration: SKU3889S

Printed: 15/05/2018 13:23



## Addresses

## Cost Summary

Total Labour	\$885.00
Total Paint/Material	\$158.40
Total Parts	\$522.50
Total of Additional Costs	\$300.00
Excess:	TBA
Grand Total Exc GST:	\$1,865.90
7 % GST:	\$130.61
Grand Total Inc GST:	\$1,996.51

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR  
Price/Dent = \$50.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
8111A5	RENEW REAR BUMPER	4.0	20.00
	INCLUDES: BUMPER AND ALL		
	REQUIRED ATTACHED PARTS R + R		
714125	R + R LEFT TAILLAMP	2.0	10.00
2711	REPAIR REAR PANEL	20 40.0*	200.00
3481	REPAIR L/R SIDE PANEL	30 50.0*	250.00

### LABOUR COST

Total Work Units	96.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	9.6HRS	\$480.00
Paint Labour	8.1HRS	\$405.00
Total Labour	17.7HRS	\$885.00

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

### Guide Number Description

		WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- TWO COAT PEARL/MICA		
2583	REAR BUMPER NEW PART PAINT K1R	10.0	
2711	REAR PANEL REPAIR PAINTING <50%	9.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	14.0	
2931	BOOTLID/TAILGATE SURFACE PAINT	10.0	
3482	R/R SIDE PANEL SURFACE PAINT	7.0	
3905	CTR REAR CROSSMEMBERSURFACE PAINT	5.0	
LABOUR COST - PAINT			
TIME(PAINT)		55.0	
Preparation Main Work Metal		21.0	



# Shu Fatt Auto Works

Claim Reference:

Assessment Number: SF000136

Version: SHU FATT/1

Date Calculated: 15/05/2018 06:23

Full Report - V1

Registration: SKU3889S

Printed: 15/05/2018 13:23

Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	81.0	
Total Paintwork Labour	8.1HRS	\$405.00
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting - Plastic K1R		\$48.22
Surface-/Blend Paint		\$53.04
Repair Painting		\$30.04
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$158.40
Pearlescent Uplift @ 0.0%		\$0.00
<b>Total Paint Material Cost</b>		<b>\$158.40</b>

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2619	1	L/R BUMPER BRACKET	71598TE7K01		0%	24.00*
3283	1	L/R LAMP	33551TE7T01		0%	110.00*
2959	1	L/T-GATE RUBB BRKT	74829TF0000		0%	8.00*
2620	1	R/R BUMPER BRACKET	71593TE7K01		0%	24.00*
2583	1	REAR BUMPER	71501TE7K00ZZ		0%	200.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0%	24.00*
2593	1	RR BUMPER CTR COVER	71502TE7K90		0%	85.00*
f: OEM Parts			Sub Total			\$475.00
g: Original			Mark Up From Cost	(10 %)		\$47.50
h: Secondhand			Sundry Parts	(Fixed)		\$0.00
p: Parallel			<b>Total Parts</b>			<b>\$522.50</b>
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
RR SENSORS SPECIALIST	0%	\$260.00
Corr Prot Materials External		\$40.00
<b>Total Extras</b>		<b>\$300.00</b>

## Final Calculation

<b>Total Parts</b>	<b>\$522.50</b>
<b>Labour</b>	
Total Panel/Mechanical	\$480.00
Total Paintwork	\$405.00
<b>Total Labour</b>	<b>\$885.00</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$40.00
Cost of Specialist	\$260.00
<b>Total of Additional Costs</b>	<b>\$300.00</b>
<b>Total Paint/Material Costs</b>	<b>\$158.40</b>
<b>Grand Total Excludes GST</b>	<b>\$1,865.90</b>
GST @ 7 %	\$130.61
<b>Grand Total Includes GST</b>	<b>\$1,996.51</b>

## Assessment Notes

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Revert

Claim Reference: SF28  
Assessment Number: SF000136  
Version: SHU FATT/2  
Date Calculated: 31/05/2018 07:21

Full Report - V1  
Registration: SKU3889S  
Printed: 31/05/2018 14:22

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	07/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	SF28	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	



### Vehicle Details

Vehicle		Model Specs	
Manufacturer:	HONDA	FROM MODEL 2016	AUTO AIR CON
Model:	Mobilio	ELECT DOOR MIRRORS	REARVIEW CAMERA
Sub Model:	RS(O)	SEATBELT TENSIONER	TOUCHSCREEN
Model Sheet Number:	HM2 14	XENON HEADLAMPS	FOG LAMPS
Registration:	SKU3889S	SIDE FLASHER	AUTO HEADLAMP LEVEL
Registration Month:		REAR WIPER	CTR BUMP CTR CVR
Registration Year:		PAINTED DOOR HANDLES	MOULDINGS PAINTED
VIN Number:		1.5 LTR 88KW	CVT AUTO GEARBOX
Odometer:	Not Known	ELECT POWER STEERING	ABS SYSTEM
Colour:		AIRBAG	TYRES 185/65 VR 15
Engine Number:		S-WHEEL RADIO CONT	LWR GRILLE PAINTED
Fuel Level:	%	ROOF SPOILER	FRONT/REAR MUDFLAPS
		SILL TRIMS	PAINTING OFF VEHICLE
		TWO COAT PEARL/MICA	

## Vehicle Condition

### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



## Addresses

## Cost Summary

Total Labour	\$885.00
Total Paint/Material	\$158.40
Total Parts	\$420.20
Total of Additional Costs	\$40.00
Excess:	TBA
Grand Total Exc GST:	\$1,503.60
7 % GST:	\$105.25
Grand Total Inc GST:	\$1,608.85

## Repair Information

## LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR  
Price/Dent = \$50.00/HR

## Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
8111A5	RENEW REAR BUMPER	4.0	20.00
	INCLUDES: BUMPER AND ALL		
	REQUIRED ATTACHED PARTS R + R		
714125	R + R LEFT TAILLAMP	2.0	10.00
2711	REPAIR REAR PANEL	40.0*	200.00
3481	REPAIR L/R SIDE PANEL	50.0*	250.00

## LABOUR COST

Total Work Units	96.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	9.6HRS	\$480.00
Paint Labour	8.1HRS	\$405.00
Total Labour	17.7HRS	\$885.00

## PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- TWO COAT PEARL/MICA		
2583	REAR BUMPER NEW PART PAINT K1R	10.0	
2711	REAR PANEL REPAIR PAINTING <50%	9.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	14.0	
2931	BOOTLID/TAILGATE SURFACE PAINT	10.0	
3482	R/R SIDE PANEL SURFACE PAINT	7.0	
3905	CTR REAR CROSSMEMBERSURFACE PAINT	5.0	

## LABOUR COST - PAINT

TIME(PAINT)	55.0
Preparation Main Work Metal	21.0

Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	81.0	
Total Paintwork Labour	8.1HRS	\$405.00
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting - Plastic K1R		\$48.22
Surface-/Blend Paint		\$53.04
Repair Painting		\$30.04
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$158.40
Pearlescent Uplift @ 0.0%		\$0.00
<b>Total Paint Material Cost</b>		<b>\$158.40</b>

#### PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
2619	1	L/R BUMPER BRACKET	71598TE7K01		0% 24.00*
3283	1	L/R LAMP	33551TE7T01		0% 110.00*
2620	1	R/R BUMPER BRACKET	71593TE7K01		0% 24.00*
2583	1	REAR BUMPER	71501TE7K00ZZ		0% 200.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0% 24.00*
f: OEM Parts		Sub Total			\$382.00
g: Original		Mark Up From Cost		(10 %)	\$38.20
h: Secondhand		Sundry Parts		(Fixed)	\$0.00
p: Parallel		<b>Total Parts</b>			<b>\$420.20</b>
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

RR SENSORS	SPECIALIST	0%	\$0.00
------------	------------	----	--------

#### Extras

Description	Price
Corr Prot Materials External	\$40.00
<b>Total Extras</b>	<b>\$40.00</b>

#### Final Calculation

<b>Total Parts</b>	<b>\$420.20</b>
<b>Labour</b>	
Total Panel/Mechanical	\$480.00
Total Paintwork	\$405.00
<b>Total Labour</b>	<b>\$885.00</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$40.00
<b>Total of Additional Costs</b>	<b>\$40.00</b>
<b>Total Paint/Material Costs</b>	<b>\$158.40</b>
<b>Grand Total Excludes GST</b>	<b>\$1,503.60</b>
GST @ 7 %	\$105.25
<b>Grand Total Includes GST</b>	<b>\$1,608.85</b>

#### Assessment Notes

**51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore**

**Claim Reference: SF28**

**Full Report - V1**

**Assessment Number: SF000136**

**Registration: SKU3889S**

**Version: SHU FATT/2**

**Printed: 31/05/2018 14:22**

**Date Calculated: 31/05/2018 07:21**

---

**Shu Fatt Auto Works**  
**Bukit Merah Lane 3**  
**Blk 1009 #01-90**  
**Singapore 568047**

**Claim Reference:**  
**Assessment Number: SF000136**  
**Version: SHU FATT/1**  
**Date Calculated: 15/05/2018 06:23**

**Full Report - V1**  
**Registration: SKU3889S**  
**Printed: 15/05/2018 13:23**

**Summary Information**

**Claim**

Location: Singapore (SG)  
 Printed by: Shu Fatt  
 Authorisation Status: Interim  
 Work Provider: MSIG Insurance (Singapore) Pte

Currency: SGD  
 Date of Incident: 07/05/2018  
 Able to Authorise Repairs: TBA  
 Repairs Authorised: TBA

Claim Reference:  
 Policy Number:  
 Other Reference:  
 Third Party:  
 Insured Amount:  
 Under Warranty:  
 Warranty Expired:

Estimated Repair Time:  
 Quote Due Date:  
 Actual Repair Days:  
 Parts Ordered Date:  
 Hire Car Start:  
 Hire Car End:  
 Vehicle Collected:

*Tanpin 97495749*  
*Ex \$500*  
*3-5/18 @ 150pm*  
*Not Authorise*  
*\*Resonance before paint*  
*0.5 days*

**Vehicle Details**

**Vehicle**

Manufacturer: HONDA  
 Model: Mobilio  
 Sub Model: RS(O)  
 Model Sheet Number: HM2 14  
 Registration: SKU3889S  
 Registration Month:  
 Registration Year:  
 VIN Number:  
 Odometer: Not Known  
 Colour:  
 Engine Number:  
 Fuel Level: %

**Model Specs**

FROM MODEL 2016  
 ELECT DOOR MIRRORS  
 SEATBELT TENSIONER  
 XENON HEADLAMPS  
 SIDE FLASHER  
 REAR WIPER  
 PAINTED DOOR HANDLES  
 1.5 LTR 88KW  
 ELECT POWER STEERING  
 AIRBAG  
 S-WHEEL RADIO CONT  
 ROOF SPOILER  
 SILL TRIMS  
 TWO COAT PEARL/MICA

AUTO AIR CON  
 REARVIEW CAMERA  
 TOUCHSCREEN  
 FOG LAMPS  
 AUTO HEADLAMP LEVEL  
 CTR BUMP CTR CVR  
 MOULDINGS PAINTED  
 CVT AUTO GEARBOX  
 ABS SYSTEM  
 TYRES 185/65 VR 15  
 LWR GRILLE PAINTED  
 FRONT/REAR MUDFLAPS  
 PAINTING OFF VEHICLE

*sup @ the auto co*

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:  
 Steering:

Severity of Impact:  
 Vehicle Status on  
 Inspection:

Date of Inspection: 15/05/2018

Brakes Pedal Travel:  
 Place of Inspection:  
 Pre-Accident Damage:

Tyres Condition:  
 Tread Depth LHF:  
 Tread Depth LHR:  
 Damage Areas:

Tread Depth RHF:  
 Tread Depth RHR:  
 Direction of Impact:

*Parts: 248.00*  
*10%: 24.80*  
*272.80*

*Panel/mechanical: 520.00*  
*Paintwork: 405.00*  
*Panel/mechanical: 158.40*  
*1,356.20*

# Shu Fatt Auto Works

Claim Reference:

Assessment Number: SF000136

Version: SHU FATT/1

Date Calculated: 15/05/2018 06:23

Full Report - V1

Registration: SKU3889S

Printed: 15/05/2018 13:23

Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	81.0	
Total Paintwork Labour	8.1HRS	\$405.00
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting - Plastic K1R		\$48.22
Surface-/Blend Paint		\$53.04
Repair Painting		\$30.04
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$158.40
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$158.40

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2619	1	L/R BUMPER BRACKET	71598TE7K01		0%	24.00*
3283	1	L/R LAMP	33551TE7T01		0%	10.00*
2959	1	L/T-GATE RUBB BRKT	74829TF0000		0%	8.00*
2620	1	R/R BUMPER BRACKET	71593TE7K01		0%	24.00*
2583	1	REAR BUMPER	71501TE7K00ZZ		0%	200.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0%	24.00*
2593	1	RR BUMPER CTR COVER	71502TE7K90		0%	85.00*
f: OEM Parts			Sub Total			\$475.00
g: Original			Mark Up From Cost	(10 %)		\$47.50
h: Secondhand			Sundry Parts	(Fixed)		\$0.00
p: Parallel			Total Parts			\$522.50
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
RR SENSORS SPECIALIST	0%	\$260.00
Corr Prot Materials External		\$40.00
<b>Total Extras</b>		<b>\$300.00</b>

## Final Calculation

<b>Total Parts</b>		<b>\$522.50</b>
<b>Labour</b>		
Total Panel/Mechanical	\$480.00	
Total Paintwork	\$405.00	
<b>Total Labour</b>		<b>\$885.00</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$40.00	
Cost of Specialist	\$260.00	
<b>Total of Additional Costs</b>		<b>\$300.00</b>
<b>Total Paint/Material Costs</b>		<b>\$158.40</b>
<b>Grand Total Excludes GST</b>		<b>\$1,865.90</b>
GST @ 7 %		\$130.61
<b>Grand Total Includes GST</b>		<b>\$1,996.51</b>

## Assessment Notes





日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SHU FATT AUTO WORKS

BLK 1009 #01-90 BUKIT MERAH LANE 3

S(159723)

SINGAPORE 159723

TEL : 62730119 FAX : 62707065

ATTN : PAT/ JULIA

WINDSCREEN GLASS  
Dept Direct: 9417 9791 / 9748 9926



Dept Direct: 9306 9810

Dept Direct: 9306 9811

Dept Direct: 9417 9790



Dept Direct: 9417 9794

Dept Direct: 9417 9795

Dept Direct: 9417 9796

Dept Direct: 9417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),  
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-16173

DATE : 31/05/2018

CUSTOMER ID : SHU001

VEH REG. NO. : SKU3889S

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. H91503-S73-003	CLIP > 650	U1 I,1-P6	12	2.00	24.00

SUB-TOTAL : 24.00

ADD GST 7.00 % 1.68

T. & O.E

TOTAL AMOUNT SGD : 25.68

[P] 31/05/2018 2:52:51PM

[E] 31/05/2018 2:51:37PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : AH BEE



\* AR 201805-16173 \*

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date





日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

=====~~GST REG. NO: M2-0119201-3 CO. REG. NO: 198307741M~~=====

SHU FATT AUTO WORKS

BLK 1009 #01-90 BUKIT MERAH LANE 3

S(159723)

SINGAPORE 159723

TEL : 62730119 FAX : 62707065

ATTN : PAT/ JULIA

WINDSCREEN GLASS  
Dept Direct: 6417 0791 / 0745 8838



Dept Direct: 6417 0794

Dept Direct: 6417 0796

Dept Direct: 6417 0798

Dept Direct: 6417

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)

Spark plug: Nippon-Chem, 40C (Made in Japan)

TAX INVOICE : AR201805-1587

DATE : 31/05/2018

CUSTOMER ID : SHU00

VEH REG. NO. : SKU3889

TERMS : 30 day

PO NO. :

PAGE NO. : Page 1 of

CURR. : SGI

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H71501-TR7-K907Z, DD5	BUMPER RR 2620	U1 HL3-B4	1	200.00	200.00
2	H71598-TR7-K01 DD5	SPACER RR LH 2619	U1 L2-B2-E	1	24.00	24.00

SUB-TOTAL : 224.00  
ADD GST 7.00 % 15.60

E. & O.E TOTAL AMOUNT SGD : 239.60

[P] 31/05/2018 10:50:34AM

[E] 31/05/2018 10:49:55AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : AH BEE



\* AR201805-15873 \*

Goods Received in Good Order

CW

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL

## Veron Chen (LKKAuto)

---

**From:** Pat-Shu Fatt Auto Works <shufatt@singnet.com.sg>  
**Sent:** Wednesday, 20 June 2018 3:39 PM  
**To:** Veron Chen (LKKAuto)  
**Subject:** RE: SKU 3889 S - finalised

Dear Veron,

Confirmed.

Kindly send offer.

Thanks & regards,  
Pat  
Shu Fatt Auto Works

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Wednesday, 20 June, 2018 2:29 PM  
**To:** Pat-Shu Fatt Auto Works  
**Subject:** RE: SKU 3889 S - finalised

Dear Pat,

Offer finalize amount \$973.16 before excess \$500 @ 3 working days.

Kindly check and confirmed.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Pat-Shu Fatt Auto Works [mailto:shufatt@singnet.com.sg]  
**Sent:** Wednesday, 20 June 2018 11:08 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** RE: SKU 3889 S - finalised

Dear Veron,

Thank you for your email.  
Please also include work unit for remove & refit for the reverse sensors which is not in the AudaTex.

Thanks & regards,  
Pat  
Shu Fatt Auto Works

---

**From:** Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]

**Sent:** Monday, 18 June, 2018 2:59 PM

**To:** Pat-Shu Fatt Auto Works; Taufikh (LKKAUTO)

**Subject:** RE: SKU 3889 S - finalised

Dear Pat,

Offer finalize amount \$831.28 before excess \$500 @ 3 working days.

Kindly check and confirmed.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Pat-Shu Fatt Auto Works [<mailto:shufatt@singnet.com.sg>]

**Sent:** Friday, 8 June 2018 5:17 PM

**To:** Taufikh (LKKAUTO) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>; Veron Chen (LKKAUTO) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Subject:** SKU 3889 S - finalised

Dear Veron / Taufikh,

Please see attached after paint photos, finalized calculation and supplier invoice.

Cost of repair: \$1356.20 before GST.

Excess: \$500.00

Thanks & regards,

Pat

Shu Fatt Auto Works

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Finalised

Claim Reference: SF28  
Assessment Number: SF000136  
Version: LKKAUTOC/4  
Date Calculated: 20/06/2018 07:24

Full Report - V1  
Registration: SKU3889S  
Printed: 20/06/2018 14:24

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	07/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte SF28	Repairs Authorised:	TBA
Claim Reference:	SF28	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	HONDA
Model:	Mobilio
Sub Model:	RS(O)
Model Sheet Number:	HM2 14
Registration:	SKU3889S
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



#### Model Specs

FROM MODEL 2016	AUTO AIR CON
ELECT DOOR MIRRORS	REARVIEW CAMERA
SEATBELT TENSIONER	TOUCHSCREEN
XENON HEADLAMPS	FOG LAMPS
SIDE FLASHER	AUTO HEADLAMP LEVEL
REAR WIPER	CTR BUMP CTR CVR
PAINTED DOOR HANDLES	MOULDINGS PAINTED
1.5 LTR 88KW	CVT AUTO GEARBOX
ELECT POWER STEERING	ABS SYSTEM
AIRBAG	TYRES 185/65 VR 15
S-WHEEL RADIO CONT	LWR GRILLE PAINTED
ROOF SPOILER	FRONT/REAR MUDFLAPS
SILL TRIMS	PAINTING OFF VEHICLE
TWO COAT PEARL/MICA	

## Vehicle Condition

### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



## Addresses

## Cost Summary

Total Labour	\$565.00
Total Paint/Material	\$105.36
Total Parts	\$272.80
Total of Additional Costs	\$30.00
Excess:	TBA
Grand Total Exc GST:	\$973.16
7 % GST:	\$68.12
Grand Total Inc GST:	\$1,041.28

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR  
 Price/Dent = \$50.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
8111A5	RENEW REAR BUMPER	4.0	20.00
	INCLUDES: BUMPER AND ALL		
	REQUIRED ATTACHED PARTS R + R		
2711	REPAIR REAR PANEL	20.0*	100.00
3481	REPAIR L/R SIDE PANEL	30.0*	150.00

### LABOUR COST

Total Work Units	54.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	5.4HRS	\$270.00
Paint Labour	5.9HRS	\$295.00
Total Labour	11.3HRS	\$565.00

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

### Guide Number Description

		WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- TWO COAT PEARL/MICA		
2583	REAR BUMPER NEW PART PAINT K1R	10.0	
2711	REAR PANEL REPAIR PAINTING <50%	9.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	14.0	

### LABOUR COST - PAINT

TIME(PAINT)	33.0	
Preparation Main Work Metal	21.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	59.0	
Total Paintwork Labour	5.9HRS	\$295.00

**51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore**

**Claim Reference: SF28**

**Full Report - V1**

**Assessment Number: SF000136**

**Registration: SKU3889S**

**Version: LKKAUTOC/4**

**Printed: 20/06/2018 14:24**

**Date Calculated: 20/06/2018 07:24**

**MATERIAL COST - PAINT**

New Part Painting - Plastic K1R	<b>Cost Price</b>
Repair Painting	\$48.22
Material-Const Main Work Metal	\$30.04
Material-Const Comp. Work Plastic	\$18.10
Total Excluding Pearlescent Uplift	\$9.00
Pearlescent Uplift @ 0.0%	\$105.36
Total Paint Material Cost	\$0.00
	<b>\$105.36</b>

**PARTS**

Guide No. Qty		Description	Part Number	Supplier	Bet.	Price (\$)
2619	1	L/R BUMPER BRACKET	71598TE7K01		0%	24.00*
2583	1	REAR BUMPER	71501TE7K00ZZ		0%	200.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0%	24.00*
f: OEM Parts			Sub Total			\$248.00
g: Original			Mark Up From Cost	(10 %)		\$24.80
h: Secondhand			Sundry Parts	(Fixed)		\$0.00
p: Parallel			<b>Total Parts</b>			<b>\$272.80</b>
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
RR SENSORS	0%	\$30.00
	<b>Total Extras</b>	<b>\$30.00</b>

**Final Calculation**

**Total Parts** **\$272.80**

**Labour**

Total Panel/Mechanical	\$270.00
Total Paintwork	\$295.00
<b>Total Labour</b>	<b>\$565.00</b>

**Additional Costs**

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$30.00

**Total of Additional Costs** **\$30.00**

**Total Paint/Material Costs** **\$105.36**

**Grand Total Excludes GST** **\$973.16**

GST @ 7 % **\$68.12**

**Grand Total Includes GST** **\$1,041.28**

**Assessment Notes**

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018 <a href="#">Sendback Est</a>	15 May 2018 13:56 <b>\$1,865.90</b>	28 May 2018 16:03 <a href="#">Edit Adj Rpt</a>	<b>\$973.16</b> <a href="#">Edit Estimates</a>	<b>\$973.16</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	ONG GEOK TIN, SHEILA, ID: S7824553J, Tel: +6593675373								
Vehicle Reg. No.:	SKU3889S	Date of Loss:	05/05/2018 14:00 - :59 [33 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 557752	Policy/Cover Note No.:	P4022801DMV (Comprehensive) Coverage: 23/07/2017 - 22/07/2018						
		Excess:	S\$500.00						
Repairer:	Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90, 159723 Bukit Merah - Tel: 62730119								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/06/2018]								
Driver/Custodian:	TAN EE CHONG (38 / Male), NRIC: S7923842B, Tel: +6593675373								
Adj Asg. Remarks:	Survey on 30/05/18(Wed), car in 10am. Survey & revert. Please contact us ASAP if you cannot attend this assignment.								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<ul style="list-style-type: none"> <li>MSIG_SG (21/06/2018): Alert - Adj Mandate Approved (\$973.16) - SKU3889S - Claim Handler: Eliza Ho Ten...</li> <li>MSIG_SG (01/06/2018): Alert - Adj Mandate Approved (\$1503.60) - SKU3889S - Claim Handler: Eliza Ho Te...</li> <li>MSIG_SG (31/05/2018): Hi Veron, please resubmit the revised prelim advice once u have access to Audate...</li> <li>MSIG_SG (31/05/2018): Alert - Adj Mandate Approved (\$1616.20) - SKU3889S - Claim Handler: Eliza Ho Te...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents









**SKU3889S (557752)**  
**OD**  
**May 5 2018 2:00PM**  
**[ONG GEOK TIN, SHEILA]**  
**Shu Fatt Auto Works**

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail	Print					
1	15/05/18 13:56	Repairer Estimates	1	Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	30/05/18 15:58	Adjuster Immediate Advice	1	Load HTM						
2	31/05/18 14:34	Adjuster Immediate Advice	1	Load HTM						
3	20/06/18 16:06	Adjuster Immediate Advice	1	Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail	Print					
1	15/05/18 13:04	1	1	Load JPG	<input checked="" type="checkbox"/>					
2	15/05/18 13:04	2	1	Load JPG	<input checked="" type="checkbox"/>					
3	15/05/18 13:04	3	1	Load JPG	<input checked="" type="checkbox"/>					
4	15/05/18 13:04	4	1	Load JPG	<input checked="" type="checkbox"/>					
5	15/05/18 13:04	5	1	Load JPG	<input checked="" type="checkbox"/>					
6	15/05/18 13:04	6	1	Load JPG	<input checked="" type="checkbox"/>					
7	15/05/18 13:04	7	1	Load JPG	<input checked="" type="checkbox"/>					
8	15/05/18 13:04	8	1	Load JPG	<input checked="" type="checkbox"/>					
9	15/05/18 13:04	9	1	Load JPG	<input checked="" type="checkbox"/>					
10	15/05/18 13:04	10	1	Load JPG	<input checked="" type="checkbox"/>					
11	15/05/18 13:04	11	1	Load JPG	<input checked="" type="checkbox"/>					
12	15/05/18 13:04	12	1	Load JPG	<input checked="" type="checkbox"/>					
13	15/05/18 13:04	tyre make	1	Load JPG	<input checked="" type="checkbox"/>					
14	15/05/18 13:04	tyre size	1	Load JPG	<input checked="" type="checkbox"/>					
15	15/05/18 13:04	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>					
16	15/05/18 13:04	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
2	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
3	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
4	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
5	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
6	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
7	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
8	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
9	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
10	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
11	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
12	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
13	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
14	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					
15	31/05/18 09:36	General View	1	Load JPG	<input checked="" type="checkbox"/>					



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
16	31/05/18 09:36	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/05/18 09:36	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/05/18 09:36	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/05/18 09:36	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/05/18 09:36	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/05/18 09:36	General View	 Load JPG	<input checked="" type="checkbox"/>
22	20/06/18 15:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	20/06/18 15:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	20/06/18 15:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	20/06/18 15:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	20/06/18 15:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	15/05/18 13:07	Certificate of Insurance	 Load PDF	
2	15/05/18 13:07	Driver's Driving License	 Load PDF	
3	15/05/18 13:07	part value enquiry	 Load PDF	
4	15/05/18 13:42	AudaTex Report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/18 15:59	MARK ESTIMATE	 Load PDF	
2	31/05/18 14:34	AUDATEX	 Load PDF	
3	20/06/18 16:03	1ST MARK ESTIMATE	 Load PDF	
4	20/06/18 16:03	AUDATEX 20.6.18	 Load PDF	
5	25/06/18 09:18	Parts Invoice	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	07/05/18 15:58	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	07/05/18 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	07/05/18 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	07/05/18 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	07/05/18 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	07/05/18 14:40	THIRD PARTY VEHICLE PHOTO	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	07/05/18 14:37	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG18009793/T1VD3E2

Date: 25/06/2018

### REFERENCE

Insured/Claimant:	ONG GEOK TIN, SHEILA	Policy No:	P4022801DMV	
Date of Loss:	05/05/2018	Nature of Claim:	OD	Claim No: 557752

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU3889S	Engine No:	L15Z12100740
Make & Model:	HONDA MOBILIO SV, 1.5 CVT (A)	Chassis No:	MRHDD4870FP000188
Reg. Date:	23/07/2015 (Man. Year: 2015)	Odometer:	27718 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65R16	Rear Tyre Size:	185/65R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	522.50	272.80	249.70	47.79
Miscellaneous Items	300.00	30.00	270.00	90.00
Paintwork Materials	158.40	105.36	53.04	33.48
Labour	885.00	565.00	320.00	36.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,865.90</b>	<b>973.16</b>	<b>892.74</b>	<b>47.85</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>1,365.90</b>	<b>473.16</b>	<b>892.74</b>	<b>65.36</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>95.61</b>	<b>33.12</b>	<b>62.49</b>	<b>65.36</b>
<b>Nett Amount (S\$)</b>	<b>1,461.51</b>	<b>506.28</b>	<b>955.23</b>	<b>65.36</b>

### INSPECTION

Date of Assignment:	28/05/2018	Present Location:	Shu Fatt Auto Works (HQ)
Date Inspected:	30/05/2018	Inspected At:	Block 1009 Bukit Merah Lane 3, #01-90 Singapore 159723
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2018)
<b>Parts:</b>	M1-MPV	HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKU3889S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts.		522.50 F	*248.00 F
						F=Franchise part.
Sub Total (S\$)					522.50	248.00
+ Margin on L,N Items 0.00/10.00% (S\$)					0.00	24.80
Total Parts (S\$)					522.50	272.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Paintwork materials	158.40	105.36
<u>Miscellaneous Items</u>				
2	1	Corr Prot Materials	40.00	0.00
3	1	Reverse sensors	260.00	30.00
Sub Total (S\$)			458.40	135.36

## Recommended Labour


No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Paintwork.	New	405.00	295.00
2	Panel/Mechanical	New	480.00	270.00
Gross Labour Cost (S\$)			885.00	565.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;

# Sketch Plan Pg. 2

## SKETCH PLAN



A : SKU 3829 S

B : 3MB HTB

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I turned left on the 2nd lane. The bus is going straight on 1st lane. The right-front of the bus contacted with the back-left of the my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature

Date & Time: 7/5/18

12:40 pm

*[Signature]*

Driver's Signature

(If driver is not the policyholder)

Date & Time: 7 May 18 12:40pm

*[Signature]*

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Address	BLK 119C KIM TIAN ROAD #21-228
Postcode	163119
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	SKV4885R
	-
Insurance Company of Driver's Own Vehicle	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO