

ASS. REC. BY

REF: CS/FCI18009814/Kqd3n2

Special Instruction:

Surveyor

Korneth

ASSIGNMENT (Office)

From (Person)

CWS

Lureregaw

of

FEI

Date/Time:

28/5/18 @ 2.16 pm

Estimated Cost:

Bill to:

OD ☒ TT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 4566E

Insured:

SHD 8549R

at Workshop m/s

Ah Chung motor

Tel:

648 35434

of

Blk 10, AMK Ind. 2A #03-10

Policy No:

Claim No:

D18004216 MPFH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/05/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

1:15pm @ 30/5/18

Person Contacted:

Draner

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLB 4566E-x

SHD 8549R-CS/FCI18006626/T/Hd 3n2

DOA: 10/4/18

On 6/18 @ 3:12pm revised to Lureregaw by email.

11/18 8430d

25/10/18 @ 1.14pm wksp informed that the owner already make payment for his vehicle.

25/10/18 submit Prel. report.

ASS. REC. BY:

REF: 1-071

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 871k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLB 4566E

Yr Regn: 04, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda

c.c. 1498

Colour: M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 20254

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU 1

1106752

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 3 mm

R/Bal. 6 mm

L/Bal. 3 mm

L/Bal. 6 mm

D.O.A. 23/5/18

D.O.I. 30/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

M N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/5 File pass to Catherine

RECEIVED 23 OCT 2018

Date/Time, File Pass to?

1) 25/10 1950

Date/Time, File Return to?

2)

☒ : Prell. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

13x15=195

170+195

50

50

25

490

Report Format :

Lump Sum / I.B.I: (\$)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004216MFSH

Date: 01 June 2018

Our Ref: CS/FCI18009814/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 4566E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/05/2018 at the premises of M/s SLB 4566E, and have the following to report:-

Workshop Estimate Amount	: S\$ 23,420.40 .
Revised Estimate Amount	: S\$ 6,938.40 .
"Check" Items Amount	: S\$ 1,668.80 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	25-05-2018	Our Ref No. D18004216MFSH
Accident Date	23-05-2018	Claim Type. Third Party
Insured Vehicle	SHD8549R	Third Party Vehicle. SLB4566E
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2A ANG MO KIO AUTO POINT #03-16	
Contact Person.	DIANA	
Contact No.	64835434/ 0	Fax No. 64842124
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH CHANG MOTOR SERVICE CENTRE	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 1 June 2018 3:12 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004216MFSH/1
Attachments: CSFCI18009814Kqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLB 4566E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 30 May 2018 1:19 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004216MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 28 May 2018 2:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004216MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.


Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Not Notified
 11 Sep @ 4300h
 Recovery After Paint
 5 days

SLB4566E Honda Vezel

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper assy 801.70	B1 \$ 1,290.00	✓
2	1	Front bumper left bracket	D11 \$ 86.00	✓
3	1	Front bumper left side retainer	CMT \$ 88.00	✓
4	1	Front bumper reinforcement 321.30	B1 \$ 352.00	✓
5	1	Front bumper lower grille	S2 \$ 176.00	X
6	1	Front bumper tow cover	S2 \$ 88.00	X
7	1	Front grille assy	ADH \$ 397.00	✓
8	1	Front grille emblem	M \$ 105.00	✓
9	1	Front bonnet assy	R \$ 1,681.00	X
10	2	Front bonnet hinges	R \$ 66.00	X
11	2	Front bonnet inner rubber	S2 \$ 76.00	X
12	1	Front bonnet lock mechanism	R \$ 156.00	X
13	1	Front bonnet lock catch	R \$ 66.00	X
14	1	Front lock brace panel	R \$ 156.00	X
15	1	Front support panel assy	R \$ 964.00	X
16	1	Front support panel top garnish	S2 \$ 205.00	X
17	2	Front support panel side garnish	S2 \$ 165.00	X
18	1	Front horn	S2 \$ 108.00	X
19	1	Front left headlamp assy 1460-30	M3M \$ 1,678.00	✓
20	1	Front left headlamp lower bracket	CMT \$ 97.00	✓
21	1	Front left fog lamp	M3M \$ 280.00	✓
22	1	Front left fog lamp garnish 68.00	D11 \$ 121.00	✓
23	1	Front air-con condenser	S2 \$ 1,120.00	X
24	1	Front air-con suction pipes	S2 \$ 388.00	X
25	1	Front air-con discharge pipe	S2 \$ 385.00	X
26	1	Front radiator assy	S2 \$ 1,470.00	X
27	1	Front radiator fan cowling	S2 \$ 186.00	X
28	1	Front radiator fan motor	S2 \$ 282.00	X
29	1	Front radiator fan blade	S2 \$ 186.00	X
30	1	Front wiper tank	S2 \$ 120.00	X

Less 20%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 12,538.00

\$ 2,507.60

\$ 10,030.40



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SLB4566E Honda Vezel

No	Qty	Parts Description	Estimated Parts Price	
31	1	Front left fender assy 415.90	Ru \$ 882.00	✓
32	1	Front left fender inner cowling 186.20	D11 \$ 278.00	✓
33	1	Front left fender protector	D11 \$ 198.00	✓
34	1	Front left suspension assy	Sn \$ 1,287.00	X
35	1	Front left lower control arm	Sn \$ 398.00	X
36	1	Front left knuckle arm	Sn \$ 348.00	X
37	1	Front left wheel hub with bearing	Vn \$ 352.00	X
38	1	Front left inner panel	R \$ 979.00	X
39	1	Front left inner wheel house	R \$ 1,135.00	X
40	1	Front left reinforcement bracket	R R \$ 393.00	X
41	1	Front centre support panel lower panel	R \$ 1,025.00	X
			\$ 7,275.00	
Less 20%			\$ 1,455.00	
			<u>\$ 5,820.00</u>	

Special Nett Items

1	10	Front bumper clips	Ru \$ 50.00	✓
2	4	Front bumper lower grille clips	Ru \$ 20.00	✓
3	1	Front bumper lower spoiler P. 7 351.00	Bu \$ 1,400.00	✓
4	10	Front bumper lower spoiler clips	Ru \$ 50.00	✓
5	1	Front bumper lower spoiler sealant	Vn \$ 60.00	X
6	4	Front grille clips	Ru \$ 20.00	✓
7	2	Front radiator coolant	Vn \$ 80.00	X
8	1	Front air-con gas	Vn \$ 80.00	X
9	6	Front left fender inner cowling clips	Ru \$ 30.00	✓
10	6	Front left fender protector clips	Ru \$ 60.00	✓
11	1	Front left aluminium rim	Sn \$ 850.00	X
12	1	Front left tyre	Sn \$ 350.00	X
13	6	Front support panel top garnish clips	Vn \$ 30.00	X
14	1	Front no plate with garnish	Vn \$ 80.00	X
			<u>\$ 3,160.00</u>	

Total parts

\$ 19,010.40



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SLB4566E Honda Vezel

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 1,400.00	5001
2	To putty and spray painting front and front left portion.	\$ 1,400.00	6601
3	To check wiring and focus front headlamp.	\$ 50.00	201
4	To remove and install front bonnet lock mechanism.	~ \$ 80.00	X
5	To remove and install air-con system to facilitate the repair and refill gas.	\$ 150.00	X
6	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 150.00	X
7	To repair, straighten and re-align front left door panel.	~ \$ 180.00	X
8	To apply anti rust proofing to front affected area.	\$ 120.00	301
9	To remove and install front left undercarriage parts.	~ \$ 300.00	X
10	To balance front left wheel.	~ \$ 50.00	X
11	To conduct wheel alignment.	~ \$ 80.00	X
12	To conduct chassis alignment.	~ \$ 350.00	X
13	Towing service.	~ \$ 100.00	X
Total labour :		\$ 4,410.00	

Total parts : \$ 19,010.40

Total labour : \$ 4,410.00

Total repair cost : \$ 23,420.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009814/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8549R	Veh. Inspected	SLB 4566E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004216MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	28/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11106752	Colour	METALLIC BLUE	
Odometer	20254	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	3 mm	
L/H Front Tyre	215/60 R16	DUNLOP	3 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/05/2018	Inspection Date	30/05/2018	
Survey held at	AH CHANG MOTOR SERVICE CENTRE BLK 10 ANG MO KIO IND PARK 2A AMK AUTOPOINT #03-16 SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 4566E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER ASSY	BENT	1,290.00	801.70
1	FRONT BUMPER LEFT BRACKET	DISTORTED	86.00	86.00
1	FRONT BUMPER LEFT SIDE RETAINER	CRACKED	88.00	88.00
1	FRONT BUMPER REINFORCEMENT	BENT	352.00	321.30
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	176.00	-
1	FRONT BUMPER TOW COVER	SERVICEABLE	88.00	-
1	FRONT GRILLE ASSY	DENTED / CUT	397.00	397.00
1	FRONT GRILLE EMBLEM	NECESSARY	105.00	105.00
1	FRONT BONNET ASSY	TO REPAIR SEE LABOUR	1,681.00	-
2	FRONT BONNET HINGES	TO REPAIR SEE LABOUR	66.00	-
2	FRONT BONNET INNER RUBBER	SERVICEABLE	76.00	-
1	FRONT BONNET LOCK MECHANISM	TO REPAIR SEE LABOUR	156.00	-
1	FRONT BONNET LOCK CATCH	TO REPAIR SEE LABOUR	66.00	-
1	FRONT LOCK BRACE PANEL	TO REPAIR SEE LABOUR	156.00	-
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	964.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	205.00	-
2	FRONT SUPPORT PANEL SIDE GARNISH	SERVICEABLE	165.00	-
1	FRONT HORN	SERVICEABLE	108.00	-
1	FRONT LEFT HEADLAMP ASSY	MTG CRACKED	1,678.00	1,460.30
1	FRONT LEFT HEADLAMP LOWER BRACKET	CRACKED	97.00	97.00
1	FRONT LEFT FOG LAMP	MTG CRACKED	280.00	280.00
1	FRONT LEFT FOG LAMP GARNISH	DISTORTED	121.00	68.00
1	FRONT AIR-CON CONDENSER	SERVICEABLE	1,120.00	-
1	FRONT AIR-CON SUCTION PIPE	SERVICEABLE	388.00	-
1	FRONT AIR-CON DISCHARGE PIPE	SERVICEABLE	385.00	-
1	FRONT RADIATOR ASSY	SERVICEABLE	1,470.00	-
1	FRONT RADIATOR FAN COWLING	SERVICEABLE	186.00	-

Report Ref No. CS/FCI18009814/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RADIATOR FAN MOTOR	SERVICEABLE	282.00	-
1	FRONT RADIATOR FAN BLADE	SERVICEABLE	186.00	-
1	FRONT WIPER TANK	SERVICEABLE	120.00	-
1	FRONT LEFT FENDER ASSY	BUCKLED	882.00	415.90
1	FRONT LEFT FENDER INNER COWLING	DISTORTED	278.00	188.20
1	FRONT LEFT FENDER PROTECTOR	DENTED	198.00	198.00
1	FRONT LEFT SUSPENSION ASSY	SERVICEABLE	1,287.00	-
1	FRONT LEFT LOWER CONTROL ARM	SERVICEABLE	398.00	-
1	FRONT LEFT KNUCKLE ARM	SERVICEABLE	348.00	-
1	FRONT LEFT WHEEL HUB WITH BEARING	NOT NECESSARY	352.00	-
1	FRONT LEFT INNER PANEL	TO REPAIR SEE LABOUR	979.00	-
1	FRONT LEFT INNER WHEEL HOUSE	TO REPAIR SEE LABOUR	1,135.00	-
1	FRONT LEFT REINFORCEMENT	TO REPAIR SEE LABOUR	393.00	-
1	FRONT CENTRE SUPPORT PANEL LOWER PANEL	TO REPAIR SEE LABOUR	1,025.00	-
	LESS 20% DISCOUNT		-3,962.60	-901.28
			15,850.40	3,605.12
	SPECIAL NETT ITEMS			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
4	FRONT BUMPER LOWER GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
1	FRONT BUMPER LOWER SPOILER (SN)	BUCKLED	1,400.00	351.00
10	FRONT BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER SPOILER SEALANT (SN)	NOT NECESSARY	60.00	-
4	FRONT GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
2	FRONT RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
1	FRONT AIR-CON GAS (SN)	NOT NECESSARY	80.00	-
6	FRONT LEFT FENDER INNER COWLING CLIPS (SN)	NECESSARY	30.00	30.00
6	FRONT LEFT FENDER PROTECTOR CLIPS (SN)	NECESSARY	60.00	60.00
1	FRONT LEFT ALUMINIUM RIM (SN)	SERVICEABLE	850.00	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	350.00	-
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/FCI18009814/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NO PLATE WITH GARNISH (SN)	NOT NECESSARY	80.00	-
			3,160.00	581.00
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT LEFT AFFECTED AREA AND REPLACE FRONT LEFT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET ASSY, FRONT BONNET HINGES, FRONT BONNET LOCK MECHANISM, FRONT BONNET LOCK CATCH, FRONT LOCK BRACE PANEL, FRONT SUPPORT PANEL ASSY, FRONT LEFT INNER PANEL, FRONT LEFT INNER WHEEL HOUSE, FRONT LEFT REINFORCEMENT AND FRONT CENTRE SUPPORT PANEL LOWER PANEL.		1,400.00	500.00
	TO PUTTY AND SPRAY PAINTING FRONT AND FRONT LEFT PORTION.		1,400.00	660.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	20.00
	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL AIR-CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS.	NOT NECESSARY	150.00	-
	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE.	NOT NECESSARY	150.00	-
	TO REPAIR, STRAIGHTEN AND RE-ALIGN FRONT LEFT DOOR PANEL.	NOT NECESSARY	180.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA.		120.00	30.00
	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS.	NOT NECESSARY	300.00	-
	TO BALANCE FRONT LEFT WHEEL.	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	350.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			4,410.00	1,210.00
	GRAND TOTAL		23,420.40	5,396.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)			4,300.00

Report Ref No. CS/FCI18009814/Kqd3n2



Report Ref No. CS/FCI18009814/Kqd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.