

22/03/2003

ASS. REC. BY:

REF: 08/EGJ18009815/Kvd3m Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Yeu pi Li

of

EGT

Date/Time: 30/5/18 @ 5:07pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 5799M

Insured:

G2 4238K

at Workshop m/s

Supreme Auto

Tel:

64528211

of

176 Linking Drive # 02-01

Policy No:

Claim No:

G24283K / SL / PI

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:30am @ 31/5/18

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLC 5799M-CS/EGJ16019018/Kvh3m2 DOA: 2/10/16
4/6/18	Email preli revised to Pei Li
22/6/18	L1 Rm 8660a email @ 445pm LS 6600 confirmed with Mr Chew (Reel 4686-85, 429y)

REF: EGI

## ASSIGNMENT

From:

Date: 01/06/2018

Veh No: SLC 5799M Yr Regn: 05, 16

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SLC 5799M

Make:

Toy Axi

C.C.

1496

at Workshop m/s

Supreme Auto

Colour

M-Silver

A/C:

Insured / Std / NI / NA

of

176 Sin Ming Drive #02-01

Sp. Reading

171111

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

NRE161 0016812

Policy No:

C/No:

Claims No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi:


Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Agenda 175/65R15R: Dun

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

7

mm

R/Bal.

2

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

7

mm

L/Bal.

2

mm

Est. Repairs:

09

days

Res.: Yes or No

D.O.A.

29/5/18

D.O.I.

1/6/18

Lum Sum:

20

%

3 Val: Yes or No

Survey held at

✓

CA / REV / REP. / 24 HRS typ

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/6 File pass to Customer

RECEIVED 25 JUN 2018

Date/Time: File Pass to?

☐

: Preli. Report

Days Of Repair:

9

1)

☐

: Final Report

Resurvey No. of Trip:

2

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

350

Date/Time: File Return to?

2)

05/6 - typist

Add Fee:

☐

: Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I: (\$

6600/-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18009815/Kvd3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 31-05-2018



Code : EGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 4238K	Veh. Inspected	SLC 5799M
Policy No.		Coverage (\$)	0.00
Claim No.	GZ4283K/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	31/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	29/05/2018	Inspection Date	31/05/2018
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 4 June 2018 3:46 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: GZ4238K / TP : SLC5799M/LKK / DOA : 29/05/2018  
**Attachments:** SLC 5799M PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLC 5799M  
Date of survey: 1/6/2018  
Number of days:9 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 31 May 2018 10:34 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: GZ4238K / TP : SLC5799M/LKK / DOA : 29/05/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Wednesday, 30 May 2018 5:07 PM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** OI : GZ4238K / TP : SLC5799M/LKK / DOA : 29/05/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **SUPREME AUTO SERVICE PTE LTD.**

ADDRESS : 176 SIN MING DRIVE  
#02-01 SIN MING AUTOCARE  
SINGAPORE 575721

PERSON TO CONTACT : 6452 8211

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached is insured SAS (note: reports not to be released to any Third Party). No estimates was provided

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Fax: 65 6829 9247  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: GZ4283K/SL/pl

Our ref: CS/EGI18009815/Kvd3

Date: 4/6/2018

The Motor Claims Department  
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SLC 5799M**


We thank you for your instruction on 30/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/6/2018 at the premises of M/s SUPREME AUTO SERVICE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,286.85
Revised Estimate Amount	: S\$7,869.68
"Check" Items Amount	: S\$1,102.35
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the rear portion



Comments/Present Status:  
Damages Consistent

Yours faithfully,

Kenneth Kong  
**Licensed Appraiser**

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Wednesday, 30 May 2018 5:07 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : GZ4238K / TP : SLC5799M/LKK / DOA : 29/05/2018  
**Attachments:** GZ4238K - SAS.pdf; SLC5799M - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **SUPREME AUTO SERVICE PTE LTD.**

ADDRESS : 176 SIN MING DRIVE  
#02-01 SIN MING AUTOCARE  
SINGAPORE 575721

PERSON TO CONTACT : 6452 8211

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached is insured SAS (**note: reports not to be released to any Third Party**). No estimates was provided

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Fax: 65 6829 9247  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# ERGO

Date: 30.05.2018  
Our Reference: GZ 4238K/SL/pl  
Your Reference: SLC 5799M

Sent via Fax

6451 7420

or

Email

To: SUPREME AUTO SERVICE PTE LTD

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLC 5799M  
Insured's Vehicle: GZ 4238K  
Date Of Accident: 29.05.2018


We acknowledge receipt of your request for PRS on: 30.05.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☐ Our Insured's driver has not reported the accident to us todate.
- ☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

MCQUIRENS RENTAL PTE LTD

c/o 46 Lenton Plain  
Singapore 786548

*Not with him*  
*61 Sm & 6600k*  
*Resony After Paing*  
*9 days*

Date: 30-05-18

QUANTITY	PARTICULARS	AMOUNT (\$)
	<b>RE : TOYOTA COROLLA AXIO. <i>SLC 5799M</i></b>	
1 pc	rear boot lid	<i>B1</i> 975.30 ✓
1 pc	rear boot emblem logo <i>61-10</i>	<i>m</i> 97.60 —
1 pc	rear boot emblem 'AXIO'	<i>m</i> 86.50 —
1 pc	rear boot emblem 'COROLLA'	<i>m</i> 75.80 —
2 pcs	rear boot hinge @ 192.40	<i>B1</i> 384.80 2 ✓
1 pc	rear boot lock	<i>Red</i> 397.80 —
1 pc	rear boot lock catch	<i>R</i> 68.30 X
1 pc	rear boot weatherstrip	<i>Red/Dir</i> 296.80 <i>5015w</i> 148.40
1 pc	rear boot outer chrome moulding	<i>Wan</i> 325.80 —
1 pc	rear bumper <i>390-60</i>	<i>B1</i> 836.70 —
1 pc	rear bumper retainer	<i>CM/Dir</i> 197.50 —
1 pc	rear bumper lamp	<i>Sm</i> 115.30 X
2 pcs	rear bumper bracket @ 89.40	<i>R</i> 178.80 X
1 pc	rear end panel	<i>B1</i> 487.50 —
1 pc	rear end panel garnish <i>m/Dir</i>	<i>R</i> 309.70 —
2 pcs	rear tail lamp assy <i>512.00</i>	<i>CM</i> 1,097.80 —
2 pcs	rear tail lamp housing @ 283.60	<i>B1</i> 567.20 —
1 pc	rear camera	<i>Sm</i> 462.60 X
2 pcs	fender inner garnish <i>443.00</i>	<i>CM</i> 995.60 —
1 pc	spare tyre board <i>1/5 Deform</i> @ 497.80	<i>CM</i> 308.70 —
1 pc	exhaust silencer	<i>R</i> 612.50 X
1 pc	rear fender <i>1/5 Br</i> @ 973.60	<i>CM</i> 1,947.20 —
2 pcs	rear fender dust cover <i>1/5 CM</i> @ 105.00	<i>Sm</i> 210.00 X 2 ✓
	Sub-total	10,062.20 11,035.80
	Less 25%	2,515.55
	Sub-total	7,546.65 8,276.85
1 pc	number plate housing s.nett	<i>Sm</i> 35.00 X
1 pc	number plate s.nett	<i>Sm</i> 35.00 X
	Sub-total	7,616.65

Balance brought forward	7,616.65	
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	1,100.00	1000
To check wiring system.	50.00	200
To spray painting on affected areas.	1,100.00	1000
To apply rust proofing on affected areas.	80.00	✓
To apply waterproof sealant on affected areas.	80.00	300
To install reverse sensors & reverse camera	60.00	} 600
To install reverse camera	60.00	
To carry our exhaust works	80.00	600
To remove rear windscreen glass to enable repair	150.00	1200
To remove carpet, trimming and seats to enable repair	180.00	1000
<b>Total</b>	<b>10,556.65</b>	
	11,086.85	
	11587.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

MCQUIRENS RENTAL PTE LTD

c/o 46 Lentor Plain  
Singapore 786548

Date: 30/05/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE : TOYOTA COROLLA AXIO/ SLC 5799 M</u>	
1pc	rear windscreen moulding <i>112.00</i>	<i>193.70</i>
1 pc	rear windscreen glass iner seal	<i>87.50</i>
	Sub-total	281.20
	Less 25%	70.30
	Sub-total	210.90
1pc	windscreen glass sealant s.nett	<i>90.00</i>
	Totall	300.90




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18009815/Kvd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 27-06-2018		
		Code : EGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GZ 4238K	Veh. Inspected	SLC 5799M	
Policy No.		Coverage (\$)	0.00	
Claim No.	GZ4283K/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	30/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA AXIO (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NRE1610016812	Colour	METALLIC SILVER	
Odometer	171111	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	ACENDA	7 mm	
L/H Front Tyre	175/65 R15	ACENDA	7 mm	
R/H Rear Tyre	175/65 R15	DUNLOP	2 mm	
L/H Rear Tyre	175/65 R15	DUNLOP	2 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/05/2018	Inspection Date	01/06/2018	
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 5799M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOT LID	BENT	975.30	975.30
1	REAR BOOT EMBLEM LOGO	NECESSARY	97.60	61.10
1	REAR BOOT EMBLEM "AXIO"	NECESSARY	86.50	86.50
1	REAR BOOT EMBLEM "COROLLA"	NECESSARY	75.80	75.80
2	REAR BOOT HINGE @\$192.40	BENT	384.80	384.80
1	REAR BOOT LOCK	DENTED	397.80	397.80
1	REAR BOOT LOCK CATCH	TO REPAIR SEE LABOUR	68.30	-
1	REAR BOOT OUTER CHROME MOULDING	WARPED	325.80	325.80
1	REAR BUMPER	BENT	836.70	590.60
1	REAR BUMPER RETAINER	CRACKED / DISTORTED	197.50	197.50
1	REAR BUMPER LAMP	SERVICEABLE	115.30	-
2	REAR BUMPER BRACKET @\$89.40	TO REPAIR SEE LABOUR	178.80	-
1	REAR END PANEL	BENT	487.50	487.50
1	REAR END PANEL GARNISH	MTG DISTORTED	309.70	309.70
2	REAR TAIL LAMP ASSY @\$548.90	CRACKED	1,097.80	1,024.00
2	REAR TAIL LAMP HOUSING @\$283.60	BENT	567.20	567.20
1	REAR CAMERA	SERVICEABLE	462.60	-
2	FENDER INNER GARNISH @\$497.80	N/S DEFORMED	995.60	443.00
1	SPARE TYRE BOARD	CRACKED	308.70	308.70
2	REAR FENDER @\$973.60	N/S BUCKLED	1,947.20	973.60
2	REAR FENDER DUST COVER @\$105.00	N/S CRACKED	210.00	105.00
1	REAR WINDSCREEN MOULDING (ADDITIONAL)	NECESSARY	193.70	112.00
1	EXHAUST SILENCER	TO REPAIR SEE LABOUR	612.50	-
	LESS 25% DISCOUNT		-2,733.17	-1,856.48
			8,199.53	5,569.42
1	REAR BOOT WEATHERSTRIP (50%)(SN)	DENTED / DISTORTED	296.80	148.40

Report Ref No. CS/EGI18009815/Kvd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN GLASS INER SEAL (SN) (ADDITIONAL) LESS 25% DISCOUNT	NECESSARY	87.50 -96.08 288.22	30.00 - 178.40
	<b>SPECIAL NETT ITEMS</b>			
1	NUMBER PLATE HOUSING (SN)	SERVICEABLE	35.00	-
1	NUMBER PLATE (SN)	SERVICEABLE	35.00	-
1	WINDSCREEN GLASS SEALANT (SN)(ADDITIONAL)	NECESSARY	90.00	40.00
			160.00	40.00
	<b>LABOUR</b>			
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS, INCLUSIVE OF THE REPAIR OF REAR BOOT LOCK CATCH, EXHAUST SILENCER AND REAR BUMPER BRACKET.		1,100.00	1,000.00
	TO CHECK WIRING SYSTEM.		50.00	20.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,100.00	1,000.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		80.00	80.00
	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS.		80.00	30.00
	TO INSTALL REVERSE SENSORS & REVERSE CAMERA. }		60.00	60.00
	TO INSTALL REVERSE CAMERA. }		60.00	-
	TO CARRY OUT EXHAUST WORKS.		80.00	60.00
	TO REMOVE REAR WINDSCREEN GLASS TO ENABLE REPAIR.		150.00	120.00
	TO REMOVE CARPET, TRIMMING AND SEATS TO ENABLE REPAIR.		180.00	100.00
			2,940.00	2,470.00
	<b>GRAND TOTAL</b>		<b>11,587.75</b>	<b>8,257.82</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,600.00</b>

Report Ref No. CS/EG18009815/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.