

ASS. REC. BY:

REF:

CS/FCI18009818/ Gnd3ⁿ²

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Gnd3ⁿ²
Sithara

of

FCI

Date/Time: 30/5/18 @ 5:33pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLV 1442T

Insured:

SHA 8652R

at Workshop m/s:

Hup Motor Trading

Tel:

6784 0039

of

Blk 9004 Tempines st. 93 #01-120

Policy No:

Claim No:

D18CD4297MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/5/2018

CA / REV / REP. / REV 24 HRS

'up

4/6/18 @ 3pm - 4pm

H.O.D. Endorsement:

Date/Time:

10:41am @ 31/5/18

Person Contacted:

David

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV1442T-X
	SHA 8652R-CS3/FCI14019770/R/qj3d1 DUA: 18/10/14
21/6/18 @ 4.17pm	revised to Sithara by email.

REF: FCI

ASSIGNMENT

From:

Date:

04/06/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLV 1442 T

at Workshop m/s

Hup Motor

o: Blk 9004, pumpings 8f 93 #01-120

Insured:

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

~~3pm - 4pm~~

Make of Veh:

David @ 67840039

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$26K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SLV 1442 T

Yr Regn: 25 Sep 2009

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Picnic

c.c. 1998

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

92529

T/Radio: Insured / Std / NI / NA

Eng/No:

JTEGH 23B 4000 26953

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F: 2.5 / 60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

04-6-18
12pm

Survey held at

w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

20/6/18 confirmed 1/5 @ 3300 with David.
(Ref # 3601.62, 572)

RECEIVED 21 JUN 2018

Date/Time: File Pass to?

11/11/16



Preli. Report



Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation

\$ + RE + SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.A. (\$

TP

3300

145

50

50 + 50

40

335



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009818/Gqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8652R	Veh. Inspected	SLV 1442T
Policy No.		Coverage (\$)	0.00
Claim No.	D18004297MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/05/2018	Inspection Date	
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004297MFSH
Our Ref: CS/FC118009818/Gqd3

Date: 21 June 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 1442T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/06/2018 at the premises of M/s HUP MOTOR TRADING . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,901.62</u> .
Revised Estimate Amount	: S\$ <u>3,300.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	30-05-2018	Our Ref No. D18004297MFSH
Accident Date	26-05-2018	Claim Type. Third Party
Insured Vehicle	SHA8652R	Third Party Vehicle. SLV1442T
Survey Location	BLK 9004 TAMPINES STREET 93 #01-120	
Contact Person.	DAVID ANG	
Contact No.	67840039/ 0	Fax No. 67840076
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUP MOTOR TRADING & SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 June 2018 4:17 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004297MFSH/1
Attachments: CSFCI18009818Gqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLV 1442T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 31 May 2018 10:44 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004297MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 30 May 2018 5:52 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004297MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9895A
Vehicle Details	
Vehicle No.:	SLV1442T
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	1AZH359681
Chassis No.:	JTEGH23B400026953
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$24,216.00
Original Registration Date:	25 Sep 2009
First Registration Date:	25 Sep 2009
Transfer Count:	1
Actual ARF Paid:	\$24,216.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2019
PARF Rebate Amount:	\$13,318.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,189.00
COE Rebate Amount:	\$2,339.00
Total Rebate Amount:	\$15,657.00

The information contained herein is correct as at 11 Jun 2018

OK

Enquire Transfer Fee

Vehicle Details

Vehicle No.: SLV1442T
Vehicle Type: P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1: No Attachment
Vehicle Scheme: Normal
Vehicle Make: TOYOTA
Vehicle Model: PICNIC AUTO W/O ROOF RACK
Chassis No.: JTEGH23B400026953
Propellant: Petrol
Engine No.: 1AZH359681
Engine Capacity: 1998 cc
Maximum Power Output: 110.0 kW (147 bhp)
Maximum Laden Weight: 2185 kg
Unladen Weight: 1540 kg
Year Of Manufacture: 2009
Original Registration Date: 25 Sep 2009
Lifespan Expiry Date: -
COE Category: E - Open Category
Quota Premium: \$18,189.00
COE Expiry Date: 24 Sep 2019
Road Tax Expiry Date: 24 Sep 2018
PARF Eligibility Expiry Date: 24 Sep 2019
:
Inspection Due Date: 24 Sep 2018
Intended Transfer Date: 16 Apr 2018
CO2 Emission: -
CO Emission: -
HC Emission: -
NOx Emission: -
PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2907/05/18

Your Ref:

MS KOM SIOH NGOH JENNY
141, Westwood Crescent,
Westville, Singapore 648508

Guo Qiang
82880282
04/6/18
Lumpsum repair.
After repair photos.
GuoQiang@KKAuto.com

LKK Hence notify the Repairer the following:

- To return to the Repairer for painting
- To display the car for inspection during survey
- Parts price to be subject to confirmation
- Third party insurance claim to be submitted to the insurance company
- Supplementary items must be provided and is subject to confirmation

Date: 28th May 2018
Acknowledged by Repairer
Signature: _____
Date: _____

Estimate cost of repair to TOYOTA PICNIC 2.0 (A) S/Wagon - SLV 1442 T

1 pc rear bumper	MC	\$ 511.20	✓
8 pcs rear bumper clips	MC	\$ 30.40	✓
1 pc rear bumper damper	MC	\$ 105.00	X
1 pc rear bumper reinforcement	MC	\$ 379.20	X
3 pcs rear bumper reverse sensor	MC	\$ 810.00	2cc(SN)
2 pcs rear bumper o/s & n/s reflector	MC	\$ 104.60	X
2 pcs rear bumper o/s & n/s side retainer	MC	\$ 76.40	X
2 pcs rear bumper o/s & n/s top retainer	MC	\$ 44.40	X
8 pcs rear bumper lower clips	MC	\$ 30.40	✓
1 pc tail gate door	MC	\$ 1,309.90	✓
1 pc tail gate door lock	MC	\$ 217.50	X
1 pc tail gate door lock stricker	MC	\$ 34.90	X
1 pc tail gate door 'TOYOTA' emblem	MC	\$ 70.90	✓
1 pc tail gate door 'PICNIC' emblem	MC	\$ 48.40	✓
1 pc rear windscreen glass outer moulding	MC	\$ 120.30	✓
1 pc rear windscreen glass inner dam rubber	MC	\$ 75.00	✓
1 pc rear windscreen glass sealant	MC	\$ 60.00	405.~
16 pcs tail gate door inner trim board clips	MC	\$ 67.20	✓
1 pc rear end panel	MC	\$ 416.10	✓
1 pc rear end panel top garnish	MC	\$ 206.20	X
5 pcs rear end panel top garnish clips	MC	\$ 17.50	X
		\$ 4,735.50	2679.8
		\$ 1,183.88	2009.8
		\$ 3,551.62	

To wiring check up & transfer affected wiring system.	60.00	30
To remove & refix rear windscreen glass & necessary parts.	150.00	100
To transfer tail gate door inner trim board cover, wiper motor, shock absorber, hinge, third brake light, inner lock, garnish, licence lamp & necessary parts.	180.00	60
To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts.	120.00	60
To respray Tuff-Kote on all affected accident parts.	90.00	60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear end panel & necessary parts, to weld, renew & align above parts.	1,250.00	800
To putty & respray painting on all affected accident parts.	1,500.00	800

\$ 6,901.62
6901.62

HUP MOTOR TRADING & SERVICE

BUN 1018
21/01/2018
Jishu

2/5 3300 & long.



LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
 TEL: 6256 3561 FAX: 6256 4315
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009818/Gqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8652R	Veh. Inspected	SLV 1442T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004297MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	30/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PICNIC	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTEGH23B400026953	Colour	BLACK	
Odometer	92529	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	MICHELIN	6 mm	
L/H Front Tyre	205/60 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/05/2018	Inspection Date	04/06/2018	
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1442T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	511.20	511.20
8	REAR BUMPER CLIPS @\$3.80	NECESSARY	30.40	30.40
1	REAR BUMPER DAMPER	NOT NECESSARY	105.00	-
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	379.20	-
2	REAR BUMPER O/S & N/S REFLECTOR @\$52.30	NOT NECESSARY	104.60	-
2	REAR BUMPER O/S & N/S SIDE RETAINER @\$38.20	NOT NECESSARY	76.40	-
2	REAR BUMPER O/S & N/S TOP RETAINER @\$22.20	NOT NECESSARY	44.40	-
8	REAR BUMPER LOWER CLIPS @\$3.80	NECESSARY	30.40	30.40
1	TAIL GATE DOOR	BUCKLED	1,309.90	1,309.90
1	TAIL GATE DOOR LOCK	NOT NECESSARY	217.50	-
1	TAIL GATE DOOR LOCK STRICKER	NOT NECESSARY	34.90	-
1	TAIL GATE DOOR "TOYOTA" EMBLEM	NECESSARY	70.90	70.90
1	TAIL GATE DOOR "PICNIC" EMBLEM	NECESSARY	48.40	48.40
1	REAR WINDSCREEN GLASS OUTER MOULDING	NECESSARY	120.30	120.30
1	REAR WINDSCREEN GLASS INNER DAM RUBBER	NECESSARY	75.00	75.00
16	TAIL GATE DOOR INNER TRIM BOARD CLIPS @\$4.20	NECESSARY	67.20	67.20
1	REAR END PANEL	BADLY DENTED	416.10	416.10
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	206.20	-
5	REAR END PANEL TOP GARNISH CLIPS @\$3.90	NOT NECESSARY	17.50	-
	LESS 25% DISCOUNT		-966.38	-669.95
			2,899.12	2,009.85
3	REAR BUMPER REVERSE SENSOR @\$270.00 (SN)	DAMAGED	810.00	200.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	60.00	40.00
	LESS 25% DISCOUNT		-217.50	-
			652.50	240.00
LABOUR				
	TO WIRING CHECK UP & TRANSFER AFFECTED WIRING SYSTEM.		60.00	30.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS.		150.00	100.00

Report Ref No. CS/FCI18009818/Gqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER TAIL GATE DOOR INNER TRIM BOARD COVER, WIPER MOTOR, SHOCK ABSORBER, HINGE, THIRD BRAKE LIGHT, INNER LOCK, GARNISH, LICENCE LAMP & NECESSARY PARTS.		180.00	60.00
	TO REMOVE & REFIX CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER, SPARE TYRE, TOOL SET & NECESSARY PARTS.		120.00	60.00
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.		90.00	60.00
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAR FLOOR BOARD PANEL, REAR END PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS.		1,250.00	800.00
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		1,500.00	800.00
			3,350.00	1,910.00
	GRAND TOTAL		6,901.62	4,159.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CS/FC118009818/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.