







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18009836/Kha3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 31-05-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 5457C	Veh. Inspected	SDW 1521M
Policy No.		Coverage (\$)	0.00
Claim No.	S8M001L0	Excess (\$)	0.00
Assign From		Assign Date	31/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/05/2018	Inspection Date	30/05/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
Tel: 6559 8944 / Fax: 6269 2404

**AXA Insurance Singapore Pte Ltd**  
8 Shenton Way  
#27-01 AXA Tower  
Singapore (068811)  
ATTN: MOTOR CLAIM DEPARTMENT  
Tel : 6338 7288 Fax : 6880 4838  
DEAR SIR / MADAM :

*Not Authorized  
611mp @ 5000k??  
Paying After Pain*

**ACCIDENT REPAIR ON: SDW1521M**

**MODEL : HONDA CIVIC 1.6A**

**POLICY NO : 10198255**

**CHASSIS NO : JHMES56805S202757**

**YEAR OF MANUFACTURE : 2005**

**DATE/TIME OF ACCIDENT: 24/05/2018 Time: 1845Hrs at EXIT JALAN TOA PAYOH TWDS POTONG PASIR**

**THIRD PARTY VEHICLE NO: XD5457C**

Date: 28/05/2018

Page : 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

**Replacement Of Parts**

S/N	Quantity	Unit Price	Condition	Amount	
		SS		SS	
1	1	623.00	Dented	623.00	✓
2	1	623.00	Dented	623.00	✓
3	1	155.00	Kinked	155.00	7X
4	1	155.00	Kinked	155.00	7X
5	1	861.00	Smashed	861.00	✓
6	1	140.00	Necessary	140.00	✓
7	1	271.00	Cracked	271.00	✓
8	1	551.00	Kinked	551.00	✓
9	1	226.00	Broken	226.00	✓
10	1	226.00	Broken	226.00	✓
11	1	65.00	Dented	65.00	✓
12	1	65.00	Dented	65.00	✓
13	1	25.00	Necessary	25.00	✓
14	1	25.00	Necessary	25.00	✓
15	6	5.50	Necessary	33.00	✓
16	1	495.00	Dented	495.00	✓
17	1	58.00	Bented	58.00	✓
18	1	58.00	Bented	58.00	✓
19	1	45.00	Bented	45.00	7X
20	1	45.00	Bented	45.00	7X
21	1	75.00	Broken	75.00	✓
22	1	35.00	Bented	35.00	✓
23	1	38.00	Bented	38.00	7X
24	1	124.00	Necessary	124.00	7X
25	1	103.00	Cut	103.00	501111
26	1	86.00	Torn	86.00	7X
27	1	171.00	Broken	171.00	✓
28	1	171.00	Broken	171.00	✓
29	1	155.00	Jammed	155.00	✓
30	1	28.00	Necessary	28.00	✓
31	1	125.00	Cracked	125.00	✓
32	1	30.00	Broken	30.00	7X
33	1	30.00	Broken	30.00	7X
34	1	85.00	Malfunction	85.00	7X

*Shattered*

*Handwritten marks in table: Bu, Bu, WA, un, m, CR, Ad/lt, B, B, B, WA, un, Tm, B, B, un, CR, WA*

35	Boot side trim LH	1	75.00	Kinked	uu	75.00	7X
36	Boot side trim RH	1	75.00	Kinked	uu	75.00	7X
37	Rear bumper	1	630.00	Cut	Buc	630.00	✓
38	Rear bumper clips	10	5.50	Necessary	uu	55.00	—
39	Rear bumper side retainer LH	1	25.00	Necessary	Diy	25.00	—
40	Rear bumper side retainer RH	1	25.00	Necessary	Diy	25.00	—
41	Rear bumper side bracket LH	1	12.00	Bented	uu	12.00	7X
42	Rear bumper side bracket RH	1	12.00	Bented	uu	12.00	7X
43	Rear bumper stiffener LH	1		Dented			
44	Rear bumper stiffener RH	1		Dented			
45	Rear stiffener panel LH	1		Dented			
46	Rear stiffener panel RH	1		Dented			
47	Rear end panel	1	324.00	Dented	B	324.00	—
48	Rear end panel top garnish	1	86.00	Kinked	nd	86.00	—
49	Spare tyre panel	1	1,036.00	Dented	uu	1,036.00	7X
50	Spare tyre cover board	1	98.00	Broken	uu	98.00	7X
51	Spare tyre tools box	1	217.00	To Check	uu	217.00	7X
52	Rear floor inner panel	1		Dented			kn
53	Rear floor side panel LH	1	128.00	Dented	R	128.00	X
54	Rear floor side panel RH	1	128.00	Dented	R	128.00	X
55	Rear wheelhouse inner LH	1	441.00	Bented	R	441.00	X
56	Rear wheelhouse inner RH	1	441.00	Bented	R	441.00	X
57	Rear stiffender jack bracket	1	289.00	Dented	R	289.00	X
58	Rear chassis outer assy LH	1	307.00	Bented	R	307.00	X
59	Rear chassis outer assy RH	1	307.00	Bented	R	307.00	X
60	Rear air vent assy outer LH	1	55.00	Broken	B	55.00	X
61	Rear exhaust silencer assy	1	465.00	Dented	B	465.00	✓
62	Rear exhaust rubber mounting	2	35.00	Necessary	uu	70.00	7X
63	Rear exhaust pipe assy	1		Bented			na
64	Rear exhaust heat shield	1	40.00	Dented	uu	40.00	7X
65	Front bumper	1	455.00	Torn	Bu	455.00	—
66	Front bumper side retainer LH	1	25.00	Necessary	su	25.00	X
67	Front bumper side retainer RH	1	25.00	Necessary	su	25.00	X
68	Front bumper clips	10	5.50	Necessary	uu	55.00	—
69	Front bumper number plate garnish holder	1	38.00	Torn	su	38.00	X
70	Front grille	1	216.00	Broken	uu	216.00	7X
71	Front grille emblem	1	25.00	Necessary	uu	25.00	7X
72	Front grille lining chrome moulding	1	90.00	Necessary	uu	90.00	7X
73	Headlamp LH	1	486.00	Torn	uu	486.00	7X
74	Headlamp RH	1	486.00	Torn	su	486.00	X

Sub-Total: 13,243.00  
Less: 20% discount - 2,648.60  
**Total Parts after 20% discount: 10,594.40**

**Special Nett Items**

1	Anti-rust coating	7	80.00				
2	Front number plate with casing	1	100.00		B	560.00	150l
3	Rear number plate with casing	1	100.00		nd	100.00	205n
4	Rear windscreen sealant	1	120.00		uu	100.00	455n
5	Rear end panel sealant	1	100.00		uu	120.00	405n
6	Spare tyre panel sealant	1	100.00		uu	100.00	305n
7	Rear fender sealant	2	100.00		uu	100.00	305n
8	Rear bumper sensor set	1	250.00		uu	200.00	605n
9	Rear windscreen tint film	1	250.00		nd	250.00	2005n
					uu	250.00	1205n
						1,780.00	

**Total Parts: 12,374.40**

**Labour Charges For Front & Rear Portion**

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	3,750.00	2800l
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	2,750.00	1800l
3	Provide skill labour to disconnect and check electrical wiring	60.00	20l
4	Remove and reinstall cushions, seats, backrest, inner trim,garnish, roof lining and or upholstery to facilitate repairs	180.00	120l
5	Dismantle and transfer bootlid fittings and mechanism to new door/facilitate repair	80.00	50l
6	Provide skill labour to to check and re-adjust all wheel alignment	80.00	60l
7	Provide skill labour to remove and replace rear windscreen	200.00	120l
8	Remove and refit whole rear with axle undercarriage to facilitate repair	350.00	180l
9	Provide skill labour to remove and replace bumper sensors	80.00	50l
10	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair	100.00	60l
11	Provide skill labour to remove and refit fuel tank fixture and attachment	80.00	60l
12	Provide skill labour to mount vehicle onto chassis alignment bench	350.00	250l

**Total Labour:**

**Total Parts & Labour:  
GST 7%  
Grand Total:**

8,060.00
20,434.40
1,430.41
<b>21,864.81</b>

**Estimate Repair Duration**

26 days

ACCIDENT VEHICLE OF : **SDW1521M**

Page : 3 of 3

21 days

**Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth  
 Company : LKK  
 Date : 30/5/18  
 Time : \_\_\_\_\_  
 Contact No : 96910663  
 Email : \_\_\_\_\_

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/5/2018

### Survey Details:

Date of loss	24-May-18
Date of appointment	30-May-18
Date of survey	30-May-18
Location of survey	BH Auto Services Pte Ltd

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SDW 1521M
Make and Model	HONDA CIVIC 1.6 A
Date of registration	27-May-05
Excess	
Market Value	\$ 18,000.00
Parf Rebate	\$ 12,638.00
Nett Loss	\$ 5,362.00

### Repair details:

Initial Estimate	\$ 20,434.40
------------------	--------------

### Proposed/Revised repair cost:

Parts	6,526.50
Check items (estimate)	2,596.00
Labour	\$ 5,570.00
<b>Total</b>	\$ 14,692.50
<b>Lump Sum(if applicable)</b>	\$ -

<b>Number of days for repair</b>	<b>21 days</b>
----------------------------------	----------------

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 Fax: 6269 2404

AXA Insurance Singapore Pte Ltd  
8 Shenton Way  
#27-01 AXA Tower  
Singapore (068811)  
ATTN: MOTOR CLAIM DEPARTMENT  
Tel : 6338 7288 Fax : 6880 4838  
DEAR SIR / MADAM :

*Not Authorized  
L1Pmp & 5000p??  
Purway After Pain*

ACCIDENT REPAIR ON: SDW1521M  
MODEL : HONDA CIVIC 1.6A  
POLICY NO : 10198255  
CHASSIS NO : JHMES56805S202757  
YEAR OF MANUFACTURE : 2005  
DATE/TIME OF ACCIDENT: 24/05/2018 Time: 1845Hrs at EXIT JALAN TOA PAYOH TWDS POTONG PASIR  
THIRD PARTY VEHICLE NO: XD5457C

Date: 28/05/2018  
Page : 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount	
S/N			SS		SS	
1	Rear fender LH	1	623.00	Dented	623.00	✓
2	Rear fender RH	1	623.00	Dented	623.00	✓
3	Rear fender inner upper trim LH	1	155.00	Kinked	155.00	?
4	Rear fender inner upper trim RH	1	155.00	Kinked	155.00	?
5	Rear windscreen	1	861.00	Smashed	861.00	✓
6	Rear windscreen moulding set	1	140.00	Necessary	140.00	✓
7	Rear third brake light	1	271.00	Cracked	271.00	✓
8	Rear speaker cover board	1	551.00	Kinked	551.00	✓
9	Rear tail lamp assy LH	1	226.00	Broken	226.00	✓
10	Rear tail lamp assy RH	1	226.00	Broken	226.00	✓
11	Rear tail lamp panel LH	1	65.00	Dented	65.00	✓
12	Rear tail lamp panel RH	1	65.00	Dented	65.00	✓
13	Rear tail lamp gasket LH	1	25.00	Necessary	25.00	✓
14	Rear tail lamp gasket RH	1	25.00	Necessary	25.00	✓
15	Rear tail lamp clips	6	5.50	Necessary	33.00	✓
16	Bootlid	1	495.00	Dented	495.00	✓
17	Bootlid hinge LH	1	58.00	Bented	58.00	✓
18	Bootlid hinge RH	1	58.00	Bented	58.00	✓
19	Bootlid spring LH	1	45.00	Bented	45.00	?
20	Bootlid spring RH	1	45.00	Bented	45.00	?
21	Bootlid lock assy	1	75.00	Broken	75.00	✓
22	Bootlid lock striker	1	35.00	Bented	35.00	✓
23	Bootlid lock rod	1	38.00	Bented	38.00	?
24	Bootlid stopper	1	124.00	Necessary	124.00	?
25	Bootlid weatherstrip	1	103.00	Cut	103.00	50lin
26	Bootlid lock cable	1	86.00	Torn	86.00	?
27	Bootlid lamp LH	1	171.00	Broken	171.00	✓
28	Bootlid lamp RH	1	171.00	Broken	171.00	✓
29	Bootlid key lock cylinder	1	155.00	Jammed	155.00	✓
30	Bootlid emblem	1	28.00	Necessary	28.00	✓
31	Bootlid finisher lining chrome	1	125.00	Cracked	125.00	✓
32	Bootlid license lamp LH	1	30.00	Broken	30.00	?
33	Bootlid license lamp RH	1	30.00	Broken	30.00	?
34	Bootlid opener switch	1	85.00	Malfunction	85.00	?

*Shotted*

*Bu Bu*

*Mu CPM*

*Red/Gr Bu*

*Bo Bu*

*Bu Bu*

*Mu Bu*

*Bu Bu*

*Bu Bu*

*Tu Bu*

*Bu Bu*

*Bu Bu*

*Bo Bu*

*Red Mu*

*CPM*

35	Boot side trim LH	1	75.00	Kinked	75.00	?
36	Boot side trim RH	1	75.00	Kinked	75.00	?
37	Rear bumper	1	630.00	Cut	630.00	✓
38	Rear bumper clips	10	5.50	Necessary	55.00	—
39	Rear bumper side retainer LH	1	25.00	Necessary	25.00	—
40	Rear bumper side retainer RH	1	25.00	Necessary	25.00	—
41	Rear bumper side bracket LH	1	12.00	Bented	12.00	?
42	Rear bumper side bracket RH	1	12.00	Bented	12.00	?
43	Rear bumper stiffener LH	1		Dented		
44	Rear bumper stiffener RH	1		Dented		
45	Rear stiffener panel LH	1		Dented		
46	Rear stiffener panel RH	1		Dented		
47	Rear end panel	1	324.00	Dented	324.00	✓
48	Rear end panel top garnish	1	86.00	Kinked	86.00	✓
49	Spare tyre panel	1	1,036.00	Dented	1,036.00	?
50	Spare tyre cover board	1	98.00	Broken	98.00	?
51	Spare tyre tools box	1	217.00	To Check	217.00	?
52	Rear floor inner panel	1		Dented		
53	Rear floor side panel LH	1	128.00	Dented	128.00	✓
54	Rear floor side panel RH	1	128.00	Dented	128.00	✓
55	Rear wheelhouse inner LH	1	441.00	Bented	441.00	✓
56	Rear wheelhouse inner RH	1	441.00	Bented	441.00	✓
57	Rear stiffender jack bracket	1	289.00	Dented	289.00	✓
58	Rear chassis outer assy LH	1	307.00	Bented	307.00	✓
59	Rear chassis outer assy RH	1	307.00	Bented	307.00	✓
60	Rear air vent assy outer LH	1	55.00	Broken	55.00	✓
61	Rear exhaust silencer assy	1	465.00	Dented	465.00	✓
62	Rear exhaust rubber mounting	2	35.00	Necessary	70.00	?
63	Rear exhaust pipe assy	1		Bented		
64	Rear exhaust heat shield	1	40.00	Dented	40.00	?
65	Front bumper	1	455.00	Torn	455.00	✓
66	Front bumper side retainer LH	1	25.00	Necessary	25.00	✓
67	Front bumper side retainer RH	1	25.00	Necessary	25.00	✓
68	Front bumper clips	10	5.50	Necessary	55.00	✓
69	Front bumper number plate garnish holder	1	38.00	Torn	38.00	✓
70	Front grille	1	216.00	Broken	216.00	?
71	Front grille emblem	1	25.00	Necessary	25.00	?
72	Front grille lining chrome moulding	1	90.00	Necessary	90.00	?
73	Headlamp LH	1	486.00	Torn	486.00	?
74	Headlamp RH	1	486.00	Torn	486.00	✓

\$ 7225 - 20%  
= \$ 5780.00

Sub-Total: 13,243.00  
Less: 20% discount - 2,648.60  
Total Parts after 20% discount: 10,594.40

**Special Nett Items**

1	Anti-rust coating	7	80.00		560.00	150l
2	Front number plate with casing	1	100.00		100.00	201a
3	Rear number plate with casing	1	100.00		100.00	455a
4	Rear windscreen sealant	1	120.00		120.00	401a
5	Rear end panel sealant	1	100.00		100.00	301a
6	Spare tyre panel sealant	1	100.00		100.00	301a
7	Rear fender sealant	2	100.00		200.00	601a
8	Rear bumper sensor set	1	250.00		250.00	2001a
9	Rear windscreen tint film	1	250.00		250.00	1201a

\$ 695.00 + \$ 50

= \$ 745.00

Total Parts: 12,374.40

**Labour Charges For Front & Rear Portion**

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	3,750.00	2800
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	2,750.00	1800
3	Provide skill labour to disconnect and check electrical wiring	60.00	20
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	180.00	120
5	Dismantle and transfer bootlid fittings and mechanism to new door/facilitate repair	80.00	50
6	Provide skill labour to to check and re-adjust all wheel alignment	80.00	60
7	Provide skill labour to remove and replace rear windscreen	200.00	120
8	Remove and refit whole rear with axle undercarriage to facilitate repair	350.00	180
9	Provide skill labour to remove and replace bumper sensors	80.00	50
10	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair	100.00	60
11	Provide skill labour to remove and refit fuel tank fixture and attachment	80.00	60
12	Provide skill labour to mount vehicle onto chassis alignment bench	350.00	250

\$ 5570.00

Total Labour:

Total Parts & Labour:  
GST 7%  
Grand Total:

8,060.00
20,434.40
1,430.41
<b>21,864.81</b>

Estimate Repair Duration

26 days  
21 days

ACCIDENT VEHICLE OF : SDW1521M

Page : 3 of 3

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth  
Company : LKK  
Date : 30/5/18  
Time : \_\_\_\_\_  
Contact No : 96910663  
Email : \_\_\_\_\_

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Part : \$ 5780.00  
S/N : \$ 745.00  
Labour : \$ 5570.00  
Total : \$ 12095.00 - 20%  
= \$ 9676.00 = \$ 5,800.00 (Repair limit)

## ◀ Service Request Details

Claim

S8M00ILO

Reference

None ✎

Loss Date

May 24, 2018

Request Date

May 28, 2018

Due Date

June 5, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*28/5/2018 @ 3:37pm  
BH Auto  
Jacelyn veh in  
arrange survey 30/5/2018*

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SDW1521M

Make

TPVD HONDA

Service Address

---

Primary Contact/Insured

---

SOON DEE HONG CONTAINER SERVICES  
62 SUNGEI KADUT LOOP, #04-16, INTERNAL FURNITURE CENTRE, 729507, Singapore  
65674755  
hongyen.chong@allink.com.sg

Claim Handler

---

LOH Cynthia  
6568804843  
cynthia.loh@axa.com.sg

Additional Instructions

- 
- Messages
  - Invoices
  - History
  - Documents
  - Assessment
  - Metrics
  - Notes

New Message

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S66SS0020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MH118068145 Vehicle Registration No: XD54B7C
Name(as shown in NRIC) : Tamilselvan Thirugnanam NRIC/FIN/Passport No : G7663533L
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate
Address : Singapore ( )
Contact (Tel) : Mobile No. : 82607579
Email Address :
Date of Accident : 24/5/18 Time of Accident : 1855
Place of Accident : Along upper Selegie Road
Insurance Company: AXA Insurance plc Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To attach correct sketch plan

Multiple horizontal lines for additional information or amendments.

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: Jeevan
NRIC/FIN No.:
Date:



**Re:RE: Re:<MANDATE IA> S8M00IL0 ACCIDENT INVOLVING VEHICLES XD 5457C (OI) AND SDW 1521M(TP) ON 24/05/2018 TOTAL: \$9,208.00**

Type

 Question

Message

APPROVED

Reply



SWISH CAR RENTAL PTE LTD  
 390 Victoria Street  
 #01-48 Golden Landmark  
 Singapore 188061  
 phone 6296 7198  
 enquiries@swishcarrental.sg

210018  
**OFFICIAL RECEIPT**

www.swishcarrental.sg

Date 12/09/18.

Received from Ho Chee Kian (SDW1521W).

The Sum of dollars Three thousands and six hundred dollars only.

being payment of SGH 841 P from 24/05/18 to 03/06/18.  
\$120.00 x 30 days.

S\$ 3600/-.

Received by

The payment/deposit made is non-refundable or transferable

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	XD 5457C (Insd veh)	Model:	HONDA CIVIC (A)
	SDW 1521M (TP veh)		
Date of Accident:	24/05/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	21,864.81
Final Repair Cost	:	\$	6,206.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	3,000.00 30 days
LTA / GIA Search Fee	:	\$	2.00

Others: : \$

: \$  
Final Settlement Sum (GLOBAL SUM) : \$ 9,000.00

Is Third Party Workshop GIA Registered?  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks  
\_\_\_\_\_  
\_\_\_\_\_

<b>Payment Instruction: Payee's Breakdown</b>			
1)	BH AUTO SERVICES PTE LTD	:	\$ 9,000.00

NUR SHAQILAH BTE ABDOL  
WAHAB

30/01/2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18009836/Kha3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: CYNTHIA LOH

Date : 30-01-2019



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5457C	Veh. Inspected	SDW 1521M
Policy No.	VCA/P1716854	Coverage (\$)	0.00
Claim No.	S8M00ILO	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	30/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC (A)	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JHMES56805S202757	Colour	METALLIC GREY
Odometer	255901	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60R15	YOKOHAMA	8 mm
L/H Front Tyre	195/60R15	YOKOHAMA	8 mm
R/H Rear Tyre	195/60R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/60R15	YOKOHAMA	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	24/05/2018	Inspection Date	30/05/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>21 Working Days</b>
-------------------------------------	------------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDW 1521M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR FENDER LH (CONSISTENT)	BUCKLED	623.00	623.00
1	REAR FENDER RH (CONSISTENT)	BUCKLED	623.00	623.00
1	REAR FENDER INNER UPPER TRIM LH (CONSISTENT)	NOT NECESSARY	155.00	-
1	REAR FENDER INNER UPPER TRIM RH (CONSISTENT)	NOT NECESSARY	155.00	-
1	REAR WINDSCREEN (CONSISTENT)	SHATTERED	861.00	861.00
1	SET REAR WINDSCREEN MOUDING (CONSISTENT)	NECESSARY	140.00	140.00
1	REAR THIRD BRAKE LIGHT (CONSISTENT)	CRACKED	271.00	271.00
1	REAR SPEAKER COVER BOARD (CONSISTENT)	DENTED / CUT	551.00	551.00
1	REAR TAIL LAMP ASSY LH (CONSISTENT)	BROKEN	226.00	226.00
1	REAR TAIL LAMP ASSY RH (CONSISTENT)	BROKEN	226.00	226.00
1	REAR TAIL LAMP PANEL LH (CONSISTENT)	BENT	65.00	65.00
1	REAR TAIL LAMP PANEL RH (CONSISTENT)	BENT	65.00	65.00
1	REAR TAIL LAMP GASKET LH (CONSISTENT)	NECESSARY	25.00	25.00
1	REAR TAIL LAMP GASKET RH (CONSISTENT)	NECESSARY	25.00	25.00
6	REAR TAIL LAMP CLIPS @ \$5.50 (CONSISTENT)	NECESSARY	33.00	33.00
1	BOOTLID (CONSISTENT)	BENT	495.00	495.00
1	BOOTLID HINGE LH (CONSISTENT)	BENT	58.00	58.00
1	BOOTLID HINGE RH (CONSISTENT)	BENT	58.00	58.00
1	BOOTLID SPRING LH (CONSISTENT)	NOT NECESSARY	45.00	-
1	BOOTLID SPRING RH (CONSISTENT)	NOT NECESSARY	45.00	-
1	BOOTLID LOCK ASSY (CONSISTENT)	JAMMED	75.00	75.00
1	BOOTLID LOCK STRIKER (CONSISTENT)	BENT	35.00	35.00
1	BOOTLID LOCK ROD (CONSISTENT)	NOT NECESSARY	38.00	-
1	BOOTLID STOPPER (CONSISTENT)	NOT NECESSARY	124.00	-
1	BOOTLID LOCK CABLE (CONSISTENT)	NOT NECESSARY	86.00	-
1	BOOTLID LAMP LH (CONSISTENT)	BROKEN	171.00	171.00
1	BOOTLID LAMP RH (CONSISTENT)	BROKEN	171.00	171.00
1	BOOTLID KEY LOCK CYLINDER (CONSISTENT)	DENTED	155.00	155.00
1	BOOTLID EMBLEM (CONSISTENT)	NECESSARY	28.00	28.00
1	BOOTLID FINISHER LINING CHROME (CONSISTENT)	CRACKED	125.00	125.00
1	BOOTLID LICENSE LAMP LH (CONSISTENT)	NOT NECESSARY	30.00	-

Report Ref No. CC4/ASM18009836/Kha3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID LICENSE LAMP RH (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOTLID OPENER SWITCH (CONSISTENT)	NOT NECESSARY	85.00	-
1	BOOT SIDE TRIM LH (CONSISTENT)	NOT NECESSARY	75.00	-
1	BOOT SIDE TRIM RH (CONSISTENT)	NOT NECESSARY	75.00	-
1	REAR BUMPER (CONSISTENT)	BUCKLED	630.00	630.00
10	REAR BUMPER CLIPS @ \$5.50 (CONSISTENT)	NECESSARY	55.00	55.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	DISTORTED	25.00	25.00
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	DISTORTED	25.00	25.00
1	REAR BUMPER SIDE BRACKET LH (CONSISTENT)	NOT NECESSARY	12.00	-
1	REAR BUMPER SIDE BRACKET RH (CONSISTENT)	NOT NECESSARY	12.00	-
1	REAR BUMPER STIFFENER LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER STIFFENER RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR STIFFENER PANEL LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR STIFFENER PANEL RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR END PANEL (CONSISTENT)	BENT	324.00	324.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DENTED	86.00	86.00
1	SPARE TYRE PANEL (CONSISTENT)	NOT NECESSARY	1,036.00	-
1	SPARE TYRE PANEL BOARD (CONSISTENT)	NOT NECESSARY	98.00	-
1	SPARE TYRE TOOLS BOX (CONSISTENT)	NOT NECESSARY	217.00	-
1	REAR FLOOR INNER PANEL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR FLOOR SIDE PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	128.00	-
1	REAR FLOOR SIDE PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	128.00	-
1	REAR WHEELHOUSE INNER LH (CONSISTENT)	TO REPAIR SEE LABOUR	441.00	-
1	REAR WHEELHOUSE INNER RH (CONSISTENT)	TO REPAIR SEE LABOUR	441.00	-
1	REAR STIFFENER JACK BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	289.00	-
1	REAR CHASSIS OUTER ASSY LH (CONSISTENT)	TO REPAIR SEE LABOUR	307.00	-
1	REAR CHASSIS OUTER ASSY RH (CONSISTENT)	TO REPAIR SEE LABOUR	307.00	-
1	REAR AIR VENT ASSY OUTER LH (CONSISTENT)	SERVICEABLE	55.00	-

Report Ref No. CC4/ASM18009836/Kha3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER ASSY (CONSISTENT)	BENT	465.00	465.00
2	REAR EXHAUST RUBBER MOUNTING @ \$35.00 (CONSISTENT)	NOT NECESSARY	70.00	-
1	REAR EXHAUST PIPE ASSY (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR EXHAUST HEAT SHIELD (CONSISTENT)	NOT NECESSARY	40.00	-
1	FRONT BUMPER (CONSISTENT)	BUCKLED	455.00	455.00
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	25.00	-
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	25.00	-
10	FRONT BUMPER CLIPS @ \$5.50 (CONSISTENT)	NECESSARY	55.00	55.00
1	FRONT BUMPER NUMBER PLATE GARNISH HOLDER (CONSISTENT)	SERVICEABLE	38.00	-
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	216.00	-
1	FRONT GRILLE EMBLEM (CONSISTENT)	NOT NECESSARY	25.00	-
1	FRONT GRILLE LINING CHROME MOULDING (CONSISTENT)	NOT NECESSARY	90.00	-
1	HEADLAMP LH (CONSISTENT)	NOT NECESSARY	486.00	-
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	486.00	-
	LESS 20% DISCOUNT		-2,628.00	-1,445.00
			10,512.00	5,780.00
1	BOOTLID WEATHERSTRIP (50%) (SN) (CONSISTENT)	DENTED / CUT	103.00	51.50
	LESS 20% DISCOUNT		-20.60	-
			82.40	51.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE WITH CASING (SN) (CONSISTENT)	BENT	100.00	20.00
1	REAR NUMBER PLATE WITH CASING (SN) (CONSISTENT)	DENTED	100.00	45.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	40.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	30.00
1	SPARE TYRE PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	30.00
2	REAR FENDER SEALANT @ \$100.00 (SN) (CONSISTENT)	NECESSARY	200.00	60.00
1	SET REAR BUMPER SENSOR (SN) (CONSISTENT)	DENTED	250.00	200.00

Report Ref No. CC4/ASM18009836/Kha3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN TINT FILM (SN) (CONSISTENT)	NECESSARY	250.00	120.00
			1,220.00	545.00
	<b>LABOUR</b>			
	ANTI-RUST COATING.		560.00	150.00
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR SIDE PANEL LH, REAR FLOOR SIDE PANEL RH, REAR WHEELHOUSE INNER LH, REAR WHEELHOUSE INNER RH, REAR STIFFENER JACK BRACKET, REAR CHASSIS OUTER ASSY LH AND REAR CHASSIS OUTER ASSY RH.		3,750.00	2,800.00
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		2,750.00	1,800.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.		60.00	20.00
	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS.		180.00	120.00
	DISMANTLE AND TRANSFER BOOTLID FITTINGS AND MECHANISM TO NEW DOOR / FACILITATE REPAIR.		80.00	50.00
	PROVIDE SKILL LABOUR TO TO CHECK AND RE-ADJUST ALL WHEEL ALIGNMENT.		80.00	60.00
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE REAR WINDSCREEN.		200.00	120.00
	REMOVE AND REFIT WHOLE REAR WITH AXLE UNDERCARRIAGE TO FACILITATE REPAIR.		350.00	180.00
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSORS.		80.00	50.00
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE EXHAUST PIPE / SYSTEM TO FACILITATE REPAIR.		100.00	60.00
	PROVIDE SKILL LABOUR TO REMOVE AND REFIT FUEL TANK FIXTURE AND ATTACHMENT.		80.00	60.00
	PROVIDE SKILL LABOUR TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH.		350.00	250.00
			8,620.00	5,720.00
<b>GRAND TOTAL</b>			<b>20,434.40</b>	<b>12,096.50</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,800.00
---	--	--	----------

Report Ref No. CC4/ASM18009836/Kha3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.