

INS. CAS. OWNER:

Richard

CC 4/AXA1800

9856, K. pbs 2

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

1/6/18

Date / Time:

7/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBC 7074B

Name of Insured:

YIN TEH KH

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

25/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

BADRUL HUSMAN BIN AHMAD -

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S0000713 / 48619

Policy No.:

Make / Model:

Isuzu

Place of Accident:

Bukit Panyam Rd

OI GIA REPORT (YES / NO):

YES / NO

TP GIA REPORT (YES / NO)

Insured Liability:

%

Final ? Yes / No

PC 77376

GBC 7074B

SHD 309

SLW 787A



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:


WSP:

Tel:

Liability:

RMKS:

01



INSRS: Trans

WSP:

Tel:

Liability:

RMKS:

Cab

Tp



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

2 CHT 8/9/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

1/6/18

Sent By:

The

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

8/12/18

Confirm with:

WAT/M

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. 22

(Acc. 010 3rd)

NO or B 28, Ass. Lia: 07c.

Repair Cost:

SS

105913.00

Loss of Rental (LOR):

SS

811.68

(8 days)

X 101.46

Loss of Use (LOU):

SS

(\$ x days)

8

X 101.46

Loss of Income (LOI):

SS

(\$ x days)

8

X 101.46

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Not/Reject/Private Settle

2) Report Format:

3) Survey fee:

1/3000

Total:

SS

11812.13

Global Sum SS:

11000.00 (as per AXA mandate)

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

11000.00

Name 1:

Trans-cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

ALA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14D 304

Yr Regn: 01, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Percut Latitude c.c 1995

Colour:

M. White / Red

A/C: Insured / Std / NI / NA

Sp. Reading

384787

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VI-1ABC15AUC 281227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/16

P.H. 121176 Carbury
L1 Reg 8 9900d

(Ref # 6552547/879)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS - SI

Fuels

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18009856/pb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 31-05-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 7074B	Veh. Inspected	SHD 30Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/05/2018	Inspection Date	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y**AAD1805-248***Not Authorised**21 Sep @ 9900h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 30Y

VF1ABL15AUC281227

RENAULT

LATITUDE

25.5.2018

ACA

		PART		LIST	
1	1	BUMPER COVER FRT	\$	<i>R</i> 1,259.42	<i>X</i>
2	1	BUMPER SPOILER FRT	\$	<i>Sh</i> 181.75	<i>X</i>
3	1	BUMPER ABSORBER FRT	\$	<i>Sh</i> 394.68	
4	1	BUMPER RETAINER FRT LH	\$	<i>Sh</i> 151.41	
5	1	BUMPER SUPPORT FRT	\$	<i>Sh</i> 123.88	
6	1	BUMPER RETAINER FRT RH	\$	<i>Sh</i> 150.77	
7	1	BUMPER SUPPORT FRT	\$	<i>Sh</i> 123.88	
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sh</i> 472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sh</i> 266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sh</i> 207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sh</i> 207.21	
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	
13	1	TOW COVER FRT	\$	<i>Sh</i> 28.61	
14	1	RADIATOR GRILLE	\$	<i>Sh</i> 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sh</i> 225.36	
16	1	RADIATOR GRILLE FRAME	\$	<i>Sh</i> 1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	
20	1	HORN	\$	<i>Sh</i> 314.17	
21	1	HORN BRACKET	\$	<i>R</i> 40.45	
22	1	HEADLAMP LH	\$	<i>Sh</i> 1,184.43	
23	1	HEADLAMP RH	\$	<i>Sh</i> 1,184.43	
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	
26	1	BONNET	\$	<i>R</i> 1,941.63	
27	1	BONNET INSULATOR	\$	<i>Sh</i> 405.73	
28	1	BONNET STRUT LH	\$	<i>Sh</i> 88.61	
29	1	A/C CONDENSER	\$	<i>Sh</i> 2,020.37	

Trans-cab Auto Services Pte Ltd

AAD1805-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

30	1	BONNET STRUT RH	\$	Sn	88.61	
31	1	BONNET HINGE LH	\$	n	348.31	
32	1	BONNET HINGE RH	\$	n	348.31	
33	1	BONNET LOCK	\$	n	305.48	X
34	1	BONNET CABLE	\$	Sn	119.19	
35	1	BONNET CABLE COVER	\$	Sn	161.03	
36	1	BONNET SEAL OUTER	\$	Sn	92.36	
37	1	BONNET SEAL INNER	\$	Sn	157.28	
38	1	FENDER PANEL FRT LH	\$	n	783.83	
39	1	FENDER PANEL FRT RH	\$	n	783.83	
40	1	WHEELARCH FRT LH	\$	Sn	278.84	
41	1	WHEELARCH FRT RH	\$	Sn	278.84	
42	1	FENDER BRACKET LOWER LH	\$	Sn	15.79	
43	1	FENDER BRACKET LOWER RH	\$	Sn	15.79	
44	1	FENDER INSULATOR LH	\$	Sn	130.84	
45	1	FENDER INSULATOR RH	\$	Sn	130.84	
46	1	BUMPER COVER REAR	\$	Bu	1,108.46	
47	1	BUMPER LOWER REAR	\$	Dis/Bu	768.84	
48	1	BUMPER BRACKET CTR REAR	\$	Dis	113.47	
49	1	BUMEPR BRACKET SIDE RH REAR	\$	Sn	135.97	X
50	1	BUMEPR RETAINER RH REAR	\$	Sn	44.99	X
51	1	BUMPER REFLECTOR RH	\$	CM	43.61	
52	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn	135.97	X
53	1	BUMEPR RETAINER LH REAR	\$	Sn	44.99	X
54	1	BUMPER REFLECTOR LH	\$	CM	43.61	
55	1	BUMPER BEAM REAR	\$	Bu	777.52	
56	1	BUMPER BEAM BRACKET LH REAR	\$	n	225.95	X
57	1	BUMPER BEAM BRACKET RH REAR	\$	Dis	225.95	
58	1	BOOT REAR	\$	Bu	2,872.68	
59	1	BOOT FINISHER	\$	nap	470.06	
60	1	BOOT WHEATERSTRIP	\$	Sn	323.05	X
61	1	BOOT REFLECTOR LAMP LH	\$	CM	493.35	
62	1	BOOT REFLECTOR LAMP RH	\$	CM	493.35	
63	1	BOOT BADGE 'RENAULT'	\$	n	225.36	
64	1	BOOT BADGE	\$	n	225.36	
65	1	BOOT STRUT LH	\$	Sn	276.08	X
66	1	BOOT STRUT RH	\$	Sn	276.08	X
67	1	BOOT HINGE LH	\$	n	367.84	X

Trans-cab Auto Services Pte Ltd**AAD1805-248**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

68	1	BOOT HINGE RH	\$	R	367.84	
69	1	BOOT INNER TRIM	\$	Sn	586.45	
70	1	BOOT SWITCH	\$	Sn	168.13	
71	1	BOOT LOCK	\$	R	202.67	
72	1	BOOT LOCK CATCH	\$	R	74.40	
73	2	LICENCE PLATE LAMP	\$	Sn	50.52	
74	2	BOOT RUBBER PLUG	\$	Sn	221.81	
75	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
76	1	FENDER PANEL REAR LH	\$	R	3,299.13	
77	1	WHEELARCH REAR LH	\$	Sn	543.47	
78	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
79	1	FENDER PANEL REAR RH	\$	R	3,299.13	
80	1	WHEELARCH REAR RH	\$	Sn	543.47	
81	1	FENDER PANEL REAR LH	\$	R	3,299.13	
82	1	WHEELARCH REAR LH	\$	Sn	543.47	
83	1	TAILLAMP RH	\$	mg cm	552.55	✓
84	1	TAILLAMP PANEL RH	\$	R	986.70	X
85	1	TAILLAMP LH	\$	mg cm	552.55	✓
86	1	TAILLAMP PANEL LH	\$	R	986.70	X
87	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
88	1	OUTER PANEL REAR (End Panel)TRIM	\$	cm	404.56	✓
89	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
90	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
91	1	EXHAUST REAR	\$	R	7,489.05	X
92	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	59,887.17
10%	\$	5,988.72
	\$	53,898.45

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	nn	52.00	
2	1SET	BUMPER CLIP FRT	\$	nn	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	

Trans-cab Auto Services Pte Ltd

AAD1805-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	}
7	1	TOW COVER FRT	\$	sn	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	}
13	1	Windscreen moulding	\$	na	100.00	
14	1SET	Front licence plate with holder	\$	nd	80.00	45sn
15	1SET	PARKING AID	\$	short	700.00	600sn
16	1SET	REAR BUMPER CLIP	\$	na	66.00	—
17	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
18	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na	10.00	X
19	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00	X
20	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
21	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00	X
22	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
23	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
24	1	EXHAUST MOUNTING REAR	\$	sn	17.82	X
25	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
26	1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
27	1	BOOT STICKER "6555-3333"	\$	na	30.00	—
28	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
29	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
30	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
31	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	X
32	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	X
33	1	TAILLAMP CLIP RH	\$	na	5.00	—
34	1	TAILLAMP CLIP LH	\$	na	5.00	—
35	2	REAR WINDSCREEN SELANT	\$	na	80.00	X
36	1	WINDSCREEN MOULDING	\$	na	100.00	X
37	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
38	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	X
39	1	SPARE TYRE	\$	sn	330.00	X
			\$	2,787.52		

Trans-cab Auto Services Pte Ltd

AAD1805-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y**TOTAL PARTS \$ 56,685.97**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6001 5,400.00
Towing Fees.	\$	na 120.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 8001
To rust-proofing of the affected areas.	\$	170.00 801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 601
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
To lift-up engine with gear box and refit.	\$	na 440.00 X

Trans-cab Auto Services Pte Ltd

AAD1805-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn	440.00	X
To remove and refit air bag system and reset.	\$	nn	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	nn	380.00	X
To replace, refix and top up coolant for radiator	\$	nn	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn	170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	Hyman	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	601
To repair and realign rear exhaust pipe.	\$	nn	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1805-248**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

To supply and re-do rear luggage floor panel insulation padding.

\$ *nn* 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X**TOTAL \$ 18,740.00****Over All Total \$ 75,425.97****(LUMP SUM) Repair Days**~~20 DAYS~~*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

« Service Request Details

Claim

S8M00J13

Reference

None 

Loss Date

May 25, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▼

Request Date

May 30, 2018

Due Date

May 31, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

[Complete Work](#)[More ... ▼](#)

Vehicle Information

Incident Vehicle Registration

SHD30Y

Make

TPVD RENAULT

Service Address

...

Primary Contact/Insured

CIVIL TECH PTE LTD
9 SENOKO LOOP, 758172, Singapore
68916119
LINA@TIB.COM.SG

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 19 November 2018 9:51 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; 'Zhe Wei' (zhewei.kek@transcab.com.sg); claims@transcab.com.sg
Subject: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHD 30Y(DOA: 25/05/2018) - AAD1805-248

Your ref: **AAD1805-248 (SHD 30Y)**
Our ref: CC4/ASM18009856/Kpb3

Without Prejudice

Hi Sirs/Mdm,

We refer to the above matter.

We are seeking mandate approval from AXA.

Kindly advise if there is any after repair/ after paint photos for SHD 30Y(DOA: 25/05/2018). If so, kindly let us have a copy of the photos.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Candy Kong <candy.kong@transcab.com.sg>
Sent: Wednesday, 30 May 2018 3:30 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: ARRANGE FOR SURVEY SHD30Y
Attachments: img-530143528-0001.pdf

Categories: Pragati

Dear all,

Please arrange for survey as below :

GBC7074B - 25.05.2018 AT 2305 HRs - SHD30Y

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet



<MANDATE IA> - S8M00J13 [ACCIDENT INVOLVING GBC 7074B(OI) / SHD 30Y(TP) / OTHERS ON 25/05/2018]

Type

🔍 Question

Message

Liability: 100%(BOLA 28). 4 vehicles chain collision whereby our insured was the 3rd car. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$11,812.13(all-in). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 19 Nov 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 193607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 19.11.2018

Survey Details:

Date of loss	25.05.2018
Date of appointment	31.05.2018
Date of survey	01.06.2018
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHD 30Y
Make and Model	Renault Latitude (1995cc)
Date of registration	14.01.2015
Excess	NIL
Market Value/ Book Value	(est)
Parf/COE Rebate	(est)
Nett Value/ ERV	\$ - (est)

Repair details:

Initial Estimate	\$ 75,425.97
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 10,638.75
Check items (estimate)	NIL
Labour	\$ 1,740.00
Supplementary	NIL
Total	\$ 12,378.75
Lump Sum(if applicable)	\$ 9,900.00

Number of days for repair	<u>5</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

5 recommended repair days + 2PRS + 1Sunday = 8days

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 10,593.00	
Loss of use	NIL	
Loss of rental	\$ 811.68	(8days x \$101.46)
Loss of income	\$ 400.00	(8days x \$50.00)
LTA/GIA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 11,812.13	

Hsiao Tong (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Monday, 26 November 2018 4:18 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: New message for service request 48615, vehicle number SHD30Y

**Re:<MANDATE IA> - S8M00J13 [ACCIDENT INVOLVING
GBC 7074B(OI) / SHD 30Y(TP) / OTHERS ON 25/05/2018]**

Type

🔍 Question

Message

Hi LKK, please assist to obtain the LOA from OI. If everything in order, pls proceed to offer global sum at \$11,000/-.

Reply

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)
Sent: Monday, 26 November 2018 9:31 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 48615, vehicle number SHD30Y

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: richard.angbs@axa.com.sg [mailto:richard.angbs@axa.com.sg]
Sent: Monday, 26 November 2018 9:30 AM
To: admin-d@lkkauto.com
Subject: New message for service request 48615, vehicle number SHD30Y

AXA Insurance has sent you a message for claim number S8M00J13.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG.

<https://www.avg.com>

Hsiao Tong (LKKAUTO)

From: Dorcas <dorcasyong@civiltech.sg>
Sent: Friday, 30 November 2018 3:34 PM
To: Hsiao Tong (LKKAUTO)
Cc: peterong@civiltech.sg; javerntoh@planarone.com.sg
Subject: Company authorize letter-Mr Badrul Hisham
Attachments: 2848_001.pdf

Hi Hsiap Tong,

See attached authorize letter for your further action.
Thank you.

Regards,
Dorcas



CIVIL TECH PTE LTD

9 Senoko Loop Singapore 758172

Tel: 6273 1217, Fax: 6272 6196

Company Registration No: 200206669E / GST Registration No: 200206669-E

28 May 2018

Attention to AXA Insurance Pte Ltd

Dear Sirs

LETTER OF CERTIFICATION

We hereby certify that Mr Badrul Hisham Bin Ahmad of NRIC No. S7241085H is under our employment as Driver and we authorize him to drive vehicles GBC7074B.

Thank you.

Yours Faithfully

CIVIL TECH PTE LTD

F. 

Lucy Tin
HR Manger



Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Saturday, 1 December 2018 11:49 PM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'
Cc: claims@transcab.com.sg
Subject: RE: OFFER FOR SHD 30Y(DOA: 25/05/2018) - AAD1805-248 *LKK REF: CC4/ASM18009856/Kpb3

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Friday, 30 November 2018 5:23 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: jasminetan@transcab.com.sg; "Zhe Wei" <zhewei.kek@transcab.com.sg>; claims@transcab.com.sg
Subject: OFFER FOR SHD 30Y(DOA: 25/05/2018) - AAD1805-248 *LKK REF: CC4/ASM18009856/Kpb3

Without Prejudice

Hi Wai Yin,

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$11,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Monday, 19 November 2018 1:34 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: jasminetan@transcab.com.sg; "Zhe Wei" <zhewei.kek@transcab.com.sg>; claims@transcab.com.sg

Subject: RE: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHD 30Y(DOA: 25/05/2018) - AAD1805-248

WITHOUT PREJUDICE

Dear Hsiao Tong

As per your requested.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Monday, 19 November, 2018 9:51 AM

To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; 'Zhe Wei' (<zhewei.kek@transcab.com.sg>) <zhewei.kek@transcab.com.sg>; claims@transcab.com.sg

Subject: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHD 30Y(DOA: 25/05/2018) - AAD1805-248

Your ref: **AAD1805-248 (SHD 30Y)**

Our ref: CC4/ASM18009856/Kpb3

Without Prejudice

Hi Sirs/Mdm,

We refer to the above matter.

We are seeking mandate approval from AXA.

Kindly advise if there is any after repair/ after paint photos for SHD 30Y(DOA: 25/05/2018). If so, kindly let us have a copy of the photos.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBC 7074B (Insd veh)	Model:	RENAULT LATITUDE (A)
	SHD 30Y (TP veh)		
Date of Accident:	25/05/2018		

Global Sum Settlement	: [X] Yes	[] No	
Repair Estimate	: \$	80,705.77	
Final Repair Cost	: \$	10,593.00	
Loss of Token Sum	: \$	400.00	8 days at \$50.00 per day
Rental (if any)	: \$	811.68	8 days
LTA / GIA Search Fee	: \$	7.45	

Others: : \$

	: \$	
Final Settlement Sum (GLOBAL SUM)	: \$	11,000.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63 SINGAPORE 569111

Payment Instruction: Payee's Breakdown		
1)	TRANS-CAB AUTO SERVICES PTE LTD	: \$ 11,000.00

NUR SHAQILAH BTE ABDOL
WAHAB

26/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18009856/Kpb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: RICHARD ANG		Date : 26-12-2018 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 7074B	Veh. Inspected	SHD 30Y
Policy No.	CN888406	Coverage (\$)	0.00
Claim No.	S8M00J13	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	31/05/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC281227	Colour	METALLIC WHITE / RED
Odometer	384787	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	9 mm
L/H Front Tyre	215/60R16	GITI	9 mm
R/H Rear Tyre	215/60R16	GITI	9 mm
L/H Rear Tyre	215/60R16	GITI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/05/2018	Inspection Date	01/06/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 30Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT (CONSISTENT)	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER SPOILER FRT (CONSISTENT)	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT (CONSISTENT)	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH (CONSISTENT)	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH (CONSISTENT)	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT (CONSISTENT)	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT (CONSISTENT)	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT (CONSISTENT)	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT (CONSISTENT)	SERVICEABLE	28.61	-
1	RADIATOR GRILLE (CONSISTENT)	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT' (CONSISTENT)	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME (CONSISTENT)	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	615.90	-
1	FRAME FULL SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	177.22	-
1	HORN (CONSISTENT)	SERVICEABLE	314.17	-
1	HORN BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-

Report Ref No. CC4/ASM18009856/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	405.73	-
1	BONNET STRUT LH (CONSISTENT)	SERVICEABLE	88.61	-
1	A/C CONDENSER (CONSISTENT)	SERVICEABLE	2,020.37	-
1	BONNET STRUT RH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE (CONSISTENT)	SERVICEABLE	119.19	-
1	BONNET CABLE COVER (CONSISTENT)	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER (CONSISTENT)	SERVICEABLE	92.36	-
1	BONNET SEAL INNER (CONSISTENT)	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	783.83	-
1	FENDER PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	278.84	-
1	WHEELARCH FRT RH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH (CONSISTENT)	SERVICEABLE	15.79	-
1	FENDER BRACKET LOWER RH (CONSISTENT)	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH (CONSISTENT)	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH (CONSISTENT)	SERVICEABLE	130.84	-
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	DISTORTED / DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-

Report Ref No. CC4/ASM18009856/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER REFLECTOR LH (CONSISTENT)	CRACKED	43.61	43.61
1	BUMPER BEAM REAR (CONSISTENT)	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	DISTORTED	225.95	225.95
1	BOOT REAR (CONSISTENT)	BENT	2,872.68	2,872.68
1	BOOT FINISHER (CONSISTENT)	WARPED	470.06	470.06
1	BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAULT' (CONSISTENT)	NECESSARY	225.36	225.36
1	BOOT BADGE (CONSISTENT)	NECESSARY	225.36	225.36
1	BOOT STRUT LH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT STRUT RH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM (CONSISTENT)	SERVICEABLE	586.45	-
1	BOOT SWITCH (CONSISTENT)	SERVICEABLE	168.13	-
1	BOOT LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP (CONSISTENT)	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG (CONSISTENT)	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-

Report Ref No. CC4/ASM18009856/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	TAILLAMP RH (CONSISTENT)	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH (CONSISTENT)	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM (CONSISTENT)	SERVICEABLE	612.21	-
1	EXHAUST REAR (CONSISTENT)	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR (CONSISTENT)	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-5,988.71	-1,084.30
			53,898.43	9,758.75
	<u>SPECIAL NETT ITEMS</u>			
1	SET RADIATOR GRILLE FRAME CLIP (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN) (CONSISTENT)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN) (CONSISTENT)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN) (CONSISTENT)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-

Report Ref No. CC4/ASM18009856/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT LICENCE PLATE WITH HOLDER (SN) (CONSISTENT)	DENTED	80.00	45.00
1	SET PARKING AID (SN) (CONSISTENT)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN) (CONSISTENT)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN) (CONSISTENT)	NECESSARY	5.00	5.00
1	TAILLAMP CLIP LH (SN) (CONSISTENT)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
			2,787.52	880.00

Report Ref No. CC4/ASM18009856/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT, BUMPER BEAM FRT, FRAME FULL SUPPORT PANEL, FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, HEADLAMP PANEL FRT LH, HEADLAMP PANEL FRT RH, BONNET, BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK, FENDER PANEL FRT LH, FENDER PANEL FRT RH, BUMPER BEAM BRACKET LH REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, } BOOT LOCK CATCH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR. }		5,400.00	600.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	880.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHE, TO ENABLE REPAIR.		380.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-

Report Ref No. CC4/ASM18009856/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	REPEATED	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			18,740.00	1,740.00
GRAND TOTAL			75,425.95	12,378.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,900.00

Report Ref No. CC4/ASM18009856/Kpb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.