

ASS. REC. BY:

REF: CS/C7718009860/Kvd3

Special Instruction:

Surveyor:

Menthen

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

31/5/18 @ 2.24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 7118 Z

Insured:

GBE 8497 Y

at Workshop m/s

Cheng Hwe Motor

Tel:

6755 6142

of

Blk 1019 # 01- 374 / 382

Policy No:

DMCVSN 1725461801

Claim No:

SNM 18 D 02541 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/5/2018

CA / REV / REP. / REV 24 HRS

up

11/6/2018

H.O.D. Endorsement:

Date/Time:

3.09pm @ 31/5/18

Person Contacted:

Wu Ling

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBE 7118 Z -x
	GBE 8497 Y -x
26/6/18	83828.00 Cashier Tune (Red 600, 1390)

ASS. REC. BY:

REF: CT21

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 0.13.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBE 71182 Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Dyno c.c. 2882Colour: White A/C: Insured / Std / NI / NASp. Reading: 458615 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA T35480K 2058P3Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: Goodridge 195R15x8R: 155R12x80D

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 14/5/18

Survey held at

Rear

R/Bal. 3 3 mmL/Bal. 3 3 mmD.O.I. 31/5/18Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/6 File pass to Catherine

RECEIVED 27 JUN 2018

26/6/2018

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

27/6 - typistDays Of Repair: 6Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

S - RS - SI

Fictos

Others

TOTAL

220

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

merimen

3928/2

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2018 Sendback Est	30 May 2018 13:43 \$4,528.00	31 May 2018 14:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SEN MAO ENGINEERING PTE LTD, Co. Reg. No.: -		
Main Claimant:	WAN HENG LEE CONSTRUCTION & ENGINEERING, Co. Reg. No.: 52894024D		
Vehicle Reg. No.:	GBE7118Z	Date of Loss:	14/05/2018 17:00 - :59 [25 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02541C02	Policy/Cover Note No.:	DMCVSN1725461801
Vehicle Reg. No. (Insured):	GBE8497Y	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/06/2018]		
Driver/Custodian (Insured):	RASHEL (/ Male), NRIC: G6685387Q		
Adj Asg. Remarks:	EST \$4844.96, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 4024D

Vehicle Details

Vehicle No.: GBE7118Z

Vehicle to be Exported: No

Intended De-registration Date: 15 May 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA DYNA 150 MANUAL

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 1KD2585978

Chassis No.: JTFAT35Y80K205993

Maximum Power Output: -

Open Market Value: \$24,944.00

Original Registration Date: 15 Mar 2016

First Registration Date: 15 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$1,248.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 14 Mar 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10


PQP Paid: \$28,546.00

COE Rebate Amount: \$22,341.00

Total Rebate Amount: \$22,341.00

The information contained herein is correct as at 15 May 2018

OK



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
SEN MAO ENGINEERING PTE LTD

Singapore

Claimant Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP CHINA
Policy No:		Date of Loss:	14/05/2018
Vehicle Reg. No.:	GBE7118Z	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	RASHEL		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	15/03/2016
Vehicle Colour:	WHITE		
Engine No:	1KD2585978	Chassis No:	JTFAT35Y80K205993
Odometer:	0 KM		

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) **0**

Description of Accident/Loss: **PLS REFER EFILE REPORT**
 Present Location: **CHENG HOE MOTOR PTE LTD (YISHUN)**

Not Authorized
Penalty B4 paint
Edan
 KK Auto Consultants hence notify the Repairer of the following:
 • To inspect before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • No "Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

COST OF CLAIMS

	Amount
Parts	618.00
Miscellaneous Items	1,810.00
Labour	2,100.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,528.00
+ GST 7.00% (S\$)	316.96
Nett Amount (S\$)	4,844.96

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

GBE 7118 Z

Reference

Part Source: (Last Synchronised: 30 May 2018)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/GBE7118Z/30/05/2018 13:43

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Rear tailgate	0.00	0.00	*450.00 F	✓
2	1		*Rear no. plate panel	0.00	0.00	*48.00 F	✓
3	1		*Rear tailgate sticker TOYOTA	0.00	0.00	*105.00 F	✓
4	1		*Rear tailgate sticker Dyna	0.00	0.00	*15.00 F	✓
Total Parts (S\$)						618.00	

F=Franchise part.

Cheng Hoe Motor Pte Ltd/GBE7118Z/30/05/2018 13:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount	
<u>Miscellaneous Items</u>				
1	1	13 PAX STICKER	10.00	✓
2	1	70KM/HR STICKER	10.00	✓
3	1	CARGO FLOOR PROTECTOR	900.00	✓
4	1	REAR NO. PLATE	20.00	✓
5	1	REAR SAFETY BAR	350.00	X
6	1	REVERSE SENSOR	200.00	✓
7	1	TAILGATE INNER PROTECTOR	320.00	✓
Sub Total (S\$)			1,810.00	

Estimates on Labour

No	Particulars	Lab.Type	Amount	
<u>Labour Items</u>				
1	1) To remove and refix tailgate assy, tailgate lock assy, rr no.plate panel, rr safety bar; straighten, knock and repair rr floor board panel, rr truck end lower panel & member, cabin frt lh door pillar and re-align truck in position	New	1,000.00	900
2	2) To remove and refix canopy, rr cargo floor board protector and re-align to same including supply rivets	New	300.00	250
3	3) To putty and respray on rr truck floor board, end panel and memeber, frt lh door ppillar, rr safety bar and all affected areas	New	800.00	700
Gross Labour Cost (S\$)			2,100.00	

Cheng Hoe Motor Pte Ltd/GBE7118Z/30/05/2018 13:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18009860/KVD3N2

Date: 29/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMCVSN1725461801

Claimant Vehicle No: GBE7118Z

Insured Vehicle No: GBE8497Y

Date of Loss: 14/05/2018

Nature of Claim: TP

Claim No: SNM18D02541C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE7118Z

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Reg. Date: 15/03/2016 (Man. Year: 2015)

Colour: White

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

Engine No: 1KD2585978

Chassis No: JTFAT35Y80K205993

Odometer: 58615 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15X8

Rear Tyre Size: 155R12X8 (D)

Front Left Side: Goodride 9 mm

Rear Left Side: Goodride 3/3 mm

Front Right Side: Goodride 9 mm

Rear Right Side: Goodride 3/3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	618.00	618.00	0.00	0.00
Miscellaneous Items	1,810.00	1,460.00	350.00	19.34
Labour	2,100.00	1,850.00	250.00	11.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,528.00	3,928.00	600.00	13.25
+ GST 7.00/7.00% (S\$)	316.96	274.96	42.00	13.25
Nett Amount (S\$)	4,844.96	4,202.96	642.00	13.25

INSPECTION

Date of Assignment: 31/05/2018 Present Location:

Date Inspected: 31/05/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Jun 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE7118Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear tailgate	Bent	450.00 F	*450.00 F
2	1		*Rear no. plate panel	Distorted	48.00 F	*48.00 F
3	1		*Rear tailgate sticker TOYOTA	Necessary	105.00 F	*105.00 F
4	1		*Rear tailgate sticker Dyna	Necessary	15.00 F	*15.00 F
F=Franchise part.						
Total Parts (S\$)					618.00	618.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	13 PAX STICKER (Necessary)	10.00	10.00
2	1	70KM/HR STICKER (Necessary)	10.00	10.00
3	1	CARGO FLOOR PROTECTOR (Buckled)	900.00	900.00
4	1	REAR NO. PLATE (Bent)	20.00	20.00
5	1	REAR SAFETY BAR (Repair)	350.00	0.00
6	1	REVERSE SENSOR (Scratched)	200.00	200.00
7	1	TAILGATE INNER PROTECTOR (Buckled)	320.00	320.00
Sub Total (S\$)			1,810.00	1,460.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1) To remove and refix tailgate assy, tailgate lock assy, rr no.plate panel, rr safety bar; straighten, knock and repair rr floor board panel, rr truck end lower panel & member, cabin frt lh door pillar and re-align truck in position	New	1,000.00	900.00
2	2) To remove and refix canopy, rr cargo floor board protector and re-align to same including supply rivets	New	300.00	250.00
3	3) To putty and respray on rr truck floor board, end panel and memeber, frt lh door ppillar, rr safety bar and all affected areas	New	800.00	700.00
Gross Labour Cost (S\$)			2,100.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >