

INS CASE OWNER:

Stacy

CC 4 ASM AXA1800

9861

KWB252

LKK:

IDAC:

Surveyor:

Hsc

DOI:

ASSIGNMENT

20/7/18

Date / Time:

21/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Sfm 2607y.

Name of Insured:

Tan Bin Seng

Insured Tel No.:

HP: 971111

Excess Sec II :SS

D.O.A: 26/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8M00111 / 48611

Policy No.:

9AD6116011

Make / Model:

TOMY

Place of Accident:

near of HAREVOU Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLC 7007c



INSRS:

WSP:

Tel:

Liability:

RMKS:

mbm



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

1/6/18
Vian

SLC 7007c - 4

Sfm 2607y - 11/11/18 (11/11/18) (11/11/18)

* Smartclaim

1/6/18

Process D.S.

26/6/18

Called O2, over sea tone

27/7/18

Called O2, Mr Tan confirm accident inform
we receive CCV from TP. later send out

12/8/18

File pass to typist type report

5/11/18

Seek mandate via SMART

15/11/18

Mandate approve via SMART

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

27/7/18
Vian

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2514.50

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

400.00

(\$ 100 x 4 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

2916.50

Global Sum SS:

2900.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2900.00

Name 1:

mbm wheel/power & te (td)

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
11/4/18

(08/11/13) wef

ACC. REC. BY:

REF:

ASM(AXA)

W

ASSIGNMENT

From:

Date:

30/7/18

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLC 7007C

at Workshop m/s

MBM Wheelpower

of

176 Hin Ming Drive # 06-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

After 10:30am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$110k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 7007C

Yr Regn:

07 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Harrier

c.c

1988

Colour

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

44074

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZSU60 . 0075999

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

255 / 150R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

P

mm

D.O.A.

26/5/18

D.O.I.

30/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/7 File pass to Catherine

13/8/18

Confirm US \$2350.00 with 4 working days.

(2nd. \$2350.00
79%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18009861/wb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 31-05-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFM 2607Y	Veh. Inspected	SLC 7007C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	31/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/05/2018	Inspection Date	
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MBM WHEELPOWER PTE LTD

Your Ref: SFM2607Y
Our Ref: SLC7007C

To: AXA INSURANCE
CC

*Not Withain
11 Lp 82350/p
Penny Ate Point
4clan*

Date: 31/5/2018
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: TOYOTA HARRIER 2.0 PREMIUM
Chassis No.: ZSU600075999
Engine No.: 2ZRB764934
Year of Make: 2016
Accident Date: 26 May 2018

Fax

ESTIMATE FOR VEHICLE NO.: SLC7007C

DESCRIPTION	
FRONT BUMPER	1450.50
FRONT BUMPER CLPS	
FRONT BUMPER RH SPONGE	
FRONT BUMPER LOWER COVER	
FRONT RADIATOR GRILLE ASSY	
FRONT BUMPER LOWER GRILLE	
FRONT BUMPER RH FOG LAMP	
FRONT BUMPER RH FOG LAMP COVER	
FRONT BUMPER RH SIDE RETAINER	
FRONT BUMPER RH SIDE BRACKET	
RH HEAD LAMP	
FRONT RH FENDER	1090.50
FRONT RH FENDER INNER SHIELD	
FRONT RH FENDER INNER SHIELD CLIPS	

QTY		List Price	
1	\$	Bu/Ad	1,600.0
10	\$	M	✓ 50.0
1	\$	Sm	X 125.0
1	\$	Sm	X 405.0
1	\$	Sm	X 645.0
1	\$	Sm	X 300.0
1	\$	Sm	X 385.0
1	\$	Sm	X 180.0
1	\$	Sm	✓ 135.0
1	\$	TL	155 X
1	\$	Sm	X 3,500
1	\$	Bu	✓ 1,650
1	\$	Sm	7 500 X
10	\$	nn	7 50 X
Total	\$		9,680
LESS 25%	\$		(2,420)
Parts Total:	\$		7,260

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SPECIAL NETT

BODY SEALANT	1	\$	<i>nn</i> 80.00 <i>X</i>
FRONT RH RIM	1	\$	<i>5m</i> 1,800.00 <i>X</i>

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	<i>400</i> 1,000.00
TO DISMANTLE AND REFIT NEW RIM	\$	<i>nn</i> 80.00 <i>X</i>
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>201</i> 80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>500</i> 900.00
Total:	\$	11,200.00
7% GST:	\$	784.00
Grand Total:	\$	<u>11,984.00</u>

Mbm wheelpower pte ltd

160 SIN MING DRIVE


#06-02

SIN MING AUTOCITY

t 62928888 f 64525333

Company Registration Number 200204110W

MBM WHEELPOWER PTE LTD



Your Ref: SFM2607Y

Our Ref: SLC7007C

To: AXA INSURANCE

CC

Fax

*Not Withash
1/1/18
Penny Abu Point
4 days*

Date: 31/5/2018
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: TOYOTA HARRIER 2.0 PREMIUM
Chassis No.: ZSU600075999
Engine No.: 2ZRB764934
Year of Make: 2016
Accident Date: 26 May 2018

ESTIMATE FOR VEHICLE NO. : SLC7007C

DESCRIPTION

FRONT BUMPER
FRONT BUMPER CLPS
FRONT BUMPER RH SPONGE
FRONT BUMPER LOWER COVER
FRONT RADIATOR GRILLE ASSY
FRONT BUMPER LOWER GRILLE
FRONT BUMPER RH FOG LAMP
FRONT BUMPER RH FOG LAMP COVER
FRONT BUMPER RH SIDE RETAINER
FRONT BUMPER RH SIDE BRACKET
RH HEAD LAMP
FRONT RH FENDER
FRONT RH FENDER INNER SHIELD
FRONT RH FENDER INNER SHIELD CLIPS

QTY	List Price	
1	\$	Bu / Bu 1,600.00 ✓
10	\$	Mu ✓ 50.00
1	\$	Sm X 125.00
1	\$	Sm X 405.00
1	\$	Sm X 645.00
1	\$	Sm X 300.00
1	\$	Sm X 385.00
1	\$	Sm X 180.00
1	\$	Mu ✓ 135.00
1	\$	7 155.00
1	\$	Sm X 3,500.00
1	\$	Bu ✓ 1,650.00
1	\$	7 500.00
10	\$	7 50.00
Total: \$		9,680.00
LESS 25% \$		(2,420.00)
Parts Total: \$		7,260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

BODY SEALANT	1	\$	<i>nn</i> 80.00 X
FRONT RH RIM	1	\$	<i>sn</i> 1,800.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	<i>400</i> 1,000.00
TO DISMANTLE AND REFIT NEW RIM	\$	<i>nn</i> 80.00 X
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>200</i> 80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>500</i> 900.00
Total:	\$	11,200.00
7% GST:	\$	784.00
Grand Total:	\$	<u>11,984.00</u>

Mbm wheelpower pte ltd

100 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62828888 f 64525333

Company Registration Number : 200204110W

◀ Service Request Details

Claim

S8M00IV1

Reference

None 

Loss Date

May 26, 2018

Request Date

May 31, 2018

Due Date

May 31, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

[Complete Work](#)[More ▾](#)

Vehicle Information

Incident Vehicle Registration

SLC7007C

Make

TPVD TOYOTA

Service Address

...

Primary Contact/Insured

TAN BIN SENG

BLK 724 BEDOK RESERVOIR ROAD, #10-5234, 470724, Singapore

92219129

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFM 2607Y (Insd veh)	Model:	TOYOTA
	SLC 7007C (TP veh)		HARRIER (A)
Date of Accident:	26/05/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	11,984.00
Final Repair Cost	:	\$	2,514.50
Loss of Use	:	\$	400.00
Rental (if any)	:	\$	4 days at \$100.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	2,900.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____100____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown			
1)	MBM WHEELPOWER PTE LTD	:	\$ 2,900.00

NUR SHAQILAH BTE ABDOL
WAHAB

16/04/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18009861/Kwb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: STACEY NG

Date : 16-04-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFM 2607Y	Veh. Inspected	SLC 7007C
Policy No.	GA061160/1	Coverage (\$)	0.00
Claim No.	S8M00IVI	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600075999	Colour	METALLIC PEARL WHITE
Odometer	44074	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/50R19	MICHELIN	9 mm
L/H Front Tyre	255/50R19	MICHELIN	9 mm
R/H Rear Tyre	255/50R19	MICHELIN	9 mm
L/H Rear Tyre	255/50R19	MICHELIN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/05/2018	Inspection Date	30/07/2018
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 7007C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	BUCKLED / DENTED	1,600.00	1,450.50
10	FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER RH SPONGE (CONSISTENT)	SERVICEABLE	125.00	-
1	FRONT BUMPER LOWER COVER (CONSISTENT)	SERVICEABLE	405.00	-
1	FRONT RADIATOR GRILLE ASSY (CONSISTENT)	SERVICEABLE	645.00	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	SERVICEABLE	300.00	-
1	FRONT BUMPER RH FOG LAMP (CONSISTENT)	SERVICEABLE	385.00	-
1	FRONT BUMPER RH FOG LAMP COVER (CONSISTENT)	SERVICEABLE	180.00	-
1	FRONT BUMPER RH SIDE RETAINER (CONSISTENT)	NECESSARY	135.00	135.00
1	FRONT BUMPER RH SIDE BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	155.00	-
1	RH HEAD LAMP (CONSISTENT)	SERVICEABLE	3,500.00	-
1	FRONT RH FENDER (CONSISTENT)	BUCKLED	1,650.00	1,090.50
1	FRONT RH FENDER INNER SHIELD (CONSISTENT)	SERVICEABLE	500.00	-
10	FRONT RH FENDER INNER SHIELD CLIPS (CONSISTENT)	NOT NECESSARY	50.00	-
	LESS 25% DISCOUNT		-2,420.00	-681.50
			7,260.00	2,044.50
SPECIAL NETT ITEMS				
1	BODY SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT RH RIM (SN) (CONSISTENT)	SERVICEABLE	1,800.00	-
			1,880.00	-
LABOUR				
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER RH SIDE BRACKET.		1,000.00	400.00
	TO DISMANTLE AND REFIT NEW RIM.	NOT NECESSARY	80.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	20.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		900.00	500.00
			2,060.00	920.00

Report Ref No. CC4/ASM18009861/Kwb3s2



GRAND TOTAL		11,200.00	2,964.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,350.00

Report Ref No. CC4/ASM18009861/Kwb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.