

22/03/2001 REF: 08/FCI18009888/Asdb | n2  
ASS. REC. BY: Special Instruction:

Surveyor: Adrian ASSIGNMENT (Office)  
AWS

From (Person): Levone jaw of PEP Date/Time: 30/5/18 @ 10:29am

Estimated Cost: Bill to:

OD  TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV1655X Insured: SHA 0699J

at Workshop m/s: MG solution Tel: 62431373

of 23 Kuki Bulkit Ave 4 #02-03

Policy No: Claim No: D18004258MPST

Sum Insured: Excess:

Make of Veh: D.O.A. 25/05/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS lup H.O.D. Endorsement:

Date/Time: 12:43pm @ 30/5/18 Person Contacted: Ms. Hong Vehicle:  IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV1655X-X
	SHA 699J-CS-FCI15009326/Rgy3d1 DOA: 2/6/15
04/06/18	@ 10:53 a.m. revert pending estimate to here via email.
	( \$ 8,825.34 Red - 59% )

ASS. REC. BY: Adrian King

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : **Yes** or **No**  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes** or **No**  
 Est. Repairs: \_\_\_\_\_ days Res.: **Yes** or **No**  
 Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: **IN / OUT**

Veh No: SLV1655X Yr Regn: 2017, Dec  
 Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Sienta Hybrid C.C. 1496  
 Colour: Blue A/C: **Insured / Std / NI / NA**  
 Sp. Reading: 6015 T/Radio: **Insured / Std / NI / NA**  
 Eng/No: \_\_\_\_\_  
 C/No: NHP1707101894  
 Gen. Cond: **Good / Fair / Poor / Burnt**  
 Steering: **Inorder / Jammed / Leaked / Burnt** or  
 Brake: **Inorder / Jammed / Leaked / Burnt** or  
 Modi: **Nil / S/Rim / STD A/Rim** or  
 Tyre Size: F: 185/60R15  
 R: 185/60R15  
**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**  
**TOYO / YOKO** or  
 Front 06 mm R/Bal. 06 mm  
 Rear 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 31/05/18  
 Survey held at MG Solution  
 Des. of Damages: **Frt / Rear / O/S / N/S / UIC / Rooftop** or  
 The **UIC / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
<b>RECEIVED 02 AUG 2018</b>	

Date/Time, File Pass to? 02/03/18  
 1) Typist  
 Date/Time, File Return to?

: Preli. Report  
 : Final Report

Days Of Repair: 6  
 Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$ )  
 Interview (\$ )  
 Tech. Invs (\$ )  
 Weekend (\$ )

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS: \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL

4x15 = 60
170 + 60
50
50
60
<b>390</b>

Report Format :

Lump Sum / I.B.I: (\$ L/S \$ 6,100/-)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118009888/Asd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 699J	Veh. Inspected	SLV 1655X
Policy No.		Coverage (\$)	0.00
Claim No.	D18004258MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	31/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/05/2018	Inspection Date	31/05/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	28-05-2018	<b>Our Ref No.</b> D18004258MFSH
<b>Accident Date</b>	25-05-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA0699J	<b>Third Party Vehicle.</b> SLV1655X
<b>Survey Location</b>	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
<b>Contact Person.</b>	MS HONG	
<b>Contact No.</b>	62431373/ 0	<b>Fax No.</b> 62431376
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	MG SOLUTION PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	LURENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 4 June 2018 10:53 AM  
**To:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'  
**Cc:** 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: SURVEY ASSESSMENT - D18004258MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SLV 1655X on 31/05/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)]  
**Sent:** Thursday, 31 May 2018 9:53 AM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'SUR' <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18004258MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [mailto:[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)]  
**Sent:** Wednesday, 30 May 2018 10:28 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [LURENEJAW@MSFIRSTCAPITAL.COM.SG](mailto:LURENEJAW@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004258MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team

Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

<b>TO</b>	: FIRST CAPITAL INSURANCE	<b>DATE</b>	: 28/05/2018
<b>ATTENTION</b>	: MOTOR CLAIMS DEPT	<b>JOB TYPE</b>	: T/P CLAIM
<b>ESTIMATE REPORT</b>	:		
<b><u>VEHICLE DETAILS</u></b>			
<b>VEHICLE NO</b>	: SLV1655X	<i>XIH P170701894</i>	
<b>MODEL</b>	: TOYOTA SIENTA 1.5A	<i>Shiley</i>	
<b>CHASSIS NO</b>			
<b><u>ACCIDENT DETAILS</u></b>		<b>DATE</b>	: 25-May-18
		<b>TIME</b>	: 18:50HRS
<b>THIRD PARTY REQUESTOR / CONTACT</b>	: JACK LI		

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Distorted</i>	1	\$ 1,725.90	\$ 1,725.90
2	TAIL GATE LOGO <i>New</i>	1	\$ 61.00	\$ 61.00
3	TAIL GATE EMBLEM 'HYBRID SYNERGY DRIVE' <i>New</i>	1	\$ 60.00	\$ 60.00
4	TAIL GATE HINGE <i>New</i>	2	\$ 89.00	\$ 178.00
5	TAIL GATE DAMPER <i>New</i>	2	\$ 162.00	\$ 324.00
6	TAIL GATE LOCK <i>Repaired</i>	1	\$ 281.70	\$ 281.70
7	TAIL GATE CATCH <i>New</i>	1	\$ 62.00	\$ 62.00
8	TAIL GATE INNER TRIM <i>New</i>	1	\$ 494.30	\$ 494.30
9	TAIL GATE INNER HANDLE <i>Repaired</i>	1	\$ 95.30	\$ 95.30
10	TAIL GATE WEATHERSTRIP <i>Lot</i>	1	\$ 282.30	\$ 282.30
11	TAIL GATE DETECTOR <i>Repaired</i>	1	\$ 250.00	\$ <del>250.00</del>
12	TAIL GATE WINDSCREEN MOULDING <i>New</i>	1	\$ 197.10	\$ 197.10
13	REAR BUMPER <i>Repaired</i>	1	\$ 1,397.10	\$ 1,397.10
14	REAR BUMPER CENTRE <i>Repaired</i>	1	\$ 350.00	\$ 350.00
15	REAR BUMPER SIDE <i>New</i>	2	\$ 233.20	\$ 466.40
16	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 83.50	\$ 167.00
17	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 96.40	\$ 192.80
18	REAR BUMPER TOW HOOK COVER <i>New</i>	1	\$ 62.30	\$ 62.30
19	REAR FENDER INNER TRIM BOARD <i>Repaired</i>	2	\$ 879.20	\$ 1,758.40

*1286.60*

*68*

*1089.70*

*125.80*

20	REAR END PANEL (OUTER) <i>Replaced</i>	1	\$ 689.75	\$ 689.75
21	REAR END PANEL (INNER) <i>Dislubed</i>	1	\$ 544.60	\$ 544.60
22	REAR END PANEL TOP GARNISH <i>Replaced</i>	1	\$ 383.20	\$ 383.20
23	REAR FLOOR PANEL <i>Repair</i>	1	\$ 1,349.70	\$ 1,349.70
24	REAR EXHAUST PIPE <i>Replaced</i>	1	\$ 925.40	\$ 925.40
25	REAR TOOL TRAY COVER <i>Replaced</i>	1	\$ 322.20	\$ 322.20

182-80

6919.65  
5189.73

TOTAL PRICE \$ 12,620.45  
LESS 25% \$ 3,155.11  
SUB TOTAL PRICE \$ 9,465.34

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Ne Ne</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE WINDSCREEN SEALANT <i>Ne</i>	1	\$ 80.00	\$ 80.00
3	TAIL GATE INNER TRIM CLIP(SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
4	REAR BUMPER CLIP(SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
5	REAR FENDER INNER TRIM CLIPS(SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL INSULATION SEAL <i>Ne</i>	1	\$ 120.00	\$ 120.00
8	REAR FLOOR PANEL INSULATION SEAL <i>Ne</i>	1	\$ 150.00	\$ 150.00
9	REVERSE SENSOR <i>Damaged</i>	1	\$ 280.00	\$ 280.00

380

TOTAL \$ 760.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$2,000.00	90	
2	TO SPRAY PAINT AFFECTED AREA	\$1,800.00	80	
3	TUFF COAT	\$150.00	60	
4	WIRING CHECK	\$80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$150.00	80	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$100.00	50	
7	TRANFER TAILGATE MECHANISM	\$120.00	80	
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$120.00	100	

9	REMOVE AND REFIX REAR EXHAUST PIPE	\$180.00	2	
<b>TOTAL</b>		<b>\$4,700.00</b>		2000

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 10,225.34  
 TOTAL LABOUR COST : \$ 4,700.00  
 TOTAL REPAIR COST : \$ 14,925.34

**APPROVED DETAILS**

SURVEYOR :  
 CONTACT NO :  
 PART BY PART / LUMP SUM :  
 NO OF DAYS :

FAX

Adrian King  
 H/S 31/05/18  
 06 Days  
 Total: 7569.73  
 H/S: 6.1k

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009888/Asd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-08-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 699J	Veh. Inspected	SLV 1655X
Policy No.		Coverage (\$)	0.00
Claim No.	D18004258MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	30/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA SIENTA HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NHP1707101894	Colour	BLUE
Odometer	6015	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	25/05/2018	Inspection Date	31/05/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1655X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAIL GATE	DISTORTED	1,725.90	1,286.60
1	TAIL GATE LOGO	NECESSARY	61.00	61.00
1	TAIL GATE EMBLEM "HYBRID SYNERGY DRIVE"	NECESSARY	60.00	60.00
2	TAIL GATE HINGE @\$89.00	NOT NECESSARY	178.00	-
2	TAIL GATE DAMPER @\$162.00	NOT NECESSARY	324.00	-
1	TAIL GATE LOCK	DAMAGED	281.70	281.70
1	TAIL GATE CATCH	NOT NECESSARY	62.00	-
1	TAIL GATE INNER TRIM	NOT NECESSARY	494.30	-
1	TAIL GATE INNER HANDLE	DEFORMED	95.30	95.30
1	TAIL GATE WEATHERSTRIP	CUT	282.30	282.30
1	TAIL GATE DETECTOR	CRACKED	250.00	68.00
1	TAIL GATE WINDSCREEN MOULDING	NECESSARY	197.10	197.10
1	REAR BUMPER	DEFORMED	1,397.10	1,089.70
1	REAR BUMPER CENTRE	DEFORMED	350.00	350.00
2	REAR BUMPER SIDE @\$233.20	NOT NECESSARY	466.40	-
2	REAR BUMPER REFLECTOR @\$83.50	NOT NECESSARY	167.00	-
2	REAR BUMPER SIDE RETAINER @\$96.40	NECESSARY	192.80	192.80
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	62.30	-
2	REAR FENDER INNER TRIM BOARD @\$879.20	CRACKED	1,758.40	1,215.80
1	REAR END PANEL (OUTER)	DENTED	689.75	689.75
1	REAR END PANEL (INNER)	DISTORTED	544.60	544.60
1	REAR END PANEL TOP GARNISH	DEFORMED	383.20	182.80
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,349.70	-
1	REAR EXHAUST PIPE	NOT NECESSARY	925.40	-
1	REAR TOOL TRAY COVER	DEFORMED	322.20	322.20
	LESS 25% DISCOUNT		-3,155.11	-1,729.91
			9,465.34	5,189.74
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	TAIL GATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00

Report Ref No. CS/FCI18009888/Asd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET TAIL GATE INNER TRIM CLIP (SN)	NOT NECESSARY	20.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	120.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			760.00	380.00
	<b>LABOUR</b>			
	PANEL BEATING,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		2,000.00	900.00
	TO SPRAY PAINT AFFECTED AREA.		1,800.00	800.00
	TUFF COAT.		150.00	60.00
	WIRING CHECK.		80.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR.		150.00	80.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		100.00	50.00
	TRANFER TAILGATE MECHANISM.		120.00	80.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	100.00
	REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	180.00	-
			4,700.00	2,100.00
	<b>GRAND TOTAL</b>		<b>14,925.34</b>	<b>7,669.74</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,100.00</b>

Report Ref No. CS/FC118009888/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.