

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0784/2018
DATE : 28-MAY-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : GREEN JONATHAN WARREN
ADDRESS : 150D EAST COAST ROAD

S(428840)
TELEPHONE NO : 9155 3735 MS GRACE

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100477262-01
VEHICLE NO : SLE7048Z
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20A973798
CHASSIS NO : JF1SJGK85GG074905
MILEAGE : 1 KM
DATE IN : 28/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 28/05/2018

Print Date : 28/05/2018
Print Time : 18:14:32

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE7048Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	REPAIR/REPLACE FRONT BUMPER, RHS FENDER, DOOR, HOOD AND PANEL 250	1750.00	1000
3	ZZ/002	RESPRAY FRONT BUMPER, RHS FENDER, DOOR, HOOD AND PANEL 200	1200.00	1000
4	ZZ/003	TRANSFER/BALANCE TYRE/RIM	28.00	/
5	ZZ/004	TRANSFER DOOR FRONT RHS MECHANISM	142.00	/
6	ZZ/005	WHEEL ALIGNMENT	171.00	/
7	ZZ/006	TO CONDUCT FRONT LIGHTING TEST	28.00	/
8	ZZ/007	TO CONDUCT FRONT RHS PROTECTANT COATING	250.00	X
9	ZZ/008	TO CONDUCT FRONT RHS ANTI-RUST COATING	290.00	150
10	ZZ/009	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	125.00	80
11	ZZ/10	SUNDRIES	100.00	50.
TOTAL LABOUR CHARGES			4084.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE7048Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 DISC WHEEL AL 18 C75 X 2 / SCR .	28111SG140				700.00
2 WHEEL APR SUBCP FRH / Puc .	51609SG0109P				396.00
3 FRT FENDER RH / Dis .	57120SG0209P				270.00
4 HOOD F CPL X Repair .	57229SG0009P				882.00
5 LOCK ASSY F HOOD RHD X	57310SG000				54.00
6 STRIKER X	57311AG010				36.00
7 BUMPER FACE F (FOR HL/W) / Dis .	57709SG011				594.00
8 BACK BEAM CPL F X	57711SG0009P				288.00
9 ENERGY ABSOR F X	57722SG020				126.00
10 COVER HOOK F SP / De .	57731SG070				5.40
11 MUD GUARD ASSY F RH / TN	59110SG021				86.40
12 PNL COMPL DR F RH / BT	60009SG0429P				720.00
13 HANDLE OUT DR SMT X	61160FJ010E4				158.40
14 WSTR OUT DR F RH X / cut .	61280SG020				100.80
15 LAMP ASSY HEAD EOF / CIA .	84002SG220				2380.00
16 LAMP ASSY-SIDE TURN MIRROR RH X	84401AJ000				102.00
17 FOG LAMP ASSY F ?	84501AJ060				272.00
18 NOZZLE COVER ASSYRH X	86636SG340Q1				54.00
19 NOZZLE COVER ASSYLH X	86636SG350E1				54.00
20 NOZZLE H L WASHERRH X	86636SG361				79.20
21 NOZZLE H L WASHERLH X	86636SG371				79.20
22 TAPE DR SASH F F RH /	90422SG000				5.40
23 TAPE DR SASH F M RH /	90422SG020				18.00
24 TAPE DR SASH F R RH /	90422SG040				18.00
25 R VIEW MIR UNIT RHR X	91036SG824				504.00

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	COVER MIR BODY RH X	91054AJ221				34.00
27	COVER CAP REPAIR RH X	91059AJ200				64.80
28	SIDE MIRROR LED SIGNAL SET X	LPHSML-9005				500.00
29	RH FRONT TYRE / SCR.	T001FRH			500.00	?
SUB TOTAL			0.00	0.00	500.00	8581.60
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	2574.48
GRAND TOTAL			0.00	0.00	500.00	6007.12
OVERALL TOTAL			6507.12			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

RH Sinder cover / DE
 " " Bracket / BT

~~WTS RH Door~~

pilliar cover / DE

Frt Bumper sider bracket / CRA

Headlamp bracket / CRA

Fog lamp cover / M's

Bumper cover / M's

RH fender Garnish / M's

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLE7048Z

TOTAL LABOUR CHARGES	4084.00
TOTAL SPARE PARTS CHARGES	6507.12
GRAND TOTAL	10591.12 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Guo Qiao - 8288028.2
31/5/18

Excess : TBA
Not Authorised.
7 Days.
before paint photos.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____