

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7282P

QBE/LKK

DATE 30/5/2018 15:00

Fz

MAKE :

RIGHT FRONT

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>- actual</i>			\$ 562.30
	Front Bumper Sponge <i>X see</i>			\$ 142.20
	Front Bumper Reinforcement <i>X see</i>			\$ 526.10
	Front Bumper Grille (RH) <i>- cut</i>			\$ 40.30
	Front Bumper Bracket Top (RH) <i>X see</i>			\$ 22.40
	Front Bumper Side Bracket <i>X see</i>			\$ 14.30
	Headlamp Support Panel Assy <i>X see</i>			\$ 1,067.50
	Headlamp (RH) <i>- broken</i>			\$ 1,388.00
	Front Fender (RH) <i>- dent</i>			\$ 619.00
	Front Fender Shield (RH) <i>X see</i>			\$ 169.80
	Front Fender Retainer <i>X see</i>			\$ 9.20
	SUB TOTAL			\$ 4,561.10
	LESS 20% <i>25%</i>			\$ 912.22
	DISCOUNTED TOTAL			\$ 3,648.88
	 Frt Fender Advertisement Logo (RH) <i>- net</i>			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 850.00 ⁴⁰⁰
	Spray Painting Charge			\$ 600.00 ⁴⁰⁰
	Wiring Charge			\$ 50.00 ²⁰
	Tuff Kote			\$ 50.00 ²⁰
	Remove/Refix Aircon & Refill Gas			\$ 150.00 ^{X 40}
	TOTAL LABOUR			\$ 1,700.00
	ESTIMATE TOTAL			\$ 5,448.88

Kaha' (LKK)
30/5/18 1530h
2 Bys
4/5
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.