CITY CAB PTE LTD **REPAIR ESTIMATE***

VEHICLE NO: SHB 3383U

MAKE

: HYUNDAI i40

DATE 31/5/2018 11:45

AIG. LKIC PZ-

IODEL	: HYUNDAI i40					1
Qty	Parts Description/ Labour	Type	Unit Price		Amount	
	Rear Bumper X Mg 67			\$	603.60	
	Rear Bumper Reinforcement XSV		100 miles 100 mi	\$	504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$	360.00	
	Rear Bumper Side Bracket			\$	49.00	
	Rear Bumper Clips × 11			\$	22.00	
	Rear Bumper Sponge 🕺 🔭			\$	143.40	
	Rear Bumper Sponge ** Rear Bumper Under Cover **			\$	225.00	
	SUB TOTAL			\$	1,907.35	
	LESS 20%			\$	381.47	
	DISCOUNTED TOTAL			\$	1,525.88	
	Poor Burmer Powerse Sensor X 515			\$	135.70	Ne
	Rear Bumper Reverse Sensor X SCARREAR Bumper Rubber Mat X			\$	50.00	Ne
	Rear Bumper Rubber Mat			Ψ	50.00	1
				\$	185.70	1
				Φ	105.70	
	Labour Charge				(00)	
	Panel Beating			\$	350.00	
	Spray Painting Charge			\$	250.00	12
				\$	50.00	1
	Wiring Charge			\$	120.00	h
	R/Refix Reverse Sensor			Þ	120.00	^
	TOTAL LABOUR			\$	770.00	-
	ESTIMATE TOTAL			\$	2,481.58	
	Kalw. ICMIY	e Repairer	nsultants hence notify of the following: bre/after spray painting			
	// 31/5/18	Parts prices and Third party sur No illegal mod	aged part(s) during resurvey e subject to confirmation rey is on a "Without Prejudice" fication(s) is allowed y item(s) must be resurveyed a	nd		
	Afke Repair photo	is subject to fi Acknowledged Signature:	nal approval from insurance ou	ιμαιιγ		
		Date:			numerod .	
	This is an initial estimate based on a visual inspection of the	ne above ve	ehicle. The final repair	quant	um will	1

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.