

REPAIR ESTIMATE\*

VEHICLE NO : SHD 7185M

DATE 30/5/2018 9:42

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Mirror (RH) — Broken			\$ 980.50
	Front Door Outer Moulding (RH) — Dry			\$ <del>63.70</del> 42.10
	<b>SUB TOTAL</b>			<b>\$ 1,044.20</b>
	<b>LESS 20%</b>			<b>\$ 208.84</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 835.36</b>
	<b>Labour Charge</b>			<b>100</b>
	Panel Beating			\$ <del>280.00</del>
	Spray Painting Charge			\$ <del>200.00</del> 50
	Wiring Charge			\$ <del>50.00</del> X 21
	<b>TOTAL LABOUR</b>			<b>\$ 530.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,365.36</b>
<p>Ka/m 11/11/18</p> <p>30/5/18 1030 L.</p> <p>1 Dry</p> <p>P/P</p> <p>Before Part p.Lt.</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				