

	EDIT	SER NO	QUAN TITY	MATERIAL	SIZE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		13	1			TAILGATE INNER TRIM BOARD		Deformed	284			20		227.2	Reviewing	
		14	1			SET TAILGATE INNER TRIM BOARD CLIPS		Necessary	30			20		24	Reviewing	
		15	1			TAILGATE GLASS MOULDING		Necessary	70.6			20		56.48	Reviewing	
		16	1			STREAM EMBLEM		Necessary	31.6			20		25.28	Reviewing	
		17	1			FLOOR PANEL		Repair	0			20		0	Reviewing	
		18	2			FLOOR PANEL TOP COVER - LH & RH		Serviceable	0			20		0	Reviewing	
		19	2			REAR FENDER INNER TRIM BOARD - LH & RH		Deformed	224.7			20		359.52	Reviewing	
		20	2			SETS REAR FENDER INNER TRIM BOARD CLIPS		Necessary	30			20		48	Reviewing	
		21	1			SPARE TYRE CARRIER		Bent	121.6			20		97.28	Reviewing	
		22	1			REAR EXHAUST PIPE		Serviceable	0			20		0	Reviewing	
		23	1			REAR EXHAUST MOUNTING		Serviceable	0			20		0	Reviewing	

Labour

	EDIT	SER NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR HRS	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS.	1200	0	0	Reviewing		
		2		TO PUTTY & SPRAY PAINT WORKS.	1000	0	0	Reviewing		
		3		TO CHECK WIRING.	30	0	0	Reviewing		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	PNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Type		
Market Value	0		License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	332 UPPER EAST, COAST ROAD, #04-08, 466456, Singapore	
			Address type	Personal Correspondence	
			Gender	Female	
			Marital status	Unknown	
			Identification #	S1637507A	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	9/21/18 1:27 PM	5500	5500	Open	Share	Clone
DHAKAL Raghav	5/28/18 4:29 PM	6888.64	6888.64	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice and Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018
LTA Search Fee_0001.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018
LKK Re-Inspection Photo 1.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018
Rental.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018
LKK INSPECTION PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018
SGF58SP INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	May 28, 2018
TP PRI RECEIVED FROM WORKSHOP WITH GIA REPORT.msg	Letters and Correspondence	Workshop	DHAKAL Raghav	May 28, 2018
SDD663T TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	May 28, 2018