



Our Ref : CS/QW18009939/K1rbs2

Date: 05<sup>th</sup> June 2018

Comfort Transportation Pte Ltd  
383 Sin Ming Drive  
Singapore 575717

Attn: Doris Lim

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO.: SHB 3237J  
ACCIDENT ON 19/05/2018**

Instruction was received to inspect the vehicle Reg. No. SHB 3237J. The inspection was conducted on 30/05/2018 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHB 3237J
Make/Model	: Hyundai i40
Year of Registration	: 2016
Body Colour	: Yellow
Chassis Number	: KMHLB41UMHU097854

The following are our comments:-

- (a) The vehicle sustained damages at the front n/s windscreen and n/s body. (Details see photographs enclosed)

- (b) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989**, that:  
*no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle.*  
 and we therefore recommend it to be written off as **"Total Loss"**

Vehicle Inspected By:



KALVIN ANG WEI KUN  
Automotive Assessor / Investigator



K.K.LAU  
*MSc(Eng M), B Eng(Hons), Peng(UK),  
 MASME(USA), B Bus(Aust), MBA(UK),  
 IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
 MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
 AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
 Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.