ASS. REC. BY:	/ C3/TP18009941/Krbez
nneth	ASSIGNMENT
From: Date:	Veh No: S178 P857 E Yr Regn: 08, 13
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD/TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Revaux Lorinde c.c 198
at Workshop m/s Trans	Cob Colour M. White / Red A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: VIEI ABZ 15 AUC 273386
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inqrder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Ingrder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII I S/Rim / STD A/Rim or
(	Tyre Size: F: 215/60R16
(Policy Condition)	R:
Remark: The veh had commenced its	N/S O/S BS / DUN / EXNOVA /GY/ FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	
GIA / PR Seen: Consistent? : Yes or No	lo L/Bal. 7 mm L/Bal. 7 mm
Est. Repairs: / 4 days Res.: Yes or N	No D.O.A. 29/1/13 D.O.I. 26/11/13
Lum Sum: /- // % 3 Val.: Yes or N	No Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehic	icle: IN/OUT & Many
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
310 183112	
Submit \$14,624.65, 14	4 days
Red: \$ \8,460.42,56%	· · · · · · · · · · · · · · · · · · ·
estimate minorare de la constante de la consta	
RECEIV	ED 1 3 JUL 2018
Date/Time, File Pass to? : Prell. Report	Days Of Repair: LY 23XIS 2
1) typed : Final Report	Resurvey No. of Trip: - Survey Fee: 170+34
Date/Time, File Return to?	Transportation: 50
2)	Add Fee:: Site Insp (\$)s+Rssi
- TD (4)	:Interview (\$ ) Photos 37
Report Format: TP- Ideputed on	: Tech. Invs (\$ ) Others
Lump_Sum / I.B.I: (\$ 14624.65)	: Weekend (\$
	TOTAL 682

# Janice Lee (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Tuesday, May 22, 2018 11:14 AM

To:

SUR

Cc:

JASMINETAN@TRANSCAB.COM.SG; claims@transcab.com.sg

Subject:

<REQUEST FOR SURVEY REPORT> TCS REF: AAD1311-267--Accident involving

SHC1825U & SHB9857E on 24.11.13

Attachments:

image001.wmz; SHB9857E 24.11.2013 - GIA.pdf; AAD1311-267 - ESTIMATE

MARKING.pdf

## WITHOUT PREJUDICE

Dear Sir/Madam

Please refer to the above case, may I request a copy of the survey report?

Enclosed is the GIA report and estimate marking for your easy reference.

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

\*\*\* Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



## TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACC	DENT	STAT	TEM	IENT
-----	------	------	-----	------

25/11/2013 11:00 Date Of Report 24/11/2013 19:15 Date Of Accident

OPHIR ROAD TO ECP (FLYOVER) Exact Location Of Accident

Singapore Country/State of Loss

#### DETAILS OF OWN VEHICLE

SHB9857E Vehicle Registration Number

Insured/Policyholder

TRANS-CAB SERVICES PTE LTD Name Of Registered Owner

200303878K Co Reg No

Vehicle Particulars

RENAULT Manufacturer

LATITUDE-2.0 CVT ABS (A) Model

Exact Purpose for which vehicle was being used

at time of accident

HIRE AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

Third Party

Vehicle Category

Taxi

No

Insurance Company

Name of Insurance Company

First Capital Insurance Ltd

Type Of Coverage

Third Party

Fleet Policy

Yes

Policy Number

D-12047359MFSH/02

Cover Note Number

#### Driver

HO KAH JOO Name of Driver S1431529B NRIC No 04/11/1960 Date Of Birth Outdoor Occupation 27/02/1995 Date Of Driving Pass

Driving Experience 18 Years And 8 Months

Male Gender

(Local) +65-84887700 Mobile Number

Fax Number Contact Number

NOEMAIL EMail Address

BLOCK 120 HO CHING ROAD Address #01-67 610120 Postcode

Was driver an employee of the Insured's Company No

Page 1 of 12

If No. Relationship of the Driver with the Insured Other - HIRER Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle

General Information of the Accident

Collision- Chain Collision Type Of Accident

Weather Conditions Clear Dry Road Surface

Other Information

Was any foreign vehicle involved in this accident? No Was any body injured in the Accident? No Was any other material or property damaged? Yes

Was there any video captured by Car Camera? No

Details of Police Action

Was the accident reported to the police? No If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

#### Circumstances of Accident

ON 24 11 2013 AT ABOUT 1915HRS. I WAS AT THE RIGHT LANE TRAVELING STRAIGHT ALONG OPHIR ROAD AND WAS HEADING TO ECP. WHILE TRAVELING AT THE FLYOVER, VEHICLES AHEAD WERE STARTING TO STOP DUE TO TRAFFIC BUILD UP. SO, I FOLLOWED SUIT. A FEW SECONDS WHILE MY TAXI WAS STATIONARY, I FELT A STRONG IMPACT FROM THE REAR OF MY TAXI, AFTER THE IMPACT, MY INITIAL REACTION WAS TO ALIGHT TO SEE THE CONDITION OF MY TAXI, AFTER LOOKING AT MY TAXI'S REAR PORTION, I NOTICED THAT THE DRIVER OF VEHICLE IN FRONT OF ME ALSO ALIGHTED AND JUST BEFORE I WAS ABOUT TO APPROACH THE SAID DRIVER, HE QUICKLY DROVE OFF AND I WAS NOT ABLE TO COPY THE VEHICLE NUMBER. THEN, I REALIZED THAT MY TAXI'S FRONT PORTION ALSO SUSTAINED DAMAGES. IT WAS VEHICLE B - SHC1825U WHICH COLLIDED ONTO THE REAR OF MY TAXI AND CAUSED THE ACCIDENT, VEHICLE A - NO PASSENGER VEHICLE B - NO PASSENGER VEHICLE C - NOT AWAR

No

Are accident photos available for attachment?

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

S1073574B

SHC1825U Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

GURCHARAIV GAE SINGH Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### **Details of Witness**

Name

Phone Number

Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

**Details Of Properties** 

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### **Details of Witness**

Name

Phone Number

Email Address

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1 Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5 Any false reporting may be referred to the Police for investigation
  6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
  7. By the indigement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan	Singapore Flyer		
	Road )	Lamp Rist K52F	
	3		
5	ECP FA	lover	A SHB905TE B. SHC182SU C. UNKNOWN
Describe Circumstance	s of the Accident		
	Refer to e	FIA REPORT	
		1	
Declaration			
I/We declare the foregoing pa	rticulars are true in every respect		
	. Quelo .	2 5 NOV 2013	Andrea
Policyholder's Signature / Duti Time	in & Driver's Signature (if de & Time	ver is not the policyholder) / Date	Witnessed by Reporting Centre Personnel





### **Accident Photo**



















### **Accident Photo**



TRANS-CAB AUTO SERVICES PTE LTD NO.42 SUNGEL KADUT ST 1 SINGAPORE 729346 FAX NO.6366 8862 TEL NO 6287 6686 CO/GST FLEG NO.201019626G SHB 9857E - III

Not Authorial 1. B. 1 . 415, 155,29 Px P

Andrea

Vehicle No.: Chassis No.: Vehicle Make: Vehicle Model: Date of Accident: Third Party Insurer:

SHB 9857E - Andrea VF1ABL15AUC273386 RENAULT LATITUDE 24.11.2013 III

		PART		LIST
1	1	BUMPER COVER FRT L70Y	S	Ber 638.20 -
2	1	BUMPER SPOILER FRT L70Y	S	Sh 92.10 X
3	î	BUMPER BEAM FRT L70Y前科号架	S	1 463.20 2
4	1	BUMPIR ABSORBER FRT 前点泡沫	\$	A 200.00 Z
5	7	BUMPER BRACKET KIT FRI LAW RH	\$	Sv 76.40.7
6	1	BUMPER SUPPORT FRT L70Y RH	\$	017 12.10
7	1	BUMPER SUPPORT FRT L70Y LH	\$	12.10 ×
8	1	BUMCER GRILLE LOWER FRT L70Y前太下面的	52.	135 20 🛪
9	1	BUMPER COVER REAR L70Y	S	BT 561.70
10	1	BUMPER BRACKET CTR REAR L70Y	\$	CAA 57.50
11		BUMPER BRACKET KIT REAR L70Y (INCLUD	5	ma 132.10
12	1	BUMEPR BRACKET SIDE LH REAR L70Y	S	017 68.90
13 '	1	BUMEPR RETAINER LH REAR L70Y	S	DIY 22.801
14	1	BUME?R BRACKET SIDE RH REAR L70Y	\$	DIV 68.90 -
15	1	BUME?R RETAINER RH REAR L70Y	\$	018 22.80 -
16	1	DED CEAR DE OCK LEI DE AR I 70VA	\$	₹ 76.10 X
17	1	BUME?R BLOCK RH REAR L70Y / K和3包沫	\$	76.10 🛚
18	1	BUMPER LOWER REAR L70D	\$	389.60
19	1	BUMPER BEAM REAR L70Y	\$	394.00
20	1	BUMPER BEAM BRACKET LH REAR L70Y	\$	B7 114.50 —
21	1	BUMPER BEAM BRACKET RH REAR L70Y	5	114.50
22	1	BUMPER REFLECTOR LH L70Y 名私上的灯版	28	S~ 22.10 X
23	1	BUMP: REFLECTOR RH L70Y	S	CPA 22.10
24	1	BUMP:3R UNDERTRAY REAR L70Y后在下面的对	约板.	389.60
25	1	BOOT REAR L70D	S	Bue 1,455.70
26	2	BOOT RUBBER PLUG L70D	\$	º≈ 112.40 X
27	1	BOOT FINISHER L70Y后系的防水散条。	\$	238.20
28	1	BOOT LOCK L70Y	\$	not 102.70
29	1	BOOT LOCK CATCH L70Y	\$	/ 37.70 X
30 -	2	BOOTSTRUT	\$	S~ 139.90 X
31	1	BOOT LOCK LINKAGE L70Y	S	In 17.50 /
32	1	BOOT LOCK LINKAGE HOLDER L70Y	\$	√~ 78.30 X
33	1	BOOT TRIM BOARD L70Y	\$	Suc463.60 X

## TRANS-CAB AUTO SERVICES PTE LTD

Andrea

NO.42 SUNGELKADUT ST 1 SINGAPORE 729346 TEL NO.61287 6666 FAX NO.6366 8862 CO/GST REG NO.201019526G SHB 9857E - III

63 1 EXHAUST CAP REAR L70Y

34	1	BOOT LOCK CATCH TRIM BOARD L70Y	Ş	S 126.30 X
35	1	BOOT WHEATERSTRIP L70Y	Ş	077 163.70 -
36		BOOT REFLECTOR LAMP LH L70Y	S	CR4 250.00 -
37	1	BOOT REFLECTOR LAMP RH L70Y	\$	CM 250.00 -
38	1 1 1	BOOT BADGE 'RENAULT'	\$	Ma 114.20 -
39	1	BOOT BADGE	5	ra 114.20 -
40	1.	BOOT HINGE LH L70Y	S	R 186.40 K
41	1	BOOT HINGE RH L70Y	S	186.40 X
42	1	FENDER PANEL REAR LH L70Y	S	/2 1,671.80 ×
43	1	FENDER PANEL REAR RH L70Y	S	BUL 1,671.80
44	1	FUEL FLAP L70Y	S	36 174 10 X
45	1	TAILLAMP LH L70Y	\$	mg c/24 280.00 —
46	1 1 1 1 1 1 1 1 1 1 1 1 1	TAILL AMP RH L70Y	\$	cm 280.00 -
47	1	TAILL AMP PANEL LH L70Y	S	12 460.00 ×
48	1	TAILLAMP PANEL RH L70Y	\$	Bt 460.00 -
49	1	WHEELARCH REAR LH L70Y	5	54 275.40 X
50	1	WHEELARCH REAR RH L70Y	\$	√~ 275.40 X
51	1	AIR VENT 后时3 校上的风网口.	\$	49.30 7×50
52	1	CHASSIS PANEL REAR LH L70Y	\$	7 1,908.60 X
53	1	CHASSIS PANEL REAR RH L70Y后整条大管 (大	(\$)	1,908.60 ?K
54	1	SPARE WHEEL PANEL L70Y (Luggage Floor	5	B1 1,109.70
55	1	SPARE WHEEL SIDE PANEL BRACKET LH L7		
56	1	SPARE WHEEL SIDE PANEL BRACKET RH L7	5融为地域	远的祭 62.70?)
57	1	OUTER PANEL REAR L70Y (End Panel)	\$	Br 745.80 -
58	1	WHEEL HOUSE PANEL INNER REAR RH	\$	723.10 X
59	1	FENDI'R INNER BOARD LH L70Y	\$	503.90 X
60	1	CHASSIS PANEL RR LH side (EXT RR LH SIDI		206.60×
61	1	CHASSIS PANEL RR RH side (EXT RR LH SID)	新石段大	
62	1	EXHAUST REAR L70Y	\$	7 365.60 X

TOTAL	\$ 21,718.30
10%	\$ 2,171.83
	\$ 19,546.47

Src116.80 X

### Specical Nett

1	ISET	BUMPER BEAM PAD FRT L70Y	S	Nec 15.00 -
2	15 ET	BUMPER BEAM SCREW L70Y	\$	Na 130.00 ~
3	15ET	BUMPER UNDERTRAY SCREW L70Y	打在Trastrictor	7岁34 2.70 7十9
		1	们如何都极到	引线丝

1	10.42 EL NO	SUNGEI 0.6::87 66			Andrea
		857E -	0.201019626G III		Ø.
	4	1SET	BOOT FINISHER NUT L70Y	\$	13.60
	5	1SET	BOOT HUFFER	S	38.20 7 \ x su
	6	15ET		\$	12.00 7
	7	1SET	1 円/変 利用 ルロ 製造 イニ	S	13.80 ? J
	8	1SET	BOOT TRIM BOARD CLIP L70Y (Necessary)	\$	Ma 15.00 -
	9	1SET	WHEELARCH CLIP (Necessary)	\$	~~ 29.40 X
	10	1SET	PARKING AID L70Y (Necessary)	5	Delsher 600.00
	11	1SET	BUMPER RR RIVET (Necessary)	5	Nec 26.00 -
	12	15ET		S	ru 60.00 -
	13	1SET	1 B. 1 (1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	S	wa 15.00 -
	14	15ET	BUMPIR UNDERTRAY SCREW (Necessary)	5	na 2.70 -
	15	1SET	BUMPER BEAM BOLT (Necessary)	\$	Ma 20.20 —
	16	1	Rear boots sticker "trans-cab"	\$	ME 30.00 -
	17	1	Rear boots sticker "6555-3333"	\$	ma 30.00 -
	18	2	Rear windscreen sealant	\$	AG 80.00 FOVE
	19	1	Windscreen moulding	\$	ma 100.00 -
	20	i	Rear Windscreen Inner Sponge Seal	\$	Nec 100.00 3052
	21	2	EXHAUST NUT L70Y	S	NO.8 ON
	22	2	EXHAUST SCREW L70Y	S	~~ 18.60 x
	23	1	EXHAUST MOUNTING REAR L70Y	Ş	Su 16.20 ×
	24	1	EXHAUST BRACKET REAR L70Y	\$	× 20.20×
	25	1	Front licence plate with holder	\$	BT 192.00 455W-
	20	*	Tion is, circo plate with notice.	10-400	CON THE SUMPLY TO GOOD AS
			TOTAL	\$	1,588.60
	+				
			TOTAL PARTS	\$	21,135.07
			¥5		
			Panel beating, knocking and straightening		
	100		the necessary portion, remove and renewal		2621
			of parts, adjust and realign the same	\$	4,200.00 2400
			To rust-proofing of the affected areas.	\$	170.00 1201
			To Check Electrical Lighting Concerned.	\$	170.00 401
			Putty and spray painting of the affected portion.	\$	4,500.00 15401

Andrea

TRANS-CAB AUTO SERVICES PTE LTD NO.42 SLINGEI KADUT STIL SINGAPORE 729346 TEL NO.6287 6666 FFX NO.6366 8862

CO/GS	0.6287 6666 FFX NO.6366 8862 ST REG NO.201019026G 98:57E - III				
	3.741. <del>7</del> .49				
	To transfer of rear luggage floor panel			(2)	
	fittings, attachment and perform water				
	seepage test.	\$		170.00	
				/	
	To transfer of rear end panel fittings,			71	200
	attachrient and perform water seepage test.	\$		170.00	
		0.00		1	
	To transfer of rear fender fittings,	4		170.00	
	attachment and perform water seepage test.	\$		170.00	
	To supply and re-do rear luggage floor panel				
	insulation padding.	\$		380.00 Ja	1
	To transfer of bootlid fittings, attachments				
	and perform water seepage test.	\$		170.00 60	/
	To dismantle and refit rear seat, backrest,				
	trimings, garnish, roof-lining, speaker		*		
	shelfboard, carpeting and other to enable	di	nu	380.00 X	
	body work repair.	\$		380.00 /	
	To Remove And Refit Rear W/Screen Glass				
	To Facil tate Bodywork Repair.	\$		170.00 /2	01
	To transfer of rear windscreen fittings,				
	attachments and perform water seepage		0		
	test.	\$	hyene	170.00 X	
			*17	170.00 X	
	To reins all rear bumper parking sensor.	\$	90	170.00 60	1
		0.000	196	7.74	100
	To drop diesel tank, pipes, hoses to				
	facilitate bodywork repair, final checking	9530		0	130
	and test ng.	\$		380.00 %	2/
	G				
	To drop rear exhaust box, renew the same,				
	to repair and realign centre exhaust pipe.	\$		170.00 7	
		351 11/255		76	9
	To repair and realign rear exhaust pipe.	\$	65	170.00	
				- C	

TRANS-IDAB AUTO SIERVICES PTE LTD NO.42 SU IGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6;187 6666 FAK NO.6366 8862 CO/GST FEG NO.201019626G SHB 9857E - III	16		Andrea
Towing Fees.	\$	336	120.00 50/
To reseal sealant on gap	\$		120.00 801
	TOTAL \$		11,950.00
Over A	Ill Total \$		33,085.07
(FARTS BY PARTS) Repair Da	ıys	15 I	Days

(FARTS BY PARTS) Repair Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En Automo	bile
TRAI	NS-CAB AUTO SE	RVICES PTE LTD	Ref : CS/TP18009941/	Krbe2
NO.2	ANG MO KIO ST	REET 63SINGAPORE 56911	Date: 16-07-2018	
١.	real transfer	Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.		Veh. Inspected	SHB 9857E
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	26/11/2013
2.		Vehicle Part	iculars & Condition	Person and Physics
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	VF1ABL15AUC273386	Colour	METALLIC WHITE / RED
	Odometer	42103	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Condi	tions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	GOODYEAR	7 mm
	L/H Front Tyre	215/60 R16	GOODYEAR	7 mm
	R/H Rear Tyre	215/60 R16	GOODYEAR	7 mm
	L/H Rear Tyre	215/60 R16	GOODYEAR	7 mm
4.			tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR AND FRONT PORTION	N.
	DAMAGES SEE D	ETAILS.		
5.		Gener	al Information	
	Accident Date	24/11/2013	Inspection Date	26/11/2013
	Survey held at	TRANS-CAB AUTO SERVICES	S PTE LTD	
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.			Remarks	
	A)THE INSPECTION B)IN ACCORDAN	ON WAS CONDUCTED ON A'W CE TO YOUR INSTRUCTIONS,	WE HAVE NOT AUTHORIS	S. ED REPAIRS.
5b.			e Days of Repair	
1/4-7	ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9857E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT L70Y	BUCKLED	638.20	638.20
1	BUMPER SPOILER FRT L70Y	SERVICEABLE	92.10	
1	BUMPER BEAM FRT L70Y	TO REPAIR SEE LABOUR	463.20	
1	BUMPER ABSORBER FRT	TO REPAIR SEE LABOUR	200.00	3
1	BUMPER BRACKET KIT FRT L70Y RH	SERVICEABLE	76.40	
1	BUMPER SUPPORT FRT L70Y RH	DISTORTED	12.10	12.10
1	BUMPER SUPPORT FRT L70Y LH	SERVICEABLE	12.10	
1	BUMPER GRILLE LOWER FRT L70Y	SERVICEABLE	135.20	
1	BUMPER COVER REAR L70Y	BENT	561.70	561.7
1	BUMPER BRACKET CTR REAR L70Y	CRACKED	57.50	57.5
1	BUMPER BRACKET KIT REAR L70Y (INCLUDI	NECESSARY	132.10	132.1
1	BUMPER BRACKET SIDE LH REAR L70Y	DISTORTED	68.90	68.9
1	BUMPER RETAINER LH REAR L70Y	DISTORTED	22.80	22.8
1	BUMPER BRACKET SIDE RH REAR L70Y	DISTORTED	68.90	68.9
1	BUMPER RETAINER RH REAR L70Y	DISTORTED	22.80	22.8
1	BUMPER BLOCK LH REAR L70Y	SERVICEABLE	76.10	
1	BUMPER BLOCK RH REAR L70Y	SERVICEABLE	76.10	
1	BUMPER LOWER REAR L70D	BENT	389.60	389.6
1	BUMPER BEAM REAR L70Y	BENT	394.00	394.0
1	BUMPER BEAM BRACKET LH REAR L70Y	BENT	114.50	114.5
1	BUMPER BEAM BRACKET RH REAR L70Y	BENT	114.50	114.5
1	BUMPER REFLECTOR LH L70Y	SERVICEABLE	22.10	
1	BUMPER REFLECTOR RH L70Y	CRACKED	22.10	22.1
1	BUMPER UNDERTRAY REAR L70Y	SERVICEABLE	389.60	
- 11	BOOT REAR L70D	BUCKLED	1,455.70	1,455.7
2	BOOT RUBBER PLUG L70D	SERVICEABLE	112.40	
1	BOOT FINISHER L70Y	SERVICEABLE	238.20	
	BOOT LOCK L70Y	DENTED	102.70	102.7
38	BOOT LOCK CATCH L70Y	TO REPAIR SEE LABOUR	37.70	
2	BOOT STRUT	SERVICEABLE	139.90	
-	BOOT LOCK LINKAGE L70Y	SERVICEABLE	17.50	
2	BOOT LOCK LINKAGE HOLDER L70Y	SERVICEABLE	78.30	)

Report Ref No. CS/TP18009941/Krbe2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
-1	BOOT TRIM BOARD L70Y	SERVICEABLE	463.60	
1	BOOT LOCK CATCH TRIM BOARD L70Y	SERVICEABLE	126.30	
	BOOT WHEATHERSTRIP L70Y	DISTORTED	163.70	163.70
	BOOT REFLECTOR LAMP LH L70Y	CRACKED	250.00	250.00
	BOOT REFLECTOR LAMP RH L70Y	CRACKED	250.00	250.00
1	BOOT BADGE 'RENAULT'	NECESSARY	114.20	114.20
1	BOOT BADGE	NECESSARY	114.20	114.20
	BOOT HINGE LH L70Y	TO REPAIR SEE LABOUR	186.40	
1	BOOT HINGE RH L70Y	TO REPAIR SEE LABOUR	186.40	
1	FENDER PANEL REAR LH L70Y	TO REPAIR SEE LABOUR	1,671.80	1
1	FENDER PANEL REAR RH L70Y	BUCKLED	1,671.80	11 (500) 900 40
1	FUEL FLAP L70Y	SERVICEABLE	174.10	
1	TAILLAMP LH L70Y	MTG CRACKED	280.00	280.0
1	TAILLAMP RH L70Y	CRACKED	280.00	280.0
1	TAILLAMP PANEL LH L70Y	TO REPAIR SEE LABOUR	460.00	)
3	TAILLAMP PANEL RH L70Y	BENT	460.00	460.0
	WHEELARCH REAR LH L70Y	SERVICEABLE	275.40	
	WHEELARCH REAR RH L70Y	SERVICEABLE	275.40	
	AIR VENT	SERVICEABLE	49.30	
1	CHASSIS PANEL REAR LH L70Y	TO REPAIR SEE	1,908.60	
	CHASSIS PANEL REAR RH L70Y	TO REPAIR SEE LABOUR	1,908.60	
	SPARE WHEEL PANEL L70Y (LUGGAGE FLOOR	BENT	1,109.70	1,109.7
	SPARE WHEEL SIDE PANEL BRACKET LH L7	SERVICEABLE	62.70	
	SPARE WHEEL SIDE PANEL BRACKET RH L7	SERVICEABLE	62.70	5
	OUTER PANEL REAR L70Y (END PANEL)	BENT	745.80	NEW COLOR
1	WHEEL HOUSE PANEL INNER REAR RH	TO REPAIR SEE LABOUR	723.10	
	FENDER INNER BOARD LH L70Y	SERVICEABLE	503.9	D
3	1 CHASSIS PANEL RR LH SIDE (EXT RR LH SIDI	TO REPAIR SEE LABOUR	206.6	0
1 8	1 CHASSIS PANEL RR RH SIDE (EXT RR LH SI	SERVICEABLE	206.6	0
1 8	1 EXHAUST REAR L70Y	TO REPAIR SEE LABOUR	365.6	0

Report Ref No. CS/TP18009941/Krbe2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST CAP REAR L70Y	SERVICEABLE	116.80	
**	LESS 10% DISCOUNT		-2,171.83	-961.75
			19,546.47	8,655.75
	SPECIAL NETT ITEMS			
1	SET BUMPER BEAM PAD FRT L70Y (SN)	NECESSARY	15.00	15.00
- 1	SET BUMPER BEAM SCREW L70Y (SN)	NECESSARY	130.00	130.00
1	SET BUMPER UNDERTRAY SCREW L70Y (SN)	SERVICEABLE	2.70	2-
1	SET BOOT FINISHER NUT L70Y (SN)	SERVICEABLE	13.60	
1	SET BOOT BUFFER (SN)	SERVICEABLE	38.20	
1	SET BOOT LOCK SCREW (SN)	SERVICEABLE	12.00	
1	SET BOOT LOCK CATCH SCREW (SN)	SERVICEABLE	13.80	
	SET BOOT TRIM BOARD CLIP L70Y (NECESSARY) (SN)	NECESSARY	15.00	15.00
1	SET WHEELARCH CLIP (NECESSARY) (SN)	NOT NECESSARY	29.40	
1	SET PARKING AID L70Y (NECESSARY) (SN)	DENTED / SHORTED	600.00	600.00
1	SET BUMPER RR RIVET (NECESSARY) (SN)	NECESSARY	26.00	26.00
1	SET BUMPER RR CLIP (NECESSARY) (SN)	NECESSARY	60.00	60.00
1	SET REFLECTOR SCREW (NECESSARY) (SN)	NECESSARY	15.00	15.00
1	SET BUMPER UNDERTRAY SCREW (NECESSARY) (SN)	NECESSARY	2.70	2.70
1	SET BUMPER BEAM BOLT (NECESSARY) (SN)	NECESSARY	20.20	20.20
1	REAR BOOTS STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	REAR BOOTS STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
2	EXHAUST NUT L70Y (SN)	NOT NECESSARY	8.00	
2	EXHAUST SCREW L70Y (SN)	NOT NECESSARY	18.60	
1	EXHAUST MOUNTING REAR L70Y (SN)	SERVICEABLE	16.20	8
1	EXHAUST BRACKET REAR L70Y (SN)	TO REPAIR SEE LABOUR	20.20	l la
1	FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	192.00	45.00
	A PROPERTY (FED CHARLE CONTAINS NO SOUTH MAN SOUTH MAN CONTAINS NA		1,588.60	1,158.90



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT L70Y, BUMPER ABSORBER FRT, BOOT LOCK CATCH L70Y, BOOT HINGE LH L70Y, BOOT HINGE RH L70Y, FENDER PANEL REAR LH L70Y, TAILLAMP PANEL LH L70Y, CHASSIS PANEL REAR RH L70Y, }		4,200.00	2,400.00
	WHEEL HOUSE PANEL INNER REAR RH, CHASSIS PANEL RR LH SIDE (EXT RR LH SIDI, EXHAUST REAR L70Y AND EXHAUST BRACKET REAR L70Y. }			
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	1,540.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGET TEST. }		170.00	120.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	i i
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	20000000
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	
	TO DISMANTLE AND REFIT REAR SEAT, BACKREST, TRIMING, GARNISH, ROOF-LINING, SPEAKER SHELFBOARD, CARPETING AND OTHER TO ENABLE BODY WORK REPAIR.	NOT NECESSARY	380.00	
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.		380.00	22500
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }		170.00	
	TOWING FEES.		120.00	50.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESEAL SEALANT ON GAP.		120.00	80.00
	CDAND TOTAL		11,950.00	4,810.00
	GRAND TOTAL		33,085.07	14,624.65

14,624.65

Report Ref No. CS/TP18009941/Krbe2

KONG SENG CHEONG

Licensed Appraiser