

22/03/2002

ASS. REC. BY:

REF: CS/7CL18007946/Deb n2

Special Instruction:

Surveyor: Bryan.

ASSIGNMENT (Office)

From (Person): CWS Joanne Yong of

FCL

Date/Time: 01062018 1254pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 2297X

Insured:

SHA 1647C

at Workshop m/s

Teamwork

Tel:

6844 2475

of

Blk 53 Ubi Ave 1 #01-24

Policy No:

Claim No:

D18004242MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25052018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 01062018 356pm

Person Contacted:

Sue

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJK 2297X - NA / CTL18009581/h4	DA: 25052018
	SHA 1647C - CCS / TINT18005695/Klrbe2	DA: 26032018

Surryville


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 G/A / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SSK 2297X Yr Regn: 2008 Octob
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Wish C.C. 1794
 Colour: Blue A/C. Insured / Std / NI / NA
 Sp. Reading: 225688 T/Radio: Insured / Std / NI / NA
 Eng/No: 1223143111
 C/No: STDER12W303000818
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/50 R17
 R: — 11 —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Palken
 Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 25/05/2018 D.O.I. 01/06/2018
 Survey held at Tremwork Page ubi
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
First Capital SHA 1647C
Vehicle before abt 4.5 mths at time of loss.
LTA 9.9K. rebate MV 151C.
finder 1/5 520/- with 5 days.
MV = \$ 15,500 (EST)
LTA \$ 9,902
Nett value \$ 5598.00

RECEIVED 12 FEB 2019

Date/Time, File Pass to?



Preli. Report

Days Of Repair: 5

1)



Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation.

2)

Add Fee:



Site Insp (\$)

) \$ + PS. SI



Interview (\$)

) Photos



Tech. Invs (\$)

) Others



Weekend (\$)

) 888

Report Format: TPLump Sum / I.B.I. (\$) 5,000

TOTAL

3x15 = 45

170 + 45

50

50 + 50

110

475

MOTOR SURVEY ASSIGNMENT

Date	28-05-2018	Our Ref No. D18004242MFSH
Accident Date	25-05-2018	Claim Type. Third Party
Insured Vehicle	SHA1647C	Third Party Vehicle. SJK2297X
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	SUE	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8241J

Vehicle Details

Vehicle No.: SJK2297X
Vehicle to be Exported: Yes
Intended De-registration Date: 26 May 2018
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 AUTO
Primary Colour: Blue
Manufacturing Year: 2008
Engine No.: 1ZZ3143111
Chassis No.: JTDER12W303000818
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$18,803.00
Original Registration Date: 13 Oct 2008
First Registration Date: 13 Oct 2008
Transfer Count: 1
Actual ARF Paid: \$18,803.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 Oct 2018
PARF Rebate Amount: \$9,401.00

Intended COE Rebate Details

COE Expiry Date: 12 Oct 2018
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$13,301.00
COE Rebate Amount: \$501.00
Total Rebate Amount: \$9,902.00

The information contained herein is correct as at 26 May 2018

OK

First Capital Insurance Ltd
 6 Raffles Quay
 Singapore 048580

Vehicle number	SJK2297K
Make / Model	TOYOTA WISH
Chassis number	JTDER12W303000818
Accident date	25 May 2018
Reference	1805-37

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER <i>Dented S80</i>	580.00 ✓
2	REAR BUMPE SIDE BRACKET <i>SVC</i>	120.00 X
2	REAR BUMPER SIDE RETAINER <i>SVC</i>	80.00 X
2	REAR BUMPER DAMPER <i>o/s Dented n/s NH</i>	143.50 287.00 ✓
2	REAR BUMPER REFLECTOR <i>o/s crack n/s NH</i>	42.00 84.00 ✓
1	END PANEL <i>SVC S81</i>	581.00 ✓
1	END PANEL TOP GARNISH <i>minimly deformed</i>	384.00 ✓
1	REAR FLOOR LOWER MEMBER <i>NH</i>	280.00 X
1	REAR FLOOR PANEL <i>rep~</i>	660.00 X
2	REAR TAILLAMP <i>minimly crack</i>	583.00 ✓
1	REAR EXHAUST SILENCER <i>NH</i>	980.00 X
1	REAR EXHAUST HEAT SHIELD <i>NH</i>	170.00 X
2	REAR FENDER INNER TRIM <i>NH</i>	930.00 X
1	TAILGATE <i>SVC</i>	1317.00 ✓
2	TAILGATE ABSORBER <i>SVC</i>	289.00 X
1	TAILGATE EMBLEM <i>NH</i>	61.00 ✓
1	TAILGATE LAMP <i>NH</i>	320.00 X
1	TAILGATE WEATHERSTRIP <i>turn</i>	380.00 ✓
1	TAILGATE LOCK <i>st</i>	389.00 ✓
1	TAILGATE LOCK STRIKER <i>turn</i>	63.00 X
2	TAILGATE HINGE <i>NH</i>	280.00 X
1	TAILGATE INNER TRIM <i>minimly crack</i>	381.00 ✓
		9199.00
Less 25 %		2299.75
Subtotal		6899.25
Balance C/F		6899.25
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
Balance B/F		6899.25
1 SET	REAR BUMPER CLIP <i>NH</i>	60.00 301-
1 SET	REAR FENDER INNER TRIM CLIP <i>NH</i>	50.00 X
1 SET	TAILGATE INNER TRIM CLIP <i>NH</i>	40.00 201-
1	JOINT SEALANT <i>NH</i>	150.00 401-
1	WINDSCREEN SEALANT <i>NH</i>	150.00 401-
1	FLOOR INSULATOR <i>NH</i>	180.00 X
1 SET	REVERSE SENSOR <i>Dam</i>	400.00 2201-
1	REAR BUMPER LOWER LIP <i>crack</i>	1200.00 6001-
Subtotal		2230.00
Balance C/F		9129.25

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	9129.25
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND RENEW REAR EXHAUST	150.00 60/-
5	REMOVE AND RENEW FLOOR INSULATOR	150.00 44
6	REMOVE AND REFIT FUEL TANK	150.00 44
7	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
8	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60/-
9	PANEL BEATING ON AFFECTED AREAS	1500.00 800/-
10	SPRAY PAINTING ON AFFECTED AREAS	1400.00 800/-
11	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	4260.00
	Grand total	13389.25

01/06/2018 @ 1030hrs

6611.12

Not Actual

4/5 5200/-

2/5mm

5 days.
Ryan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009946/Dcbrn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-02-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1647C	Veh. Inspected	SJK 2297X
Policy No.		Coverage (\$)	0.00
Claim No.	D18004242MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	01/06/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JTDER12W303000818	Colour	BLUE
Odometer	225688	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/50 R17	FALKEN	5 mm
L/H Front Tyre	215/50 R17	FALKEN	5 mm
R/H Rear Tyre	215/50 R17	FALKEN	5 mm
L/H Rear Tyre	215/50 R17	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/05/2018	Inspection Date	01/06/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 2297X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	580.00	580.00
2	REAR BUMPER SIDE BRACKET	SERVICEABLE	120.00	-
2	REAR BUMPER SIDE RETAINER	SERVICEABLE	80.00	-
2	REAR BUMPER DAMPER	O/S DENTED / N/S NOT NECESSARY	287.00	143.50
2	REAR BUMPER REFLECTOR	O/S CRACKED / N/S NOT NECESSARY	84.00	42.00
1	END PANEL	BUCKLED	581.00	581.00
1	END PANEL TOP GARNISH	MOUNTING DEFORMED	384.00	384.00
1	REAR FLOOR LOWER MEMBER	NOT NECESSARY	280.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	660.00	-
2	REAR TAILLAMP	MOUNTING CRACKED	583.00	583.00
1	REAR EXHAUST SILENCER	NOT NECESSARY	980.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	170.00	-
2	REAR FENDER INNER TRIM	NOT NECESSARY	930.00	-
1	TAILGATE	BUCKLED	1,317.00	1,317.00
2	TAILGATE ABSORBER	SERVICEABLE	289.00	-
1	TAILGATE EMBLEM	NECESSARY	61.00	61.00
1	TAILGATE LAMP	NOT NECESSARY	320.00	-
1	TAILGATE WEATHERSTRIP	TORN	380.00	380.00
1	TAILGATE LOCK	BENT	389.00	389.00
1	TAILGATE LOCK STRIKER	TO REPAIR SEE LABOUR	63.00	-
2	TAILGATE HINGE	NOT NECESSARY	280.00	-
1	TAILGATE INNER TRIM	MOUNTING CRACKED	381.00	381.00
	LESS 25% DISCOUNT		-2,299.75	-1,210.38
			6,899.25	3,631.12
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00

Report Ref No. CS/FCI18009946/Dcbn2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	SET TAILGATE INNER TRIM CLIP (SN)	NECESSARY	40.00	20.00
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00
1	FLOOR INSULATOR (SN)	NOT NECESSARY	180.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	400.00	220.00
1	REAR BUMPER LOWER LIP (SN)	CRACKED	1,200.00	600.00
			2,230.00	950.00
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		200.00	80.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND RENEW REAR EXHAUST.		150.00	60.00
	REMOVE AND RENEW FLOOR INSULATOR.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL AND TAILGATE LOCK STRIKER.		1,500.00	800.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,400.00	800.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			4,260.00	2,030.00
GRAND TOTAL			13,389.25	6,611.12

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00
---	--	--	-----------------

Report Ref No. CS/FCI18009946/Dcbn2

MARKET VALUE: \$15,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,902.00=NETT VALUE: \$5,598.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.