

ASS. REC. BY:

REF: 08

FCI 18009958 / Ctd3n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

May chuan

of

FCI

Date/Time:

1/6/18 08:46am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PBF 8910R

Insured:

SHC 3440H

at Workshop m/s

Hua Ho Trading

Tel:

628 44487

of

Blk 6 Defu Lane 10 # 01-540

Policy No:

Claim No:

DIE004197MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/05/2018

CA / REV / REP. / REV 24 HRS (up)

4/6/18 after 10am

H.O.D. Endorsement

Date/Time:

12:26pm 1/6/18

Person Contacted:

Mdm. fun

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

PBF 8910R - x

SHC 3440H - C83/FCI 17022557 / Wbs 2

D.O.A: 7/10/17

u/6/18 @ 3pm revised to May chuan by email.

16/10/2018 - Lump Sum \$9007. 3days Cred: 1873:6770)

REF: FCI

21640

ASSIGNMENT

From:

Date:

4/6/2018

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No:

FBF 8910R

at Workshop m/s

of

Hug Ho trading
31k6 Defu lane 10 # 01-540

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

After 10 am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBF 8910R

Yr Regn:

13 Jan 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha YBR 125 c.c. 124

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp Reading

89766

T/Radio: Insured / Std / NI / NA

Eng/No:

CBPKE 1787 C000 1912

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

2.75 - 18

R:

3.00 - 18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METZELER

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

D.O.I.

04-06-18

Survey held at

W/S

2pm

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Fr / Rear / O/S

and.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 16 OCT 2018

Date/Time: File Pass to?



Preli. Report

1) 16/10 Typst



Final Report

Date/Time: File Return to?

2)

Days Of Repair:

3 1

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation

Y S + RE \$

Photos

Others

TOTAL

50
50
62

Report Format:

Lump Sum / I.B.I. (\$)

TP
900+



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009958/Gtd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3440H	Veh. Inspected	FBF 8910R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004197MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	01/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/05/2018	Inspection Date		
Survey held at	HUA HO TRADING BLK 6 DEFU LANE 10 #01-540 SINGAPORE 539537			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004197MFSH
Our Ref: CS/FCI18009958/Gtd3

Date: 11 June 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. FBF 8910R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/06/2018 at the premises of M/s HUA HO TRADING, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,773.00</u>
Revised Estimate Amount	: S\$ <u>2,017.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the front and o/s portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-05-2018	Our Ref No. D18004197MFSH
Accident Date	23-05-2018	Claim Type. Third Party
Insured Vehicle	SHC3440H	Third Party Vehicle. FBF8910R
Survey Location	BLK 6 DEFU LANE 10 #01-540DEFU IND PARK C	
Contact Person.	NA	
Contact No.	62844487/ 0	Fax No. 62898180
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA HO TRADING	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 11 June 2018 3:03 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004197MFSH/1
Attachments: CSFCI18009958Gtd3.pdf

Dear May,

Enclosed herewith preliminary advice of FBF 8910R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 1 June 2018 12:28 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004197MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 1 June 2018 8:45 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004197MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

- Please find attached the necessary documents for survey.
- Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7164D
Vehicle Details	
Vehicle No.:	FBF8910R
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR 125 MANUAL
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	E3J2E000540
Chassis No.:	LBPKE1787C0001912
Maximum Power Output:	-
Open Market Value:	\$1,290.00
Original Registration Date:	13 Jan 2012
First Registration Date:	13 Jan 2012
Transfer Count:	1
Actual ARF Paid:	\$194.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,682.00
COE Rebate Amount:	\$604.00
Total Rebate Amount:	\$604.00

The information contained herein is correct as at 09 Jun 2018

OK

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.: FBF8910R
 Vehicle Type: P00 - Passenger Motorcycle/Autocycle/Moped
 Vehicle Attachment 1: No Attachment
 Vehicle Scheme: Normal
 Vehicle Make: YAMAHA
 Vehicle Model: YBR 125 MANUAL
 Chassis No.: LBPKE1787C0001912
 Propellant: Petrol
 Engine No.: E3J2E000540
 Engine Capacity: 124 cc
 Maximum Power Output: -
 Maximum Laden Weight: 285 kg
 Unladen Weight: 124 kg
 Year Of Manufacture: 2011
 Original Registration Date: 13 Jan 2012
 Lifespan Expiry Date: -
 COE Category: D - Motorcycle
 Quota Premium: \$1,682.00
 COE Expiry Date: 12 Jan 2022
 Road Tax Expiry Date: 12 Jan 2019
 Inspection Due Date: 12 Jan 2019
 Intended Transfer Date: 30 May 2018
 CO2 Emission: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

和 好 貿 易

HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FBF8910R

Items	Price
1 Set Meter / CRA	\$360 /
Head light 1 Set / CRA	\$220 /
Top Cowling / Cut	\$88 /
Head Lamp Stem X X X / NN	\$165
Front Fork X X X / NN	\$480
Front Number Plate / Cut	\$12 /
Front Fender / Cut	\$78 /
Handle Bar X / NN	\$70
Brake Lever / Cut	\$16 /
Front Footrest / Cut	\$55 /
Rear Footrest X / NN	\$55
Footrest Rubber / Cut	\$28 /
Side Box Cover / Cut CRA	\$98 /
Rear Box / Cut	\$300 150 /
Exhaust Pipe X Cover / Cut	\$466 65
Signal Light X / Cut	\$32 /
Labour Charge	\$250 100
Total	\$2773



HUA HO TRADING

2 Days.

Wingsun Repair

After repair photos.

Gno Qiang - 82880282

04/6/18.

1103 H37 1202
10%: 994.5 + 1023.3
+100
1094.5
2%: 850 800

和 好 贸 易

HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FBF8910R

Insurance notify
To resurvey of the following:
• Damaged part(s) during resurvey
• Confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Items	Price
1 Set Meter / CRA	\$360 /
Head light 1 Set / CRA	\$220 /
Top Cowling / Cut	\$88 /
Head Lamp Stem X X X X X	\$165 /
Front Fork X X X X X	\$480 /
Front Number Plate / Cut	\$12 /
Front Fender / Cut	\$78 /
Handle Bar X X X X X	\$70 /
Brake Lever / Cut	\$16 /
Front Footrest / Cut	\$55 /
Rear Footrest X NN	\$55 X
Footrest Rubber / Cut	\$28 /
Side Box Cover / Cut CRA	\$98 /
Rear Box / Cut	\$300 150 /
Exhaust Pipe X Cover / Cut	\$466 65
Signal Light X / Cut	\$32 /
Labour Charge	\$250 100
Total	\$2773



HUA HO TRADING

2 Days.

Lumpsum Repair

After repair photos.

Gino Qiao - 82880282

04/6/18.

1105 1137 1202
10%: 994.5 1023.3
+100
1094.5
2%: 850 900

13/6/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009958/Gtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3440H	Veh. Inspected	FBF 8910R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004197MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	01/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA YBR 125	c.c	124	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	LBPKE1787C0001912	Colour	BLUE	
Odometer	89766	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	2.75-18	METZELER	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	3.00-18	METZELER	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/05/2018	Inspection Date	04/06/2018	
Survey held at	HUA HO TRADING BLK 6 DEFU LANE 10 #01-540 SINGAPORE 539537			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 8910R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET METER	CRACKED	360.00	360.00
1	SET HEAD LIGHT	CRACKED	220.00	220.00
1	TOP COWLING	CUT	88.00	88.00
1	HEAD LAMP STEM	NOT NECESSARY	165.00	-
1	FRONT FORK	NOT NECESSARY	480.00	-
1	FRONT NUMBER PLATE	CUT	12.00	12.00
1	FRONT FENDER	CUT	78.00	78.00
1	HANDLE BAR	NOT NECESSARY	70.00	-
1	BRAKE LEVER	CUT	16.00	16.00
1	FRONT FOOTREST	BENT	55.00	55.00
1	REAR FOOTREST	NOT NECESSARY	55.00	-
1	FOOTREST RUBBER	CUT	28.00	28.00
1	SIDE BOX COVER	CRACKED	98.00	98.00
1	REAR BOX	CUT	300.00	150.00
1	EXHAUST PIPE COVER	CUT	466.00	65.00
1	SIGNAL LIGHT	CUT	32.00	32.00
	LESS 10% DISCOUNT		-	-120.20
			2,523.00	1,081.80
	<u>LABOUR</u>			
	LABOUR CHARGE.		250.00	100.00
			250.00	100.00
	GRAND TOTAL		2,773.00	1,181.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00

Report Ref No. CS/FC118009958/Gtd3n2

XING GUO QIANG**M.MATAI, AMSAE-A****Automotive Assessor****ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.