

22/03/2002

ASS. REC. BY:

REF:

CS3/AG18009965/G240310

Special Instruction:

Surveyor:
member

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Winnie Fan

of

AIG

Date/Time:

28/5/2018 @ 3:11 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 2046 M

Insured:

SLR 4896T

at Workshop m/s

N-SI Automotive

Tel:

6842 0051

of

Blk 2 Kaki Bukit Ave # 01-17 / 18

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/5/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

10:43am @ 1/6/18

Person Contacted:

Melody

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLS 2046 M-X
	SLR 4896T-X
4/6/18	Dismantled

ASSIGNMENT

From: _____ Date: *1/6/18*
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SLS 2046 M*
 at Workshop m/s: *N-51 Automotive*
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *9* days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *up*

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLS2046M* Yr Regn: *13 Sep 2017*
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: *Toyota Prius Alpha* *Hybrid 1.8*
 Colour: *grey* A/C: *Insured / Std / NI / NA*
 Sp. Reading: *7552* T/Radio: *Insured / Std / NI / NA*
 Eng/No: _____
 C/No: *ZVW400025897*
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: *Nil* / ☒ S/Rim / STD A/Rim or
 Tyre Size: F: *205/60 R16*
 R: *4*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

~~HAILEAD~~ HAIDA

Front

Rear

R/Bal. *5* mm

R/Bal. *5* mm

L/Bal. *5* mm

L/Bal. *5* mm

D.O.A.

D.O.I. *01-06-18*

Survey held at

w/s

4:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / ☒ U/C / Rooftop or

N/S FA

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>2/7/18</i>	<i>Submit DAR Report.</i>

RECEIVED 03 JUL 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

180

20

200

TOTAL

200

From: Fan, Winnie-LW <Winnie-LW.Fan@aig.com>
Sent: Monday, 28 May 2018 3:11 PM
To: 'admin-a@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Fong, Andy-SY; Chin, Lee-Ying
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR4896T AND SLS2046M ON 26/5/2018
Attachments: SecureMessageAtt.html



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ
เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을
읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2018-06-04 15:11 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009965/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 01-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLR 4896T	Veh. Inspected	SLS 2046M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	WINNIE FAN	Assign Date	01/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/05/2018	Inspection Date	01/06/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 28/05/2018 13:34
Date Of Accident 26/05/2018 22:25
Exact Location Of Accident SERANGOON RD->UPPER SERANGOON RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLS2046M
Insured/Policyholder
Name Of Registered Owner DARWIN-51 CAR RENTAL PTE LTD
Co Reg No 201407970C
Email Address SALES@N51.COM.SG
Mobile Phone No OFFICE-68425151
Alternative Phone No
Vehicle Particulars
Manufacturer TOYOTA
Model PRIUS ALPHA HYBRID-1.8 S CVT (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company LIBERTY INSURANCE PTE LTD
Type Of Coverage THIRD PARTY
Fleet Policy YES
Policy Number SD17V08976/VPZ/R00
Cover Note Number

Driver

Name of Driver WONG YONG FATT
NRIC No S1724625I
Date Of Birth 11/11/1965
Occupation OUTDOOR
Date Of Driving Pass 16/07/1988
Driving Experience 29 YEARS AND 10 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96659618
Fax Number
Contact Number NOEMAIL
EMail Address

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7909C
Vehicle Details	
Vehicle No.:	SLS2046M
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS ALPHA HYBRID 1.8S CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2ZR1980889
Chassis No.:	ZVW400025897
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,703.00
Original Registration Date:	13 Sep 2017
First Registration Date:	13 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Sep 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$43,978.00
Total Rebate Amount:	\$47,728.00

The information contained herein is correct as at 09 Jun 2018

OK

MOTOR CAR (Fr)

Front Version

NAC	INC	Item	CON	AC	Qty
1001	991560	Frt Number Plate			
1002	991587	Frt Number Plate Base			
1003	991589	Frt Number Plate Garnish			
1004	991590	Frt Bumper	CUT ✓		
1005	992341	Frt Bumper Clips	NEC ✓		
1006	991525	Frt Bumper Bracket	BR ✓		
1007	991452	Frt Bumper Side Retainer	BR ✓		
1008	991433	Frt Bumper Reinforcement	BT ✓		
1009	991318	Frt Bumper Beam	DD ✓		
1010	991468	Frt Bumper Sponge	KRU ✓		
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding	Signal Lamp CUT ✓		
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CUT ✓		
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990132	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995069	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowl			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990131	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990059	Air Cleaner Resonator			
1063	991713	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991714	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Frt Exhaust Pipe			
1067	991714	Exhaust			
1068	991714	Exhaust			
1069	991714	Exhaust			
1070	991714	Exhaust			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	DD ✓		
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp Emblem	NEC ✓		
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	TN ✓		
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	DM ✓		
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre	CUT ✓		60%
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim	DM ✓		
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre	PUN ✓		60%
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: 16 Assets of: 151111

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	SCR	R	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: 515 2046 M

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	SCR	R	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim	SCR	R	
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre	PUN	✓	60%
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 14

Assessor: T.G.U.M.

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ALUMINUM

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

ONE COPY

Vehicle No: SLS 2046 M

[illegible]

Assessor: T. C. Brown

Original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 May 2018 Edit Reg		28 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

POPULAR RENT A CAR PTE LTD, Co. Reg. No.: 199608195Z

Main Claimant:

DARWIN-51 CAR RENTAL PTE LTD, Co. Reg. No.: 201407970C

Vehicle Reg. No.:

SLS2046M

Claim Type:

TP / 5238555091SG

Vehicle Reg. No. (Insured):

SLR4896T

Repairer:

N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2018]

Date of Loss:

26/05/2018 22:00 - :59
[8 Months and 13 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

0999994983 (Comprehensive)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (12/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS2046M (5238555091SG)**
[SLR4896T]
TP
DARWIN-51 CAR RENTAL PTE LTD
May 26 2018 10:00PM
[POPULAR RENT A CAR PTE LTD]
N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	12/06/18 11:15	General View														Load JPG		
2	12/06/18 11:15	General View														Load JPG		
3	12/06/18 11:15	General View														Load JPG		
4	12/06/18 11:15	General View														Load JPG		
5	12/06/18 11:15	General View														Load JPG		
6	12/06/18 11:15	General View														Load JPG		
7	12/06/18 11:15	General View														Load JPG		
8	12/06/18 11:15	General View														Load JPG		
9	12/06/18 11:15	General View														Load JPG		
10	12/06/18 11:15	General View														Load JPG		
11	12/06/18 11:15	General View														Load JPG		
12	12/06/18 11:15	General View														Load JPG		
13	12/06/18 11:15	General View														Load JPG		
14	12/06/18 11:15	General View														Load JPG		
15	12/06/18 11:15	General View														Load JPG		
16	12/06/18 11:15	General View														Load JPG		
17	12/06/18 11:15	General View														Load JPG		
18	12/06/18 11:15	General View														Load JPG		
19	12/06/18 11:15	General View														Load JPG		
20	12/06/18 11:15	General View														Load JPG		
21	12/06/18 11:15	General View														Load JPG		
22	12/06/18 11:15	General View														Load JPG		
23	12/06/18 11:15	General View														Load JPG		
24	12/06/18 11:15	General View														Load JPG		
25	12/06/18 11:15	General View														Load JPG		
26	12/06/18 11:15	General View														Load JPG		
27	12/06/18 11:15	General View														Load JPG		
28	12/06/18 11:15	General View														Load JPG		
29	12/06/18 11:15	General View														Load JPG		
30	12/06/18 11:15	General View														Load JPG		
31	12/06/18 11:15	General View														Load JPG		
32	12/06/18 11:15	General View														Load JPG		
33	12/06/18 11:15	General View														Load JPG		
34	12/06/18 11:15	General View														Load JPG		
35	12/06/18 11:15	General View														Load JPG		
36	12/06/18 11:15	General View														Load JPG		
37	12/06/18 11:15	General View														Load JPG		

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 11:15	General View	 Load JPG	☒
39	12/06/18 11:15	General View	 Load JPG	☒
40	12/06/18 11:15	General View	 Load JPG	☒
41	12/06/18 11:15	General View	 Load JPG	☒
42	12/06/18 11:15	General View	 Load JPG	☒
43	12/06/18 11:15	General View	 Load JPG	☒
44	12/06/18 11:15	General View	 Load JPG	☒
45	12/06/18 11:15	General View	 Load JPG	☒
46	12/06/18 11:15	General View	 Load JPG	☒
47	12/06/18 11:15	General View	 Load JPG	☒
48	12/06/18 11:15	General View	 Load JPG	☒
49	12/06/18 11:15	General View	 Load JPG	☒
50	12/06/18 11:15	General View	 Load JPG	☒
51	12/06/18 11:15	General View	 Load JPG	☒
52	12/06/18 11:15	General View	 Load JPG	☒
53	12/06/18 11:15	General View	 Load JPG	☒
54	12/06/18 11:15	General View	 Load JPG	☒
55	12/06/18 11:15	General View	 Load JPG	☒
56	12/06/18 11:15	General View	 Load JPG	☒
57	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
58	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
59	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
60	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
61	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
62	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
63	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
64	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
65	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
66	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
67	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
68	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
69	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
70	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
71	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
72	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
73	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
74	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
75	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
76	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
77	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
78	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
79	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
80	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
81	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
82	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
83	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
84	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
85	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
86	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
87	12/06/18 11:16	Dismantled Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
89	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
90	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
91	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
92	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
93	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
94	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
95	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
96	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
97	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
98	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
99	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
100	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
101	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
102	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
103	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
104	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
105	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
106	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
107	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
108	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
109	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
110	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
111	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
112	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
113	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
114	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
115	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
116	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
117	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
118	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
119	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
120	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
121	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
122	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
123	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
124	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
125	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
126	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
127	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
128	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
129	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
130	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
131	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
132	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
133	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
134	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
135	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
136	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
137	12/06/18 11:16	Dismantled Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
139	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
140	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
141	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
142	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
143	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
144	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
145	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
146	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
147	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
148	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
149	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
150	12/06/18 11:16	Dismantled Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/18 11:27	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009965/GZ4D3E2

Date: 04/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994983
 Claimant Vehicle No: SLS2046M Insured Vehicle No: SLR4896T
 Date of Loss: 26/05/2018 Nature of Claim: TP Claim No: 5238555091SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS2046M**
 Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A) Engine No: 2ZR1980889
 Reg. Date: 13/09/2017 (Man. Year: 2017) Chassis No: ZVW400025897
 Colour: Grey Odometer: 75552 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Haida 5 mm Rear Left Side: Haida 5 mm
 Front Right Side: Haida 5 mm Rear Right Side: Haida 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2018
 Date Inspected: 01/06/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI
 BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 9.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Broken	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*FRT BUMPER BEAM	Dented	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Crumpled	0.00 F	*- F
8	1		*FRT BUMPER SIGNAL LAMP	Cut	0.00 F	*- F
9	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F
10	1		*FRT LH FENDER	Dented	0.00 F	*- F
11	1		*FRT LH FENDER EMBLEM	Necessary	0.00 F	*- F
12	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
13	1		*FRT LH WHEEL RIM	Damaged	0.00 F	*- F
14	1		*FRT LH TYRE (60%)	Cut	0.00 F	*- F
15	1		*FRT RH WHEEL RIM	Damaged	0.00 F	*- F
16	1		*FRT RH TYRE (60%)	Punctured	0.00 F	*- F
17	1		*REAR BUMPER	Repair	0.00 F	*- F
18	1		*REAR LH FENDER	Repair	0.00 F	*- F
19	1		*REAR RH WHEEL RIM	Repair	0.00 F	*- F
20	1		*REAR RH TYRE (60%)	Punctured	0.00 F	*- F
21	1		*REAR LH SHOCK ABSORBER	Bent	0.00 F	*- F
22	1		*FRT RH KNUCKLE ARM	Bent	0.00 F	*- F
23	1		*FRT RH LOWER ARM	Bent	0.00 F	*- F
24	1		*FRT RH TIE ROD	* Check	0.00 F	*- F
25	1		*FRT RH DRIVE SHAFT	* Check	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >