

ASS. REC. BY:

REF:

C83AIG18009072/G24d302

Special Instruction:

SURVIVOR:

penmen

GQ

ASSIGNMENT (Office)

From (Person):

Chin lee ying

of

AIG

Date/Time:

31/5/18 @ 4:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 9426G

Insured:

SKT 8179E

at Workshop m/s

Heng Kee

Tel:

9666 3922

of

Blk 1033, Eunus Ave 5A # 01-30

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/05/2018

CA / REV / REP. / REV 24 HRS 'wup'

H.O.D. Endorsement:

Date/Time: 2:03pm @ 1/6/18

Person Contacted:

Izwan

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SKP 9426G *
	8/1/18
11/6/18	After Repair

08-10-18
Surrey

PRS
K22

REF: AIG

ASSIGNMENT

From: _____ Date: **4/6/18**
Estimated Cost: _____
OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: **SKP 94266**
at Workshop m/s: **Heng Kee**
of: **81K 1033, Eunus Ave SA #01-30**
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: **46** days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **1 up**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SKP 94266** Yr Regn: **-** /
Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **Nissan Sylphy** C.C. **1598**
Colour: **White** A/C: Insured / Std / NI / NA
Sp. Reading: **37589** T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: **MNTBBA B 172 00 20552**
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: ☒ Nil / S/Rim / STD A/Rim or
Tyre Size: F: **195/60R16**
R: **11**
☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal. **6** mm R/Bal. **6** mm
L/Bal. **6** mm L/Bal. **6** mm
D.O.A. _____ D.O.I. **04-06-18**
Survey held at **W/S** **11:30 AM**
Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
3/7/18	Submit DAR Reg 09.

RECEIVED 03 JUL 2018

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I. (\$) _____

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

_____ \$ + RS. _____ \$

) Photos

) Others

TOTAL

180

20

200

From: Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Sent: Thursday, 31 May 2018 4:26 PM
To: assignments@lkkauto.com; Admin A
Cc: Fong, Andy-SY
Subject: - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKT8179E AND SKP9426G ON 23/05/2018
Attachments: SecureMessageAtt.html



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ
เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을
읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2018-06-07 16:26 +08 to read your message.
' After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009972/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 01-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKT 8179E	Veh. Inspected	SKP 9426G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	01/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/05/2018	Inspection Date	
Survey held at	HENG KEE WORKSHOP 1033 EUNOS AVENUE 5A #01-31 EUNOS INDUSTRIAL ESTATE SINGAPORE 409703		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

MOTORCAR (Rear)

Rear Portion

Vehicle No: **SKP 94264**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	SCR	R	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	SCR	✓	
1156	993044	Rear Bumper Reflector	CUT	✓	1
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	BT	✓	
1160	993339	Rear End Panel Top Garnish	BT	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR	R	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding (Lower Chrome)	SCR	✓	
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber	CUT	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: **10**

Assessor: **TG Lim**

[Signature]
29/6/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jun 2018		31 May 2018 00:00	\$S\$0.00	\$S\$0.00		Pending for Survey Report
	Edit Reg		Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	WONG JIAN LI JACKSON, ID: S8211697D								
Main Claimant:	-								
Vehicle Reg. No.:	SKP9426G	Date of Loss:	23/05/2018 00:00 - :59						
Claim Type:	TP / 5736534867SG	Policy/Cover Note No.:	2100419081 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKT8179E	Policy No. (Claimant):							
		Excess:							
Repairer:	Heng Kee Workshop (HQ) BLK 1033 EUNOS AVENUE 5A #01-31, 409703 Eunos - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2018]								
Claimant's Solicitor:	KERTAR & SANDHU LLC - Tel: 65366266								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
• AIG_SG (12/06/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS			View All	Search Tasks	Create New Task	Complete			
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKP9426G (5736534867SG)**
[SKT8179E]

TP

-

May 23 2018 12:00AM
[WONG JIAN LI JACKSON]
Heng Kee Workshop

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Photos/ Images											3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print
1	12/06/18 11:12	General View									 Load JPG	☒
2	12/06/18 11:12	General View									 Load JPG	☒
3	12/06/18 11:12	General View									 Load JPG	☒
4	12/06/18 11:12	General View									 Load JPG	☒
5	12/06/18 11:12	General View									 Load JPG	☒
6	12/06/18 11:12	General View									 Load JPG	☒
7	12/06/18 11:12	General View									 Load JPG	☒
8	12/06/18 11:12	General View									 Load JPG	☒
9	12/06/18 11:12	General View									 Load JPG	☒
10	12/06/18 11:12	General View									 Load JPG	☒
11	12/06/18 11:12	General View									 Load JPG	☒
12	12/06/18 11:12	General View									 Load JPG	☒
13	12/06/18 11:12	General View									 Load JPG	☒
14	12/06/18 11:12	General View									 Load JPG	☒
15	12/06/18 11:12	General View									 Load JPG	☒
16	12/06/18 11:12	General View									 Load JPG	☒
17	12/06/18 11:12	General View									 Load JPG	☒
18	12/06/18 11:12	General View									 Load JPG	☒
19	12/06/18 11:12	General View									 Load JPG	☒
20	12/06/18 11:12	General View									 Load JPG	☒
21	12/06/18 11:12	General View									 Load JPG	☒
22	12/06/18 11:12	General View									 Load JPG	☒
23	12/06/18 11:12	General View									 Load JPG	☒
24	12/06/18 11:12	General View									 Load JPG	☒
25	12/06/18 11:12	General View									 Load JPG	☒
26	12/06/18 11:12	General View									 Load JPG	☒
27	12/06/18 11:12	General View									 Load JPG	☒
28	12/06/18 11:12	General View									 Load JPG	☒
29	12/06/18 11:12	General View									 Load JPG	☒
30	12/06/18 11:12	General View									 Load JPG	☒
31	12/06/18 11:12	General View									 Load JPG	☒
32	12/06/18 11:12	General View									 Load JPG	☒
33	12/06/18 11:12	General View									 Load JPG	☒
34	12/06/18 11:13	Photo After Spray									 Load JPG	☒
35	12/06/18 11:13	Photo After Spray									 Load JPG	☒
36	12/06/18 11:13	Photo After Spray									Load JPG	☒
37	12/06/18 11:13	Photo After Spray									Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 11:13	Photo After Spray	Load JPG	☒
39	12/06/18 11:13	Photo After Spray	Load JPG	☒
40	12/06/18 11:13	Photo After Spray	Load JPG	☒
41	12/06/18 11:13	Photo After Spray	Load JPG	☒
42	12/06/18 11:13	Photo After Spray	Load JPG	☒
43	12/06/18 11:13	Photo After Spray	Load JPG	☒
44	12/06/18 11:13	Photo After Spray	Load JPG	☒
45	12/06/18 11:13	Photo After Spray	Load JPG	☒
46	12/06/18 11:13	Photo After Spray	Load JPG	☒
47	12/06/18 11:13	Photo After Spray	Load JPG	☒
48	12/06/18 11:13	Photo After Spray	Load JPG	☒
49	12/06/18 11:13	Photo After Spray	Load JPG	☒
50	12/06/18 11:13	Photo After Spray	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/18 17:08	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009972/GZ4D3E2

Date: 04/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100419081
Claimant Vehicle No : SKP9426G **Insured Vehicle No :** SKT8179E
 Date of Loss: 23/05/2018 Nature of Claim: TP Claim No: 5736534867SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP9426G**
 Make & Model: NISSAN SYLPHY, 1.5 (A) Engine No: HIDDEN
 Reg. Date: (Man. Year:) Chassis No: MNTBBAB17Z0020552
 Colour: White Odometer: 37589 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/05/2018
 Date Inspected: 04/06/2018 Inspected At: Heng Kee Workshop (HQ)
 BLK 1033 EUNOS AVENUE 5A #01-31
 Singapore 409703
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	0.00 F	*- F
2	1		*REAR BUMPER MOULDING	Scratched	0.00 F	*- F
3	1		*REAR BUMPER REFLECTOR	Cut	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR END PANEL	Bent	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Bent	0.00 F	*- F
7	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
8	1		*BOOTLID	Repair	0.00 F	*- F
9	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
10	1		*BOOTLID MOULDING (LOWER CHROME)	Scratched	0.00 F	*- F
11	1		*BOOTLID LAMP LH	* Check	0.00 F	*- F
12	1		*BOOTLID LOCK	Bent	0.00 F	*- F
13	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >