

ASS. REC. BY:

REF: CS3/AIG18010043/G24d312

Special Instruction:

Survivor
Nurmen

GQ

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

4/6/18 @ 10:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLQ 8554J

Insured:

SLB 6249H

at Workshop m/s

Heng Kee

Tel:

9666 3922

of

Blk 1033, Eunus Ave SA # 01-30

Policy No.:

Claim No.:

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A.

24/5/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:47am 4/6/18

Person Contacted:

Irwan

Vehicle IN OUT

IN

Date/Time

Action/Instruction (X) Estimate

SLQ 8554J - X

SLB 6249H - NBA / AIG18009506/Y

DUA: 24/5/2018

11/6/18

Dismantled

PRS
XAL

REF: AIG

ASSIGNMENT

From: _____ Date: **4/6/18**
 Estimated Cost: _____
 OD / TP / N/S / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SLQ 8554J**
 at Workshop m/s: **Heng Kee**
 of: **Blk 1033, Euros Ave SA# 01-30**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: **Irwan@96663922**



(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **9** days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS **up**
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SLQ 8554J** Yr Regn: -
 Type: **M** Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota wish** cc **1797**
 Colour: **white** A/C Insured / Std / NI / NA
 Sp Reading: - T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **8GE 20 6031 092**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD **A/B** or
 Tyre Size: F: **215/50R17**
 R: **11**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A. _____ D.O.I. **04-06-18**
 Survey held at: **w/s** **11:50 AM**
 Des. of Damages: **Front** / **Rear** / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
21/6/18 **Submit DAR Report**

Date/Time: File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time: File Return to?

Add Fee: ☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech. Insp. (\$)
☐ Weekend (\$)

Survey Fee: _____
 Transportation: _____
 1. Photos _____
 1. Chart _____

Report Format: _____
 Lump Sum / I.B.I. (\$)

180
20
200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SLB6249H AND SLQ8554J ON 24/05/2018.**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: 4/6/2018 10:18:45 AM
Attachments:  Fax95F1.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



KERTAR & SANDHU

ADVOCATES & SOLICITORS

UEN: 201625241N

Kertar Singh LLB (Hons) England
Barrister-at-Law, Middle Temple

James Sebastian LLB (Hons) Singapore
Advocate & Solicitor (Singapore)

Anil Sandhu LLB/LLP (Hons) Australia (S.A.)
Solicitor (Supreme Court of South Australia)

Adam Ong LLB (Hons) King's College London, UK
Advocate & Solicitor (Singapore)

Kertar & Sandhu LLC
133 New Bridge Road
#11-10, Chinatown Point
Singapore 059413
Tel: 6536 6266 | Fax: 6557 0313
(not for service of court documents)
E-mail: kertar@kertarlaw.com.sg

Your Ref: To be Advised
Our Ref: JS/0845/18/rs

Date: 1st June 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claims Department

Dear Sir

PRE-REPAIR INSPECTION

**YOUR INSURED VEHICLE REGISTRATION NO: SLB6249H
ACCIDENT ON 24th MAY 2018 INVOLVING SLQ8554J, GBG8357H, SGK5284Z, SLB6249H
AND GBG9786X AT 1700 HRS ALONG SLE TOWARDS CTE BEFORE EXIT 9**

We are instructed by General Leasing Pte Ltd to notify you of a road traffic accident on 24/05/2018 at approximately 1700 hours along SLE towards CTE before Exit 9 involving our client's vehicle registration number SLQ8554J and the vehicle registration number SLB6249H driven by your insured at the material time. A copy of the Singapore Accident Statement filed is enclosed herewith.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **TWO (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulation timeline, our client shall proceed to repair the said vehicle without further reference to you.

Please note that the pre-repair survey can be carried out at Blk 1033, Eunos Avenue 5A, #01-30, Singapore 409703 and the contact person is Mr. Irwan who can be reached at 96663822.

BY FAX (6835 7416) &
BY POST



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18010043/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLB 6249H	Veh. Inspected	SLQ 8554J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/05/2018	Inspection Date	04/06/2018
Survey held at	HENG KEE WORKSHOP 1033 EUNOS AVENUE 5A #01-31 EUNOS INDUSTRIAL ESTATE SINGAPORE 409703		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Front Fillion

NAC	INC	Item	CON	AC	Qty
1001	991580	Frt Fender Flare	BT		
1002	991587	Frt Number Plate Base	RA		
1003	991589	Frt Number Plate Garnish			
1004	991590	Frt Bumper			
1005	991591	Frt Bumper Clips			6
1006	991592	Frt Bumper Brackets			
1007	991593	Frt Bumper Side Reinforcer			
1008	991594	Frt Bumper Reinforcement	BT		2
1009	991595	Frt Bumper Beam			
1010	991596	Frt Bumper Sponge	RA		
1011	991597	Frt Bumper Protector			
1012	991598	Frt Bumper Pad			
1013	991599	Frt Bumper Grille			
1014	991600	Frt Bumper Moulding			
1015	991601	Frt Bumper Lower Spoiler			
1016	991602	Frt Bumper Sensor			
1017	991603	Frt LH Bumper Fog Lamp Cover	ER		
1018	991604	Frt RH Bumper Fog Lamp Cover	ER		
1019	991605	Frt LH Bumper Fog Lamp			
1020	991606	Frt RH Bumper Fog Lamp			
1021	991607	Frt Grille	BN		
1022	991608	Frt Grille Emblem			
1023	991609	Frt Grille Chrome Moulding			
1024	991610	Frt Apron Panel			
1025	991611	Frt Support Panel	BT		
1026	991612	Frt Support Panel Top Garnish Cover	BT		
1027	991613	Horn			
1028	991614	Frt Bumper Panel			
1029	991615	Frt LH Headlamp Assy	ER		
1030	991616	Frt RH Headlamp Assy	ER		
1031	991617	Frt LH Side Lamp			
1032	991618	Frt RH Side Lamp			
1033	991619	Bonnet	DO		
1034	991620	Bonnet Emblem	NG		
1035	991621	Bonnet Lock	BT		
1036	991622	Bonnet Insulator			
1037	991623	Bonnet Flange	BT		2
1038	991624	Bonnet Damper			
1039	991625	Bonnet Rubber			
1040	991626	Bonnet Cable			
1041	991627	Bonnet Stand			
1042	991628	Air Con Condenser	DO		
1043	991629	Air Con Fan Assy	GT		
1044	991630	Air Con Suction Pipe (Low Pressure)			
1045	991631	Air Con Suction Hose			
1046	991632	Air Con Discharge Pipe (High Pressure)			
1047	991633	Air Con Discharge Hose			
1048	991634	Air Con Liquid Pipe			
1049	991635	Air Con Receiver Drier			
1050	991636	Air Con Compressor Assy			
1051	991637	Air Con Belt			
1052	991638	Radiator			
1053	991639	Radiator Cooling	GT		
1054	991640	Radiator Fan Assy			
1055	991641	Radiator Fan Clutch			
1056	991642	Radiator Hose Top			
1057	991643	Radiator Hose Bottom			
1058	991644	Radiator Expansion Tank			
1059	991645	Air Duct	GT		
1060	991646	Air Cleaner Assy			
1061	991647	Air Cleaner Hose			
1062	991648	Air Cleaner Resistor			
1063	991649	Frt Exhaust Manifold			
1064	991650	Frt Exhaust Manifold Cover			
1065	991651	Exhaust Manifold Sensor (Oxygen)			
1066	991652	Exhaust Pipe			
1067	991653	Exhaust Flange			
1068	991654	Exhaust Gasket			
1069	991655	Exhaust Hanger			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990948	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Fuel Tank Panel			
1124	990753	Dashboard Assy			
1125	992382	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994483	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Brake Pedal			

Signature
18/6/2018

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	cut ✓		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	new ✓	6	
1147	992976	Rear Bumper Bracket	LA ✓	DD	
1148	993068	Rear Bumper Side Retainer	DIS ✓	2	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	LA ✓	BC ✓	1
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM ✓		
1159	993327	Rear End Panel	DIS ✓		
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	cut ✓		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD ✓		
1182	991328	Tailgate Emblem	new ✓	2	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector	cut ✓		
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	BT ✓		
1198	994651	Tailgate Rubber	BT ✓		
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

Vehicle No: SKR 855AJ

No of Items: _____

Assessor: _____

18/6/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2018 Edit Reg		04 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	RUHAIDI BIN HASSAN, Co. Reg. No.: -								
Main Claimant:	GENCARS PTE LTD, Co. Reg. No.: -								
Vehicle Reg. No.:	SLQ8554J	Date of Loss:	24/05/2018 17:00 - :59						
Claim Type:	TP / 7508032534SG	Policy/Cover Note No.:	2100460719 (Comprehensive)						
Vehicle Reg. No. (Insured):	SL86249H	Policy No. (Claimant):							
		Excess:							
Repairer:	Heng Kee Workshop (HQ) BLK 1033 EUNOS AVENUE 5A #01-31, 409703 Eunos - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2018]								
Claimant's Solicitor:	KERTAR & SANDHU LLC - Tel: 65366266								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (12/06/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ8554J (7508032534SG)
[SLB6249H]
TP
GENCARS PTE LTD
May 24 2018 5:00PM
[RUHAIDI BIN HASSAN]
Heng Kee Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	12/06/18 11:19	General View														Load JPG	☒	
2	12/06/18 11:19	General View														Load JPG	☒	
3	12/06/18 11:19	General View														Load JPG	☒	
4	12/06/18 11:19	General View														Load JPG	☒	
5	12/06/18 11:19	General View														Load JPG	☒	
6	12/06/18 11:19	General View														Load JPG	☒	
7	12/06/18 11:19	General View														Load JPG	☒	
8	12/06/18 11:19	General View														Load JPG	☒	
9	12/06/18 11:19	General View														Load JPG	☒	
10	12/06/18 11:19	General View														Load JPG	☒	
11	12/06/18 11:19	General View														Load JPG	☒	
12	12/06/18 11:19	General View														Load JPG	☒	
13	12/06/18 11:19	General View														Load JPG	☒	
14	12/06/18 11:19	General View														Load JPG	☒	
15	12/06/18 11:19	General View														Load JPG	☒	
16	12/06/18 11:19	General View														Load JPG	☒	
17	12/06/18 11:19	General View														Load JPG	☒	
18	12/06/18 11:19	General View														Load JPG	☒	
19	12/06/18 11:19	General View														Load JPG	☒	
20	12/06/18 11:19	General View														Load JPG	☒	
21	12/06/18 11:19	General View														Load JPG	☒	
22	12/06/18 11:19	General View														Load JPG	☒	
23	12/06/18 11:19	General View														Load JPG	☒	
24	12/06/18 11:19	General View														Load JPG	☒	
25	12/06/18 11:19	General View														Load JPG	☒	
26	12/06/18 11:19	General View														Load JPG	☒	
27	12/06/18 11:19	General View														Load JPG	☒	
28	12/06/18 11:19	General View														Load JPG	☒	
29	12/06/18 11:19	General View														Load JPG	☒	
30	12/06/18 11:19	General View														Load JPG	☒	
31	12/06/18 11:19	General View														Load JPG	☒	
32	12/06/18 11:19	General View														Load JPG	☒	
33	12/06/18 11:19	General View														Load JPG	☒	
34	12/06/18 11:19	General View														Load JPG	☒	
35	12/06/18 11:19	General View														Load JPG	☒	
36	12/06/18 11:19	General View														Load JPG	☒	
37	12/06/18 11:19	General View														Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 11:19	General View	 Load JPG	☒
39	12/06/18 11:19	General View	 Load JPG	☒
40	12/06/18 11:19	General View	 Load JPG	☒
41	12/06/18 11:19	General View	 Load JPG	☒
42	12/06/18 11:19	General View	 Load JPG	☒
43	12/06/18 11:19	General View	 Load JPG	☒
44	12/06/18 11:19	General View	 Load JPG	☒
45	12/06/18 11:19	General View	 Load JPG	☒
46	12/06/18 11:19	General View	 Load JPG	☒
47	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
48	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
49	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
50	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
51	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
52	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
53	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
54	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
55	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
56	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
57	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
58	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
59	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
60	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
61	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
62	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
63	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
64	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
65	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
66	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
67	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
68	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
69	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
70	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
71	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
72	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
73	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
74	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
75	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
76	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
77	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
78	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
79	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
80	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
81	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
82	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
83	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
84	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
85	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
86	12/06/18 11:19	Dismantled Parts	 Load JPG	☒
87	12/06/18 11:19	Dismantled Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/18 11:58	01 GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties	

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18010043/GZ4D3E2

Date: 27/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100460719
 Claimant Vehicle No: SLQ8554J Insured Vehicle No: SLB6249H
 Date of Loss: 24/05/2018 Nature of Claim: TP Claim No: 7508032534SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ8554J
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: HIDDEN
 Reg. Date: (Man. Year:) Chassis No: ZGE206031092
 Colour: White Odometer: 0 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/06/2018
 Date Inspected: 04/06/2018 Inspected At: Heng Kee Workshop (HQ)
 BLK 1033 EUNOS AVENUE 5A #01-31
 Singapore 409703
 Estimated Period of Repair: 9.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*-F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*-F
3	1		*FRT BUMPER	Cracked	0.00 F	*-F
4	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
5	2		*FRONT BUMPER SIDE RETAINER	Distorted	0.00 F	*-F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*-F
7	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*-F
8	1		*FRT BUMPER GRILLE	Broken	0.00 F	*-F
9	1		*FRT LH BUMPER FOG LAMP COVER	Broken	0.00 F	*-F
10	1		*FRT RH BUMPER FOG LAMP COVER	Broken	0.00 F	*-F
11	1		*FRT GRILLE	Broken	0.00 F	*-F
12	1		*FRT SUPPORT PANEL	Bent	0.00 F	*-F
13	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Distorted	0.00 F	*-F
14	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*-F
15	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*-F
16	1		*BONNET	Repair	0.00 F	*-F
17	1		*BONNET EMBLEM	Necessary	0.00 F	*-F
18	1		*BONNET LOCK	Bent	0.00 F	*-F
19	2		*BONNET HINGE	Bent	0.00 F	*-F
20	1		*AIR CON CONDENSER	Dented	0.00 F	*-F
21	1		*AIR CON FAN ASSY	Cut	0.00 F	*-F
22	1		*RADIATOR COWLING	Cut	0.00 F	*-F
23	1		*AIR DUCT	Cut	0.00 F	*-F
24	1		*REAR BUMPER	Cut	0.00 F	*-F
25	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
26	1		*REAR BUMPER BRACKET LH	Dented	0.00 F	*-F
27	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*-F
28	1		*REAR BUMPER REFLECTOR LH	Broken	0.00 F	*-F
29	1		*REVERSE SENSOR	Damaged	0.00 F	*-F
30	1		*REAR END PANEL	Bent	0.00 F	*-F
31	1		*REAR END PANEL TOP GARNISH	Distorted	0.00 F	*-F
32	1		*REAR LH TAILLAMP	Cut	0.00 F	*-F
33	1		*TAILGATE	Dented	0.00 F	*-F
34	2		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
35	1		*TAILGATE REFLECTOR	Cut	0.00 F	*-F
36	1		*TAILGATE LOCK	Bent	0.00 F	*-F
37	1		*TAILGATE RUBBER	Bent	0.00 F	*-F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >