

22/03/2002

ASS. REC. BY:

REF:

MSG18010050/GHd3et

Special Instruction:

Surveyor:

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

1/6/18 @ 4:20pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLG 1191X

Insured:

SFR 30232

at Workshop m/s

Soon Seng Company

Tel:

96431861

of

160 Bin Ming Drive # 04-05

Policy No:

28688534DMA

Claim No:

559917

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/5/2018

CA / REV / REP. / REV 24 HRS

(cup)

06.062018

H.O.D. Endorsement:

Date/Time:

9:35am @ 4/6/18

Person Contacted:

Sherol

Vehicle:

IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLG 1191X - X

SFR 30232 - X

7/6/18

Dismantled

(08/11/13)

Surveyor

KRS
Karl

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SLG1191X

Yr Regn: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Mazda 3

c.c

1496

Colour

Black

A/C:

Insured / Std / NI / NA

Sp.Reading

60815

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JM6B M 42A 8G0340783

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

06-06-18

Survey held at

w/s

4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 2500 - 3500

* 2 days

12/6/18 Submit PRS Report.

RECEIVED 13 JUN 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

120

50

10

180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 May 2018		01 Jun 2018 16:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Mr Janardan Rai, ID: S1842130E		
Main Claimant:	A&A CAPITAL SINGAPORE PTE. LTD., Co. Reg. No.: 201727424G		
Vehicle Reg. No.:	SLG1191X	Date of Loss:	28/05/2018 19:00 - :59 [20 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559917	Policy/Cover Note No.:	28688534DMA Coverage: 15/03/2018 - 14/03/2019
Vehicle Reg. No. (Insured):	SFR3023Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Soon Seng Company () 160 Sin Ming Drive, #04-05 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/06/2018]		
Adj Asg. Remarks:	on WP, TP disagree on SJE- Please appoint to LKK Auto Consultants. Liability not clear - OI non reporting. Contact Person : Mr Amos @ 9643 1861		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18010050/Gz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-06-2018



Code : MSG

Policy Particulars :- (THIRD PARTY CLAIM)

1.	Insured Veh.	SFR 3023Z	Veh. Inspected	SLG 1191X
	Policy No.	28688534DMA	Coverage (\$)	0.00
	Claim No.	559917	Excess (\$)	0.00
	Assign From	MERIMEN (KATHERINE WONG)	Assign Date	04/06/2018

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.	Engine No.	HIDDEN	Inspection Date	04/06/2018
	Accident Date	28/05/2018		
	Survey held at	160 SIN MINGDRIVE # 04-05		
	Repairer	SOON SENG COMPANY		

Remarks

5a.

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 May 2018		01 Jun 2018 16:18 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Mr Janardan Rai , ID: S1842130E									
Main Claimant: A&A CAPITAL SINGAPORE PTE. LTD., Co. Reg. No.: 201727424G									
Vehicle Reg. No.:	SLG1191X	Date of Loss:	28/05/2018 19:00 - :59 [20 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 559917	Policy/Cover Note No.:	28688534DMA Coverage: 15/03/2018 - 14/03/2019						
Vehicle Reg. No. (Insured):	SFR3023Z	Policy No. (Claimant):							
		Excess:							
Repairer: Soon Seng Company () 160 Sin Ming Drive, #04-05 Sin Ming Autocity, 575722 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Imm.Advice due 02/06/2018]									
Adj Asg. Remarks: on WP, TP disagree on SJE- Please appoint to LKK Auto Consultants. Liability not clear - OI non reporting. Contact Person : Mr Amos @ 9643 1861									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG1191X (559917)**
[SFR3023Z]
TP
A&A CAPITAL SINGAPORE PTE. LTD.
May 28 2018 7:00PM
[Mr Janardan Rai]
Soon Seng Company

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/06/18 12:36	General View	Load JPG	<input checked="" type="checkbox"/>
21	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
22	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
23	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
24	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
25	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
26	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
27	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
28	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
29	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
30	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
32	12/06/18 18:27	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/06/18 08:45	PRI notice.	Load PDF	
2	01/06/18 09:42	TP disagree on SJE + workshop details & our reply.	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18010050/GZ4D3E2

Date: 14/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28688534DMA

Claimant Vehicle No : SLG1191X

Insured Vehicle No : SFR3023Z

Date of Loss: 28/05/2018

Nature of Claim: TP

Claim No: 559917

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG1191X

Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A)

Engine No: P520363490

Reg. Date: 21/09/2016 (Man. Year: 2016)

Chassis No: JM6BM42A8G0340783

Colour: Black

Odometer: 60815 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Toyo 6 mm

Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/06/2018

Date Inspected: 06/06/2018 Inspected At:

Soon Seng Company
160 Sin Ming Drive, #04-05 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2018)
Parts:	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG1191X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >